

FILE NAME: Johns-Manville (JMA)

DATE: 1976 Sept 30

DOC#: JMA293

DOCUMENT DESCRIPTION: Report - Study of Asbestos Elimination
Replacement and Personnel Protection - Prepared for the Naval
Ship Engineering Center

102 800240


9

30 September 1976

STUDY OF
ASBESTOS ELIMINATION
REPLACEMENT AND
PERSONNEL PROTECTION

Prepared for
Naval Ship Engineering Center
Mr. A. Winer
Code 6101E

Under
NAVSEC Contract N00024-76-C-4451
Task 6101-30



By: Designers & Planners, Inc.
3700 East West Highway, #106
Hyattsville, Maryland 20782
D&P Task 4476/50

502633

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 Introduction	1
1.1 Scope	1
1.2 Approach	1
2.0 Results	3
2.1 Background	3
2.2 Protective Clothing	4
2.2.1 Coveralls	6
2.2.2 Shoe Coverings	6
2.2.3 Gloves	7
2.2.4 Hoods	7
2.3 Respirators	8
2.3.1 General	8
2.3.2 OSHA Requirements	8
2.3.3 NIOSH Requirements	9
2.3.4 Navy Requirements	10
2.3.5 Activities Involved	10
2.3.6 Identification of Approved Respirators	11
2.4 Welders Blanket	13
2.5 Asbestos Millboard	14
2.5.1 Kaowool "M" Board and Fiberfrax Hot Board	14
2.5.2 Millboard Used in Boilers	14
2.5.3 Joiner Bulkheads (PHM-1)	15
2.5.4 Welders Booths	16
2.6 Pipe Hanger Liners	17
2.6.1 Present Requirements	17
2.6.2 Status of Liner Program	19

TABLE OF CONTENTS (Cont'd.)

<u>Section</u>	<u>Page</u>
2.6.3 Results	20
2.7 Measurement Program	21
2.8 Miscellaneous Items	22
2.8.1 Fireman's Clothing	22
2.8.2 Asbestos Pump Vanes	22
2.8.3 Machinery Space Escape Trunks	22
2.8.4 Anti Sweat Paints	23
3.0 Recommendations	24
3.1 General	24
3.2 Insulation color coding	24
3.3 Technical Manual Revision	24
3.4 Respirator Air Supplies	26
3.5 Disposable Clothing	27
3.6 Pipe Hanger Liners	29
3.7 Millboard	29
APPENDIX A - Facilities and Agencies Consulted	30
APPENDIX B - Item Control Recommendations	33

1.0 INTRODUCTION

1.1 Scope

This report has been prepared by Designers and Planners (D&P) Inc. in response to NAVSEC Task 6101-30 under contract NU-024-76-4451. The task concerns engineering studies of asbestos replacement and personnel protection in Naval shipboard applications.

Specifically, the following subtasks were identified as part of this task.

- o Consultation with the Navy Environmental Health Center with reference to equipment and protective clothing to be used during asbestos rip-out, selection of pass/fail criteria for operations on asbestos containing materials and examination of the usefulness of electron microscopy.
- o Preparation of Item Control Recommendations for entering new items into the Supply System.
- o Determination of substitutes for asbestos millboard.
- o Provision of liaison with NAVSECPHILADIV on tests of asbestos substitute materials.
- o Provision of support and liaison with NAVSECPHILADIV relative to substitutes for asbestos pipe hanger liners.

1.2 Approach

In order to accomplish the task, several actions were taken based largely upon the knowledge and contacts made during the preceding studies carried out under NAVSEC Task 6101-22. Those actions included:

- o Consultation with each of the Naval Shipyards on the status protective clothing, pipe hanger liners, and the use of asbestos millboard.
- o Consultation with NAVSECPHILADIV and NAVSHIPYDPHILA on the status of pipe hanger liner substitutes and test results and asbestos millboard substitutes.
- o Consultation with vendors of protective clothing, respirators and insulation.
- o Consultation with NAVENVIRHLTHCEN personnel on the asbestos pass/fail criteria, measurement program, and selection of materials.

Results of the study are discussed in Section 2 of this report which is organized as follows:

Protective clothing,
Respirators, Supplied-Air
Welders blankets

Millboard

Pipe hanger liners

Measurement Program

Miscellaneous Items

Recommendations are made in Section 3 of this report.

2.0 RESULTS

2.1 Background

The U.S Navy, in response to national safety and health requirements concerning asbestos, has instituted procedures designed to insure reduced personnel exposure to this hazard. These procedures include use of safety equipment, ventilation, and improved asbestos removal procedures. Concurrent efforts have been initiated to define suitable replacement materials for asbestos containing products.

OPNAVINST 6260.1 of 9 April 1974, specified limits of exposure of Naval personnel to asbestos. The Chief, Bureau of Medicine and Surgery, was assigned technical responsibility for evaluating asbestos exposures. The Chief of Naval Material was directed to provide technical assistance to define appropriate industrial hygiene controls and develop remedial projects.

NAVSEA Instruction 5100.2, 24 October 1975, established NAVSEA policy on the elimination of asbestos in ship construction and maintenance and directed actions to further reduce asbestos exposure. The following specific policy items were addressed:

- a. Asbestos and materials containing asbestos shall not be used in the construction, overhaul, repair, and maintenance of naval vessels nor shall such materials be used in any facility or operational application where suitable alternate materials have been designated. However, in locations where asbestos materials are presently installed rip-out operations shall not be performed for the sole purpose of eliminating asbestos.

502638

b. This instruction applies to all asbestos containing materials but the implementation details are currently available for thermal insulation only. As additional substitute materials are developed, appropriate specification and instruction revisions shall be made for implementation of this policy.

c. Personnel working with asbestos shall be provided with, and be required to use, protection and safeguards in accordance with OPNAVINST 6260.1.

Chapter 635 of the Naval Ships Technical Manual (NSTM) was revised, 15 April 1976, to eliminate asbestos containing insulation, bringing it into correspondence with MIL-STD-769 and related specifications for asbestos free insulation. Appendix A of Chapter 635 provides safety instructions for insulation workers.

Under the title of "Asbestos Replacement/Personnel Protection Program," tasks were assigned in support of OPNAVINST 6260.1 and NAVSEA INST 5100.2. Subtasks were assigned to NAVSECPHILADIV for tests of asbestos substitutes, to NAVENVIRHLTHCEN for measurements of asbestos contamination and program recommendations, and to D&P as described in Section 1.1.

2.2 Protective Clothing

Appendix A of Chapter 635 of the NSTM states (635-A.2.2)

d. Asbestos and fibrous glass handlers disposable coveralls and clothing in accordance with MIL-C-29133 (Navy) providing whole body, head, hand, and foot coverings for use by personnel exposed to airborne concentrates of asbestos fibers shall be provided. Cloth hoods, such as painters hoods, shall be worn for head covering. Disposable plastic gloves

shall be worn to protect hands. Cloth gloves may be worn inside the plastic gloves for comfort, but shall not be used alone. Sleeves shall be made secure at the wrist by use of flaps provided or by use of masking tape. Stock numbers for coveralls by size are:

X-Small	NSN 8415-00-601-0792
Small	NSN 8415-00-601-0793
Medium	NSN 8415-00-601-0794
Large	NSN 8415-00-601-0797
X-Large	NSN 8415-00-601-0801
XX-Large	NSN 8415-00-601-0802

The Naval Shipyards were surveyed to find how acceptable were the coveralls listed above and to find out what shoe coverings and gloves were being used and their acceptability.

It was painfully clear that the instructions contained in the NSTM have not filtered down to the shop level as of 15 September 1976. At least four of the lagging shops in the eight yards had not seen the new Chapter 635 of the NSTM, and were not aware of the clothing requirements.

The Navy Clothing and Textile Research Unit, Natick, Massachusetts is the activity responsible for the development of clothing items and related specifications. The Clothing and Textile Unit, Defense Supply Agency, Philadelphia, Pennsylvania, is the control point.

The information contained in this protective clothing section of this report is current as of 15 September 1976.

Disposable protective clothing is widely available in plastic materials. Polyolefin (TYVEK is duPonts' trade name for spun bonded olefin), polyethylene, polyvinylchloride and rayon are a few of those materials. While flame resistance varies, all melt when exposed to flame and under some conditions may cause serious burns.

2.2.1 Coveralls

A laminated cellulosic material is called MIL-C-29133, from which the MIL-C-29133 coveralls are made. The specification requires that the material not melt or drip in the flame test. One trade name for the cellulosic material is KAYCEL.

Three users of the coveralls in the stock system (MIL-C-29133) report general satisfaction with the items. Every user reported that they tear easily when snagged on sharp objects. Two users reported that the XX-Large size is not large enough for some of their workers. One previous user reported that the stitching is inadequate and is now using double stitched KAYCEL coveralls obtained on local purchase.

One previous user found that the clothing did not breathe well enough and tended to creep and bind in the shoulder and crotch. As a result that yard is using a launderable 60/40 cotton dacron blend coverall. Several iterations of laundering procedure (done under contract) were required to get the residual asbestos fiber content down. The problem was primarily in pocket areas; pockets are being eliminated.

The remaining three yards are using local purchase disposable coveralls, made of TYVEK.

2.2.2 Shoe Coverings

Two yards are using the shoe covering (bootie), in insulation work, that has been put into the system for nuclear workers (NSN 8430-00-890-2079). These booties meet MIL-F-82240, and are

vinyl chloride film (Type 1, class 2 of L-P-375). One of the two yards is ordering the bootie, to MIL-F-82240, except for white or green color (the stock numbered item is yellow). Two other yards are using plastic booties bought under local purchase. Four are not using any shoe covering or are taping plastic to coveralls.

2.2.3 Gloves

Three yards are using cotton gloves (NSN 8415-00-268-8330). One yard is using a leather drivers glove. One yard is using a vinyl coated cloth glove. Three yards are using disposable plastic gloves of differing types; two are using surgical gloves, one yard for all applications, one yard only when handling cement (which irritates skin).

2.2.4 Hoods

Two yards are not using hoods. Two are fabricating hoods locally from cotton cloth. Two are using a disposable hood made of TYVEK. One is using a hood which is part of an approved air-fed respirator systems.

When air-fed respirators are used, NIOSH approval is for respirator systems, which include specific hoods. Substitution of elements of the respirator system, for example, using one hood in place of another, technically invalidates the approval. For additional information on respirator systems see Section 2.3.

2.3 Respirators

2.3.1 General

Basic standards are set by the Occupational Health and Safety & Health Administration (OSHA). The National Institute for Occupational Safety and Health (NIOSH) acts in an advisory capacity to OSHA and, among other duties, tests and certifies items of safety equipment for workers such as respirators. NIOSH prepares and publishes lists of certified products.

The Navy, by means of OPNAVINST 6206.1 and NAVSEAINST 5100.2, promulgated requirements for respiratory protection (and other protective devices) for workers engaged in asbestos work. In addition, the Naval Ship Technical Manual Chapter 635, Appendix A, deals with the required protective devices.

2.3.2 OSHA Requirements

These are found in CFR Title 29, Chapter XVII. Section 1910.93(d)(2)iii delineates three different classes of respirators depending on the expected concentration of airborne asbestos. The type of respirators required vs the limiting airborne asbestos concentrations are given below. Limit refers either to the ceiling or to the eight hour time weighted average.

<u>TWA</u>	<u>Type respirator</u>
Less than 10X limit	A
10 - 100X limit	B
over 100X limit	C

502643

The current time weighted average limit (effective 1 July 1976) is 2 asbestos fibers per cubic centimeter of air, with a ceiling exposure limit of 10 fibers per cubic centimeters of air. Since the extent of exposure cannot be predicted well it must be assumed that a shipboard worker engaged in asbestos insulation removal would require a Type C respirator.

Type C respirators are defined as a supplied-air continuous flow or pressure demand respirator which consists of a source of respirable breathing air, a hose, a detachable coupling, a control valve, an orifice, a demand valve or pressure demand valve, an arrangement for attaching the hose to the wearer, and a facepiece, hood or helmet. Regulations for approval of respirators are defined in 30 CFR Part 11. Approvals under these regulations are issued jointly by the U.S. Department of the Interior, Mining Enforcement and Safety Administration (MESA) and NIOSH.

Additional requirements relating to the air supply are found in OSHA regulation 1910.134(d)2(ii) which requires temperature monitoring of the air.

The quality of air supply for human breathing is defined in the Compressed Gas Association Commodity Specification G-7.1-91966 (Class D).

2.3.3 NIOSH Requirements

NIOSH under authorization of the Coal Mine Health and Safety Act of 1969 and the Occupational Safety and Health Act of 1970, provides a testing, approval and certification program and develops performance regulations, tests and certifies

protective devices and verifies the quality of manufacture of these devices.

Supplied respirators which are certified by NIOSH are given by manufacturer and model number in Appendix G of the D4 report on Task 6101-22, dated 30 June 1976. It must be emphasized here that these certifications are for complete Type C supplied air respirator systems and any interchange of parts from different vendors would render the NIOSH certification invalid.

2.3.4 Navy Requirements

General

The requirements for respiratory protection for personnel engaged in asbestos work are given in OPNAVINST 6260.1 and NAVSEA INST 5100.2. In addition Appendix A to Naval Ships Technical Manual Chapter 635 (NAVSEA 901-LP-635-0000) calls out safety requirements for insulation workers. This chapter also references Chapter 9880, Section II, of NSTM (Damage Control: Practical Damage Control).

In general, these three documents follow the OSHA and NIOSH requirements but to be in strict accordance, Chapter 635 requires minor changes. These are given in Section III, Recommendations, of this report.

2.3.5 Activities Involved

Within the Department of Defense, the Defense Supply Agency unit at Richmond, Va. controls Defense General Supplies including PSC 4240, respirators. The Naval Construction Battalion, Port

Hueneme, California, prepares specifications for respirators. Edgewood Arsenal, Maryland, tests respirators for the Military services.

GGG-M-125 is the general specification for respirators and respirator assemblies. Shash sheets specify individual types of respirators. Supplied air respirators are covered in the following shash sheets:

GGG-M-125/1	Respirator Assemblies: Air Line, with Facepiece (Supplied Air).
GGG-M-125/2	Respirator Assemblies: Air Line, Helmet, (Supplied Air).
GGG-M-125/3	Respirator Assemblies: Air Line, with Disposable Hood, (Supplied Air).

GGG-M-125/9 is a supplied air respirator for abrasive blasting operations and /10 and /11 have powered-air-purifying units. The other respirators protect against gases and dusts. In addition to the MESA/NIOSH approval requirement under 30 CFR, Part 11, the specifications contain requirements for such aspects as lens quality, marking, etc.

GGG-M-130 is a specification for disposable filter masks.

2.3.6 Identification of Approved Respirators

An attempt was made to correlate the OSHA, NIOSH, and Navy requirements for respirators with the applicable federal specifications and standards and to determine which approved supplied-air respirators had National Stock Numbers (NSN) and could be assumed to be in the federal supply system.

To this end, various codes in NAVSEC and NAVSEA were queried

5026.6

as well as the Defense Supply Agency (DSA) Item Identification Group in Richmond, Va. No correlation could be established. Therefore, two principal manufacturers of this equipment were consulted and no correlation could be established. It does not appear that air supplied respirators of an approved type are in the federal stock system.

2.4 Welders Blanket

While no completely satisfactory substitute for welders blankets and cloths has been found, a number of materials are available for use. To introduce these materials into the stock system as interim materials, Item Control Recommendations, NAVSUP Form 87, were prepared for the following items, see Appendix B:

1. An 18 ounce amorphous silica fabric (REFRASIL - UC 100-48)
2. A 34 ounce amorphous silica fabric (REFRASIL - UC 100-06)
3. An amorphous silica fabric, coated with silicone rubber (to 22 ounces) (REFRASIL C 100-48 (Red))
4. A fibrous glass fabric coated with silicone rubber (to 32 ounces) (FABRICOTE 1584)

100

THE UNITED STATES OF AMERICA

DEPARTMENT OF THE ARMY

OFFICE OF THE ADJUTANT GENERAL

WASHINGTON, D. C.

1. THE ADJUTANT GENERAL IS THE OFFICIAL

WHOSE DUTY IT IS TO ASSIST THE COMMANDING

OFFICER IN THE PERFORMANCE OF HIS

DUTIES AND TO ACT AS HIS DEPUTY


AND

TO ASSIST HIM IN THE PERFORMANCE

OF HIS DUTIES AND TO ACT AS HIS

DEPUTY IN THE PERFORMANCE OF HIS

RETAKE TARGET .



2.5 Asbestos Millboard

Asbestos millboard is intended for interior use to serve as temporary protection against fire (surface flame spread), heated gas, liquid or solid objects and against acids and corrosive liquids.

It is available in sheet form with thicknesses of 1/6, 1/8, 3/16, 1/4, 3/8, and 1/2 inch, and widths of 42 inches and lengths of 48 or 96 inches (HH-M-351E).

2.5.1 Kaowool "M" Board and Fiberfrax Hot Board

NAVSECPHILADIV investigated the acceptability of Kaowool M board and Fiberfrax Hot Board as a substitute for calcium silicate high temperature insulation block (MIL-I-2819F). This check was undertaken because 1" thick insulation block was sometimes in short supply. Preliminary reports are that "M" board and Hot Board are acceptable substitutes, however, costs are considerably higher and they are not manufactured in thicknesses less than 1/2 inch. Indications are that the 1" calcium silicate is no longer in short supply and substitution should not be necessary.

2.5.2 Millboard Used in Boilers

NSTM 9510, Boilers, defines methods for constructing boiler furnace decks, rear and sidewall linings. The use of millboard is not called for, and materials other than those listed under NSTM 9510.116 are to be used only in an emergency.

502649

NSTM 9510 calls for a one inch thickness of insulating block next to the steel casings. It has been reported that some boiler furnace plans call for 1-1/8 or 1-1/4 inch of insulating block next to the boiler casing. Insulating block under MIL-I-2819F is supplied in thickness of 1, 1-1/2, 2, 2-1/2, 3, 3-1/2, or 4 inches. Therefore, asbestos millboard is sometimes used to make up the required thickness of insulating block next to the boiler casing. As an alternative to asbestos millboard it was reported that a layer of mineral wool has sometimes been used.

An example of the variance in the Naval shipyard use of asbestos millboard can be drawn between Philadelphia and Norfolk Naval Shipyards. Philadelphia Naval Shipyard, Shop 41 (Boiler) stated they did not use asbestos millboard and had no need for a substitute; at Norfolk Naval Shipyard, Shop 41 reported that they occasionally used asbestos millboard in 1/8 or 1/4 inch thicknesses to build up the required thickness of insulation next to the boiler casings. An example given was the recent use of asbestos millboard in the boilers on the USS America (CV66).

2.5.3 Joiner Bulkheads (PHM-1)

An asbestos containing material was used as a bulkhead liner in the engine compartment and as some joiner bulkheads on the PHM-1. It was not identified as asbestos millboard but as asbestos containing material.

The specifications for the follow on PHM-3 class vessels state that asbestos free material shall be used in its construction.

502650

No retrofit is presently scheduled to remove the asbestos containing material. However, when an ROH is scheduled, replacement will be considered.

2.5.4 Welders Booths

No instances were found where asbestos millboard was being used as dividers for welders booths. These booths are normally partitioned using REFRASIL or one of the many other fibrous glass cloths available.

2.6 Pipe Hanger Liners

In some applications, asbestos tape or cloth has been used to line hangers which support piping runs aboard ships. The lining reduces heat transmission. Some Naval shipyards have been substituting fibrous glass tape in those applications. D&P was requested to review the acceptability of the substitution.

2.6.1 Present Requirements

General Specifications for Ships, Section 505

For services below 200 degrees F, pipe hangers shall be lined with a liner material to prevent metal to metal contact between the pipe clamp and pipe when the pipe clamp and pipe are of dissimilar materials.

For services from 200 degrees F up to 650 degrees F, pipe hangers shall be lined with a liner material to prevent metal-to-metal contact between the pipe clamp and the pipe. For services above 650 degrees F., minimum contact hangers shall be used.

For all hot services, the hanger rod between the pipe clamp and resilient mount shall be of sufficient length to preclude mounts from being subjected to temperatures in excess of 140 degrees F.

Applicable liner materials shall be in accordance with Table 6. Asbestos liner materials shall not contain any metallic particles or reinforcing wires.

TABLE 6. PIPE HANGER LINER MATERIAL

Temp., degrees F	Liner material & Form	Applicable specification
Up to 180	Synthetic rubber channel, block type or sheet rubber cemented to hanger clamp	MIL-B-6855, class II, 60 durometer
Over 180 to 450	Silicone rubber	ZZ-R-765, class II, 60 durometer
Over 450 to 650	Asbestos: Felt, Tape,	HH-P-1784 SS-C-466, form IV, or HH-T-1782 class I, grade AA or AAA

TABLE 6. (CONTINUED)

Cloth

SS-C-466, form
I, grade AA or
Reinforced); or
SS-C-1783, class
I, grade AA or
AAA;

Sheet

HH-P-46

Standard Drawings

Hangers, pipe for surface ships Dwg # 810-1385781
For sound and vibration reduction, the pipe clamp
shall be lined with 1/4 in. thick rubber. Liner
to be in accordance with MIL-R-6855, class 2, 60
durometer for fluid temperatures up to 125°F.

For piping with fluid temperatures above 125°F a
liner of 1/8 in. asbestos in accordance with SS-
C-466, type IV shall be provided between the
pipe and clamp.

Hangers, pipe for submarines Dwg. # 5000-S4823-1385782
where piping temperature exceeds 180°F the following
materials shall be used in lieu of rubber, MIL-S-6855
specified in the list of materials:

- (A) Silicon rubber, SS-R-765 Class II grade 60
Max 550°F), or
- (B) Asbestos felt, MIL-F-20077, or
- (C) Asbestos tape MIL-C-4117, Cl 1 (non-metallic)
Type XX or XXI Grade AA, AAA or AAAA
- (D) Non-wire reinforcing cloth, SS-C-466 (Navy-
ships), of a style containing not less than
90 percent asbestos.

2.6.2 Status of Liner Program

NAVSEC, Philadelphia had previously been assigned a task to determine through shop (laboratory) test, the acceptability of fibrous glass pipe hanger liners. This is an ongoing task which has not been completed as of the date of this report.

In conjunction with this an attempt was made (by both NAVSECPHILADIV and D&P) to determine if the Naval Shipyards had used fibrous glass pipe hanger liners aboard ship in the past and if so, had the application/results been satisfactory.

Personnel in the Design and Production Departments of the Naval Shipyards were asked to identify ships in which fibrous glass liners had been installed. The following ships were tentatively identified as having had fibrous glass pipe hanger liners installed:

SSN 596	Mare Island
SSN 618	Mare Island
SSN 620	Portsmouth
SSN 635	Portsmouth
SSN 646	Portsmouth
SSN 664	Portsmouth
SSN 673	Portsmouth
SSN 674	Portsmouth
SSN 676	Portsmouth
FF 1072	Charleston
FF 1078	Charleston

Three fibrous glass products have been identified as being used by the shipyards as pipe hanger liner material.

ALPHA	ALPHA
Portsmouth	Claremont #100
Charleston	NSN 8315-00-267-1632
	NSN 8315-00-267-1633

It was the intent of this task to identify and visit several ships which had had fibrous glass pipe hanger liners installed, and the liners would then be examined to see how well they had withstood pounding, vibration, wetness, etc.

2.6.3 Results

Since shipyard personnel could not positively identify on which piping system or in which compartments the liners had been installed, no ship visits were made.

Without positive location of fibrous glass liners, it would be costly and difficult to examine their performance because in general the hangers and liners are enclosed by the insulation covering the pipes. To inspect the liner the insulation must be removed, and subsequently it must be replaced.

If inspection of liners in service revealed no damage, it would not guarantee that fibrous glass would be an acceptable substitute in all applications for long term use because the conditions of use would not be known. On the other hand, if inspection revealed damaged liners, it could lead to a general prohibition of use.

Three fibrous glass products have been identified as being used by the shipyards as pipe hanger liner material.

Mare Island	ALPHA Catalog #3201
Portsmouth	Claremont #19T25
Charleston	NSN 8315-00-267-1632
	NSN 8315-00-267-1633

It was the intent of this task to identify and visit several ships which had had fibrous glass pipe hanger liners installed, and the liners would then be examined to see how well they had withstood pounding, vibration, wetness, etc.

2.6.3 Results

Since shipyard personnel could not positively identify on which piping system or in which compartments the liners had been installed, no ship visits were made.

Without positive location of fibrous glass liners, it would be costly and difficult to examine their performance because in general the hangers and liners are enclosed by the insulation covering the pipes. To inspect the liner the insulation must be removed, and subsequently it must be replaced.

If inspection of liners in service revealed no damage, it would not guarantee that fibrous glass would be an acceptable substitute in all applications for long term use because the conditions of use would not be known. On the other hand, if inspection revealed damaged liners, it could lead to a general prohibition of use.

Therefore, it is believed that inspection of existing fibrous glass liners would have limited value. If the two pipe hanger liner drawings and the NSTM requirements are taken together, fibrous glass liners are required only in the range 550°F to 650°F. One option is to extend the use of limited contact liners downward to include the range 550°F to 650°F to eliminate the use of asbestos and the need for another substitute.

2.7 Measurement Program

The Navy Environmental Health Center has been funded to conduct an asbestos measurement program and to make recommendations for changes to asbestos handling procedures and equipment. Discussions were held with the Center to transmit, in advance of this report, our findings and what information we had gained since the report on Task 6101-22.

2.8 Miscellaneous Items

In the course of the study a number of applications of asbestos were uncovered or reviewed. Discussion of each of these items follows.

2.8.1 Fireman's Clothing

D&P was asked to review the status of fireman's clothing.

As with the disposable clothing, the Navy Clothing and Textile Research Unit is responsible for fireman's clothing. At present fireman's clothing is made from an aluminized asbestos/aramid (nylon) fabric (MIL-C-29143) backed up with a quilted lining. While the Clothing and Textile Research Unit is aware of the asbestos problem they are not funded in FY 1977 to develop a replacement for the asbestos/aramid cloth.

2.8.2 Asbestos Pump Vanes

The Auxiliary Equipment Branch (NAVSEC 6153D) has approved the substitution of Ryton (Polyphenylene Sulfide plus glass and Teflon filler) for the previously used Melamine Asbestos in vane pumps supplied to the Navy by Blackmer Pump Division of the Dover Corporation.

2.8.3 Machinery Space Escape Trunks

To minimize heat transfer to ladders in machinery space escape trunks, the present design uses asbestos insulating pads between the ladder and the bulkhead. In proposing redesigns which meet the intent of the General Specifications for Ships, one of the criteria being assumed by D&P is the use of non asbestos insulation in the application.

2.8.4 Anti Sweat Paints

D&P was asked to investigate anti-sweat paints of two types.

1. Coating Compound, Paint Antisweat, TT-C-492C.
2. Paint, Fire-Retardant, MIL-P-15144, plus Vermiculite, MIL-V-15196.

The coating compound, FSC 8010, is controlled by the Federal Supply Service. TT-C-492C specifies the components of the paint except for an extender which is nominally 90% by weight of the pigment (27% of the product weight). There are two approved suppliers. One supplier states that the extender is entirely antimony oxide. The other supplier states the extender is 20% diatomaceous silica and 7% asbestos by weight of solids.

The fire retardant paint contains no asbestos. The specification for vermiculite, MIL-V-15196 has been superseded by HH-I-585, Insulation, Thermal, Vermiculite, which calls out ASTM Standard C516 for Vermiculite. No mention is made of asbestos.

3.0 RECOMMENDATIONS

3.1 General

In the course of this study a number of recommendations were made. Discussion of those recommendations is presented below.

3.2 Insulation Color Coding

The bulk of the insulation in Navy ships is block or pre-formed insulation. Use of such insulation containing asbestos is presently prohibited, but it is difficult to distinguish between asbestos-containing and asbestos-free forms of block and preformed insulation during rip-out. (It is relatively much easier to distinguish between asbestos cloth and fibrous glass cloth and between other forms of asbestos containing insulation and the substitutes.) It is suggested that insulation manufacturers be requested to color code the insulation for all users. (Manufacturers have objected to the problems involved in setting up a separate line for Navy products). In that way, if in future rip-out non-color-coded insulation were encountered, personnel would at least be alerted to the danger. Non-color-coded asbestos-free insulation installed up to the change over point would continue to be treated as though it were asbestos-containing. At present there is no way of knowing which material is being torn-out, and there appears to be no assurance that the situation will be resolved at any point in the future.

3.3 Technical Manual Revision

It is apparent that the promulgation of safety requirements through Chapter 635 of the Naval Ships Technical Manual is not

rapid enough to insure compliance in a timely manner. Also, in view of the unsettled status of protective clothing and respirators in terms of what is both safe and acceptable and in terms of clear identification, it is recommended that the Technical Manual be revised to contain only policy statements and that the implementation of those policy statements through recommendations for use of specific items of equipment or clothing be made directly to the expected users. For example:

1. Change Appendix A to NSTM Chapter 635 relating to respiratory protection as follows:
 - (a) Paragraph 2.b.1 change "type A, class II" to read "NIOSH Certified Type C supplied air respirators."
 - (b) Delete paragraphs 2.b.(2) & 2.b.(3) for two reasons: one, the specified breathing apparatus is not NIOSH certified for this application and also these respirators are emergency equipment stored in the damage control locker and should be so reserved.
2. Do not assign NSN's to air-supplied respirators. Approved respirators are available from industry in a timely fashion via purchase under "Authorized Federal Supply Schedule Catalogs" by manufacturers' item numbers. The respirators are under FSC Group 4240. Example: Item NIS-2390, New Item Introductory Schedule, Contract Number GS-00C-31030, Minnesota Mining & Manufacturing Co., St. Paul, Minn., 55101 Dept. 220-7W.

502600

However, one problem is that fleet activities do not normally have access to such documents. For those activities data must be provided so that they can order suitable protective equipment. The NSTM should not be relied upon to provide timely dissemination.

This recommendation is made in light of the large number of repair and replacement parts required for each model respirator and the fact that mixing of various items of vendors equipment is not only difficult but would invalidate the NIOSH Certification.

3.4 Respirator Air Supplies

Investigate the compatibility of existing air supplies for these respirators with the applicable OSHA and NIOSH requirements. Of particular interest are the safety and standby devices per OSHA regulation 1910.134(d)2(ii).

3.5 Disposable Clothing

As discussed above, in spite of the instructions contained in Chapter 635 of the NSTM, lagging shops in the shipyards are using a wide variety of clothing items, including in some cases no protection. It is also clear that there is some dissatisfaction with the disposable coveralls now in the stock system. The following are recommended.

1. Request the Navy clothing and Textile Research Unit to revise the existing specifications for disposable coveralls (MIL-C-29132 for the material and MIL-C-29133 for the coverall) to increase tear resistance, revise the stitching, add additional sizes, and add requirements to minimize creep and bunching.
2. Since Recommendation 1 is expected to require a year to two years to accomplish, as an interim solution permit the yards to use local purchase of coveralls.
3. Review the fire safety requirements of the coveralls, and if found to be a hazard, prohibit the use of plastic disposable clothing (such as TYVEK and vinyl).
4. Request the Navy Environmental Health Center to determine whether KAYCEL clothing is adequate to protect against asbestos dust.

5. Direct the Naval Shipyards to use full protective clothing and supplied air respirators, as described in Appendix A of NSTM Chapter 635, by more rapid and direct means than the NSTM.
6. Revise Chapter 635 of the NSTM to include the rationale for use of Class C (supplied-air) respirators, i.e., that 100 X the 8 hour time weighted average limit or ceiling limit is expected to be exceeded during any asbestos rip-out.

3.6 Pipe Hanger Liners

1. Continue the effort to identify locations on the ships listed where fibrous glass pipe hanger liners were installed. If such locations can be identified visit those ships to determine acceptability.

2. Continue laboratory tests being conducted by NAVSEC-PHILADIV.

3. Inform all Naval Shipyards that fibrous glass has not been approved as an acceptable material for pipe hanger liners, and to use General Specifications for Ships and Naval Standard Drawings as reference for approved materials.

4. Select a ship now in overhaul and install alternative liner materials in identified locations with the intent of examining the liners after, say, a years' operating service.

5. Alternatively, revise the General Specification and pipe hanger drawings to delete reference to asbestos materials and to require the use of silicone rubber (ZZ-R-765) up to temperatures of 550°F and minimum contact pipe hangers above that temperature. (There are differences in application temperatures in the drawings and the specifications, see 2.6.1.)

3.7 Millboard

Since no application can be found for millboard (for which it is required), it is recommended that its use be prohibited.

50266-1

APPENDIX A
FACILITIES AND AGENCIES CONSULTED

502665

Federal Supply Service

Paints

Mr. Baldeman

(212) 557-5357 *

Defense Supply Agency, Richmond, Va.

Item Identification

Mr. Oakley

695-4410

Engineering

Mr. Woods

695-3664

U.S. Navy

Portsmouth Naval Shipyard

Shop 56 Superintendent

Mr. Parent

684-2364

Shop 56 Planner

Mr. Patch

684-2350

Code 260.12

Mr. Legere

684-2293

Philadelphia Naval Shipyard

Shop 56 Asst. Supt.

Mr. Sweeney

443-3320

Code 262

Mr. Wolfe

433-3387

Shop 41

Mr. Hilton

433-2260

Norfolk Naval Shipyard

Industrial Hygienist

Mr. Marr

961-4319

Shop 56

Mr. Callis

961-5330

Shop 41

Mr. Scott

961-5743

Charleston Naval Shipyard

Shop 56 Materials

Mr. Schwertsberger

794-5501

Shop 56

Mr. McBride

794-5488

Shop Stores

Ms. Lindsey

794-2713

Long Beach Naval Shipyard

Shop 26 General Foreman

Mr. Vollrath

360-7797

* Commercial number if area code is given, otherwise AUTOVON.

Shop 56 General Foreman	Mr. Webi	360-6406
-------------------------	----------	----------

Code 906 Safety Issue	Mr. Cauley	360-6836
-----------------------	------------	----------

Pipe Shop	Mr. Davis	360-6449
-----------	-----------	----------

Shop Stores Supervisor	Ms. Sharlean	360-6896
------------------------	--------------	----------

Mare Island Naval Shipyard

Shop 64 General Foreman	Mr. McFadden	253-2373
-------------------------	--------------	----------

Technical Supply	Mr. Pollard	253-4402
------------------	-------------	----------

Code 260	Mr. Schmutz	253-2277
----------	-------------	----------

Puget Sound Naval Shipyard

Pipe Shop	Mr. Nelson	439-7849
-----------	------------	----------

Shop 56 General Foreman	Mr. Rogers	439-7444
-------------------------	------------	----------

Shop 56 General Foreman	Mr. Brown	439-3221
-------------------------	-----------	----------

Pearl Harbor Naval Shipyard

Safety Office	Mr. Roberts	(808) 471-3471
---------------	-------------	----------------

Naval Ship Engineering Center, Philadelphia

Mr. Rogus	433-3587
-----------	----------

Mr. Vapniarek	433-3587
---------------	----------

Mr. Burt	433-3914
----------	----------

Naval Ship Engineering Center, Hyattsville

PHM Project Office	Mr. Bebar	(301) 436-1720
--------------------	-----------	----------------

Navy Clothing and Textile Research Unit

R&D (Fireman's Clothing)	Mr. Andruk	955-2173
--------------------------	------------	----------

(Disposable Clothing)	Mr. Seigfried	955-2785
-----------------------	---------------	----------

Specifications (Disposable
Clothing)

Mr. Loparto 955-2789

Planning

Mr. Bailey 955-2785

Navy Environmental Health Center

Mr. Crawl 989-3863

Contractors

Disposable Clothing

Mars Manufacturing Co.

Mr. Fisk (704) 254-0741

Ness Disposables

Mr. Abell (704) 274-2100

Unitrex Products

Mr. Beyer (215) 365-7400

Edmont-Wilson

Mr. Welsh (614) 622-4311

Durafab

Ms. McCoy 817 545-8851

Respirators

3M

Mr. Savin (609) 667-1361

Mine Safety Appliances

Mr. Leary (202) 785-2565

Anti-Sweat Paint

Steven Industries

Mr. Steven (201) 437-6501

Farwest Paint Mfg. Co.

Mr. Sheehan (206) 762-1344

Insulation

Clairemont

Mr. Roy (203) 238-2034

APPENDIX B
ITEM CONTROL RECOMMENDATIONS

502659

1990年12月15日

NOTE: If used in form heading (1) Section of regulation not same (2) Determination of same (3) Determination of other items (4) Determination of existing items

NAME OF ITEM Protective Blanket, High Temperature, Silicone Rubber Coated Lightweight
(Name, as reported)

DISCRIPTION: For new items describe in detail on DD FORM 128, using Federal Classification Patterns, if purchased. Indicate military, Federal, or identification & specification drawing or procurement reference number and indicate known source of supply.

Continuous filament, amorphous silica fabric, 0.024 inch nominal thickness, 18 ounces per square yard, coated both sides with silicone rubber compound (Dow Corning Silastic 5235) to a nominal thickness of 0.026 inch and a nominal weight of 23 ounces per square yard. The material shall comply with MIL-STD-767 and MIL-I-24244, 33 inches wide nominal, in 50 yard rolls. Red in color

Manufacturer's Trade name: REFRASIL Item Code: C-100-48 (Red)

Manufacturer: Fabricote Division of R&S Glass Fabrics Co., Inc., 724 E. 60th Street,
Los Angeles, CA., 90001

Reason for Recommendation: Urgent requirement to eliminate asbestos containing materials

STOCK DATA OF INITIATING ACTIVITY FOR NEW ITEMS AND TRANSFERS OR SYSTEM STOCKS FOR SUPERSEDED AND DISCONTINUED ITEMS
(Numbers based on end of year)

ITEM OR STOCK NO.		ESTIMATED QUANTITY REQUIRED (Units) (Allowance only)	PAST 6 MONTHS ISSUES	ON HAND	ON ORDER	ACCOUNT	UNIT PRICE	UNIT OF ISSUE
REFRASIL C-100-48(Red)		15,000 yds.					\$8.50 yd.	
EXECUTING OFFICIAL (Name, title, and grade)							DATE	

ACTION BY DUSANDA

TADDITIONAL OFFICIAL (Name and title)	(Signature)	DATE 5026, 0...
---------------------------------------	-------------	--------------------

NAVJAG FORM 27-10-511

NOTE: For use in reclassifying (1) transfer of confidential informants; (2) discontinuance of handling of same; (3) assignment of new name; or (4) change of field office.

Protective Blanket High Temperature Silicone Rubber

NAME OF ITEM: _____ (Insert, in capital letters)

DESCRIPTION: For new items describe in detail on DD FORM 148, using Federal Description Pattern if applicable. Attach technical's specification drawing or procurement reference number and include known source if applicable.

Continuous filament, fibrous glass fabric, 0.026 inch nominal thickness, 36 inch nominal width, 50 square yard, coated both sides with silicone rubber compound (MIL-S-2351) to a nominal thickness of 0.039 inch, and nominal weight of 1.5 pounds per square yard. The material shall comply with MIL-S-10-767 and MIL-S-2351. White in color.

Manufacturers Trade Name: FABRICOTE Item Code: 1584 (white)

Manufacturer: Fabricote Division of A&S Glass Fabric Co., Inc., 1001 E. 10th Street,
Los Angeles, CA. 90001.

11 more paper is needed, use plain sheets, numbering them "Page 1 of 11" and showing on it the name and recommendation number of the work.

REASON FOR RECOMMENDATION
Urgent requirement to eliminate asbestos containing materials.
asbestos fibers is a serious health hazard.

STOCK DATA OF INITIATING ACTIVITY FOR NEW ITEMS AND TRANSFERS (ON SYSTEM TICKETS FOR SUPERSEED AND DOWNSIDE TICKETS)

STOCK DATA OF INVESTING FIRM						
(Figure based on end of month)						
ITEM OR STOCK NO.	ESTIMATED YEARLY DIVIDENDS (New companies)	PAST 3 MONTHS YIELD	ON HAND	IN LOAN	SECURITY	NET PRICE
FABRICOTE 1584 (WHITE)	80,000 yds.					\$6.25 yd.

LEADING OFFICIAL (Name, title, and code)

1. 8. 1990

0492

ACTION BY OILBANDER

LEGATIONS OFFICE (How and who)

1. Introduction

100

502671

ITEM CONTROL RECOMMENDATION

NAVSIC FORM 1110-511

NOTE: For use in recommending (1) transfer of equipment and items, (2) discontinuance of stocking of items, (3) assignment of new items, (4) recommendation of existing items for removal of equipment.

FROM: (Address)		NAVSLC (Code 6101)	Mr. A. Winer	(Code)	RECOMMENDATION YEAR NO.	DATE
TO: (Address)		SPCC (Code 5641)	Mr. J. Winer		LOCAL ITEM OR STOCK NO.	
DD FORM 1110-511		FEDERAL DESCRIPTION PATTERN NO.		FEDERAL STOCK NO.		
RECOMMENDATION FOR		RECOMMENDED INVENTORY MANAGER (USDO, Mr.)		STANDARD MILITARY STOCK NO. (If any)		
☐ TRANSFER ☒ NEW ITEM ☐ DISCONTINUANCE ☐ SUPERSEDE						

NAME OF ITEM Protective Blanket, High Temperature, lightweight (Asbestos Free)
(Insert, in capital letters)

DESCRIPTION: For new items describe in detail on DD FORM 146, using Federal Description Pattern, if published, indicate Military Federal or Agency, manufacturer's specification drawing or procurement reference number and indicate known sources of supply.

Continuous filament, amorphous silica fabric, uncoated, 0.026 inch nominal thickness, 18 ounces per square yard. Shall maintain flexibility up to 2000 degrees Fahrenheit. Chloride content shall comply with MIL-I-4754. To be 36 inches nominal width in 50 to 55 yard rolls. Natural color.

Manufacturers Trade Name: REFRASIL- Item Code: UC-100-48

Manufacturer: Materials Division of HITCO, Armco Steel Corporation, 1600 West 135th Street, Gardena, CA., 90249

(If more space is needed, use plain sheets, numbering them "Page 1 of ..." and showing on each the name and recommendation number of initiating activity.)

REASON FOR RECOMMENDATION: Urgent requirement to eliminate asbestos containing materials. Breathing asbestos fibers is a serious health hazard.

STOCK DATA OF INITIATING ACTIVITY FOR NEW ITEMS AND TRANSFERS ON SYSTEM STOCKS FOR SUPERSEDED AND DISCONTINUED ITEMS
(Figures based on end of report)

ITEM OR STOCK NO.	ESTIMATED YEARLY REQUIREMENTS (New items only)	PAST 9 MONTHS STOCK	ON HAND	ON ORDER	ACCOUNT	UNIT PRICE	UNIT OF ISSUE
REFRASIL UC-100-48	30,000 yds.					\$6.58 yd.	

INITIATING OFFICIAL (Name, rank, and code)

(Signature)

DATE

ACTION BY USANDA

INITIATING OFFICIAL (Name and title)

(Signature)

DATE

502672