



INTERNAL CORRESPONDENCE

UNION CARBIDE CHEMICALS COMPANY • INSTITUTE PLANT P. O. BOX 2831, CHARLESTON, WEST VIRGINIA


To (Name) Mr. S. C. Giambruno
Company
Location Industrial Relations

Date 23 October 1963
Originating Dept. Medical Department - Plant 512
Answering letter date

Copy to	Mr. L. N. Dickinson	Mr. J. W. Perry	Subject	Insulation Block Dust Survey
	Mr. N. S. Eastman	Mr. P. E. Henry		Construction Insulation Shop
	Mr. R. A. Huber	Mr. R. A. Neal		<u>Plant 511</u>
	Mr. B. F. King	Mr. D. R. Matheny		
	Dr. E. M. Best	Mr. N. H. Ketcham		
	Dr. C. U. Dernehl	Mr. L. B. Weddell - Safety Dept.		

Enclosed is a very excellent and very complete Industrial Hygiene report on the potential hazardousness of "Thermobestos", "Kaylo" and "Carey-Temp" insulation blocks which have been processed in the Construction Department's Insulation Shop. The report points out definitely that "Thermobestos" and "Carey-Temp" insulation blocks cannot be fabricated safely with existing equipment, but that "Kaylo" insulation blocks can be fabricated safely. Mr. Peele's recommendations are quite definite and I am sure that you will wish to comply with them. I believe this particular project should be considered completed.

If there are any comments, suggestions or criticism, please direct these to me.

Very truly yours,

R. J. Sexton, M.D.
Plant Medical Director

RJS:hl
Enclosures

A02464
PLAINTIFF'S
EXHIBIT
UC-1422

INDUSTRIAL HYGIENE SURVEY

Construction Insulation Shop - Building 511-2018

Report 63-IH-3-G-1

SUMMARY: The Construction Insulation Shop (Building 2018), Plant 512 location, routinely fabricates large quantities of insulation block with ventilated band saws. This more efficient procedure of fabrication has replaced an older, time honored, practice of using simple handsaws to do the job. However, it has, at the same time, created a health hazard resulting from exposure to excessive concentrations of atmospheric dust.

The hazard to health has been evaluated and reported previously* with the result that one material, "Thermobestos" was clearly identified with the hazard (exceeded TLV) and another material, "Kaylo", was safe to fabricate (within TLV). The present report (the third on this subject) was initiated in an attempt to supply answers to three basic questions: (1) was there any error in the original evaluation of "Kaylo", (2) can supplementary exhaust ventilation reduce the "Thermobestos" hazard to within safe acceptable limits, and (3) is a hazard to health produced in the fabrication of a third material, i.e., "Carey-Temp".

The information uncovered in the present evaluation reveals the following facts:

1. "Kaylo" insulation blocks can be safely fabricated with the existing equipment.
2. "Thermobestos" insulation blocks cannot be safely fabricated at the present time with existing equipment, but could be safely fabricated if the exhaust ventilation is improved.
3. The TLV (Threshold Limit Value) for "Carey-Temp" is identical with that established for both "Kaylo" and "Thermobestos", i.e., 20 mppcf (million particles per cubic foot) of air.
4. "Carey-Temp" also cannot be safely fabricated with the existing equipment, but could be if improvements are made in the ventilation system.
5. The original "downdraft" exhaust ventilation rates, on either band saw, do not meet the recommended capture velocity rate of 4,000 fpm (feet per minute).
6. The supplementary "overhead" exhaust ventilation on both band saws, is an improvement and the rates do meet the recommended capture velocity rate of 4,000 fpm.

* I.H. Reports 62-IH-1-G-1 and 62-IH-2-G-1

AU2465

INTRODUCTION: A report, submitted in March 1962, stated that an inhalation hazard to health was produced in the Construction Insulation Shop whenever "Thermobestos" insulation blocks were fabricated. In July 1962, a second survey was conducted in order to evaluate three new "Thermobestos" materials which had been supplied by the manufacturer for evaluation. This survey revealed that, although the inhalation-hazard-to-health had been substantially reduced from that encountered during the first survey, the atmospheric dust concentrations being emitted during fabrication of these new products, were still in excess of the Threshold Limit Values as designated in the first report. Therefore, all recommendations should remain exactly as stated in the initial report of March 1962.

The manufacturer and Union Carbide's Purchasing Department expressed a great deal of concern about the findings revealed in this initial report when it was uncovered that the manufacturer's Research Department also had evaluated these materials and was not able to produce results comparable with those contained in the report of March 1962. That is to say, the atmospheric dust concentrations reported by the manufacturer, when processing "Thermobestos" insulation blocks, were substantially higher than those revealed in Report 62-IH-1-G-1. This revelation disclosed the need for a more extensive evaluation of this problem so as to resolve all differences of opinion relative to the atmospheric dust exposures in this environment.

This decision in favor of further evaluation, promoted the production of a much more extensive study than was originally planned, a study which eventually encompassed three separate intervals of dust sampling, analysis, and evaluation before all of the unanswered health problems could be resolved.

DISCUSSION: These three investigations were actually initiated for the general purposes of both clarification and identification - purposely for clarification of the actual hazard to health (if any) connected with the fabrication of three different insulation materials and identification of acceptable measures for use in reducing all exposures to within safe acceptable limits. However, each investigation occurred for clearly identifiable reasons as explained below:

The investigation of 24 Jan 63 was conducted because:

1. The Johns Manville Company submitted a report, compiled by their Research Department, which contained data that conflicted with that submitted by this department in Report 62-IH-1-G-1.
2. This department desired to clarify the reasons for the discrepancy between the two reports and to identify positively, the actual conditions as they exist in the working environment.

The investigation of 25 and 26 Feb 63 was conducted because:

1. In the preceding investigation, the two insulation materials in question, i.e., "Thermobestos" and "Kaylo" were evaluated inadvertently during the same afternoon, a procedure which was not in keeping with an attempt to simulate the conditions of the original report. In the original report, each material was evaluated on separate occasions so as to preclude the possibility that any one sample might contain dust produced by both operations.

A02466

2. The "Kaylo" insulation material had to be re-evaluated.
3. The Construction Insulation Shop requested that a new insulation material, i.e., "Carey-Temp", be evaluated.

The investigation of 6 Mar 1963 was conducted because

1. The Construction Insulation Shop recently had installed supplementary exhaust ventilation on both band saws and desired to know if this additional control method would reduce the "Thermobestos" dust concentrations to within safe acceptable limits.

A comparison of the reasons listed above discloses that each was different in content and concerned actually with different investigations but all were interrelated in part, i.e., each was concerned with the same environment, the same location and the same specific methods of fabrication. Consequently, the sampling procedures, utilized in each instance, basically were identical and in accordance with the following condensed explanation:

- First: Two methods of fabrication, i.e., cutting and edging, and cutting a radius, were evaluated at each band saw since this is standard practice followed in the fabrication of any insulation material.
- Second: The environmental conditions of both preceding reports, i.e., 62-IH-1-G-1 and 62-IH-2-G-1, were duplicated in that all outside doors to the building were closed.
- Third: Each dust sample was collected in the operator's breathing zone as he worked in the fabrication process.
- Fourth: The complete fabrication of "Carey-Temp" insulation blocks was evaluated in two ways: First, with all available ventilation in operation and second, with only the original downdraft ventilation in operation.

Specialized sampling procedures were utilized also during portions of the latter two investigations, in an endeavor to evaluate the supplementary exhaust ventilation system which had been installed as recommended. These were as follows:

- First: The complete fabrication of "Thermobestos" insulation blocks was evaluated in two ways: First, with all available ventilation in operation and second, with only the original downdraft ventilation in operation.
- Second: The complete fabrication of "Carey-Temp" insulation blocks was evaluated while utilizing all available exhaust ventilation.

AU2467

It is necessary to explain that "Kaylo" insulation blocks were not included as a part of this evaluation since the initial investigation, (performed without supplementary exhaust ventilation) disclosed only one exposure exceeding the TLV of 20 mppcf of air and, therefore, it could be assumed that any ventilation that might be added should be more than adequate in controlling the hazard.

EVALUATIONS:

A. Atmospheric dust exposures:

1. The concentrations of inhalable dust, present in the breathing zone when fabricating any one of the three types of insulation materials, were determined in accordance with the following procedure:
 - a. Three locations and nine different conditions of exposure, as described on Page 9, were selected for evaluation.
 - b. Atmospheric dust samples were collected through the use of the impingement* principle of air sampling. The midjet impinger apparatus (described on Page 5) served as the instrument of use.
 - c. The concentration of dust collected in each sample was established through the use of standard light field microscopic counting techniques as described on Page 5.
2. The size of the particles of inhaled dust was determined, for both "Kaylo" and "Thermobestos", in the initial survey of 1962 in accordance with the procedure described on Page 5. Consequently, no effort was expended to repeat the determination for any of the insulation materials since the sawing techniques as well as equipment, i.e., saw blades with three teeth to the inch operating at 2200 linear feet per minute, were identical on both occasions and, therefore, the size of the particles should not be expected to deviate to any great degree from the prior recorded values.
3. The composition of the dust, i.e., percentage crystalline free silica or percentage asbestos was determined for both "Kaylo" and "Thermobestos" in the initial survey of 1962. Consequently, no effort was expended to repeat this determination since the materials used on both occasions, were reported as being identical in composition. However, since the composition of "Carey-Temp" was not established at any earlier date it was deemed imperative that it be determined and reported at this time. This was accomplished as described on Page 5.

B. Local exhaust ventilation controls:

1. The velocity of the air being exhausted through the ventilation hood openings on both band saws (#1 and #2) was measured through the use of a Model 60 Anemotherm air meter.
2. Four variable conditions of interest were evaluated:
 - a. The velocity of air through the downdraft hood on both saws with all other hoods on the system closed off.

* This means to strike against, as (in this application) the striking or dashing of atmospheric dust particles against the bottom of a small impinger flask containing a specific volume of dust-free water as a collecting medium.

AU2468

- b. The velocity of air through the downdraft hood on both saws with all other hoods on the system open.
- c. The velocity of air through the supplementary overhead hood on both saws with all other hoods on the system closed off.
- d. The velocity of air through the supplementary overhead hood on both saws with all other hoods on the system open.

PROCEDURES: Both sampling and analytical methods were as follows:

SAMPLING:

- 1. All samples used in determining the actual concentrations in air were collected with a midjet impinger apparatus, sampling 0.1 cubic feet of air per minute through impinger flasks containing 15 milliliters of double distilled dust-free water.
- 2. All samples used in obtaining particle size distribution data were collected on millipore filters connected to a small battery-operated pump.

ANALYTICAL:

- 1. Each dust sample was evaluated through the use of a counting procedure referred to as the light field microscopic counting technique.*
- 2. The particle sizing techniques were derived from two separate sources. First, the sample was prepared for sizing in accordance with a permanent mounting method.+ Second, the actual sizing was accomplished in accordance with the recommended technique depicting the use of a filar micrometer and a standard microscope while using both the 43X (high and dry) and the 97X (oil immersion) objectives.†
- 3. The evaluation and free silica determination of "Carey-Temp" material was accomplished through the use of two methods. First, through information supplied by Mr. E. D. Ermenc, Director of Research of the Philip Carey Manufacturing Company and second, through contracted analysis performed by Mr. Thomas M. Durkan, Chief Chemist for the Trudeau Foundation, Inc., Saranac Lake, N. Y.

RESULTS: See Pages 8, 9, 10 and 11.

* Drinker and Hatch: "Industrial Dust", 2nd Edition, pp. 152-153, McGraw-Hill Book Company, Inc., New York, 1954.
 + Pautus, H. J., Talvitie, N. A., Fraser, D. A., and Keenan, R. G.: "Use of Membrane Filters in Air Sampling", A.I.H.A. Quarterly, Vol. 18, p. 269, September, 1957.
 † Drinker and Hatch: "Industrial Dust", 2nd Edition, pp. 166-179, McGraw-Hill Book Company, Inc., New York, 1954.