

THE MANHATTAN RUBBER MFG. DIVISIONOFRAYBESTOS-MANHATTAN, INC.Passaic, N.J.

A study of the health hazards, if any, incident to the inhalation of dust and fumes at the plant of the Manhattan Rubber Mfg. Division of Raybestos-Manhattan, Inc. at Passaic, N.J. was made between September 24, 1934 and November 1, 1934 by the Industrial Health Section of the Metropolitan Life Insurance Company.

MAX GLAUBACH, C.S.R.
CERTIFIED IN
NEW JERSEY & NEW YORK

8-1

Exhibit No.

Per M. H. H. H.

Exhibit A

1*

PLANT CONSTRUCTION

This plant consists of a number of buildings constructed of brick, concrete and steel. The ground floors are of concrete and the remaining floors are of wood.

Natural illumination is furnished by clear glass windows. Artificial illumination is furnished by incandescent electric lights equipped with reflectors.

PLANT PROCESSES

Products manufactured in this plant involving the use of asbestos are: brake lining, brake blocks, and clutch facings.

Three types of brake lining are made. These are lining made from woven asbestos cloth, dry process lining, and wet process lining.

The asbestos cloth is made outside of this plant. The cloth is treated with rubber, cut into strips and folded to the size desired. The folding is done in Department 36 on machine #1513. This lining is cut to length in Department 8 on machine #1382. The dry process lining is made from a mixture of asbestos, rubber, resin, litharge and cotton. The mixture is made up in Department 53T in a rotary mixer. Canadian asbestos is used. The asbestos as received is put through a hammermill and then through a picker and over a shaker screen. The other materials are kept in containers. After the mixture is completed, it is taken to Department 53. The mixture is weighed and pressed into sheets in a heated press. Several of these sheets are heated in a press for a given time. The sheets are then cut into strips to the desired width on a mill planer. The strips are ground to the desired thickness in Gardner

25

surface grinders. They are then cut to length and formed to a given radius in a heated press. Holes are drilled in the lining on a gang drill machine. The ends are chamfered on abrasive wheels. The lining is inspected and packed for shipment.

The wet process lining is made from a mixture of asbestos, rubber, litharge and waste material from the finished product of Department 53. This mixture is made up in Department 53T. The different materials are kept in containers in stalls. A movable scale is equipped with an exhaust system so arranged that two stalls and the scale are exhausted at the same time. When the materials from the two stalls are weighed, the scale is moved to the next two stalls. The workman weighing out these materials is very careless in the handling of the lead used. He uses a hand scoop and manages to get the lead on his hands and clothes and on the floor. He wears a Willson silica respirator.

Gasoline is used as a solvent for the rubber. The mixing is accomplished in a mixer with rotating paddles. The material is then taken to Department 53 where it is formed into strips by means of an hydraulic press and a mold. The strips are dried in heated presses, ground to size in the Gardner Grinders and cut to length with an abrasive wheel. The lining is then formed on heated mandrels to the desired radius. Holes are drilled and the corners are chamfered. The lining is inspected and packed for shipment.

The brake blocks are made from a mixture of asbestos, rubber, resin, lead, etc. This mixture is made in Department 53T. The blocks are formed in heated molds and in a steam press in Department 52. The blocks are then turned to size on a lathe and cut to width on a band saw. They are finally put into

a sandblast cabinet and the surfaces are blasted. Holes are drilled and the finished block is inspected before shipment.

Dry process clutch facings are made from a mixture of asbestos, rubber, lead, resin, sulphur, carbon black and waste from Department 39. These materials are mixed in Department 53T in a rotary mixer and the mixture is carted to Department 39. The material is weighed and the clutch facings are formed in heated molds and presses. The facings are then ground to the desired thickness, holes are punched, and the facings are inspected before shipment.

One cloth type clutch facing is made from woven asbestos cloth treated with rubber. The cloth is folded and circled on a coning machine. The folded cloth is cut and the ends are fastened together. The facing is then put into heated molds and pressed in a steam press. After coming from the mold, the facing is ground to the thickness desired and holes are punched.

The other type of cloth clutch facing is made by punching the rubber treated cloth to size and then putting several thicknesses into the molds. The separate pieces are molded together and then they follow the same processes as the other facings.

The base stock of the rubber used throughout the different departments is compounded in Department 1. The raw rubber is received in wooden boxes and stored on the third floor of the building. As the rubber is needed, the boxes are opened and the mass of rubber from each box is placed in a power cutter that cuts the rubber mass into six pieces. These pieces are carried on a conveyor to the second floor where they are weighed into mixes for different base stocks along with different compounding materials.

In some of the products the rubber must be free from any foreign matter. The raw rubber is put through mills and then put through a machine to take out foreign matter.

The compounding materials such as litharge, zinc oxide, sulphur, resin, clay, and oils are kept in a row of hoppers and tanks that discharge on the first floor. A traveling scale is mounted on a small track that runs under the length of the row of hoppers. The batches of compound are weighed into open containers as desired for the different bases.

The hoppers are filled from the second floor. Some of the materials are sifted through a shaker screen before entering the hoppers. The litharge (D-70) is received in metal drums. It is dumped from the drums through a grating into a bin. This dumping is done in a small corrugated iron shed located on the north side of the storage building and receiving department. An open belt conveyor carries the litharge to the second floor of Department 1 where it enters the hopper. A cloth screened box is used to allow the air to escape from the hoppers and keep the litharge dust from the atmosphere. One man does the dumping and wears a Willson Dustite respirator.

Two Banbury mixers and six compounding mills are used to make up the various base stocks. As the rubber comes from the compounding mills, it is placed on a conveyor and carried to the center of the building where two colored men remove it, dust it with soapstone and stack it onto skids. Each base is tagged and finally stacked into open racks until needed or taken directly to the department where it is to be used.

SK

Molded rubber products are made in Department 4. The base stock is reworked in rubber mills. It is cut into strips and put in tube machines that produce solid strips. These strips are cut into pieces and placed in metal molds. The molds are heated and pressed for a certain time, setting the rubber to the shape of the molds. The molds are stripped and the finished rubber is trimmed and inspected before packing for shipment.

Rubber bonded abrasive wheels are produced in Department 2. The base stock rubber is melted and mixed with asbestos, litharge, carbon, sulphur and abrasive materials in an open container. A colored man does the weighing and mixing. He does not wear a respirator while handling the dry materials. The mixture is molded to the desired sizes in molding machines. The molded wheels are then put into ovens where the solvents are driven off and the wheels set. The wheels are trued on lathes and grinders. These machines are exhausted. The smaller wheels have Babbitt centers. These centers are poured from a hand ladle. The Babbitt is melted in a pot under an exhausted hood.

Large rubber sheets used for flooring and floor protection are made up in Department 26. The base stock is rolled to the desired thickness and put into large heated presses where the rubber is cured or set. Mats of various designs and colors are made by cutting out sections and inserting or inlaying sections of different shapes and colors.

Rubber tubing is made in Departments 5, 51, 6, 21, and 7A. Tubing is produced for various purposes and of various sizes. The base stock is usually reworked in each department before entering the tube machines where the tube is produced. The tubes are cured on metal rods to give the desired inside diameters. The tubing is dusted with soapstone, wheat flour or rice

flour as it comes from the tube machines to keep it from sticking to adjacent tubing.

In some cases the tubing passes through braiders where a fabric covering is braided around it. Departments 7A and 6 do this type of work. Some types of tubing have various layers of fabric. This is accomplished by wrapping the tubing with cloth impregnated with rubber and allowing the rubber to set at the same time. The rubber of the cloth and tubing join together and the result is a solid tube with layers of fabric. This type of tubing is much stronger than plain rubber tubing.

The V type belts are made of a solid rubber core with a fabric covering. This fabric covering is applied to the core and cured in heated molds to assure the shape and size desired.

Flat bolts are made of cloth impregnated with rubber. The cloth is folded mechanically and cured on heated mandrels, the edges being sealed together by a strip of rubber applied after the folding process. In the case of long belts the curing is accomplished in heated presses.

In Department 5A metal pipes, pipe joints and tanks are lined with rubber. The rubber is applied over a coating of rubber cement in thin layers to the desired thickness. This is uncured rubber and is applied with hand rollers. After the rubber is in place, it is cured in heated tanks making a solid rubber lining out of the several layers applied.

In Department 5 rubber tubing of various sizes is cut to length and placed on mandrels in lathe grinders. The outside diameter is ground to the size required. Other products are ground to size in this department also.

Wool scouring rings and Minturn Vacuum dryer strips were ground at the time of the survey.

Grinding of rubber rolls of large dimensions, such as paper mill rolls, is done in department 28. The majority of these grinding machines have exhaust systems.

PERSONAL FACILITIES

Drinking water is supplied throughout the plant by bubbler fountains of the electrically cooled type. Wash rooms and toilets are adequate and are kept clean.

PLANT HOUSEKEEPING

Housekeeping is good in most departments. At the time of this survey portable vacuum cleaners were used in cleaning the rafters before painting.

METHODS OF SAMPLING AND ANALYSIS

Atmospheric dust and fume samples were taken with the impinger^(1 & 2) at the breathing zone of the workmen at representative operations. This instrument, developed by the United States Public Health Service, is the standard method used in this country. Air is drawn in through a glass tube at the rate of one cubic foot per minute. The tube ends in a constricted orifice under the surface of distilled water contained in a flask. The air passes through the orifice and impinges upon a glass plate which breaks up the air stream, allowing the dust particles to be wet and entrapped in the water in the flask.

Alcohol is added to the sample as a preservative to inhibit the solution of the fine silica particles and also to prevent the formation of bacteria.

(1) Comparative Tests of Instruments for Determining Atmospheric Dusts, Public Health Bulletin #144, U.S. Public Health Service, Trans. Dept. Wash. D.C. Jan. 1925
(2) The Impinger Sampling Apparatus as Used by the U.S. Public Health Service, Public Health Reports, March 18, 1932, Vol. 47, U.S.P.H.S., Treasury Dept. Wash. D.C.

8 k

-3-

ites of the fine particles by clumping.

Suction is supplied for drawing the air sample through the impinger by means of an ejector, or else an electrically driven pump where compressed air is not available to actuate the impinger.

The dust counts were made by the methods and technique developed and used by the United States Public Health Service. Particle size measurements were made of the dust by a direct projection method. The results are tabulated and appear in the graphs attached at the rear of the report. It will be noted that from 87 to 95.1% of the particles are less than 10 microns in greatest diameter.

The following table gives the results of analyses of air samples taken at representative points.

[illegible]

Item	Material	Qty	Unit Price	Amount	Remarks
1	Gravel 1/2" to 3/4"	100	0.15	15.00	for base
2	Gravel 3/4" to 1 1/2"	100	0.20	20.00	for base
3	Gravel 1 1/2" to 2"	100	0.25	25.00	for base
4	Gravel 2" to 3"	100	0.30	30.00	for base
5	Gravel 3" to 4"	100	0.35	35.00	for base
6	Gravel 4" to 6"	100	0.40	40.00	for base
7	Gravel 6" to 8"	100	0.45	45.00	for base
8	Gravel 8" to 12"	100	0.50	50.00	for base
9	Gravel 12" to 18"	100	0.55	55.00	for base
10	Gravel 18" to 24"	100	0.60	60.00	for base
11	Gravel 24" to 30"	100	0.65	65.00	for base
12	Gravel 30" to 36"	100	0.70	70.00	for base
13	Gravel 36" to 42"	100	0.75	75.00	for base
14	Gravel 42" to 48"	100	0.80	80.00	for base
15	Gravel 48" to 54"	100	0.85	85.00	for base
16	Gravel 54" to 60"	100	0.90	90.00	for base
17	Gravel 60" to 66"	100	0.95	95.00	for base
18	Gravel 66" to 72"	100	1.00	100.00	for base
19	Gravel 72" to 78"	100	1.05	105.00	for base
20	Gravel 78" to 84"	100	1.10	110.00	for base
21	Gravel 84" to 90"	100	1.15	115.00	for base
22	Gravel 90" to 96"	100	1.20	120.00	for base
23	Gravel 96" to 102"	100	1.25	125.00	for base
24	Gravel 102" to 108"	100	1.30	130.00	for base
25	Gravel 108" to 114"	100	1.35	135.00	for base
26	Gravel 114" to 120"	100	1.40	140.00	for base
27	Gravel 120" to 126"	100	1.45	145.00	for base
28	Gravel 126" to 132"	100	1.50	150.00	for base
29	Gravel 132" to 138"	100	1.55	155.00	for base
30	Gravel 138" to 144"	100	1.60	160.00	for base
31	Gravel 144" to 150"	100	1.65	165.00	for base
32	Gravel 150" to 156"	100	1.70	170.00	for base
33	Gravel 156" to 162"	100	1.75	175.00	for base
34	Gravel 162" to 168"	100	1.80	180.00	for base
35	Gravel 168" to 174"	100	1.85	185.00	for base
36	Gravel 174" to 180"	100	1.90	190.00	for base
37	Gravel 180" to 186"	100	1.95	195.00	for base
38	Gravel 186" to 192"	100	2.00	200.00	for base
39	Gravel 192" to 198"	100	2.05	205.00	for base
40	Gravel 198" to 204"	100	2.10	210.00	for base
41	Gravel 204" to 210"	100	2.15	215.00	for base
42	Gravel 210" to 216"	100	2.20	220.00	for base
43	Gravel 216" to 222"	100	2.25	225.00	for base
44	Gravel 222" to 228"	100	2.30	230.00	for base
45	Gravel 228" to 234"	100	2.35	235.00	for base
46	Gravel 234" to 240"	100	2.40	240.00	for base
47	Gravel 240" to 246"	100	2.45	245.00	for base
48	Gravel 246" to 252"	100	2.50	250.00	for base
49	Gravel 252" to 258"	100	2.55	255.00	for base
50	Gravel 258" to 264"	100	2.60	260.00	for base
51	Gravel 264" to 270"	100	2.65	265.00	for base
52	Gravel 270" to 276"	100	2.70	270.00	for base
53	Gravel 276" to 282"	100	2.75	275.00	for base
54	Gravel 282" to 288"	100	2.80	280.00	for base
55	Gravel 288" to 294"	100	2.85	285.00	for base
56	Gravel 294" to 300"	100	2.90	290.00	for base
57	Gravel 300" to 306"	100	2.95	295.00	for base
58	Gravel 306" to 312"	100	3.00	300.00	for base
59	Gravel 312" to 318"	100	3.05	305.00	for base
60	Gravel 318" to 324"	100	3.10	310.00	for base
61	Gravel 324" to 330"	100	3.15	315.00	for base
62	Gravel 330" to 336"	100	3.20	320.00	for base
63	Gravel 336" to 342"	100	3.25	325.00	for base
64	Gravel 342" to 348"	100	3.30	330.00	for base
65	Gravel 348" to 354"	100	3.35	335.00	for base
66	Gravel 354" to 360"	100	3.40	340.00	for base
67	Gravel 360" to 366"	100	3.45	345.00	for base
68	Gravel 366" to 372"	100	3.50	350.00	for base
69	Gravel 372" to 378"	100	3.55	355.00	for base
70	Gravel 378" to 384"	100	3.60	360.00	for base
71	Gravel 384" to 390"	100	3.65	365.00	for base
72	Gravel 390" to 396"	100	3.70	370.00	for base
73	Gravel 396" to 402"	100	3.75	375.00	for base
74	Gravel 402" to 408"	100	3.80	380.00	for base
75	Gravel 408" to 414"	100	3.85	385.00	for base
76	Gravel 414" to 420"	100	3.90	390.00	for base
77	Gravel 420" to 426"	100	3.95	395.00	for base
78	Gravel 426" to 432"	100	4.00	400.00	for base
79	Gravel 432" to 438"	100	4.05	405.00	for base
80	Gravel 438" to 444"	100	4.10	410.00	for base
81	Gravel 444" to 450"	100	4.15	415.00	for base
82	Gravel 450" to 456"	100	4.20	420.00	for base
83	Gravel 456" to 462"	100	4.25	425.00	for base
84	Gravel 462" to 468"	100	4.30	430.00	for base
85	Gravel 468" to 474"	100	4.35	435.00	for base
86	Gravel 474" to 480"	100	4.40	440.00	for base
87	Gravel 480" to 486"	100	4.45	445.00	for base
88	Gravel 486" to 492"	100	4.50	450.00	for base
89	Gravel 492" to 498"	100	4.55	455.00	for base
90	Gravel 498" to 504"	100	4.60	460.00	for base
91	Gravel 504" to 510"	100	4.65	465.00	for base
92	Gravel 510" to 516"	100	4.70	470.00	for base
93	Gravel 516" to 522"	100	4.75	475.00	for base
94	Gravel 522" to 528"	100	4.80	480.00	for base
95	Gravel 528" to 534"	100	4.85	485.00	for base
96	Gravel 534" to 540"	100	4.90	490.00	for base
97	Gravel 540" to 546"	100	4.95	495.00	for base
98	Gravel 546" to 552"	100	5.00	500.00	for base
99	Gravel 552" to 558"	100	5.05	505.00	for base
100	Gravel 558" to 564"	100	5.10	510.00	for base

[illegible]

Sample No.	Date of Sample	Location of Sample	Depth of Sample (ft.)	Volume of Sample (cc)	Weight of Sample (g)	Moisture Content (%)	Specific Gravity	Notes
10	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
11	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
12	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
13	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
14	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
15	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
16	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
17	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
18	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
19	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep
20	10/10/76	General area, 100 ft. deep	10.0	10.0	10.0	10.0	1.00	General area, 100 ft. deep

Lead is present in most of the processes in combination with a number of other substances, but with the exception of lead, these substances are not in large enough quantities to be hazardous. Asbestosis will be discussed in general report.

TOXICITY OF LEAD

John H. Smith, a paper in the Journal

Lead poisoning is the commonest of the industrial intoxications.

The toxicity of lead depends upon a number of factors such as: the form of lead taken into the body - vapor, dust or solid; the solubility of the lead compound in human tissues; the mode of entry of lead into the body - inhalation, ingestion or skin absorption; the extent of exposure; individual susceptibility which is heightened by numerous conditions particularly by previous attacks of poisoning.

Among the most readily toxic of the inorganic lead compounds are the oxides, the carbonate, the sulphate and the chromate.

Lead is a cumulative poison and, with a few exceptions, industrial lead poisoning is usually a chronic condition caused by the inhalation or ingestion of small amounts of soluble lead over long periods of time. This process of poisoning may go on slowly for a long period without manifesting any of the characteristic acute symptoms. Lead inhaled, however, is far more rapidly and surely toxic than lead ingested, since it reaches the blood stream more directly and comparatively little is eliminated unabsorbed.

There is little agreement in the estimates made by various authorities on the minimum amount of lead which can cause poisoning if taken into the body. For practical guidance, however, it can be assumed that from 1 to 2 milligrams taken in daily over a period of months or years may cause poisoning. A number of factors also enter into the estimation of the amount of air breathed by a man at active work during the working day. Ten cubic meters of air in a

ten hour day is an estimate which very probably errs on the safe side for the average workman. On the basis of these calculations, the lead content of the air of workrooms where men are continuously exposed should be kept as low as 0.1 of a milligram per cubic meter of air or else strict measures for protection should be installed to prevent poisoning.

The symptoms of chronic lead poisoning are many and may manifest themselves through the gastro-intestinal tract as in the familiar "lead colic" or the neuro-muscular system or both. Among the symptoms most commonly noted are colic, metallic taste in the mouth, obstinate constipation and loss of appetite, muscular weakness, particularly of the hands and wrists, neuritis and joint pains, loss of weight, headache, dizziness, nausea or vomiting, gastric distress or fatigue are among the minor symptoms that may or may not be present.

The principal diagnostic signs for the detection of lead poisoning in its early stages or of lead absorption, which is essentially pre-clinical poisoning before the onset of symptoms, are ashen pallor of the skin, tremor, lead line on the gums, stippling or basophilic degeneration of the red blood cells, hematoporphyrin in the urine and mild secondary anemia. Other abnormalities in the blood which are characteristic of lead poisoning are polychromatophilia, changed relative proportions of lymphocytes and polymorphonuclear leukocytes, increased mononuclear cells and increased reticulocytes.

Repeated physical examinations should be made of workers exposed to lead at fairly short intervals of from two to six months, depending upon the severity of exposure. It is important to prevent the occurrence of lead poisoning, since, even though it is not often fatal under modern conditions, it frequently results in premature development of chronic degenerative conditions in

the circulatory system.

The physiochemistry of lead poisoning and the treatment to be pursued have been the subject of intensive experimentation and study by Aub⁽³⁾ and his associates at the Harvard School of Public Health and by Kohoe⁽⁴⁾ and his colleagues of the University of Cincinnati.

(3) Lead Poisoning; J. C. Aub, et al; Williams and Wilkins, Baltimore, Md. 1926, pp. 265.

(4) On the Normal Absorption and Excretion of Lead, I-IV, R. A. Kohoe, F. Thamm, J. Cholak, Journal of Industrial Hygiene, Sept. 1933.

CONCLUSIONS AND RECOMMENDATIONS

The dust counts are low with the exception of sample #4 in Department 53. This concaving and bending unit is not exhausted. Although this operation is intermittent, precautions should be taken to eliminate any hazard by adequately entrapping and exhausting the arising dust.

Samples #26 and #34 in Department 2 and sample #61 in Department 1; these operations should be done under exhausted hoods to prevent the dispersion of dust throughout the rooms. The operator at these and all other batch mixing operations should be taught and compelled to handle the materials carefully to prevent the spilling of the materials on their clothing and on the floors.

Samples #87 in Department 5 and sample #88 in Department 6; careful handling of the soapstone and flours used and proper application of exhaust hoods over the pans and at the discharge ends of the tube machines would greatly reduce the dust concentration created at these points.

It will also be noticed that where there is an increase in dust counts and where lead compounds are present, as in samples #4, #26, #34, #61 and #88, there is a considerable increase in the concentration of lead compound in the air. The elimination of dust at these points would also tend to eliminate the lead compound concentration.

In addition to the samples listed in the preceding paragraph, the following were found to contain excessive amounts of lead: sample #41, Department 53; samples #30, #31 and #36, Department 2; samples #39 and #43, Department 53T; sample #76, Department 28; samples #82 and #84, Department 5. Although these operations are exhausted, they show an excess of lead concentration which may be due to the fact that the hoods are not properly placed or the suction is

not adequate to remove the arising dust.

Sample #50, Department 26: If possible, exhaust should be applied to gum cutting operations to eliminate the lead concentration.

Samples #53, 57, 58, 59, 60 in Department 1: The Banbury mixers and rubber compounding mills where lead compounds are used should be exhausted to eliminate the lead compound dust generated. The pollution of the air at the east end of the department where the raw rubber is cleaned is probably due to the Banbury mixers and compounding mills located near this section. The operators should be warned to handle the lead carefully.

Sample #102, Department 1: This sample was taken under the respirator of the workman while he was dumping drums of litharge through a grate onto a belt conveyor which conveys the litharge to the hoppers. A mechanical means should be installed, if possible, for the dumping of litharge at this place or the workman should be supplied with a positive pressure respirator and an exhaust hood applied properly. It was noted that clouds of litharge were blown from the shed and platform and there is a possibility that this lead would be carried into adjoining buildings. This would create an unnecessary hazard.

Sample #103, 2nd floor, Department 1: The lead concentration at this point was excessive. An exhaust should be applied to the open belt conveyor and at the hopper end to prevent the pollution of the air in this room. The present method does not keep the finer particles from being dispersed into the atmosphere of the room.

Sample #68, 2nd floor, Department 8: This sample shows a slight excess of lead concentration. This may be due to the working of the belting material while the rubber is still in the uncured state or may be due to pollu-

tion from sources outside of this room. Exhaust hoods could be applied to the tables.

Sample #58, Department 6: The base stock is reworked in a mill and then put through the tube machines. The mill and the tube machines could be exhausted to eliminate the lead hazard at this point.

The workmen should be taught that lead compounds are harmful when the dust is breathed into the lungs and to handle it carefully. It was noticed that the workmen were careless in putting their hands into the lead compound and brushing it on their clothes.

Operations where there is an excess of lead and where exhaust systems are not practicable should be isolated and efficient respirators supplied to the workmen.

Lunch rooms should be maintained and separated from the departments where lead is used. Workmen should not be allowed to eat lunch in the departments.

Samples of material used in the different products were obtained and analyzed to determine harmful elements. The following results were obtained:


Lead compound (D-70)	-	93.45% lead
" (D-80)	-	94.34% "
Waste material from Dept. 53 (R-56)	-	24.65% lead; 13.91% total silica
" (R-47)	-	27.32% lead; 12.94% "


Samples of dust from three grinding operations were obtained and analyzed.


Dust from rubber grinding, Dept. 25, machine #M-746	-	7.85% lead
" " black rubber, Dept. 5, machine #1240	-	1.15% "
" " green rubber, Dept. 5, machine #1311	-	12.48% "


Samples of dust from rafters were taken in various departments and analyzed. The following results were obtained:


Dept. 2, dust from over batch mixing operations	- 5.48% lead
2, " " " grinders	.60% "
53T, " " " weighing	- 7.19% lead; 25.51% total silica
6, at end where tube machines were located	- .38% lead
25-26, 55 (4th floor)	- 1.13% lead
11	- 2.08% "
32	- 28.18% "
31	- 2.66% "
26 (1st floor)	- 3.50% "




































Size of dust particles in microns




Size of dust particles in microns








Size of dust particles in microns




Size of dust particles in microns




Percentage of dust particles


Size of dust particles in microns



Size of dust particles in microns




Size of dust particles in microns




FA


Size of dust particles in microns




Size of dust particles in microns



Size of dust particles in microns






SAMPLE NO. 6
Dept. 53

**Grinding machine #2050, one man chamfering
ends of brake lining on every wheel**


**The Manhattan-Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.**



SAMPLE NO. 7
Dept. 53

Cutting operation with carborundum wheel;
cutting wet process brake lining to length


The Manhattan-Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLE NO. 2
Dept. 53

Gardner surface grinder #2, machine #1510
dry process lining


The Manhattan Rubber Mfg. Div.



SAMPLE NO. 9
Dept. 53

Circular grinder while grinding inside
surface of brake lining


The Manhattan Rubber Mfg. Div.



SAMPLE NO. 14
Dept. 51

Panning rubber tubing


The Manhattan-Rubber Mfg. Div.,
of Raybestos-Manhattan, Inc.



SAMPLES NO. 16 and 17
Dept. 99

Grinding clutch facing

The Manhattan-Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.




SAMPLE NO. 40

Dept. 53-T

Weighing rubber for wet process mixture


The Manhattan-Rubber Mfg. Div. of
Raybestos-Manhattan, Inc.



SAMPLE NO. 14
Dept. 39

Sandblasting molds for pressing
clutch facings


The Manhattan Rubber Mfg. Div.



SAMPLES NO. 18 and 19
Dept. 39

Punching clutch-facing material out of
asbestos cloth

The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLES NO. 31, 32, 33
Dept. 2

Truing abrasive wheels


The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLE NO. 34
Dept. 2

Batch mixing for abrasive wheels

The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.




SAMPLE NO. 41
Dept. 53

Weighing and pressing dry process brake lining

The Manhattan Rubber Mfg. Div.


4



SAMPLE NO. 30
Dept. 2

Grinding bores on abrasive wheels, machine #1558


The Manhattan Rubber Mfg. Div.



SAMPLE NO. 12
Dept. 53-7

Weighing materials for wet process brake lining
mixture

The Manhattan Rubber Mfg. Div.




SAMPLE NO. 43

Dept. 53T

In mixing room during time a mix was prepared and put
into mixer. Clutch facing mix for Dept. 39


The Manhattan Rubber Mfg. Division
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 44
Dept. 53T

At hammer mill


The Manhattan-Rubber Mfg. Div.



SAMPLES NO. 45 and 46
Dept. 53T

At hopper of picker and at shaker
screen


The Manhattan Rubber Mfg. Div.



SAMPLE NO. 47
Dept. 53-T

Between two baggers


The Manhattan-Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLE NO. 48
Dept. 8

General air - taken near belting
winder - - east end


The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLE NO. 49
Dept. 26

General air sample taken at Press #16


The Manhattan Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 50
Dept. 26

General air sample taken at west end
of gum cutting table


The Manhattan-Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 51
Dept. 81

General air taken in belt press room

The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.



SAMPLE NO. 52
Dept. 8

Cutting brake lining to length; power shear
#1382


The Manhattan Rubber Mfg. Div.



SAMPLE NO. 53
Dept. 1

General air; rubber mills, east end, two mills
#1343 and 1344 - cleaning process for
raw rubber

The Manhattan Rubber Mfg. Div.
of Raybestos-Manhattan, Inc.




SAMPLE NO. 55

Dept. E-1

Grinding, reeling and measuring brake lining,
machines #1689 and
#1690


The Manhattan-Rubber Mfg.
Div. of Raybestos-Manhattan, Inc.-



SAMPLES NO. 56 and 60
Dept. 1


Rubber compounding mills #128, 129 & 130

The Manhattan-Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 58
Dept. 1


On platform of Banbury mixer #1
The Manhattan-Rubber Mfg. Division
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 61
Dept. 1

Mixing batches of compound from hoppers


The Manhattan-Rubber Mfg. Division
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 63
Dept. 1

At discharge end of conveyors from rubber
compounding mills. Two men taking
rubber off conveyor

The Manhattan-Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.



SAMPLE NO. 66
Dept. 11

**Rubber compounding mill #74 and
friction calender**

**The Manhattan-Rubber Mfg.
Div. of Raybestos-
Manhattan, Inc.**




SAMPLE NO. RQ - 24

Dept. 5 - Balcony

Grinding and sanding rubber

The Manhattan-Rubber Mfg.
Div. of Raybestos-Man-
hattan, Inc.


76K



SAMPLE NO. 27
Dept. 5 West End Room

**General air sample between three machines
panning and reeling rubber tubing**

**The Manhattan-Rubber Mfg. Div.
of
Raybestos-Manhattan, Inc.**



*Protection of Workers Exposed to Chromium
v. Its Compounds*


Edition 1120

16, 47324

33-C

R/2000-11-9-23-11-6-2

PROTECTION OF WORKERS EXPOSED TO CHROMIUM AND ITS COMPOUNDS



INTERNATIONAL HEALTH SYSTEM
METROPOLITAN LIFE
INSURANCE COMPANY
HOME OFFICE, NEW YORK
Pacific Coast Head Office,
San Francisco
Canadian Head Office, Ottawa

METROPOLITAN LIFE INSURANCE COMPANY PRESS
NEW YORK, N. Y.
64 0311 W

Protection of Workers Exposed to Chromium and Its Compounds

INTRODUCTION

THE increasingly diverse and numerous industrial applications of chromium and its compounds have renewed interest in the problem, although not serious, effects of the action on the skin of exposed workers, and in studies to determine any harmful results following introduction into the body. Efforts have been directed particularly toward methods of protection for workers so exposed.

TOXICITY

All compounds of chromium are not equally toxic. Chromic acid (CrO_3) and the chrome salts, especially potassium and sodium bichromate, are far more toxic than the neutral salts and oxide. The dichromates ($\text{K}_2\text{Cr}_2\text{O}_7$, $\text{Na}_2\text{Cr}_2\text{O}_7$) are many times more poisonous than the soluble chromium oxide compounds, while chrome ironstone, native ferrous chromite (FeCr_2O_4), and pure chromium (Cr) are nonpoisonous.

It should be remembered that the chrome oxides—yellow, orange, green, and red—are lead chromates, and the chief danger lies in the lead content, which may cause chronic lead poisoning. These compounds may be known as lemon royal, Cadizene and Paris yellow, or lead yellow.

USES

The development and rapidly increasing popularity of chromium plating have increased greatly the use of chromic acid in a variety of industrial operations. The process consists in the deposition of metallic chromium by passage of low-voltage electric

current through a solution having chromic acid as its principal constituent and is widely applied in the manufacture of automobile fittings, plumbing fixtures, and an assortment of small hardware. Important among other diverse industrial applications using chromates are the manufacture of batteries; chrome tanning; manufacture of safety matches—particularly Danish, Swedish, and "strike-anywhere" matches, which exposes the dyers rather than the users to chrome ulcers; photo-engraving and photography, especially in the "carbon-process"; wood coloring and hardening; textile printing; dyeing of leather gloves and mittens, fur, wool, and felt hats (usually in the steaming process); cotton, where chrome salts are required as "oxidizers" and "discharging" agents, and aniline dyeing; the bleaching of oils, fats, and waxes; manufacture of colored glass, porcelain, and earthenware; steel making; manufacture of pigments, dyes, and of various salts of chromic acid; manufacture of "pyrosulphuric" powder made from gun cotton with bichromate of ammonium and potassium; ink making; zinc lithography; cyanotype process of blueprints in which bichromate is the fixing agent; oxidation of alcohols, aldehydes, and other oxygenated compounds; manufacture of artificial flowers, linoleum, wallpaper, and colored crayons; in the rubber industry on secondary operations, such as paint pigments, wetting media, and tire rims, plating processes and large cleaning baths; in the leather industry (workers sometimes follow the practice of using their bare feet to soak the leather in tubs, in which case chrome sores develop between the toes); and in analytical chemistry.

MODES OF CONTACT

Chromic acid and its compounds are conveyed to the skin and mucous membranes:

First, through handling the dry material itself, either as crystals or in the form of a fine powder.

Second, through contact with solutions of the material.

Third, through exposure to the atmosphere containing the material in the form of a vapor, spray, or mist, or as a dust, in varying amounts, depending upon the technique practiced.

WEAVE ROOM

No.	Station	Date	Cu. Ft. Air Sampled	Millions of Particles per cu. ft. air sampled	Millions of Particles less than 10 microns per cu. ft. air sampled	Type of Dust	Remarks
	General air - west end of weave room	7/10/34	32.6	6.3	6.1	Asbestos	
	Same as #22	7/11/34	35.7	0.6	0.5	"	
	At inspection table weave cloth	"	27.3	2.6	2.5	"	Revolving brush - exhaust hood - two men
	General air - east end of weave room	"	27.9	5.5	5.3	"	
	Inspection table en- closed in heavy board two men - sample taken inside enclosure	"	20.2	3.2	3.0	"	Taken with revolving brush and exhaust running, Manhattan cloth G815 and 140
	Taken just outside enclosure	"	19.0	9.5	9.3	"	Same time as #31
	Taken inside enclosure	"	20.2	23.2	21.7	"	Revolving brush - no exhaust two men
	Taken outside enclosure	"	18.8	1.5	1.5	"	Same time as #33
	Taken inside enclosure	"	20.2	1.5	1.4	"	Hand brushing - three men
	Taken outside enclosure	"	19.0	2.1	2.0	"	Same time as #35
	General air - west end of weave room	7/13/34	18.8	9.3	9.2	"	Before work started in morning, shut down from midnight
	General air - east end of weave room	"	18.6	6.0	5.9	"	" " "

The dust counts of samples #43 and 44 were taken before work started in the morning. These counts are considerably higher than samples taken during operating periods. This may be due to closing of windows, shutting off of humidifiers and floor sweeping.

NAVY REPORT (Continued)

Station	Date	Cu. Ft. Air Sampled	Millions of Particles per cu. ft. air sampled	Millions of Particles less than 10 microns per cu. ft. air sampled	Type of Dust	Remarks
General air - east end of wave room	7/13/34	27.0	2.6	2.6	Asbestos	Same time as #46 and 47; wave room started at 7 o'clock
General air - west end of wave room	"	27.9	2.7	2.7	"	Same time as #45 and 47
At inspection table for woven cloth, dry woven cloth 10P225	"	30.3	0.8	0.8	"	Revolving brush and exhaust; two net, same time as #45 and 46
Same location as #45	"	27.0	3.0	2.9	"	Same time as #49 and 50
Same location as #46	"	27.9	5.1	5.0	"	Same time as #48 and 50
Inspection table - hand brushing	"	30.3	0.8	0.8	"	Three net - at same time as #48 and 49
Same location as #45	"	18.9	4.9	4.8	"	At same time as #52 and 53
Same location as #46	"	20.5	0.9	0.9	"	Same time as #51 and 53
Table inspection woven cloth, revolving brush, no exhaust	"	21.2	1.8	1.7	"	Same time as #51 and 52; two net

General air samples, #22, 24 and 26, 45, 46, 48, 49, 51 and 52, averaged

.3.5 billion particles per cubic foot air, as compared with .6 found in survey of January 1930.

PACKING DEPARTMENT

Sample No.	Station	Date	Cu. Ft. Air Sampled	Millions of Particles per cu. ft. air sampled	Millions of Particles less than ... 10 microns per cu. ft. air sampled	Type of Dust	Remarks
20	General air - molded packing department	7/10/34	62.3	0.45	0.43	Asbestos	
23	General air - rubber compounding room	"	28.2	1.4	1.3	Clay lead talc sulphur	

LEAD ANALYSES

Sample No.	Station	Date	Cu. Ft. Air Sampled	Milligrams of lead per cu. ft. air sampled	Type of dust	Remarks
21	Between two rubber compounding mills	7/10/34	33.8	Negative for lead	Clay lead talc sulphur	Exhaust hood with cloth curtains
23	General air - rubber compounding room	"	28.2	Negative for lead	"	"

CLOTH INSPECTION (WEAVE ROOM)

Table showing the results of special tests run at the cloth inspection table

	Millions of Dust Particles per cu. ft. air sampled	
	Inside enclosure (doors closed)	Normal conditions enclosure removed
Average general air - weave room during tests	3.5	3.8
Cloth inspection table - exhaust and revolving brush	3.2	0.9
Cloth inspection table - no exhaust but with revolving brush	23.2	1.8
Cloth inspection table - hand brushing, no exhaust	1.5	0.8

It was noted that only slight changes had been made in the preparation room since the survey in 1930. The method of oiling and conveying the fibre remains the same. As noted, the average dust count remained constant.

Extensive changes and increased methods of dust entrapping and removal in the card room were noted. The method of conveying the fibre from the preparation to the card room is the same and the fibre is carted from the storage bins to the feed hoppers on the cards in the same manner.

Natural ventilation is supplied by open windows which occupy approximately two thirds of the total wall space.

Samples No. 37 and 39 were taken before the fibre conveyors from the preparation room were running, while samples No. 40 and 42 were taken after the conveyors were put into operation. The increased count is evidently due to dust generated by the fibre conveyors and leakage from the storage bins in the card room.

In the test on the enclosed card, samples 37, 38, and 39 were taken before the fibre conveyors were operating and samples No. 40, 41 and 42 were taken after the conveyors were running. The muslin enclosure is not effective in keeping out the fine dust, as evidenced by the comparison of counts on samples taken simultaneously inside and outside the enclosure. The increased counts after the conveyor was operating should be noted.

The natural ventilation in the weave room is augmented by a forced air supply through the fan and distributing ducts used for heating in the winter months. The chance of dust pollution from this outside air supply is remote, as the dust collectors are located at a distance east of the weave room. Experimental work is in progress on entrapping and exhausting dust generated by the looms.

Attention is called to the tests run on the cloth inspection table, with the mechanically operated brush, which show that the exhaust system is effective in keeping the dust concentration down to the same count as under the system of hand brushing without exhaust.


The lead pollution at the rubber compounding operations of the packing department has been corrected, as shown by the absence of lead in the air samples taken.

CONCLUSIONS AND RECOMMENDATIONS


An exhaust system is under construction in the card room and experimental work is in progress for entrapping and exhausting dust generated by the looms in the weave room, and until this work is completed and checks run on the efficiency of the exhaust system, no other recommendations can be made.

Tests conducted in the card room show that there is an increase in the general air dust content when the fibre conveyors are in operation. This is due to leakage of dust from the fibre storage bins in the card room and efforts should be made to seal this leakage.


Dust particle sizes in microns




Dust particle sizes in microns




Dust particle sizes in microns




Dust particle sizes in microns




Dust particle sizes in microns




Dust particle sizes in microns




Dust particle sizes in microns



Dust particle sizes in microns




Dust particle sizes in microns




[illegible]


Percentage frequency of occurrence of dust particles

Dust particle sizes in microns





Dust particle sizes in microns






Dust particle size in microns.







Dust particle sizes in microns





Dust particle sizes in microns




Dust particle sizes in microns











GENERAL INVESTIGATIONS DIVISION OF THE BUREAU OF MINES
 1230 RICHMOND ST. S.W.
 7/22/34
 S. W. M. 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100

Percentage frequency of occurrence of dust particles



12-B

12-B




Card Room.

General Asbestos & Rubber Division
Raybestos-Manhattan, Ind.
Charleston, S.C.

13-B

13-B



SAMPLES NO. 25, 47, 50 and 53

At inspection table - woven cloth

General Asbestos & Rubber Division
Raybestos-Manhattan, Inc.
Charleston, S.C.

17-12

14-B



SAMPLES NO. 31, 32, 33, 34, 35 and 36

Enclosure built around table inspection
of woven cloth in weave room

General Asbestos & Rubber Division
Raybestos-Manhattan, Inc.
Charleston, S.C.

GENERAL ASBESTOS & FIBER DIVISION

OF

RAYMOND-WHARTMAN, INC.

En. Charleston, S. C.

• • •

This survey was conducted on April 20, 21, and 22, 1936 and is
supplementary to the survey made in July, 1934.

This survey was made to determine the extent of dust removal
accomplished by the installation of new exhaust equipment and the redesigning
of old exhaust equipment.

MAX GLAUBACH, C.E.R.

CERTIFIED BY

APR 1 1938

P. P. 20/50/14

DATE

APR 1 1938

COMPARATIVE DATA

Preparation Room

21 The average count in this room at the time of the 1974 survey was 3.6 million particles per cubic foot of air. The average count at the time of the 1936 survey was 2.7 million particles per cubic foot of air.

Card Room

21 The average count in this department at the time of the 1974 survey was 3.5 million particles per cubic foot of air. The average count at the time of the 1936 survey was 1.2 million particles per cubic foot of air.

Reinforcing Department

17 The average count in this department at the time of the 1974 survey was 2.66 million particles per cubic foot of air. Samples 14 to 17 inclusive were averaged. The average count at the time of the 1936 survey was 4.4 million particles per cubic foot of air.

Recess Room

21 The average count in this room at the time of the 1974 survey was 3.5 million particles per cubic foot of air. The average count at the time of the 1936 survey was 2.3 million particles per cubic foot of air.

Comparison of Dust Counts at Bureau

July, 1934		April, 1936	
Sample No.	Millions of Dust Particles per cu. ft. air sampled	Sample No.	Millions of Dust Particles per cu. ft. air sampled

PREPARATION ROOM

1	1.9	21	1.2
2	2.2	22	1.3
4	1.2	44	2.2
5	1.5	54	2.1
6	0.87	64	1.5
7	7.8	74	6.6
8	8.2	84	2.2
9	1.3	94	5.0
10	1.9	104	1.9

CARD ROOMS

27	5.5	274	1.0
28	15.9	284	1.2
29	13.2	294	1.3
30	2.7	304	1.3

SPINNING DEPARTMENT

11	1.6	114	2.4
12	2.1	124	1.4
13	1.1	134	0.93
14	0.99	144	4.9
15	2.3	154	9.9
16	0.93	164	6.0
17	8.1	174	3.1
18	2.5	184	1.1
19	1.1	194	1.5

RECEIVING DEPARTMENT

20	0.45	204	0.82
23	1.4	234	1.8

Spent on blower break while dust count was running in 1934.

Comparison of Dust Counts of Surveys

<u>July, 1934</u>		<u>April, 1935</u>	
<u>Sample No.</u>	<u>Millions of Dust Particles per cu. ft. air sampled</u>	<u>Sample No.</u>	<u>Millions of Dust Particles per cu. ft. air sampled</u>
<u>RAVE 8271</u>			
22	6.3	721	1.2
24	0.6	330	1.4
26	5.5	340	2.3
45	2.6	350	6.6
46	2.7	360	2.7
48	3.0	370	1.2
49	5.1	380	1.6
51	4.9	390	1.3
52	0.9		

*Samples 33 to 39 in the 1936 survey do not compare as to location with samples in the 1934 survey.

-2-

The following tables show the results of analyses of samples
taken in April, 1935. Methods of sampling and analysis are identical to those
used in 1934.

GENERAL ASBESTOS & RUBBER CO.
La. Charlotte, S.C.

Station	Date of Sample	Ct. Ft. Air Sampled	Millions of Dust Particles per cu. Ft. air sampled	Type of Dust	Remarks
SPINNING ROOM					
1A At fly chaser	4/20/36	37.4	2.2	Asbestos	
2A At fly chaser	"	35.8	2.3	"	
3A Feeder end of #1 picker exhaust hood	"	44.6	2.1	Asbestos cotton	One man supplied with respirator
4A Feeding end of Garnet machine	"	36.4	2.2	Asbestos	
5A At fly chaser exhaust	"	49.8	2.1	"	
6A Vertical fibre opener	"	44.0	2.5	"	Exhaust
7A Floor mixing of cotton and asbestos - exhaust hoods	"	9.6	6.6	Asbestos cotton	2 men - supplied respirators.
8A At shaker screen - loading band trucks with fibre	"	39.0	2.8	Asbestos	Exhaust
9A At feeder end of cotton fibre opener	"	23.3	3.0	Cotton	Exhaust - one man
10A At conveyor end of #2 picker	"	24.2	2.9	Asbestos	Exhaust at machine conveyor
WEAVING DEPARTMENT					
11A General air - braidors Building #5	4/21/36	37.2	2.4	"	Large machines
12A Between 2 ring presses Bldg. #5	"	34.5	2.4	Asbestos graphite	
13A General air - small braidors - Bldg. #5	"	43.3	0.93	Asbestos graphite cotton	Making stock for presses
14A General air - ring frame spinning	"	30.4	4.9	Cotton asbestos	
15A General air - twister	"	38.5	9.9	Asbestos	
16A General air - spoolers	"	33.5	6.0	"	Yarn from ring spinning, near W. north side.
17A General air - spoolers near partitioned wall, east side	"	33.2	3.2	"	Yarn from male & four women.
18A General air - male spinning	"	39.5	2.1	"	Between machines #9 and #10
19A General air - male spinning	"	34.6	2.5	"	Between machines #15 and #16.
20A General air - 4 spooler machines	"	30.0	2.3	"	Exhaust system.

GENERAL ASBESTOS & RUBBER CO.
Ma. Charleston, S.C.

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Dust Particles per cu. ft. air sampled	Type of Dust	Remarks
2 ROOM						
25	South aisle - between cards #21 and 22	"	27.5	1.6	10	Hopper and flint ends - exhaust west of bins.
26	North aisle - between cards #9 and 10	"	26.3	1.1	7	"
27	Center aisle - between cards #2 and #21	"	40.0	1.0	"	Canvas-back ends cards - exhaust west of bins.
28	Center aisle - between cards #10 and #23	"	34.6	1.2	7	"
29	Between cards - #16 and #33	"	32.2	1.3	7	East of bins -
30	General air - vicks, rope, and twisted card room	"	32.1	1.3	"	"
WAVE ROOM						
31	General air - west end of wave room	4/22/36	39.0	1.2	7	"
32	At inspection table - waves cloth	"	28.8	1.4	8	Two men - exhaust
33	At Broadloom #4 - west end of room	"	27.4	2.3	13	Exhaust on both vays and slay
34	At loom #17 - brake bands dry weaving	"	33.2	6.6	14	North east corner wave room.
35	General air - east end of wave room	"	36.4	2.7	15	"
36	At broadloom #10 - north west side of room	"	35.9	1.2	"	Exhaust only on vays, not on sl
37	Between looms #15 and #16, broadloom #15 and vays	"	32.3	1.6	"	#15 - exhaust vays and slay #16 - exhaust north side of
38	At two tape looms #4 and #5, south side of room	"	34.7	1.3	"	Looms face east dry weaving.
MAINE DEPARTMENT						
39	General air - molder packing department	"	48.7	0.22	5	"
40	General air - rubber compounding room	"	41.7	1.2	12	Clay, talc, lead, sulphur
41	At Pratt & Whitney grinder	"	43.3	1.1	7	Asbestos Brake lining
42	At drill press	"	47.1	1.1	7	"

GENERAL ASSOCIATION & RUBBER CO.

Ma. Charleston, S.C.

LEAD ANALYSIS

Sample No.	Station	Date and Sampling	Cu. Ft. Air Sampled	Milligrams of Lead per Cubic Foot of Air Sampled	Milligrams of Lead Intake in 10-hr. day on basis of section breathing 10 cubic meters air	Remarks
21A	Between two rubber compounding mills	4/22/56	36.0	0.000309	0.0137	Exhaust
23A	General air - rubber compounding room		41.7	000	000	
31	At Pratt & Whitney grinder		45.5	000	000	
32	At drill press		47.1	000	000	

-2-

CONCLUSIONS AND RECOMMENDATIONS


At the time of the 1936 survey the exhaust systems in the Card Room were completed, including exhaust on the storage bins. These exhaust systems were not completely finished in July, 1934.

The Spinning Department showed a slight increase over the 1934 survey. The rate of production at the time of the 1936 survey was much higher than at the time of the previous survey with more tristers in operation.

In other departments the variation is no greater than that encountered in the outside atmosphere.

It is evident from the results of this 1936 survey that the general air pollution of the Preparation Room has been decreased, but it is questionable if the exposure of the individual workmen at the floor mixing operations has been decreased.

9-c



Exhausting Equipment

View showing exhaust arrangement on discharge ends
of picker machines

General Asbestos & Rubber Division
No. Charleston, S.C.

10 - c



Preparation Department

View showing exhaust hood on right of main entrance

General Asbestos & Rubber Division
No. Charleston, S.C.

11-2




Preparation Room

View showing rubber beds and wiring bins

General Auditor & Rubber Division
No. Charleston, S.C.

12-c




Exhaust Hood

View showing exhaust hood on hopper of picker machine

General Asbestos & Rubber Division
No. Charleston, S.C.

13-c




General Inspection

Exhibit 154

General air sample taken in center of
twisting machine

General Asbestos & Rubber Div.
No. Charleston, E.C.

14-c




Spinning Department

Sample 5161

General air sample taken at spoolers on
north side of room

General Asbestos & Rubber Div.
No. Charleston, S.C.

15-c




Exhausting Equipment

View of spooler section with exhaust equipment

General Asbestos & Rubber Div.
No. Charleston, S.C.

16-c




General Air Sample

Sample #1

General air sample taken between four spooler machines
with exhaust equipment

General Arb sites & Rubber E.
No. Charleston, S.C.

17-c




Large Photo

View of brickloom showing exhaust equipment on clay

General Asbestos & Rubber Div.
No. Charleston, S.C.

18-C




Exhaust Room

**View of broadloom shoeing exhaust equipment under
tarp and on pier**

**General Abrastes & Rubber Div.
No. Charleston, S.C.**


19-c



Card Room

Close-up view of card showing part of exhaust
enclosure


General Acetylene & Rubber Div.
No. Charleston, S.C.



Card 2000

Close-up view of card showing part of exhaust enclosure

General Lubricator & Rubber Division
No. Charleston, S.C.



Card Room

General view - center aisle - card room - back ends
of cards

General Libraries and Reader Division
No. Charleston, L.C.

A STUDY OF DUST CONDITIONS
in the Manheim Plant
of the
UNITED STATES ASBESTOS & RUBBER DIVISION OF THE RAYBESTOS-MANHATTAN,
INC.

1930

MAX GLAUBACH, C.S.R.
CERTIFIED BY
NEW JERSEY & NEW YORK

EXAMINER NO. P. P. 291/30 15

Exhibit J

R-44 261 a. Rd. 5.72.77

The following report is a study of dust conditions in the Mannheim plant of the United States Asbestos & Rubber Division of the Raybestos-Manhattan, Inc. This study was carried on during February, 1930, by the Industrial Health Service of the Metropolitan Life Insurance Company.

It is the third unit in a series of studies of the asbestos industry in the United States and Canada for the purpose of determining the extent and nature of atmospheric pollution to which asbestos workers are exposed and whether there can be demonstrated any harmful effect to such workers.

This study differs from the two preceding ones in that there were included physical examinations of employees, hence it is more complete and informative.

APPARATUS AND METHODS OF SAMPLING:

The impinger method⁽¹⁾ was used for collecting samples of dust in the air. This is accomplished by aspirating the air to be sampled, and impinging it upon a flat surface under a liquid of either distilled water or alcohol. In general whenever the dust collected is of a siliceous nature an alcohol-water mixture is used to prevent any silica going into solution. Pyrex flasks are used as containers to collect the samples, as experience has shown that this glass is, for all purposes, practically insoluble. The volume of air is measured by means of a flow meter or else a vacuum gauge and the air sample is aspirated by suction supplied either by an electrically driven pump or else by an ejector actuated by compressed air. Each dust sample collected represented a volume of air of from 50 to 80 cubic feet.

Due to the high concentrations of dust in the departments of this plant this size sample was found to be representative and of sufficient size for analysis. The impinger was placed in close proximity to and at the breathing level of the workmen.

Air samples were also taken with the electric precipitator⁽²⁾ for dust particle measurements. This instrument is designed upon the principle of the Cottrell precipitator. Air is drawn through an electrostatic field, where the dust particles are deposited upon a celluloid foil, by means of a small electrically driven pump. The volume of air sampled is measured by means

(1) "Comparative Tests of Instruments for Determining Atmospheric Dusts", - Public Health Bulletin, No. 144, Treasury Dept., Washington, D.C.

(2) "Determination of Suspensoids by Alternating Current Precipitators", - Philip Drinker and Robert W. Thomson, Journal of Industrial Hygiene, Vol. VII, No. 8, June, 1925.

of a flow meter. From 10 to 50 cubic feet of air were taken for a sample.

The collected dust samples were transported to the laboratory where total dust counts were made, and particle size measurements were taken. The results are tabulated and appear in graphs attached. The percentages of the various sized particles may be interpolated from these graphs.

Microphotographs of these dust particles were taken under high power and were further enlarged by being projected upon a screen by means of a lantern slide projector. The enlarged particles were then measured with a ruler. Knowing the entire enlargement (by actual measurement) it was possible to calculate the original particle size.⁽³⁾ By the use of Hazen's⁽⁴⁾ logarithmic probability paper, the logarithms of the function to be measured - in this case microns - are plotted as ordinates against the probability of occurrence as abscissae. Since the line is straight, extrapolation and interpolation of any desired region is facilitated.

It will be noted from these curves that from 86 to 99% of the particles are less than 10 microns in their greatest diameter.


The analyses are reported in total particles per cubic foot, and also in the corresponding weight of the dust in milligrams. There is no indicated relationship between the dust counts and the corresponding weights.

DESCRIPTION OF PLANT:


The plant at Mannheim consists of a number of one-story and two two-story buildings. One of the two-story buildings houses the offices, laboratories, dispensary and store room, while the other is devoted to the preparation

⁽³⁾Green, E. "A Photomicrographic Method for the Determination of Particle Size of Paint and Rubber Pigments", Journal Franklin Institute, 1921, 192, 657.


⁽⁴⁾Whipple, G.C. Vital Statistics, N.Y. John Wiley & Sons, Inc. 1925, p. 451




Particle Size Analysis
The U.S. Army
Medical Dept.
Biology Division
Sample No. 1



Div. of Int. Affairs, Bureau of Cons. Affairs





room and brake-band weave room on the first floor and the carding, spinning and spooling operations are performed on the second floor.

The other one-story buildings are occupied by spooling, twisting and broad loom operations, brake-band treating and packing manufacturing, shops and shipping department.

PREPARATION DEPARTMENT:

The asbestos is received in bags and emptied upon the floor. It is then shoveled into pug mills or chasers from which it is passed into an opener and on a shaker sieve. Here it is piled on the floor to make up into mixtures with proportionate amounts of cotton which has already been passed through an opener. The batches of mixed cotton and asbestos are passed through a mixer picker and carried by suction through a pipe to bins in the card room on the second floor. In this suction pipe oil is applied to the mixture of cotton and asbestos by means of sprayers. Judging from the high dust counts found in the card room, as compared with those found at similar locations in the plant at Charleston, the method of applying the oil does not appear to be as effective.


Two card machines working on waste material are making wicking in this department. One loom is operating on brake-bands.

The exhaust systems at the various machines were only in partial operation due to relocation of machines. No humidifying system was in operation. The temperature of this department at the time of visit was 87° F. with a relative humidity of 37%, as compared with outdoor temperature of 80° F. and a relative humidity of 67%. The high incidence of dust in this department is partly due to the alterations being made.

TABLE NO. 1

PREPARATION ROOM

Sample No.	Building Dept. No.	Location of Sampling	Total Counts of Dust Particles per cubic foot	Vol% of Dust in milligrams per cubic foot
1	5	1. Alongside exhaust pipe from vertical opener discharging on to shaker above	45,259,156	2.5
2	5	1. Alongside loom 946. Only one loom in preparation room	2,301,597	.46
3	5	1. Alongside chasers #1 and 2	5,185,214	.47
4	5	1. At the side of shaker above	25,609,525	1.57
5	5	1. Floor wiring center of room	5,457,600	.45
6	5	1. Alongside feeder and of rack card sorting waste material, machine 158	5,087,129	.40
7	5	1. Machine #18, feeder hopper of breaker card	29,219,145	5.4
11	5	1. At the take off end of rack card machine #156	4,904,615	.65



Storeroom and Hatch Machine Room
in
Preparation Room



Fender End of Shaker Sieve
 in
 Examination Room



Take-off End of Shaker Floor
Preparation Room



Floor Plan in Presentation Room
Shows of the Mill Visible at the Right

It will be noticed that the dust count is high in places and exceeds 10,000,000 particles, the standard adopted by the U.S. Public Health Service in their study of the granite industry. (5)

BRAFF-BAND WEAVING DEPARTMENT:

This process is conducted in a room adjacent to the preparation department. This room is equipped with hand controlled water sprays for humidifying. The temperature in this department was found to be 69° F. and the relative humidity was 76%.

Artificial illumination is furnished by Cooper Hewitt lamps.

Dust counts were collected in close proximity to the workers and are as follows:


(5) Public Health Bulletin No. 187 "The Health of Workers in Dusty Trades II. Exposure to Siliceous Dust (Granite Industry)" - U.S.P.H.S., Treasury Dept., Washington, D.C. 1929.

TABLE No. 2

WEAVE ROOM (BRAKE BAND)

Sample No.	Building No.	Dept. No.	Location of Sample	Total Counts of Dust Particles per cubic foot	Weight of Dust in milligrams per cubic foot
12	1	12	Alongside loom 9 space 8. Machine #918	9,101,852	.60
18	1	12	Alongside loom 6 space 8. Machine #915	6,074,859	1.1
15	1	12	Alongside loom 3 space 12. Machine #925	4,824,606	.60
17	1	12	Front of loom 20 space 8. Machine #935	5,705,705	—
16	1	12	Front of loom 37 space 4. Machine #944	9,982,856	1.1
19	1	12	Front of loom 19 space 2. Machine #925	9,076,785	1.5

6-1



Brake Band Reeling

The number of particles per cubic foot of air in this room are considerably less than in the preparation room, and slightly under the standard quoted above.

SPOOLING, TWISTING AND BROAD LOOM WEAVING:


These processes are likewise carried out on the first floor of building number one. This department is equipped with the Carrier Air Conditioners which furnish ample humidification. The temperature was found to be 74° F. and the relative humidity was 80%.

SPINNING, TWISTING AND WEAVING

TABLE No. 5

Sample No.	Building No.	Dept. No.	Location of Sample	Total Counts of Dust Particles per cubic foot	Weight of Dust in milligrams per cubic foot
20	1	6	Between spoolers 605 and 602 N.E. corner	2,079,901	.66
21	1	6	Front of spooler #406	1,160,176	.25
22	1	10	Between universal winders 701 and 709	1,822,761	.30
24	1	7	Between twiststers 660 and 661	5,752,836	.60
25	1	10	Alongside loom #1016 weaving broad cloth	2,270,469	.28
26	1	6	Alongside machine #451. Ring spinning	1,469,320	.35
28	1	10	Alongside loom #1017. (dry weaving)	5,162,670	.80
30	1	10	Between looms 5, 21 and 20 dry weaving on wide material	2,704,291	.60

First floor of building #1 equipped with the Carrier system.



Twisting Machines

-8-

The dust counts as shown in the table indicate a relatively small number of particles.

SPINNING DEPARTMENT:


This department is located on the second floor of building No. 1 at one end of the main card room.

Wool spinning and some spooling operations are carried on here. The department is provided with the Carrier System. No ring frame spinning is done.

TABLE No. 4
SPINNING

Sample No.	Building No.	Dept. No.	Location of Sample	Total Counts of Dust Particles per cubic foot	Weight of Dust in milligrams per cubic foot
82	1 2nd Floor	4	Between miles 405 and 406 at S.E. corner of room	2,514,024	.49
83	1 2nd Floor	4	Between miles 405 and 406 at the N.E. corner of room	4,578,910	.40
84	1 2nd Floor	4	At the end of spooler 457	1,254,164	—

These counts are comparatively low and indicate effective control.



Rule Spinning

CARDING ROOM:

This room consists of two connecting departments occupying the second floors of building No. 1 and No. 3, except for a portion in building No. 1 devoted to spinning.

The section located in building No. 1 is equipped with the Carrier System. No form of humidification is used in building No. 3.


The carding machines in building No. 1 are totally enclosed by canvas covered wooden frames and each enclosure is equipped with an exhaust to remove the dust. That section located in building No. 3 is not totally enclosed. The exhaust on these machines is connected with the hood covering the comb of the card.

TABLE No. 6
QARD ROOM

Sample No.	Building No.	Dept. No.	Location of Sample	Total Counts of Dust Particles per cubic foot	Weight of Dust in milligrams per cubic foot
36	1	2	Between cards #101 and 102	20,127,514	1.58
37	1	2	Alongside of card #201	5,519,228	.70
38	1	2	On spooler #459	5,625,518	.88
39	5	5	Alongside card #104	7,530,980	1.28
40	5	5	Alongside card #172	15,677,062	1.55
41	5	5	Between carders #162 and 195	6,221,064	.57


It will be noticed that the counts vary considerably and in two instances are quite high. No marked difference is noticed where the machines are totally enclosed and only partially enclosed.

14-1



Main Card Room, Second Floor
Bldg. #1
Showing totally enclosed card machine


14-✓



Card Room, Second Floor
Blk. 41

14-3


14-3



Care Room, Second Floor
Building #3

14-4

14-4



Card Room, Second Floor
Building 4B

PLANT HOUSEKEEPING:

The floors are dry swept almost continuously throughout the working period. Each Friday the dust is removed from the ceilings, walls, and machines by means of an air hose during the working period. The dust counts during this period of cleaning would be increased considerably. It is recommended that cleaning be accomplished by means of a vacuum system. There are portable units on the market designed for this kind of work.

PHYSICAL EXAMINATIONS:

Physical examinations were made on fifty-four employees. All who worked in an asbestos industry three years or longer were included in this group. These employees were examined for symptoms usually associated with what English authorities term "asbestosis". These include anorexia, leaden hued complexion, emaciation, dyspnea, cyanosis, cough, expectoration, "asbestos corns", decrease in chest expansion, clubbing of fingers, swelling of skin at the nails, and history of chest trouble. The chests of these employees were then examined for friction rubs, râles, dullness, diminished breath sounds, increased voice sounds, and where the symptoms and findings suggested further examination, X-ray pictures of the lungs were taken.

X-ray examinations were made of 20 employees; of these 10 showed definite evidence of asbestos dust injury to the lungs; one showed tuberculosis without dust injury, and nine were negative.

The action of inorganic dust upon the lung tissue is such as to cause the development of fibrous tissue - fibrosis. Such dust fibroses are classified under the general term pneumoconiosis. The various types of pneumo-

coniosis are further differentiated by more specific titles which define themselves, such as silicosis, anthracosis, and asbestosis.

On page 2 of the first unit report of this series of studies it was stated, in relation to the action of asbestos dust on the lungs, "We are confronted with three alternatives:

- (1) Asbestos dust does not cause pulmonary damage.
- (2) Asbestos dust does cause pulmonary damage akin to silicosis, but of a milder nature.
- (3) Asbestos dust itself does cause pulmonary damage, but in a manner and of a type entirely distinct from silicosis."

The X-ray films of this study definitely inform us that individuals exposed to the inhalation of asbestos will in time show structural changes in their lungs - pneumoconiosis. Our studies have not progressed sufficiently for us to construe this type of pneumoconiosis in term of disability or of increased susceptibility to tuberculosis. This type of pneumoconiosis, to which the term asbestosis may properly be applied, is quite distinct in its X-ray film appearance from true silicosis and an experienced technician would have no difficulty in distinguishing the two conditions. The evidence so far would indicate that the action of asbestos dust is in accord with the second alternative quoted above.

Four films showing definite asbestosis also showed old tuberculous lesions, apparently inactive, 3 of the films negative for asbestosis also showed such lesions; this would lend support to the contention that asbestosis does not tend to activate quiescent tuberculous lesions which is in accord with the meagre evidence so far available from animal experimentation and with the limited clinical experience.

The following table summarizes the X-ray examinations.

No.	Sex	Age	Occupational History	Diagnosis
1	F	35	Weaving 21 yrs. off & on, 4 yrs. U.S. Asbestos Co.	Negative
2	F	37	Twisting 15 years	Late first degree asbestosis
3	M	32	Weaving 12 years	Early first degree ab- old tubercu- lous lesion
4	M	53	Spooling 6 years	Negative
5	M	47	Spooling 3 yrs. U.S.As.Co. 14 yrs. elsewhere	Negative
6	M	63	Warping 12 years	Negative; old tuberculous lesion
7	M	30	Weaving 10 years	Early first degree asbestosis
8	M	44	Carding 5 years	Early first degree asbestosis; heart lesion
9	M	33	Spooling 5 years	Beginning asbes- tosis
10	M	37	Weaving 6 years	Negative
11	M	32	Weaving 9 years	Negative. Old tuberculous lesion
12	M	38	Weaving 22 years	First degree as- bestosis. Old tuberculous lesion
13	M	45	Weaving 7 years U.S. As. Co. 11 yrs. elsewhere off & on	Negative
14	M	64	Warping 12 years	Negative

No.	Sex	Age	Occupational History	Diagnosis
15	M	39	Weaving 8 years	Negative. Old tuberculous lesion active(?)
16	M	32	Weaving 18 years	Early asbestosis
17	F	41	Spinning 8 years	Negative
18	M	33	Carding 7 years	First degree asbestosis
19	M	48	Foreman 22 years	Early second degree asbestosis
20	M		Worked in asbestos 20 years, out of plant 10 years	Late second degree asbestosis. Old tuberculous lesion

In the foregoing cases the length of exposure with the resultant degree of pneumoconiosis and the general appearance of the films all support the second alternative mentioned above.

Sputum analysis was made of ten of the individuals X-rayed, and "asbestos bodies" were found in one case.

SUMMARY:

Dust counts in the preparation room and carding room were high, several counts higher than ten million.

Individuals exposed to this dust showed definite pneumoconiosis. Their occupation and length of exposure were as follows (omitting 19 and 20 whose histories were not clear):

<u>Twisting</u>	<u>Spooling</u>	<u>Carding</u>	<u>Weaving</u>
15 years	5 years	5 years	10 years
		7 "	12 "
			18 "
			22 "

The number of these cases is too small to draw any final conclusions. They indicate a possible variation of hazard in the four processes listed, but further study will be needed to establish the facts.

RECOMMENDATIONS:

1. The method of application of the oil used in the preparation room at the Charleston plant is more effective than that used at Kenheim. Therefore, the Charleston method is preferred.

2. That the humidification and air conditioning system be continued

and extended wherever possible.

3. The dust counts indicate little difference between the two systems of exhausting dust arising from the carding machines. The canvas covers have no advantage in exhausting the dust, and have the disadvantage of making it more difficult to clean the machines. They also offer a larger surface for dust to settle. The exhaust system connected with the metal hood covering the comb of the card is recommended.

4. That the exhaust system attached to the machines in the preparation room be repaired and maintained, especially those connected with the shaker sieve and the wick carding machines.

5. That cleaning be done by means of a vacuum system instead of the present method of blowing with compressed air.

6. That all employees be given an initial physical examination and periodically thereafter. X-ray examinations should be made when indicated.

U.S. ASBESTOS & RUBBER DIVISION OF RAYBROS-KANAWASTA, INC.

Scranton, Pa.

• • •

A second survey of dust conditions in the Scranton plant of the U.S. Asbestos & Rubber Division of Raybestos-Kanawasta, Inc. was made on April 16, 17, 18, 22, and 23, 1935. This is supplementary to the survey conducted in February, 1930 and the methods of sampling and analysis are the same as in the first survey.

The first survey included only those departments involving textile operations, whereas this survey includes all departments of the plant.

The processes in the Preparation Department, Carding Department, Brake Band Weave Room, and twisting, spinning, spooling, and broad cloth weaving departments are the same as at the time of the first survey. The exhaust equipment has not been changed.

The following tables show results of dust counts and comparative data of the two surveys:

MAX GLAUBACH, C.S.R.
CERTIFIED BY
NEW JERSEY & NEW YORK

P. PEARSON 16
MADE IN U.S.A. For M. to S.

- Glueck

R-H 261 B-75-771

LAB. ANALYSIS & SUMMARY OF AIRBORNE DUSTING, 1935

Asbestos, D.

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
PREPARATION DEPARTMENT, MEZ. B.							
1	Inside discharge pipe from vertical opener discharging fibre onto screen	4/24/35	20.0	6.2	9.15	30	Asbestos 224 116 special
2	At loose fly - wet vesp	"	27.9	20.9	17.4	106	" Only loose in Prep. Dept.
3	Between chasers #1 and #2	"	15.0	21.0	20.1	106	Asbestos 224 116 special
4	Inside truck under discharge pipe from hopper on second floor	"	9.5	33.7	20.0	116	Asbestos 224 116 special
5	Floor wiring of asbestos and cotton between chasers and vertical opener	"	15.0	30.4	29.2	106	" One man, clothes covered with fibre
6	At discharge end of small fibre opener	"	20.5	10.2	0.5	51	Asbestos 224 116 special
7	General air in preparation room	"	22.0	14.2	11.0	30	Asbestos 224 116 special
8	At hopper of wiring picker	"	15.0	21.0	10.1	106	" One man, sorting wire into hopper from floor

Relative humidity in Preparation Dept. (1935) 20% -- (1930) 37%
The average of these counts is 19.9 million particles per cu. ft. air sampled.
The average count in this department in 1930 was 14.1 million particles per cu. ft. air.
The analysis of rubber dust from this department showed 365 000.
Relative humidity outside (1935) 20% -- (1930) 67%.

Sample No.	Station	Date of Sampling	Cu. Ft. of Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
SAFETY ROOMS							
9	At take-off end of breaker card #1, Dept. 2, 2nd floor	4/16/35	41.0	9.0	7.7	Asbestos cotton	
10	Between cards #7 and #16, Dept. 2, 2nd floor	"	20.5	13.7	11.7	"	129 mls - cards enclosed and exhausted
11	Between storage bins and cards #31 and #32 at operator's position	"	31.1	10.8	16.0	"	Cards partially exhausted but not enclosed #32 - 120 stock #31 - 116 special
22	Same location as #11 just after stock from mixing plunger had been blown into storage bins	4/12/35	36.5	16.2	13.8	"	Bin door opens on this floor
12	Between cards #1 and 2 and #7 and 8 operator's station, Dept. 3, second floor, 3 cards running 224 stock; 1 card running 124 stock	4/16/35	22.5	16.7	14.2	"	Cards partially enclosed and exhausted; operator wore gauze strip with cotton pad under nose.
13	Between cards #7 and #8 on saddle sides; saddles extend out from enclosures	"	10.0	36.0	34.4	"	Dept. #3, second floor
14	Between cards #18 and 19 and #25 and 26 in aisle where operator works	"	20.0	20.4	24.2	"	Cards partially enclosed and exhausted; 3 cards running 224 stock 1 card running 60/10 stock
19	Between cards #20 and 21 and #27 and 28 in aisle where operator works; cards partially enclosed and exhausted	4/17/35	30.0	0.0	7.5	"	2 cards running 60/10 stock; 1 card running 231 stock; 1 card running 224 stock

Relative humidity 20%.

The average of these counts is 10. Million particles per cu. ft. air sampled.

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
SPINNING MFL. 4L, 2nd Floor							
15	Between spindlers twisting nine and yarn, 2 men	4/14/35	20.0	20.0	17.0	Asbestos cotton	Machines #464, 463, 462, 459, 229 slack - 224 slack
16	Between mules #417 and #402 where operators work	"	27.5	29.4	25.2	"	"
17	Between mules #404 and #385 where operators work	"	20.0	12.4	10.5	"	"
18	Between mules #406 and #377 where operator works	"	20.0	17.6	15.0	"	"

Relative humidity 26%.
 The average of these counts is 19.9 million particles per cu. ft. air sampled.
 The average count in this department in 1935 was 2.72 million particles per cu. ft. air sampled

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
BRAYE BOOM (BRAKE BAND) DEPT. #12							
20	Between looms #1 and #23 dry weaving	4/17/36	30.0	14.9	12.7	Asbestos cotton	Ring steel and brake lining 224 stock, one bag
23	At operator's position of loom #17	"	23.3	14.8	12.6	"	Parties brake lining 224 stock
24	In aisle between looms #33 and #19, wet weaving	"	32.5	8.85	7.5	"	#33 - 224 stock #19 - 340 stock
25	In aisle between looms #14 and #26, and #7 and #12	"	23.0	7.3	6.3	"	#14 and #26 - truck lining #7 and #12 dry - 224 stock
26	Inspection of brake lining and ring steel	"	30.0	6.15	5.2	"	Material goes thru revolving brushes - exhaust system

Relative humidity (1935) 47% - (1936) 76%
 The average of these counts is 10.4 million particles per cu. ft. air sampled.
 The average count in this department in 1936 was 6.96 million particles per cu. ft. air.

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
PROCESSING, TREATMENT & SHEDDING							
27	Between looms #1 and 2 and #3 and 4, broad looms, #1 not running	4/17/35	49.0	8.8	7.55	Asbestos cotton	Air-water spray for humidifying, Dept. 10.
28	At looms #22 and 24, cloth	"	26.0	16.3	14.0	Asbestos cotton	#24 warp wet with a hose; #22 dry.
29	At loom #10 - wet weaving, 690 cloth, 3 ply for clutch feeding	"	22.0	10.3	6.8	"	219 - 224 air, warp passes through 63% emulsion
30	Between tristers #57 and 656	"	21.0	13.7	11.8	"	2 women, Dept. 7.
31	Between tristers	"	26.6	19.0	15.4	"	2 women, Dept. 7.
32	Between specklers #3 and 4, Dept. 6	"	20.8	25.0	21.4	"	6 women, dust on machines blown off with cardboard used as fans.

Relative humidity (1935) 415 --- (1930) 306
 The average of these counts is 15.35 million particles per cu. ft. air sampled.
 The average count in this Dept. in 1930 was 2.35 million particles per cu. ft. air sampled.

CONCLUSIONS AND RECOMMENDATIONS

SPINNING DEPARTMENT

The dust counts in the Preparation Department are high. All counts, but one, show more than ten million particles per cubic foot. The raw fibre is handled carelessly and piled on the floor at various places. The average dust counts are higher than those of the survey made in 1930. No improvements have been made since the first survey was made. The relative humidity is lower than at the time of the previous survey.

It is recommended that a mechanical method of handling the fibre be installed. Exhaust equipment, properly designed and applied, be installed at the chasers, pickers, and shaker screens and it should be properly maintained. The one loom should be removed from this department. A humidifying system should be used, if practicable. A vacuum sweeping system for sweeping and cleaning machines should be installed throughout the plant.

The average counts in the brake band weave room are higher than those of the 1930 survey. No exhaust equipment is in use on the looms. The relative humidity is lower than at the time of the first survey.

It is recommended that wet warp rearing be done whenever possible. The humidity should be kept as high as possible without causing discomfort to the workers.

The average dust counts in the spinning, twisting, and rearing departments are much higher than those of the first survey. The relative humidity is lower than at the time of the first survey.

It is recommended that the broad looms be exhausted and the humidity be kept higher.

The average dust counts in the spinning department are much higher than those of the first survey. This may be attributed to pollution of the air from the carding machines located in the same room and to the low humidity. A check of the records will show the grade of fibre used at the time of the two surveys and the rate of production.

It is recommended that the spinning department be isolated from the carding department. A humidifying system should be installed.

The average dust counts in the carding department are higher than those of the first survey. A check of the records would show the grade of fibre used at the time of the two surveys and the rate of production. The exhaust equipment does not seem to be effective in removing the dust generated.

It is recommended that exhaust equipment, similar to that in operation at the Charleston plant, be installed on the carding machines. Fibre storage bins opening into the card room should be exhausted.

BRAKE LINING AND CLUTCH FACING

PROCESSING

Two types of brake lining are made. One type is made from woven narrow bands of asbestos. The bands are saturated in an emulsion or a rubber solution according to specifications. They are cured in heated presses or on heated mandrels. If they are cured on heated mandrels, they are cut to length before being cured. The mandrels also shape them into arcs. They are ground to the thickness desired and rivet holes are drilled or punched into them. They are inspected and packed for shipment.

The second type of brake lining is the extruded type. This type is produced from a mixture of asbestos fibre, litharge, sulphur, zinc oxide, whiting, zinc, and rubber dissolved in gasoline. This wet mixture is put into an hydraulic press and is extruded through a die into long narrow strips. The strips are cured in heated presses. They are ground to the thickness and width desired and formed on heated mandrels. Holes for rivets are drilled or punched into them. The ends are chamfered. The lining is then inspected and packed for shipment.

Clutch facing is made from asbestos cloth and narrow bands of woven asbestos. The wide cloth is cut into squares on a band saw. Solid rings are cut from these squares after they have been saturated in an emulsion and dried. The rings are cured in heated presses. They are then ground to the thickness desired. Holes are drilled into them on gang drill presses. The inside and outside diameters are ground on Gardner grinders. The clutch facing is then inspected before shipping.

The narrow bands of woven asbestos are put through a coiling machine to be formed into spirals. These are then put through a rubber solution and wound onto a mandrel. The rings are cut and the ends fastened together with brass wire. They are cured in heated presses and ground to the dimensions required. They are then inspected before shipping.

RUBBER GASKETS AND PACKING

Asbestos cloth is impregnated with a solution of rubber and gasoline. The cloth is then cut into strips. The strips are folded by hand roughly to form the gasket or packing. The rough forms are then placed in forming molds and pressed and cured in steam heated presses. The edges are trimmed and the product is then inspected.

Rubber used in the various products is compounded in building #2. The raw rubber is mixed with zinc oxide, lithopone and barytes in a rubber compounding mill. The compounded rubber is dissolved in gasoline in tumbler barrels.

The emulsions used in the various products are made in building #35. The materials used are litharge, lampblack, mica, Gilsonite, linseed oil, kerosene, and water. These materials are weighed and put into an electric mixer. After the emulsion is mixed, it is put into pails and carried to the different departments where it is used.

ANALYSIS OF LABOR RECORDS

Name	Age	Occupation	Years of Experience	Hemoglobin %	Positive Leucocytes	Remarks
Leo F. March		Emulsion preparation	2	50	Frequent	Poor teeth
Harry L. Bullock		Grinding brake lining	5 (approx.)	88	Negative	
Samuel Wright		Mixing for extruded brake lining	1½	65	"	Stomach trouble
Charles Entwistle		Setting brake bands	6½	40	Occasional	Formerly ailing for extruded brake lining, changed because of sick- ness, had local poisoning 2 years ago, treated by doctor
Leroy Galt	26	Roll grinder	1½	94	Negative	Complains of nervous disorders and stomach trouble, claims to have high blood pressure
Robert Giddner	22	Extruder	3	60	"	
Leoline Winger	20	Label and stamp segments	1½	70	"	
Mark Weber	26	Segment grinder	2½	65	"	
E. F. Walter	40	Dept. of welded brake lining dept.	4½	55	"	
Olive Bauer	22	Label and stamp segments	1 1/3	70	"	
Aurilio Shanks	20	Label, stamp and ship segments	1 1/3	80	"	
Malcolm Sheaffner	20	Brailer	1	65	"	
E. Spensler	20	Mandrels	2	95	"	
John Miller	29	Rubber mixer	1½	97	"	
Bever Miller	30	Segment grinder	6 mos.	90	"	Worked 10 years previous- ly as silk weaver
Paul H. Hallinger	23	Superintendent of welded	1	100	"	

Sample No.	Station	Date of Sampling	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft. Air Sampled	Millions of Particles less than 10 microns in greatest diameter per cu. ft. Air Sampled	Type of Dust	Remarks
SPINNING, TWISTING & WEAVING							
27	Between looms #1 and 2 and #3 and 4; broad looms, #1 not running	4/17/35	49.0	0.8	7.55	Asbestos cotton	Asbestos spray for building, Dept. 10.
28	At looms #22 and 24, cloth	"	26.0	16.3	14.0	Asbestos cotton	#24 very wet with a hose; #22 dry.
29	At loom #10 - wet weaving, 670 cloth, 3 ply for clutch feeding	"	22.0	10.3	0.8	"	210 - 224 mix, very pieces through 634 cyclone
30	Between tristers #637 and 638	"	24.0	13.7	11.0	"	2 women, dept. 7.
31	Between tristers	"	26.6	18.0	15.4	"	2 women, dept. 7.
32	Between spoolers #3 and 4, dept. 6	"	20.0	25.0	21.4	"	6 women, dust on machines blown off with cardboard used as fans.

Relative humidity (1935) 415 - - - (1930) 506
The average of these counts is 15.35 million particles per cu. ft. air sampled.
The average count in this dept. in 1930 was 2.35 million particles per cu. ft. air sampled.

-7-

CONCLUSIONS AND RECOMMENDATIONS

SPINNING DEPARTMENT

The dust counts in the Preparation Department are high. All counts, but one, show more than ten million particles per cubic foot. The raw fibre is handled carelessly and piled on the floor at various places. The average dust counts are higher than those of the survey made in 1930. No improvements have been made since the first survey was made. The relative humidity is lower than at the time of the previous survey. x

It is recommended that a mechanical method of handling the fibre be installed. Exhaust equipment, properly designed and applied, be installed at the choppers, pickers, and shaker screens and it should be properly maintained. The one loom should be removed from this department. A humidifying system should be used, if practicable. A vacuum sweeping system for sweeping and cleaning machines should be installed throughout the plant.

The average counts in the brake band waste room are higher than those of the 1930 survey. No exhaust equipment is in use on the loom. The relative humidity is lower than at the time of the first survey.

It is recommended that wet sarp rearing be done whenever possible. The humidity should be kept as high as possible without causing discomfort to the workers.

The average dust counts in the spinning, twisting, and weaving departments are much higher than those of the first survey. The relative humidity is lower than at the time of the first survey.

It is recommended that the broad looms be exhausted and the humidity be kept higher.

The average dust counts in the spinning department are much higher than those of the first survey. This may be attributed to pollution of the air from the carding machines located in the same room and to the low humidity. A check of the records will show the grade of fibre used at the time of the two surveys and the rate of production.

It is recommended that the spinning department be isolated from the carding department. A humidifying system should be installed.

The average dust counts in the carding departments are higher than those of the first survey. A check of the records would show the grade of fibre used at the time of the two surveys and the rate of production. The exhaust equipment does not seem to be effective in removing the dust generated.

It is recommended that exhaust equipment, similar to that in operation at the Charleston plant, be installed on the carding machines. Fibre storage bins opening into the card room should be exhausted.

BRAKE LINING AND CLUTCH FACING

PROCESSING

Two types of brake lining are made. One type is made from woven narrow bands of asbestos. The bands are saturated in an emulsion or a rubber solution according to specifications. They are cured in heated presses or on heated mandrels. If they are cured on heated mandrels, they are cut to length before being cured. The mandrels also shape them into arcs. They are ground to the thickness desired and rivet holes are drilled or punched into them. They are inspected and packed for shipment.

The second type of brake lining is the extruded type. This type is produced from a mixture of asbestos fibre, litharge, sulphur, zinc oxide, whiting, zinc, and rubber dissolved in gasoline. This wet mixture is put into an hydraulic press and is extruded through a die into long narrow strips. The strips are cured in heated presses. They are ground to the thickness and width desired and formed on heated mandrels. Holes for rivets are drilled or punched into them. The ends are chamfered. The lining is then inspected and packed for shipment.

Clutch facing is made from asbestos cloth and narrow bands of woven asbestos. The wide cloth is cut into squares on a band saw. Solid rings are cut from these squares after they have been saturated in an emulsion and dried. The rings are cured in heated presses. They are then ground to the thickness desired. Holes are drilled into them on gang drill presses. The inside and outside discators are ground on Gardner grinders. The clutch facing is then inspected before shipping.

The narrow bands of woven asbestos are put through a coiling machine to be formed into spirals. These are then put through a rubber solution and wound onto a mandrel. The rings are cut and the ends fastened together with brass wire. They are cured in heated presses and ground to the dimensions required. They are then inspected before shipping.

PACKING GASKETS AND PACKING

Asbestos cloth is impregnated with a solution of rubber and gasoline. The cloth is then cut into strips. The strips are folded by hand roughly to form the gasket or packing. The rough forms are then placed in forming molds and pressed and cured in steam heated presses. The edges are trimmed and the product is then inspected.

Rubber used in the various products is compounded in building #2. The raw rubber is mixed with zinc oxide, lithopone and barytes in a rubber compounding mill. The compounded rubber is dissolved in gasoline in tumbler barrels.

The emulsions used in the various products are made in building #35. The materials used are litharge, lampblack, mica, Gilsonite, linseed oil, kerosene, and water. These materials are weighed and put into an electric mixer. After the emulsion is mixed, it is put into pails and carried to the different departments where it is used.

ANALYSIS OF BLOOD SPECIMENS

Name	Age	Occupation	Years of Residence	Hemoglobin %	Positive Smear	Remarks
Lee F. Blum		Machine preparation	2	50	Frequent	Fear teeth
Harry L. Bullock		Grinding brake lining	5 (approx.)	68	Negative	
Samuel Wright		Wiring for extruded brake lining	1½	65	"	Stomach trouble
Charles Matthews		Cutting brake bands	6½	40	Occasional	Formerly missing for extruded brake lining, changed because of sickness, had lead poisoning 2 years ago, treated by doctor
Louise Gold	26	Ball grinder	1½	94	Negative	Complains of nervous disorders and stomach trouble, claims to have high blood pressure
Robert Gilder	22	Extruder	3	60	"	
Louise Winger	20	Label and stamp segments	1½	70	"	
Mark Mahr	26	Segment grinder	2½	65	"	
R. F. Walter	40	Supt. of milled brake lining dept.	4½	55	"	
Olive Bauer	22	Label and stamp segments	1 1/3	70	"	
Annette Blum	20	Label, stamp and ship segments	1 1/3	80	"	
Malcolm Shaffer	20	Drifter	1	65	"	
E. Spangler	20	Inspector	2	95	"	
John Miller	29	Rubber mixer	1½	97	"	
Beaver Miller	30	Segment grinder	6 yrs.	90	"	Suffered 10 years previously as silk reeler

CONTAMINATED AND RECOMMENDATIONSGLITCH FACIES, BRAKE LINING AND PACKING DEPARTMENTS

Several dust counts in these departments are high and in almost all cases show that there is lead present in the air. Samples #14, 36, 38 and 55 show large quantities of lead present. Chemical analyses of rubber dust samples from these departments also show presence of lead. These analyses show that there is a definite health hazard present due to the use of lead. There is another health hazard present due to the use of benzol in the treating of brake bands.

Blood specimens were taken from sixteen employees and the results of these tests are shown in tabular form. Only two specimens showed punctate basophiles (stippled cells), but several other specimens showed low hemoglobin percentage.

It is recommended that a vacuum sweeping system be installed to do away with dry sweeping.

All machines in these departments should be equipped with efficient exhaust systems to carry away harmful dusts.

Employees engaged in handling lead should be supplied with positive pressure or cartridge type respirators and cautioned to handle the lead carefully. These operations should be isolated from the remainder of the departments. Female help work in the same room in which litharge is mixed for untreated brake lining. Empty litharge drums should be removed from the department.

The use of benzol should be eliminated, if practicable, or such operations should be isolated so that the least number of employees would be exposed to the fumes, or the benzol could be handled in a closed system.

The employees exposed to benzal fumes should be supplied with positive pressure respirators. All employees in these departments should be watched carefully and examined periodically for signs of lead or benzal poisoning.

Sample No.	Location	Date of Sampling	Gr. Pt. Air Sampled	Gr. Pt. of Particles per Cu. Ft. Air Sampled	Gr. Pt. of Particles, less than 10 microns in greatest diameter per Cu. Ft. Air Sampled	Gr. Pt. of Acid per Cu. Ft. Air	Gr. Pt. of Acid per Cu. Ft. Air	Lead found in Gr. Pt. of Acid per 1000 g.	Type of Acid	Remarks
RECORDS IN THE AREA										
10	General air - intersection of main highway, Dept. 99.	6/22/72	25.0	0.45	0.3	0.00177	0.0010	0.000	Antimony	6 microns - 2 mm
11	At certain printer, Dept. 99, near building	"	25.0	0.4	0.35	0.0008	0.000	0.000	"	Substantly equal
12	General air, during and working area on main highway, Dept. 99	"	25.1	0.47	0.3	0.00179	0.0011	0.001	"	Several microns - 2 mm
13	At certain printer, Dept. 99	"	25.0	0.4	0.3	0.0014	0.000	0.000	"	Substantly equal
14	At printer 2000 and 2071, entrance area building, Dept. 99	"	27.0	0.1	0.2	0.0002	0.000	0.000	"	Substantly equal
15	Working materials for entrance area building, Dept. 99	"	13.1	13.7	12.1	0.0017	0.000	0.000	Antimony	These safety appliances (respirator and eye) while working, antimony on floor, rubber boots - in position.
16	At this area during entrance area for glass factory, close and before being worked	"	25.1	0.4	0.3	-	-	-	Antimony	1 mic while entering mill 1 mic from respirator, Dept. 99
17	General air - taken near building area for entrance area building, Dept. 99	"	27.0	0.1	0.2	0.0004	0.000	0.000	Antimony	Antimony
18	At certain printer (9) entrance printer, Dept. 99	"	25.1	0.3	0.4	0.0017	0.000	0.000	Antimony	1 mic - antimony system
19	General air - taken at entrance area during entrance building	"	25.0	0.3	0.2	0.000	0.000	0.000	"	0 mic - Dept. 99
20	At certain printer (9), entrance building, Dept. 99	"	25.1	0.4	0.3	0.0015	0.000	0.000	"	1 mic - antimony system
21	See as sample 16	6/22/72	25.1	0.1	0.2	0.0004	0.000	0.000	"	"
22	Entrance printer (9) Dept. 99 at entrance's position	"	25.0	0.0	0.0	0.0007	0.000	0.000	"	Substantly equal - 1 mic entrance building
23	Drill (9), Dept. 99, drilling holes in entrance building	"	25.0	0.0	0.0	0.0017	0.000	0.000	"	1 mic - antimony system
24	Entrance printer (9), Dept. 99, printing entrance building, antimony system	"	25.0	0.0	0.0	0.000	0.000	0.000	"	Large particles through air - up from entrance area
25	General air - entrance building entrance area	"	25.0	0.0	0.0	0.000	0.000	0.000	"	0 mic - 1 mic
26	Drilling entrance area building, (9)	"	25.0	0.0	0.0	-	-	-	Antimony	1 mic - not seen to rub the area
27	General air, rubber during Dept. 99, (9)	6/22/72	27.1	0.0	0.0	0.000	0.000	0.000	Antimony	1 mic - position as seen
28	At rubber mill, Dept. 99	"	25.1	0.0	0.0	0.000	0.000	0.000	Antimony	1 mic - as respirator
29	General air - entrance intersection of entrance and entrance area for entrance, Dept. 99	"	25.0	0.0	0.0	-	-	-	Antimony	Antimony
30	Entrance Dept. 99, printing entrance area entrance building, (9)	"	25.0	0.0	0.0	-	-	-	Antimony	0 mic
31	General air, printer Dept. 99, printing entrance area entrance building, (9)	"	27.0	0.0	0.0	-	-	-	Antimony	0 mic
32	Working materials, Dept. 99, 2 mic, as entrance, as entrance	"	25.0	0.0	0.0	0.0007	0.000	0.000	Antimony	Antimony test results, 1 mic oil, entrance, rubber

General air - entrance intersection of entrance and entrance area for entrance, Dept. 99
 General air - entrance intersection of entrance and entrance area for entrance, Dept. 99
 General air - entrance intersection of entrance and entrance area for entrance, Dept. 99
 General air - entrance intersection of entrance and entrance area for entrance, Dept. 99

HEALTH HAZARDS OF ASBESTOS AND OTHER DUSTS

Asbestos dust gives rise to a pneumoconiosis or fibrosis of the lungs which has been discussed in the previous report made on the asbestos industry. Developments in our knowledge of asbestos are continually taking place and a summary of new facts discovered will be added to the general composite report of the asbestos plant survey which is to be brought out later.

Slime dust. Very little is known of the effect of slime dust on the lungs, but such evidence as there is would tend to place it in a class with the less harmful silicate dusts such as talc and clay. If inhaled in sufficiently high concentrations, these dusts would have to be considered potentially harmful, however, until the contrary is proved, although they apparently do not have the specific injurious effect of the dusts high in uncombined silica.

With the exception of litharge, or lead, an extremely toxic dust, the other dusts generated in the compounding of rubber and brake linings such as zinc oxide, sulphur, and lithopone are probably relatively harmless in the quantities present and in any event proper protection against the lead or litharge dust which is essential would protect against these also.

TOXICITY OF LEAD

Lead poisoning is probably the most common of the industrial poisonings. Practically all forms of lead are toxic, the degree of toxicity depending upon their solubility in human tissues. The oxides and basic lead carbonate are among the most soluble and therefore the most readily toxic forms.

Lead inhaled is more rapidly and more surely toxic than lead ingested. When lead enters the digestive tract some or most of it may be eliminated unchanged from the body and it is only when it is absorbed in greater quantities

then are eliminated that poisoning occurs. When lead is taken into the lungs, it reaches the blood stream rapidly and directly and comparatively little is eliminated. While lead is circulating in the body poisoning may occur. Lead absorbed in excess of lead eliminated is accumulated in various organs and is finally deposited in the bones in insoluble form in a manner similar to the deposition of calcium. It is somewhat controversial at the present time whether or not under ordinary circumstances changes in bodily metabolism can later render the lead thus stored in the bones soluble again and set it free into the circulation causing poisoning without further exposure. It has been demonstrated by Ash and his associates,⁽¹⁾ however, that this stored lead can be released by medication with weak acids and low calcium intake. Ash's studies on the subject eight or ten years ago revolutionized the treatment of lead poisoning. Extensive studies on lead poisoning have also been made recently by Kehoe and his associates⁽²⁾ who have made valuable contributions to the knowledge of the subject.

Lead absorption does not necessarily mean lead poisoning, but there is probability of lead poisoning wherever lead is being absorbed into the body. Individuals vary considerably in their ability to take in and eliminate lead. It is generally considered that negroes, women, and children are more highly susceptible and that those who have had attacks of poisoning are more liable to future attacks than those who have not.

With a few notable exceptions, industrial lead poisoning is of the chronic type due to prolonged exposure to minute quantities of lead taken in daily. Owing to the above-mentioned differences in the toxicity of lead com-

parade, in the methods of entrance into the body, and in individual susceptibility
 (1) Ash, J.C., Fairhall, L.F., and others, Lead Poisoning, Medicine Monographs, Vol. VII, The Williams & Wilkins Co., 1926, Baltimore, Md.
 (2) Kehoe, E.A., Thakara, Fred, and Cholak, Jacob, Lead Absorption and Excretion in Certain Lead Trades, Journal of Industrial Hygiene, Sept. 1933, Vol. 14, No. 5, pp. 336-339, Balt. Md., another article pp. 340-346.

city, there is little agreement in the numerous attempts that have been made to estimate the minimum amount of lead which can cause chronic poisoning if taken in over long periods of time. The various estimates range from one-tenth of a milligram to two milligrams daily. Probably one to two milligrams daily represents a fairly safe limit.

In a study made by the United States Public Health Service⁽³⁾ in a storage battery plant, for instance, it was concluded that for the conditions of exposure in that plant, 2.5 milligrams per 10 cubic meters of air appeared to be a safe limit.

It is also impossible to determine exactly the amount of air taken into the lungs daily, owing to individual differences and to differences in degree of activity. For practical purposes only, therefore, it is roughly estimated that a man at moderately heavy work inhales about 10 cubic meters of air in a ten-hour day. Where possible, it is recommended that the working atmosphere should be kept below one-tenth of a milligram per cubic meter of air or the workers should be protected by suitable respirators and other precautions. Removing lead at its source of origin is by far the best method for prevention of poisoning.

Evidence of lead absorption is shown by an ashen pallor of the skin, a lead line on the gums, stippling of the red blood cells, and a secondary anemia or other indication of damage to the blood-forming organs. Upon evidence of lead absorption workers should be removed from exposure until all signs have disappeared.

If lead exposed workers are under very careful and experienced medical control, it is possible to catch every sign of poisoning in the absorption.

(3) U.S. Public Health Service, Treasury Dept., Public Health Bulletin No. 205, Lead Poisoning in a Storage Battery Plant, Gov. Print. Off. Wash. D.C., 1933.

stage or in the early stages of intoxication and, by taking appropriate measures, to prevent the occurrence of any acute or sub-acute attacks of poisoning. It is not easy, however, to diagnose lead in its early stages without laboratory studies of the blood, and there will generally be cases which will present symptoms unexpectedly and in an unusual manner.

The symptoms of lead poisoning are numerous and it manifests itself in a great variety of ways. The most common characteristic symptoms noted are colic, constipation, weakness, especially of the extensor muscles of the hands and feet, muscular pains, nausea and vomiting, loss of appetite, bad taste in the mouth, nervousness and irritability. The proximate objective signs of lead poisoning are pallor or jaundice, tremor, reflex changes, changes in the blood picture, excessive amount of lead in the excreta.

Lead intoxication brings in its train a great many sequelae, including paralysis, optic atrophy, encephalitis, and premature old age. It causes early degenerative changes such as arterio-sclerosis and nephritis. The mortality from chronic lead poisoning is not high, but this is absolutely no indication of the extent to which cases are occurring since cases treated early have a fairly good prognosis and since many deaths are recorded as due to the final sequelae such as arterio-sclerosis rather than to the original cause.

Among the measures for control of lead poisoning recommended by the industrial physician of a large rubber manufacturing plant in Akron, Ohio are (1) monthly medical examinations of exposed workers, (2) separate lockers for work and street clothing, (3) provision of two sets of work clothing and arrangements for laundering weekly, (4) two respirators, one of them to be cleaned and sterilized each day, (5) provision of clean towels, soap and nail brushes, hot

running water, and time allowance for thorough washing, (6) wet sprinkling and sweeping or vacuum cleaning of the floor daily, (7) exclusion of all other workers except those engaged in operating lead processes from the room, and (8) rules strictly enforced against eating in the workrooms.

TOXICITY OF BENZOL, THE HOMOLOGUES, TOLUOL AND XYLOL, AND OF ETHYLACETATE

Benzol is by far the most hazardous of the solvents commonly used in industry. It was at one time quite widely employed in many processes and especially in paints and lacquers used for coating by air guns, but because of its recognized danger to the health of operatives, its use has been largely supplanted by less toxic substances. The higher homologues of benzol such as toluol and xylol have been substituted in some cases with an in some cases without success from the health standpoint. These substances are more poisonous than benzol in high concentrations such as would result in acute accidents, and, experimentally, animals die in a shorter time and with lesser concentrations than is the case with benzol. However, their lower volatility gives toluol and xylol an advantage over benzol for industrial practice with respect to health of the workers and the effects of chronic poisoning by toluol not containing any benzol seem to be less serious and not so lasting.

The Benzol Committee of the National Safety Council⁽¹⁾ found that benzol would cause signs of poisoning at concentrations of only 100 parts per million in the atmosphere. Slight effects are possible with even far lower concentrations. It should be borne in mind that benzol can also be absorbed into the system through the skin and that it is extremely dangerous to spill it on the skin or clothing.

~~The effects of chronic benzol poisoning resulting from inhalation~~
(1) National Safety Council, Final Report of the Committee on Benzol, Chemical and Rubber Section, Chicago, 1920, pp. 117-118.

over a period of time to low concentrations of benzol vapor are well known and consist of headache, dizziness, weakness, loss of appetite and weight, sore gums, shortness of breath, and, sometimes, abdominal pain, nausea and vomiting. The signs, with due allowance for atypical cases, generally consist of a marked reduction in the number of white blood cells, a changed relationship between the percent of polymorphonuclear cells and the lymphocytes, and later on pallor, due to aplastic anemia, oxygen want or internal asphyxiation, prolonged coagulation time, bleeding from the mucous membranes, purpura, and sometimes tremor and visual disturbances.

Besides the serious systemic effects, benzol, in common with many other solvents, may cause a dermatitis of the skin.

Individual susceptibility to poisoning by benzol appears marked. The fact that cases of poisoning are not being reported from workers in a given process is no guarantee of safety unless physical examinations with blood counts are carried out on employment and regularly during exposure. The symptoms are vague, the worker frequently is not aware of his exposure, and the family physician is usually not familiar with the manifestations of chronic benzol poisoning.

The National Safety Council committee has recommended that a 25% reduction in the white cell blood count should be considered as evidence of poisoning. The color index of the blood is not a reliable criterion, since destruction of red blood cells usually occurs fairly late in the picture after serious or fatal damage has been done to the blood forming organs. Other conditions may be present which could cause a picture somewhat similar to that of

~~benzol poisoning, in which case detailed study and observation are indicated.~~
(5) ~~McGraw, Harry P. M.D., The Present Status of Benzene (Benzol) Poisoning,~~
~~Journal of the American Medical Association, July 27, 1929, pp. 282-283.~~

The National Safety Council committee found that 32% of the exposed workers who were examined in various factories had leukopenia (decreased white blood cells) in mild or pronounced degree even when basal concentration in the air was low and exhaust ventilation was good.

Preventive measures in handling so dangerous a substance logically consist of completely enclosing processes or containers and in providing carefully designed downward-draft ventilation, the results of which should be checked by air sampling. The method of choice, however, is to substitute some other less harmful substance where possible.

TOXICITY OF GASOLINE AND KEROSENE

In the presence of heavy fumes from these petroleum solvents, an acute anesthetic poisoning occurs with headache, blurring of vision, mental confusion, dizziness, nausea, and loss of consciousness. Permissible maximum concentrations⁽⁶⁾ in the air breathed are estimated to be from 1000 to 3000 parts per million for short exposures and 1000 parts per million or less for prolonged exposure.


These substances are fat-solvent and skin trouble is frequently caused in those who come into continuous contact with them. Gloves are apt to aggravate the difficulty since without free evaporation, burns are caused by the gasoline getting inside the gloves. A booklet describing precautions to be taken against oil dermatitis is enclosed.


TOXICITY OF LINSEED OIL

In addition to the danger of spontaneous combustion, linseed oil, when heated gives off irritating fumes of acrolein which may be acutely toxic in concentrations of more than 20 parts per million of air, while for prolonged


(6) U.S. Bureau of Mines


exposures 3 parts per million is considered the maximum permissible by the United States Bureau of Mines. No chronic ill-effects have been noted from this substance as used in industry, though it is irritating to the eyes, nose and throat. In addition dermatitis or infections of the skin are common among workers handling these oils. Those showing hypersensitivity are best removed from contact with them.







size of dust particles in microns





Size of dust particles in microns





Q 1

Q 2

Q 3


Q 4

Q 5

Q 6

Q 7

Q 8



Size of dust particles in microns

UNITED STATES ASBESTOS DIVISION

of Raybestos-Manhattan, Inc.

Manheim, Penna.

• • •

A survey was made of this plant on March 14, 15, 16, 17, 20, 21 and 22, 1939. This report supplements reports made on similar surveys conducted in 1930, 1935, and 1938.

The manufacturing operations at the time of this survey were the same as in the previous surveys. A few changes have since been made in the relocation of machines and in the application of exhaust systems for the collection and removal of generated dusts. Such changes are noted in the remarks column in the following tables of results.

The same sequence of sample numbers has been followed as in the previous reports.

MAX GLAUBACH, C.S.R.
CERTIFIED IN
NEW JERSEY & NEW YORK

APR 1 1939
P. Pearson
SARNOFF

Exhibit L

0 11 24/39

B. E. ASBESTOS DIVISION OF RAYBROS-MANHATTAN, INC.

Manhatten, Penna.

Sample No.	Location of Sample	Date	Cu. Ft. Air Sampled	Total Count of Millions of Particles per cubic foot of air sampled	Type of Dust	Remarks
1	Preparing or opening room area of vertical opener and sucker screens; machines #19 and 39	3/15/39	38.0	8.0 47	Asbestos	The exhaust fan window under the hood has been lowered to 4 feet from floor and its capacity increased. Approximately 1 lb. of dust at this time is being outside hood.
2	At operator's position on loam #346	3/16/39	46.0	5.2 31	Asbestos and cotton	This position is near the chasers which are being enclosed and exhausted.
4	Between #1 and 2 chasers; machines #2 and 3	3/14/39	56.0	4.0 24	Asbestos	These chasers are being provided exhaust hood.
6	At loading end of tandem vertical opener; machine #15	3/15/39	56.0	5.2 31	Asbestos and cotton	
3	At discharge end of tandem vertical opener; machine #46	3/15/39	45.0	2.5 15	"	The exhaust has been ordered to cover the conveyor and truck into which the material drops.
5	General air sample taken at center of the opening room	3/15/39	44.0	1.6 10	"	The additional levels placed in this department were not in operation when this sample was taken.
7	At Williams crusher	3/15/39	38.0	2.6 16	"	No water meter on the floor at the time this sample was taken.
94	At Giant cutter	3/15/39	36.0	3.0 18	"	Sample #7 was at the picker which has since been eliminated. No exhaust air to this machine. The material discharges out the floor.

File	Location of Sample	Date	Cu. Ft. Air Sampled	Total Count of Millions of Particles per cu. ft. air sampled		Type of Dust	Remarks
Card Room - 2nd floor, Dept. 1							
	At operator's position, cards 1, 2, 7 and	1/21/39	42.0	1.5	9	Asbestos and cotton	The exhaust system on the cards is the same as in 1938.
	Condensing machine #360	"	44.6	2.5	15	"	No bagging of material at time this sample was taken. Exhaust hood applied over loading trucks.
Dept. 2							
	Between cards 1 and 7, machines #232 and 242, at take-off side.	1/20/39	42.0	1.7	8	"	
	Between cards 7 and 13, machines #232 and 242, saddle side.	"	44.0	2.6	16	"	
	Between cards 3 and 9, machines #255 and 261, at take-off side	"	42.0	3.0	18	"	
	Between cards 9 and 15, machines #234 and 248, saddle side	"	43.5	1.7	8	"	
	Between cards 5 and 12, machines #257 and 263, take-off side.	"	43.5	2.3	12	"	
	Between cards 12 and 18, machine #264, saddle side	1/21/39	43.5	1.8	10	"	
	Between cards 16 and 22, machines #266 and 270, take-off side.	1/20/39	35.6	1.8	10	"	
	Between cards 13 and 20, machines #258 and 267, take- off side.	"	36.0	2.2	14	"	
	Between cards 17 and 23, machines #271 and 276, take-off side.	1/21/39	31.5	1.1	7	"	
Spinning Dept.							
3	Between rules 1 and 2	1/17/39	29.0	2.7	16	"	
1	Between rules 5 and 6	"	34.0	2.7	16	"	
2	At Whittie spoolers, machine #418	"	34.0	3.2	20	"	Both Whittie spoolers now enclosed and exhausted.
				31.4	2.9		

Sample No.	Location of Sample	Date	Cu. Ft. Air Sampled	Total Count of Millions of Particles per cu. ft. air sampled	Type of Particles	Remarks
------------	--------------------	------	---------------------	--	-------------------	---------

Recalling, Drying and Sampling Air Flow

26	Between blisters, machines #57 and 69	3/16/79	34.0	2.6		
27	Between blisters, machines #51 and 62	"	44.0	2.6		
28	At operators, machines #60 and 61	"	42.0	1.6		
29	At universal sliders	"	36.0	1.0		
30	At looms 4 and 21 machines #1026 and 1028, operator's position	3/17/79	43.5	3.6		
31	At looms 11 and 10, machines #1031 and 1028	"	34.0	1.6		Looms #10 not operating.
32	At looms 5, 7, 8 and 9, machines #601, 1022, 1023 and 1021	3/16/79	43.5	3.3		Looms #9 not operating! water sprays shut off! dry weaving.

7/16/79

Sample No.	Location of Sample	Date	Cu. Ft. Air Sampled	Total Count of millions of particles per cu. ft. air sampled	Type of Poll.	Remarks
Residue from vacuum tests.						
32	At looms #7 and 10	3/17/39	20.0	4.9		Temp in tented with analgesin.
33	At loom #7, machine #322	"	46.5	2.5		Set wire weaving.
34	Between #33 and 17 looms; machines #339 and #323.	3/14/39	44.0	1.1		Loom #19 - wire is treated with analgesin loom #33 not correcting.
35	Between #14, 26, 7 and 12 looms	3/17/39	63.0	4.7		July #12 loose correcting with wire pressing through after.
36	At inspection table	3/14/39	42.0	2.3		Inserting regular braided band lining, air-out over brush.
Leak analysis						
Sample No.	Location of Sample	Date	Cu. Ft. Air Sampled	Milligrams of lead per Cu. Meter	Lead Intake per 10-hr. day	Remarks
37A	At inspection table	3/17/39	42.0	0.145	1.45	
37B	At loom #24	3/14/39	44.0	0.126	1.26	

Lead analyses

Sample No.	Location of Sample	Date	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft.	Milligrams of Lead per Cu. Meter	Lead Intake per 10-hr. day	Remarks
Brake lining finishing dept.							
42	At calendering machine	3/21/39	33.6	1.7	0.053	0.95	
44	At sanding machine	"	34.6	2.6	0.102	1.52	
47	At drill press	3/22/39	37.4	5.3	0.074	0.74	
43	Machine shop - general air	3/21/39	43.5	1.5	0.07	0.7	
37	Isolation mixing dept.	3/21/39	17.0	2.4	INDUSTRY		

LEAD ANALYSES							
Sl. No.	Location of Sample	Date	Cu. Ft. Air Sampled	Millions of Particles per Cu. Ft.	Milligrams of Lead per Cu. Meter	Lead Intake per 10-hr. day	Remarks
50	Atlas Mach.				RELATIVE		
50	At Campbell cutter, machine #2321	1/22/39	24.0	4.3			
51	At Campbell clutch facing segment cutter, machine #1196	"	35.6	2.5	0.06	0.6	Exhaust appli to this opera tion.
52	Hand sanding tables	"	27.0	5.0	0.261	2.61	9 women now working as compared with 5 in 1938.
53	Dept. 999 - center of mandrels	"	31.0	2.2	0.07	0.7	
54	Frett and Whitely surface grinder, machine #2340	"	34.2	5.6	0.124	1.24	This machine exhausted.
57	At Gardner grinder #14, machine #1546	"	29.6	2.8	0.07	0.7	This machine exhausted; a times pieces being ground are too large for head and the operator then raises head, defeat the purpose.
58	At Blanchard grinders machines #1579 and 1673	"	27.3	9.3	0.459	4.59	
60	Between Gardner grinder #77 and #2 drill, machine #1598	"	42.0	3.1	0.233	2.33	The dust collector is located outside the department.
62	Drilling machine #2346 and 1654	"	48.0	1.8	0.089	0.89	This machine exhausted.
63	Segment grinding, machine #2257	"	42.0	2.8	0.304	3.04	This machine has been re oated and exhausted 1 1938 survey. Formerly sample #49
64	Latex sander, machine #783	"	40.8	2.9	0.138	1.38	This machi exhausted.

CONCLUSIONS AND RECOMMENDATIONS

The dust concentrations are comparable to those found in the 1938 survey.

Lead concentrations in general are lower. This may be due to increased efficiency of exhaust systems or the material being worked may have a lower lead content.

It is suggested that the present program of extending and improving exhaust equipment be continued.