

FILE NAME: General Electric (GE)

DATE: 1937-1973

DOC#: GE201

DOCUMENT DESCRIPTION: GE Documents - 37 [From PA Archive]

12-1-65

CONTROL MEASURE

Plastics Laboratory

Gloves & hand creams

Approved dust
respirators
USBM 2166
Occasional operation
(one weigh in two days
for 5 minutes).

PA STATE ARCHIVES
 Reproduction of an Original Record
 Please Check
 DATE OF REPRODUCTION

REGION IPROD. MFG. OR SERVICE
SwitchgearsDATE OF ACTIVITY 10-2-71FIELD ACTIVITY REPORT
(Occupational Health)

PLANT

General Electric Company

ADDRESS

4901 Elmwood Avenue Phila., PA

ZIP CODE

19142

TELEPHONE

215 344-1900

PERSON INTERVIEWED

William Tenney/Hood Piccin

TITLE

Safety Specialist/ Management of

EMPLOYEES

MALE

FEMALE

TOTAL 6000

INO. CODE

36

COUNTY

Phila.

PUNCH CARD

YES ☒NO ☐

FOLDER

YES ☒NO ☐

N.S.N.

YES ☐NO ☒

PURPOSE: INVEST.; SURVEY; INSP.; PRELIM.; P.A.; COMPL.; VISIT; OTHER

REASON: SELF-INIT.; P.O. REF.; COMPL.; REQUEST; SOURCE

SAMPLES COLLECTED

(NO. & KIND)

TOTAL

DETERM. MADE 5 noise (G.R. Octave Band Analyzer)

TOTAL 5

(NO. & KIND)

MEDICAL - G.D. REPORTED, NO. & KIND

RECOMMENDATIONS AND REMARKS

SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	RECOMMENDATIONS		ACCOMPLISHED		
		R 4-8-71	WRITTEN - VERBAL	YES	NO	IN PROG.
Noise	32	1. reduce noise levels at the flame treating operation, mill no. 5090 and polyester sawing operation				x
		2. provide properly fitted ear plugs or muffs		x		
		3. institute pre-placement and periodic audiometric tests		x		
Asbestos	33	1. LEV improvement				x
		2. LEV maintenance		x		

Remarks

Followed-up above recommendations. Two adjacent flame treating operations were the major source of noise in the arc chute milling dept. There were oxy-gas torches. One of these has been replaced with a plasma arc unit which is located in an acoustically enclosed room about 40' x 25' x 20'. The immediate arc area is itself acoustically enclosed and exhausted to wet collector. The work is placed on a sliding table which, when pushed in place forms a good enclosure. The nozzle of the plasma arc unit was modified to reduce noise levels. The unit is not in full production and is still undergoing modification. Although it was not in use during the visit, the unit was turned on so that noise levels could be measured. Work was not put in the unit. Following are noise levels:

☐ OVER

By: Beckett

WINS 1.5

RIN 22

RECEIVED
OCT 10 1971
DEPT. OF HEALTH
OCCUPATIONAL HEALTH
DIVISION OF AN ORIGINAL RECORD

File

REGION 1
PROD. MFG. OR SERVICE switchgear
DATE OF ACTIVITY 6/15/71FIELD ACTIVITY REPORT
(Occupational Health)

PLANT <u>General Electric Company</u>			
ADDRESS <u>6901 Elmwood Avenue, Philadelphia, Pennsylvania</u>		ZIP CODE <u>19142</u>	TELEPHONE <u>215 SA6-1500</u>
PERSON INTERVIEWED <u>Toohy, William</u>		TITLE <u>Safety Specialist</u>	
EMPLOYEES MALE <u>3600</u> FEMALE <u>0000</u> TOTAL <u>3600</u>		COUNTY <u>Philadelphia</u>	
PUNCH CARD	YES ☒ NO ☐	FOLDER	YES ☒ NO ☐ N.S.N. YES ☐ NO ☒

PURPOSE: INVEST.; SURVEY; INSP.; PRELIM.; P.U.; CONF.; VISIT; OTHER _____

REASON: SELF-INIT.; F.D. REP.; COMPL.; REQUEST; SOURCE _____

SAMPLES COLLECTED _____ TOTAL _____
(NO. & KIND)DETERM. MADE _____ TOTAL _____
(NO. & KIND)

MEDICAL - O.D. REPORTED, NO. & KIND _____

RECOMMENDATIONS AND REMARKS						
SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	4/8/71 R. RECOMMENDATIONS		ACCOMPLISHED		
		WRITTEN	VERBAL	YES	NO	IN PROG.

Noise	32	1. Reduce noise levels	see remarks
		2. Ear protection	
		3. Audiometric tests	
Asbestos	33	1. IEV improvement	11
		2. IEV maintenance	

Remarks

I. H. visited the Greenway Ave. plant to determine noise levels in the Custom Power and Equipment Department (see F. A. 6/15/71 in that folder). During the visit I. H. asked Mr. Toohy about compliance with the above recommendations for the arc chute molding and milling departments in the main plant. Toohy did not know the status of the control measures. He said an enclosure for the flame treating operation in the milling department was being designed and a ventilation system was almost completed for the molding department. He requested I. H. to return later to discuss these topics. Revisit in two to four weeks.

☐ OVER

by Mr. Beckett _____

DATE June

4-4-67

APR 13 8 1973

Attention: Mr. William Toohy
Safety Specialist

On November 30 and December 8, 1970 a survey was conducted in the arc chute molding and milling departments of your plant to evaluate employees' exposures to asbestos dust and noise. The survey was made with the cooperation of Mr. Toohay.

The threshold limit value for asbestos is 5 million particles per cubic foot of air based on exposure for an 8-hour working day. It should be noted that the American Conference of Governmental Industrial Hygienists has proposed an additional limit based on fiber count. This intended threshold limit value is 5 fibers per milliliter of air, greater than 5 microns in length, based on exposure for an 8-hour working day.

In keeping with good industrial hygiene practices and to maintain exposures as low as possible, the following recommendations are made:

1. State of New York
 2. County of _____
 3. Know all men
 4. That _____
 5. for and in consideration of the sum of _____ Dollars
 6. to _____ of and lawful interest
 7. the receipt of which is hereby acknowledged
 8. do hereby certify that _____
 9. is the true and correct copy of the _____
 10. as the same appears from the _____
 11. and the _____
 12. and the _____
 13. and the _____
 14. and the _____
 15. and the _____
 16. and the _____
 17. and the _____
 18. and the _____
 19. and the _____
 20. and the _____
 21. and the _____
 22. and the _____
 23. and the _____
 24. and the _____
 25. and the _____
 26. and the _____
 27. and the _____
 28. and the _____
 29. and the _____
 30. and the _____
 31. and the _____
 32. and the _____
 33. and the _____
 34. and the _____
 35. and the _____
 36. and the _____
 37. and the _____
 38. and the _____
 39. and the _____
 40. and the _____
 41. and the _____
 42. and the _____
 43. and the _____
 44. and the _____
 45. and the _____
 46. and the _____
 47. and the _____
 48. and the _____
 49. and the _____
 50. and the _____
 51. and the _____
 52. and the _____
 53. and the _____
 54. and the _____
 55. and the _____
 56. and the _____
 57. and the _____
 58. and the _____
 59. and the _____
 60. and the _____
 61. and the _____
 62. and the _____
 63. and the _____
 64. and the _____
 65. and the _____
 66. and the _____
 67. and the _____
 68. and the _____
 69. and the _____
 70. and the _____
 71. and the _____
 72. and the _____
 73. and the _____
 74. and the _____
 75. and the _____
 76. and the _____
 77. and the _____
 78. and the _____
 79. and the _____
 80. and the _____
 81. and the _____
 82. and the _____
 83. and the _____
 84. and the _____
 85. and the _____
 86. and the _____
 87. and the _____
 88. and the _____
 89. and the _____
 90. and the _____
 91. and the _____
 92. and the _____
 93. and the _____
 94. and the _____
 95. and the _____
 96. and the _____
 97. and the _____
 98. and the _____
 99. and the _____
 100. and the _____

4-18-71

April 8, 1971

1. Continue with your plans to improve the local exhaust ventilation system at the charging and weighing station.
2. Establish a maintenance program for the local exhaust ventilation systems in the arc chute molding and milling department. This program should include periodic inspection of the system for leaks.

Noise measurements were made with a General Radio Company sound level meter and the results are listed in Table 2.

Table 3 lists noise threshold limits adopted by the American Conference of Governmental Industrial Hygienists which are exposure limits that should protect the ability to hear and understand speech. These limits have also been made a part of the United States Department of Labor rules under the Walsh-Healey Public Contracts Act.

As shown in Table 3 the noise exposure limits have been exceeded at the flame treating operation and mill No. 5090. Noise exposures were in the vicinity of the threshold limit value at the other milling and sawing operations. In the compound areas, where polyester plastic is milled, noise exposures were less than the threshold limit value. It should be noted that exposures will vary as the frequency of operations varies. Because of our findings, the following recommendations are made:

1. Reduce noise levels at the flame treating operation, mill No. 5090 and the polyester plastic sawing operation. This may be accomplished by the following:
 - A. Institute a periodic maintenance program that includes replacement of worn gears and bearings and keeping attachments as tight as practical.
 - B. Install vibration mounts on machinery.
 - C. Attach vibration-damping material to structural members and panels.
 - D. Acoustically enclose equipment, either partially or totally.
2. Provide properly fitted ear plugs or muffs for personnel exposed to noise.
3. Institute a program of preplacement and periodic audiometric tests for all employees exposed to noise.

General Electric Company

-3-

April 8, 1971

Tables of dust concentrations, noise measurements and noise threshold limit values, our Hygienic Information Guides entitled "Asbestos", "Ventilation" and "Noise" and Article 412, as revised, are enclosed. An additional copy of our report is enclosed. Mr. George Jackson, steward, Local 119, requested a report of our findings.

Very truly yours,

Leon T. Genshor
Regional Industrial Hygienist

LTC/mjm

Enclosures

RECEIVED
APR 12 1971
U.S. DEPARTMENT OF
HEALTH, EDUCATION &
WELFARE
WASHINGTON, D.C.

Commonwealth of Pennsylvania
Department of Environmental Resources
OCCUPATIONAL HEALTH

Table 1

Dust Concentrations

General Electric Company
6901 Elmwood Avenue
Philadelphia, Pennsylvania 19142

Location	(fibers per milliliter of air)	Dust* (millions of particles per cubic foot of air)	Remarks
Arc chute molding department	0.2		Hydraulic press operators exposures, integrated over several hours
	0.1		
		0.02	General air, 7 feet from weighing station
		0.01	General air, 15 feet from weighing station
			Operator's exposure, charging hopper and weighing asbestos and zircon
		0.6	Operator's exposure, mixing zircon, asbestos and acid
		0.2	
		0.5	Operator's exposure, welding
		0.4	Operator's exposure, molding and filing mold
		0.3	Operator's exposure, mixing material and molding

REPRODUCTION OF AN ORIGINAL RECORD
PLEASE CLIP
76 JUL 11 1976
SEANCOV 11 11 76

Commonwealth of Pennsylvania
Department of Environmental Resources
OCCUPATIONAL HEALTH

Table 1. (continued)

Dust Concentrations

General Electric Company
6901 Elmwood Avenue
Philadelphia, Pennsylvania 19142

Location	Dust* (fibers per milliliter of air)	(millions of particles per cubic foot of air)	Remarks
		0.4 0.2	Operator's exposure, cleaning press
		0.1	Operator's exposure, filing mold and sweeping floor
		0.2	General air, no activity
Arc chute milling department	0.1	4.7 0.2	Operator's exposure, cut-off mill
	0.1	0.2 0.5	Operator's exposure, mill No. 5022
	0.2	1.8 1.2 0.6 0.3 0.3	Operator's exposure, mill No. 5043
	0.3	2.4 1.3 0.3 0.2	Operator's exposure, mill No. 5050

*Threshold limit value for asbestos dust, based on exposure for an 8-hour working day -
5 million particles per cubic foot of air

Proposed threshold limit value for asbestos fibers, based on exposure for an 8-hour working
day - 5 fibers per milliliter of air, greater than 5 microns in length

Stamp: 1974 JUN 10 10 10 AM
Stamp: 1974 JUN 10 10 10 AM

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
OCCUPATIONAL HEALTH

6218

PAGE 1 OF 1
REGION I
DATE COLLECTED 12/8/70
DATE SUBMITTED 12/10/70
DATE REC'D IN LAB 12/14/70

SAMPLE AND LABORATORY REPORT

NAME OF COMPANY

General Electric Co.

ADDRESS

6901 Elmwood Avenue
Philadelphia, Pa. 19142

PRODUCT MANUFACTURED OR SERVICE	MATERIAL SAMPLED	APPARATUS AND Suction SOURCE
Switch Gears	Air	Monitaires
COLLECTED BY	COLLECTION MEDIUM	*ANALYSIS DESIRED
Duckett & Senn	3Ac Membranes	Asbestos - Fibre Count
OTHER SUBSTANCES PRESENT		

COMMENTS

SAMPLE NUMBER	SAMPLING LOCATION AND OPERATION	AIR VOLUME m ³	LABORATORY RESULTS Asbestos fibers/ml
I-3551	O.E. Cut-off	0.225	0.13
I-3552	O.E. Milling - 5070	0.143	0.25
I-3553	O.E. Slotter	0.244	0.12
I-3554	O.E. Milling - 5043	0.086	0.16
I-3555	BLANK	---	N.D.*
I-3556	BLANK	---	N.D.*

REPORT OF ANALYSIS

*None Detected

Counted by phase-contrast microscopy
(fibers greater than 5 microns)

SEARCHED
INDEXED
SERIALIZED
FILED
DEC 15 1970
FBI - PHILADELPHIA

F. Bennett

12/16/70

ANALYST

DATE

CHEMIST

DATE RECEIVED 12/18/70

DATE ANALYZED 12/18/70

DATE SUBMITTED TO REGULATING AGENCY

JUN

COMMONWEALTH OF PENNSYLVANIA
 DEPARTMENT OF HEALTH
 OCCUPATIONAL HEALTH

6804

File

 PAGE 1 OF 1
 REGION I
 DATE COLLECTED 11-30-70
 DATE SUBMITTED 12-7-70
 DATE REC'D IN LAB. 12-6-70

SAMPLE AND LABORATORY REPORT

 NAME OF COMPANY
 General Electric Co.

 ADDRESS
 6901 Elmwood Avenue
 Philadelphia, Pa. 19142

 PRODUCT MANUFACTURED OR SERVICE
 Switch Gears

 MATERIAL SAMPLED
 Air

 APPARATUS AND SUCT'ON SOURCE
 Monitor - Gilmor - PAC

 COLLECTED BY
 Beckett & Liberi

 COLLECTION MEDIUM
 EAC Membranes

 ANALYSIS DESIRED
 Asbestos - Fibre Count

OTHER SUBSTANCES PRESENT

COMMENTS

SAMPLE NUMBER	SAMPLING LOCATION AND OPERATION	AIR VOLUME	LABORATORY RESULTS
		m ³	
I-3511	O.E. Hydraulic Press Op.	0.367	Asbestos fibers/ml 0.24
I-3512	O.E. " " "	0.307	0.10
I-3513	G.A. - 15 ft. from hopper	2.84	0.01
I-3514	G.A. - 7 ft. " "	1.05	0.02
I-3515	Blank	---	N.D.*
I-3516	Blank	---	N.D.*

REPORT OF ANALYSIS

*None Detected

 Counted by phase-contrast microscopy
 (Fibers greater than 5 microns)

 SEANOV
 12/11/70
 12/11/70

ANALYST F. Bennett

DATE 12/10/70

CHEMIST

DATE REC'D 12/11/70

DATE TYPED 12/14/70

DATE SUBMITTED TO REQUESTING AGENCY

J. L. H.

REGION IPROD. MFG. OR SERVICE
SWITCH BOARDDATE OF ACTIVITY 6/8/70 - 9/4/70

FIELD ACTIVITY REPORT

PLANT General Electric Company		ZIP 19142	PHONE 215 34-1500
ADDRESS 6901 Elmwood Avenue, Phila.		TITLE Safety Specialist Plant M.E.	
PERSON INTERVIEWED Mr. Toohy A.A. Cashmere (letter) 6/8/70			
EMPLOYEES	MALE	FEMALE	TOTAL
			6000
			3600
			Phila.

PURPOSE: INVENT.; SURVEY; INSPECT.; PRELIM.; E.L.; CONF.; VISIT;

REASON: SELF-INIT.; O.S. REP.; COMPL.; REQUEST; SOURCE

SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	RECOMMENDATIONS		ACCOMPLISHED		
		WRITTEN	VERBAL	YES	NO	IN PROG.
AS	3	(see remarks)				

SAMPLES COLLECTED 4 bulk dust
(NO. & KIND)TOTAL YDETERM. MADE
(NO. & KIND)

TOTAL

MEDICAL - O.S. REPORTED, NO. & KIND

PUNCH CARD

YES

☒

NO

☐

FOLDER

YES

☒

NO

☐

REMARKS:

AL forms dated 6/4/70 received on 6/8/70. Unprocessed applications among unfinished work of J.S. reassigned on ~~reassignment~~ *reassigned*.

Called A. Cashmere of G.E. on 8/20/70 requesting additional information on filter and polishing components. This was received on 9/2/70. It was felt advisable to obtain samples from the dust collector and visit will be made for this purpose.

Addendum - 9/4/70

J.H. visited plant to obtain bulk samples from the collector, after filters and of the compounds used. J.H. also observed the system and determined approximate percentages of each polishing compound used. Comments on the AR system will be delayed until receipt of lab analysis of bulk samples for free silica. Mr. Johnson also showed to J.H. an area where asbestos fibre board is manufactured. He said he has received approval to design a ventilation system for this area. All ventilation will be exhausted to the outside. A visit will be made in 6-8 weeks to determine progress on the design. Manufacturer's bulletin containing performance charts on the Roto-Clone is in the folder. See company letter from Mr. Johnson to Regional office for additional data on the AR unit. Polishing compounds are in use for about 10% of the work. Of this 10%, the percentages of the 4 compounds comprise the following: "XXX White Diamond 2 to 3%; White and red jewelers range - 2 to 3%; Emery paste - 1%; Tripoli - 3 to 5%."

by William Beckett
J. L. H.WHS 1.5

0000000000

ARCHIVES

606 West Second Street

Erie, Pa. 16507

OCCUPATIONAL HEALTH

APPLICATION FOR APPROVAL OF AIR RECIRCULATION SYSTEM

EACH SYSTEM REQUIRES
SEPARATE APPLICATIONTTC-5
10/23/72

PLANT NAME General Electric, TTC	ADDRESS 2901 East Lake Road
CITY AND ZIP CODE Erie, Pennsylvania 16501	COUNTY Erie
CONTAMINANTS COLLECTED Dust from miscellaneous sanding operations on wood, metal, asbestos, or plastic parts.	LOCATION OF AIR RECIRCULATION SYSTEM (DEPARTMENT, BUILDING, ROOM, ETC.) M & P Laboratory, Building 14-1 Room 140-A
LIST OPERATIONS EXHAUST VENTILATED TO COLLECTOR AND ALL MATERIALS USED IN THESE OPERATIONS	
OPERATIONS 10 inch belt sander Miscellaneous Sanding Operations	MATERIALS USED IN OPERATION (Amount Used Per Month Or Year) (Specify Inappropriate) Wood, plastics, or metals

AIR RECIRCULATION SYSTEM INFORMATION

MANUFACTURER OF COLLECTOR Torit	MODEL NUMBER 54	COLLECTOR EFFICIENCY DATA Not available
TYPE COLLECTOR (Electro, Cyclonic, Filter, Precip, Wet, etc.) Cloth		
AIR VOLUME RATE OF SYSTEM 150 CFM	DAILY OPERATION TIME < 1 hour	
DIMENSIONS OF ROOM TO WHICH AIR IS RECIRCULATED		
LENGTH 15 FT.		
WIDTH 15 FT.		
HEIGHT 12 FT.		
NUMBER OF EMPLOYEE IN THE AREA	FULL TIME 0 PART TIME 1	
QUANTITY OF MAKE-UP AIR SUPPLIED TO AREA CFM		
LIST SPECIFIC REASONS WHY SYSTEM CANNOT BE EXHAUSTED TO THE OUTSIDE		
SOURCE OF MAKE-UP AIR Room connected permanently to other rooms by two unobstructed doorframes		
OTHER EXHAUST VENTILATION SYSTEMS IN THE AREA (SEEK SIDE)		

TITLE Manager SIGNATURE *[Signature]* PHONE 453-5468

SUBMITTED FOR DEPARTMENTAL USE ONLY			☐ REVIEW REPORT AND RECOMMENDATIONS ON REVERSE SIDE	
APPLICATION NO.			☐ APPROVED ☒ DISAPPROVED	
RECEIVED	DATE REC'D	BY	☐ APPROVED RECOMMENDATION	
COMMITTEE	DATE REC'D	BY		
REGION	DATE REC'D	BY		
PLANT NOTIFIED	BATCH NOTIFIED	BY		

(USE REVERSE SIDE FOR ADDITIONAL COMMENTS)

ERIE COUNTY DEPARTMENT OF HEALTH

File

OCCUPATIONAL HEALTH

FIELD ACTIVITY REPORT

(Occupational Health)

REGION VI
PROD. MFG. OR SERVICE
Transportation Equip.
DATE OF ACTIVITY 3/5/73

PLANT

General Electric Company

ADDRESS

2901 East Lake Road

PERSON INTERVIEWED

Hugh McBea

EMPLOYEES

MALE

FEMALE

TOTAL 10,500

INS. CODE

36

COUNTY

25

ZIP CODE

16511

TELEPHONE

455-3466

TITLE

Admin. Mgr. - OSHA

PUNCH CARD

YES ☐

NO ☒

FOLDER

YES ☒

NO ☐

N.S.N.

YES ☒

NO ☐

PURPOSE: INVEST.; SURVEY; INSP.; PRELIM.; F.O.; CONF.; VISIT; OTHER _____

REASON: SELF-INIT.; R.D. REPT. COMPL.; REQUEST; SOURCE _____

SAMPLES COLLECTED N/A

TOTAL _____

(NO. & KIND)

DETERM. MADE N/A

TOTAL _____

(NO. & KIND)

MEDICAL - G.D. REPORTED, NO. & KIND N/A

RECOMMENDATIONS AND REMARKS

SPECIFIC HAZARD
OR CONDITION

WORKERS
EXPOSED

RECOMMENDATIONS

WRITTEN -- VERBAL

ACCOMPLISHED

YES

NO

IN PROG.

McBea requested staff sit in on meeting of management to discuss engineering controls for asbestos exposures in building 24.

All asbestos operations to be moved to one area of building 24, and LEV provided to each operation.

LEV will enter collector - cyclone and bag house outside building.

RECEIVED
0600071111
SEALING
3000000000
0000000000

BY Vogel WINS 2.0
RTH _____

☐ OVER

February 22, 1972

General Electric Company
2901 East Lake Road
Erie, Pennsylvania 16501

Attention: Mr. Hugh McDon, Jr.
Administrative Mgr. - OSHA

Gentlemen:

This is to acknowledge receipt of your applications for approval of
air-recirculation systems A-38 through A-43.

Your applications will be reviewed and you will be notified of our
decision.

Your cooperation in this matter is appreciated.

Henry J. Gurovics, Director
Division of Occupational Health

RJS/jw

0502001/10

SEARCHED

RECEIVED
FEB 23 1972
DIVISION OF OCCUPATIONAL HEALTH

RECEIVED

FEB 23 1972

ERIE COUNTY DEPARTMENT OF HEALTH

OCCUPATIONAL HEALTH

FIELD ACTIVITY REPORT
(Occupational Health)REGION VI
PROD. MFG. OR SERVICE
Transportation Equipment
DATE OF ACTIVITY 1/19/73

PLANT

General Electric Corporation
ADDRESS2901 East Lake Road

PERSON INTERVIEWED

John Smith & Ed Laidlaw

EMPLOYERS

ZIP CODE

16511

TELEPHONE

255-5166

TITLE

Chemists

IND. CODE

36

COUNTY

25

MALE

FEMALE

TOTAL 10,500

PUNCH CARD

YES ☐NO ☒

FOLDER

YES ☒NO ☐

N.S.N.

YES ☒NO ☐

PURPOSE: INVEST.; SURVEY; INSP.; PRELIM.; F.U.; CONF.; VISIT; OTHER

REASON: SELF-INIT.; P.D. REPT. COMPL.; REQUEST; SOURCE John SmithSAMPLES COLLECTED N/A

TOTAL

(NO. & KIND)

OETERM. MADE N/A

TOTAL

(NO. & KIND)

MEDICAL - C.D. REPORTED, NO. & KIND N/A

RECOMMENDATIONS AND REMARKS

SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	RECOMMENDATIONS		ACCOMPLISHED		
		WRITTEN --- VERBAL		YES	NO	IN PROG.

John Smith was told to survey G. E. Foundry to evaluate employees exposure to contaminants adversely affecting workers.

John Smith wanted to know what to sample for and how to collect the contaminant.

Discussed potential problems discovered in the foundry during inspection of 1/8/73.

Also discussed the sampling procedures for silica, copper oxide, lead oxide, and zinc oxide, plus carbon monoxide, iron oxide and make-up air conditions.

Smith felt they had the capabilities to analyze samples using their A. A. Unit.

Also discussed who, how long, and where samples should be taken to provide a reliable indicator of workers exposure.

Mr. Smith & Mr. Laidlaw felt they had enough information to begin setting up a sampling program.

SEARCHED
SERIALIZED
INDEXED
FILED
JAN 24 1973
FBI - ERIE
RECEIVED
JAN 24 1973
FBI - ERIEby Surovica & VogelWINS. 2.0☐ OVER

ERIE COUNTY DEPARTMENT OF HEALTH

OCCUPATIONAL HEALTH

FIELD ACTIVITY REPORT

(Occupational Health)

REGION VI
PROD. MFG. OR SERVICE
Transportation Equip.
DATE OF ACTIVITY 1/8/73

PLANT

General Electric Company

ADDRESS

2901 East Lake Road

ZIP CODE

16511

TELEPHONE

455-5466

PERSON INTERVIEWED

Hugh McSee

TITLE

Admin. Mgr. - OSHA

EMPLOYEES

MALE

FEMALE

TOTAL

242

ING. CODE

36

COUNTY

25

PUNCH CARD

YES ☐

NO ☒

FOLDER

YES ☒

NO ☐

N.S.N.

YES ☒

NO ☐

PURPOSE: INVEST.; SURVEY; INSP.; PRELIM.; F.U.; CONF.; VISIT; OTHER _____

REASON: SELF-INIT.; P.O. REP.; COMPL.; REQUEST; SOURCE _____

SAMPLES COLLECTED _____

TOTAL _____

IND. & KIND _____

DETERM. MADE _____

TOTAL _____

IND. & KIND _____

MEDICAL - O.D. REPORTED, NO. & KIND _____

RECOMMENDATIONS AND REMARKS

SPECIFIC HAZARD
OR CONDITION

WORKERS
EXPOSED

RECOMMENDATIONS
WRITTEN - - - - - VERBAL - - - - -

ACCOMPLISHED

YES

NO

IN PROG

Foundry division was inspected.

Spot checks for noise showed levels possibly in excess of limit. Tremendous exhaust ventilation system throughout foundry.

No make-up air - negative pressure throughout exhaust system ineffective. John Smith to check copper, lead, zinc oxide and silica throughout foundry.

Follow up activity planned to determine possible Be exposure.

Attached control recommendations for cyanide the result of discovering several areas throughout plant that used acids and cyanides but had no emergency equipment or procedure.

RECEIVED
JAN 11 1973
Erie County Department of Health
Occupational Health Section

by Vogel, Chmielewski

WHS 3.8

☐ OVER

RH _____

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
OCCUPATIONAL HEALTH

FILE
PAGE 1 OF 1
REGION VI
DATE COLLECTED 10/1/72
DATE SUBMITTED
DATE REC'D IN LAB 11/9/72

APP ELEMENT 3601

SAMPLE AND LABORATORY REPORT

COMPANY (Name)

General Electric Co.

(Address)

2901 East Lake Road

Erie, Penna. 16511

PRODUCT MANUFACTURED OR SERVICE

Booster equipment

MATERIAL SAMPLED

Asbestos

APPARATUS AND SUCTION SOURCE

MSL

COLLECTED BY

Joseph J. Vogel

COLLECTION MEDIUM

membrane filter

ANALYSIS DESIRED

Asbestos

OTHER SUBSTANCES PRESENT

COMMENTS

SAMPLE NUMBER	SAMPLING LOCATION AND OPERATION	AIR VOL.	LABORATORY RESULTS
6-2509	operator's exposure		
6-1954	Harrier drill - South end of workshop	156.20	0.55
6-2510	operator's exposure		
6-1955	Rip sawing - North end of workshop	153.20	0.92
6-2511	Blank		
6-1956	Blank - South end of workshop	162.50	0.61
6-2512	operator's exposure		
6-1957	Harrier drill - South end of workshop	132.30	0.53
6-2513	operator's exposure		
6-1958	Rip sawing - North end of workshop	117.56	0.94
6-2514	Blank		
6-1959	Blank - North end of workshop	132.77	0.28
6-2515	Blank		
6-1960	Blank		
6-2516	Blank		
6-1961	Blank		

REPORT OF ANALYSIS

Note: Sample numbers changed at direction of Production - 1/3/73

* From 10/1/72

Exceeded 1st Phase - estimate was 0.55
also 7.5 microns

ANALYSIS TIME

DATE FINISHED

DATE RECEIVED

ANALYSIS BY

CHIEF, LABORATORY SECTION

DATE TYPED

DATE MAILED

OFFICE OF THE DIRECTOR
JUL 7 1971
BUREAU OF HUNTING &
ENVIRONMENTAL CONTROL

The undersigned employees of Building 63 at the General Electric Company in Erie, Pa. are entering a complaint against working conditions.

We have complained to the management several times, but the conditions still exist.

COPIES

George B. Little
George J. Hinckley
John W. Brown
John G. Brown
John G. Brown
John G. Brown
John G. Brown
John G. Brown

[illegible]

Wm. L. L. L.
George M. L.
Rosen M. L.
Tom Sawyer
Charles R. S. L.
Michael D. B. L.
J. L. L.
Gene T. L.
Bob Adams
Lionel L. L.
Lionel L. L.
Lionel L. L.
Lionel L. L.
Lionel L. L.
Lionel L. L.

RECEIVED
AUG 20 1971
FEDERAL BUREAU OF INVESTIGATION
U. S. DEPARTMENT OF JUSTICE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
OCCUPATIONAL HEALTH

EACH SYSTEM REQUIRES
SEPARATE APPLICATION

APPLICATION FOR APPROVAL OF AIR RECIRCULATION SYSTEM

DATE Feb. 27 '67

PLANT NAME General Electric Apparatus Service Shop ADDRESS 4930 Bittersilk Hollow Rd., West Mifflin, Pa.
CITY AND ZIP CODE West Mifflin, Pa. 15122 COUNTY Allegheny

CONTAMINANTS COLLECTED Saw Dust LOCATION OF AIR RECIRCULATION SYSTEM Coil Department
(DEPARTMENT, BUILDING, ROOM, ETC.)

LIST OPERATIONS EXHAUST VENTILATED TO COLLECTOR AND ALL MATERIALS USED IN THESE OPERATIONS
OPERATIONS Table Saw Wood, Textolite,
Boill Saw Glass Melamine, Oiled Asbestos
Belt Sander Paper

AIR RECIRCULATION SYSTEM INFORMATION

MANUFACTURER OF COLLECTOR Aget Manufacturing Co. COLLECTOR EFFICIENCY DATA _____
MODEL NUMBER DB-2 TYPE COLLECTOR Recirculating
AIR VOLUME RATE OF SYSTEM 900 CFM DAILY OPERATION TIME 2 HR.
MAINTENANCE PROGRAM (DESCRIBE) Weekly check to clean and empty unless usage greater than normal.
DESCRIPTION OF AREA TO WHICH AIR IS RECIRCULATED
LENGTH 300 FT.
WIDTH 220 FT.
HEIGHT 24 FT.
NUMBER OF EMPLOYEES IN THE AREA FULL TIME 100 PART TIME _____
SOURCE OF MAKE-UP AIR Gas-Fired space and unit heaters
QUANTITY OF MAKE-UP AIR SUPPLIED TO AREA 126,000 CFM
OTHER EXHAUST VENTILATION SYSTEMS IN THE AREA (DESCRIBE) 2- Power Roof Ventilators, 5800 CFM each
LIST SPECIFIC REASONS WHY SYSTEM CANNOT BE EXHAUSTED TO THE OUTSIDE Keep portable for layout flexibility

TITLE Mfg. Eng. SIGNATURE [Signature] PHONE 462-7150 EXTENSION NUMBER 12

FOR DEPARTMENTAL USE ONLY				REGION REPORT AND RECOMMENDATIONS ON REVERSE SIDE	
REGION	DATE REC'D	BY		☐ APPROVED ☐ DISAPPROVED ☒ APPROVED (CONDITIONAL) CONDITIONS: <u>See enclosure</u>	
COMMITTEE	DATE REC'D	BY			
REG-24	DATE REC'D	BY			
PLANT NOTIFIED	DATE NOTIFIED	BY			

USE REVERSE SIDE FOR ADDITIONAL COMMENTS

Air Recirculation

Re: General Electric Company - Apparatus Service

Points:

1. The use is very occasional.
2. The mention is made about oiled asbestos paper being used. I telephoned the company. This was used on one particular job and is not a normal operation at this machine or any where else in the plant. They had to produce blocks to be used as fillers.
3. The area is large.

OK 3/12/67
OK 3/12/67
OK 3/12/67 - no asbestos

Atkins 3/14/67

SEARCHED
SERIALIZED
INDEXED
FILED
MAR 15 1967
FBI - NEW YORK

INVESTIGATION OF HAZARD OF ASBESTOS DUST

GENERAL ELECTRIC CO.

YORK WIRE WORKS

York, Pennsylvania.

July 14, 1937

Allen E. Dooley.

Julia L. Matthews.

08000717

SEAINC 2 20 1937

RECORDS SECTION

Investigation of Asbestos Dust Hazard

General Electric Co.

York, Penna.

Reason for Investigation.

The management of the York Wire Works of the General Electric Company requested the Division of Industrial Hygiene to determine the degree of hazard caused by the use of asbestos in the plant. Installation of an exhaust system had been contemplated to remove dust produced in the braiding operation but a question had arisen concerning whether or not the degree of hazard was sufficient to warrant the proposed installation.

Collection of the Samples.

Samples for the determination of the concentration of asbestos dust were collected by means of the modified form of the impinger dust sampling apparatus⁽¹⁾. Ninety-five per cent. ethyl alcohol, U. S. P., was used as the collecting medium. The use of alcohol eliminated any clumping of the asbestos particles, a condition which does occur if distilled water is used. The rate of sampling was one cubic foot per minute. All samples were collected in the breathing zone of the workers. Samples were counted within twenty-four hours after collection. A total of fourteen samples were collected at various locations in the plant.

Results.

1. Braiding Department.

There are 23 asbestos braidere in this department, arranged in two rows with an aisle for the operators between the two rows. At the time

(1). Faish, T., Warren, H., and Briker, P.: Modified Form of the Greenburg-Smith Impinger for Field Use, with a Study of its Operating Characteristics. Jour. Ind. Hyg., Vol. 14, No. 8, October, 1932.

of the investigation a 10-cut yarn was being used on all machines. A total of six samples were collected in the braiding department. The results expressed in particles per cubic foot of air are shown in Table 1.

Table 1.

Sample No.	Location of Sample	Time Started	Cu. ft. Sampled	Particles per cubic foot of air	Date Sampled
1	#22 braider	11:30 A.M.	24.5	502,857	8-29-37
2	do.	1:18 P.M.	30	532,000	do.
3	#3-4 braiders	1:52 P.M.	29	464,827	do.
4	do.	2:54 P.M.	30	504,000	do.
5	#7-8 braiders	10:48 A.M.	30	382,648	8-30-37
6	do.	11:14 A.M.	30	236,000	do.

The average concentration in the braiding department represented by six samples is 470,391 particles per cubic foot of air.

3. Experimental hood on # 24 Braider

The # 24 braider has been equipped with a hood in an attempt to remove the asbestos lint or "fly" which collects on the braiders during operation. ^{The experiment} They asked that dust counts be made on this braider in order to determine, if possible, the effectiveness of the exhaust ventilation. Accordingly, during the lunch period when all the other braiders were not operating two samples were collected with the # 24 braider operating. One sample was collected while the exhaust ventilation was shut off and the second one was collected at the same location with the exhaust ventilation turned on. The results are indicated in Table 2.

Table 2.

Sample No.	Time Started	Cu. ft. sampled	Particles per cubic foot of air	Conditions of ventilation	Date Sampled
7	11:37 A.M.	23	601,732	Off	8-30-37
8	12:07 P.M.	26	264,300	On	do.

3. Asbestos Dust Collector.

The management was interested to know the concentration of asbestos dust produced during the daily cleaning of the asbestos dust collector. This work is done during the lunch hour by an employee who sweeps and brushes all asbestos lint and dust from the room into which the asbestos exhaust from the "K" and "M" machines is discharged. The employee wears a respirator while performing this work. The operation requires approximately forty-five minutes per day. One sample was collected and the results shown in Table 3.

Table 3.

Sample No.	Location	Time Started	Cu. ft. Sampled	ft. Particles per cubic foot of air	Date Sampled
11	Dust collector	12:01	14	218,514,283	7-7-37

4. "K" Machines.

Each "K" machine has a small asbestos card which is used to apply a covering of asbestos to the wire prior to application of the halonax. Five samples were collected in the workers breathing zones on a group of these machines in order to determine the concentration of asbestos dust to which the operators were exposed. Results are shown in Table 4.

Table 4.

Sample No.	Location	Time Started	Cu. ft. Sampled	ft. Particles per cubic foot of air	Date Sampled	Remarks
9	12-13	10:54 A.M.	25	748,086	7-7-37	Door closed
10	do.	11:01 A.M.	30	163,733	do.	do.
12	21	1:49 P.M.	30	836,400	do.	
13	1-2-3-4	11:23 A.M.	15	1,928,800	7-13-37	Door opened
14	do.	1:11 P.M.	30	1,172,000	do.	do.

STAMP

NOTE.

July 14, 1957

RECEIVED
JUL 15 1957
U.S. AIR FORCE
HEADQUARTERS
WASHINGTON, D.C.

Conclusions.

The results of this investigation indicate that the concentrations of asbestos dust at the operations enumerated, with the exception of the work of cleaning the asbestos dust collector, are well below the maximum safe concentration of asbestos dust in air. Studies up to the present time indicate that the maximum safe concentration for asbestos dust lies somewhere between five and ten millions of particles per cubic foot of air.

The installation of exhaust ventilation equipment on the asbestos breakers is unnecessary from an industrial hygiene viewpoint in light of the results obtained in this study.

Recommendations.

ELD Commonwealth Bldg.,

May 11, 1937

General Electric Co.,
York Wire Works,
453 S. Albemarle St.,
York, Pa.

Att: Mr. F. R. Kaimor.

Gentlemen:

There will be a little delay in our survey to determine the dust concentrations in the asbestos braiding department of your plant. This delay is due to the fact that our purchase of tax-free ethyl alcohol, which must be used in the determinations, has been held up pending approval of storage facilities by the Bureau of Internal Revenue.

That approval will be issued shortly and just as soon as alcohol is procured, we will commence the study.

We regret this delay, but, as I explained to Mr. Kaimor on my recent visit, rather anticipated it because of the numerous channels through which such a request must travel before final approval.

Yours very truly

Allen E. Dooley, Chemist,
Industrial Hygiene Division.

RECORDED
INDEXED
MAY 11 1937
U.S. DEPT. OF HEALTH
INDUSTRIAL HYGIENE DIVISION

COPY

GENERAL ELECTRIC

York Wire Works
453 S. Albemarle St.
York, Pennsylvania

Department of Industrial Hygiene
Bureau of Industrial Standards
Harrisburg, Pa.

Gentlemen:

We have recently installed, at our York plant, new equipment for the braiding of asbestos yarn in the manufacture of asbestos insulated wires and cable. This equipment, as supplied by its manufacturer, does not incorporate provisions for exhausting the dust and particles of asbestos fiber which emanate from this operation. We have had under consideration quite recently, the problem of adequately ventilating the area surrounding each braiding machine, in order to remove the suspended particles. However, some question has arisen concerning whether or not the degree of hazard caused by these machines would be sufficient to warrant complete exhausting.

In view of our interest in this problem, we would request and appreciate your consideration of conducting a survey for us, with proper instruments of precision in order to determine by such tests the advisability of carrying out the proposed installation.

As you are already familiar with our plant conditions as a result of former surveys at which the solvent vapors were primarily considered, we would appreciate your further cooperation and advice in the immediate problem we have under consideration.

s/ F. E. Kaiser.

SEARCHED 1960 Va

INDEXED 1960 Va

December 29, 1939

Mr. Franklin Keesey
President
York County Industrial Union
Council of the C. I. O.
York, Pennsylvania

Dear Mr. Keesey:

Your letter dated December 12, 1939, requesting information concerning the harmful effects of inhalation of asbestos dust, and information concerning chloronaphthalene and chlorodiphenyls has been referred to this Division for reply.

In recent years the Public Health Service has been studying the possible harmful effects of chlorinated diphenyls. The study has not been completed for publication. However, a similar study has been completed and reported by Dr. Cecil K. Drinker, Department of Physiology, Harvard School of Public Health, Boston, Massachusetts. This article, entitled "The Problem of Possible Systemic Effects From Certain Chlorinated Hydrocarbons", appeared on page 283 of the Journal of Industrial Hygiene and Toxicology in the September issue, 1937. A copy of this article may be obtainable through your public library.

Other references of interest on this subject are:

1. A preliminary report of the dermatological and systemic effects of exposure to hexachloronaphthalene and chlorodiphenyl. W. E. Fulton and J. L. Mathews. Special Bulletin No. 43, Pennsylvania Department of Labor and Industry, Harrisburg, Pennsylvania.
2. Safe Practice Bulletin No. 21 entitled "Insulation of Wire With Synthetic Wax (Chloro Compounds)." Department of Labor and Industry, Harrisburg, Pennsylvania.
3. Flinn, F. B., and Jarvik, H. M.: Proceedings of the Society for Experimental Biology and Medicine, 34, 118 (1936).
4. The halogenated hydrocarbons, their toxicity and potential dangers. W. F. von Oettingen, Journal of Industrial Hygiene, 19, 349, October 1937.

December 29, 1939

Mr. Franklin Keesey
President
York County Industrial Union
Council of the C. I. O.
York, Pennsylvania

Dear Mr. Keesey:

Your letter dated December 12, 1939, requesting information concerning the harmful effects of inhalation of asbestos dust, and information concerning chloronaphthalene and chlorodiphenyls has been referred to this Division for reply.

In recent years the Public Health Service has been studying the possible harmful effects of chlorinated diphenyls. The study has not been completed for publication. However, a similar study has been completed and reported by Dr. Cecil L. Drinker, Department of Physiology, Harvard School of Public Health, Boston, Massachusetts. This article, entitled "The Problem of Possible Systemic Effects From Certain Chlorinated Hydrocarbons", appeared on page 283 of the Journal of Industrial Hygiene and Toxicology in the September issue, 1937. A copy of this article may be obtainable through your public library.

Other references of interest on this subject are:

1. A preliminary report of the dermatological and systemic effects of exposure to hexachloronaphthalene and chlorodiphenyls. W. B. Fulton and J. L. Mathews. Special Bulletin No. 43, Pennsylvania Department of Labor and Industry, Harrisburg, Pennsylvania.
2. Safe Practice Bulletin No. 21 entitled "Insulation of Wire With Synthetic Wax (Chloro Compounds)". Department of Labor and Industry, Harrisburg, Pennsylvania.
3. Fliin, F. B., and Jarvik, H. E.: Proceedings of the Society for Experimental Biology and Medicine, 35, 118 (1936).
4. The halogenated hydrocarbons, their toxicity and potential dangers. F. F. von Oettingen, Journal of Industrial Hygiene, 19, 347, October 1937.

Mr. Franklin Keesey

- 2 -

December 29, 1939

5. Toxicity of Halowax and chlorinated naphthalene. *Journal American Medical Association*, 1927, 1386, October 23, 1927.

This Division has recently reported a study of the effects of asbestos dust upon the health of workers in the textile industry. I am sending a copy of this report under separate cover.

With regard to your request for the services of a federal chemist or pathologist, I regret to advise that we are not prepared at this time for this work. Furthermore, this work is within the province of the State officers. It is suggested that you communicate with Dr. William H. Fulton, Director of the Division of Industrial Hygiene, State Department of Health, Harrisburg, Pennsylvania, as his department is engaged in this type of work.

If this Division can be of any further assistance in any way, we shall be glad to hear from you again.

Very truly yours,

H. H. Sayre, Senior Surgeon
Chief, Division of Industrial Hygiene
National Institute of Health

CC: Dr. Fulton
HBF/BB

July 9, 1963

Inspection of General Electric Company
Valley Forge Space Technology Center

Leon T. Gonahor
Regional Industrial Hygienist
Region VII

Through: Chief
Industrial Hygiene Section

F. G. Rantos
Industrial Hygienist III
Division of Occupational Health

Attached is the eleventh installment of the above inspection.

FOR:hl

Attachment

OPERATION

HAZARD

CONTROL

M - 9425

SPACE STRUCTURES LABORATORY

Nondestructive structural testing of epoxy resin, Fiberglass or plastic granular filled composites. A hydraulic Materials Testing System, Servo-Hydraulic Load Frame (100,000 lbs. pressure) is used for this purpose.

Potting of miniature
electronic components

Methyl anhydride
Resorcinol diglycidylether
A-Aminopropyltriethoxy silane
EDMA

General ventilation
Disposable protective
gloves
Hand creams

Epon Resin #826
Shell Chemical Co.
New York, N. Y.
Mold Release #225
Ran Chemicals, Inc.
P. O. Box 192
Cardena, California

Tetrahydrofurane
Dermatitis

Sealing and
mold casting
electric
160° F.

Rabbitt metal fumes
Carrotru metal fumes

Exhaust hood
Occasional and inter-
mittent operation

Ball mill and
Manual asbestos grinding

Crocidolite asbestos dust

General ventilation
Enclosed unit
Wet operation
Small quantity
Intermittent and
occasional exposure

Recommendation: Improve housekeeping at the epoxy resin mixing area. Potting operations should be conducted under the exhaust hood where possible.

The manual grinding of asbestos should be conducted within the exhaust hood.

BUILDING - 1 (OC & F)

Radiation Laboratory

The degradation of electronic equipment parts as a result of neutron bombardment is studied. Electronic equipment and parts are placed within reactors elsewhere (Nevada), irradiated and shipped radioactive to the laboratory where they are disassembled and studied.

The Radiation Laboratory is divided into two areas: Electronic Components and Sensor Development.

996 South Main Street
 Meadville, Pennsylvania
 March 23, 1965

General Electric Surveys
 Erie

to F. G. Rentos
 Industrial Hygienist III

from J. A. Fierro *John Fierro*
 Industrial Hygienist
 Region III

Thru: Regional Industrial Hygienist

Below is a list of the surveys planned for General Electric. The areas marked with a (*) have already been surveyed.

Carbon Monoxide	Building 2	Motor Barrel & Magnetic Section
	Building 6	Commutator Assembly Area
	Building 13	Core Assembly Area, Bay-B
Noise	Building 5	Engine Cab Area
	Building 6	Commutator Assembly Area Sec. 64647
	*Building 6	Armature Spin Test
	*Building 10E	Control Test & Development
	Building 13	Core Assembly Area Bay-B
	Building 17	Armature Coil Area
	Building 26	Motor Test & Development
	Building 64	Aerospace Section Bay-C
	Building 64	Aerospace Section Generator Test Area
Iron Oxide Fumes	Building 5	Welded Components
Asbestos	Building 6	Mixing Incubation Pastes
O-chlorobenzene	Building 18	Bay-E
Beryllium & Copper	Building 64	Aerospace Section Bay-A
Copper (Oxide- Oxides of Nitrogen)	*Building 6	Generator Armature Test Spin Area
Lead	*Building 6	Generator Armature Test Spin Area

JAF:sah

REGION		COUNTY	PLANT NAME	ALPHABETIC						
COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF HEALTH			PLANT INFORMATION RECORD							
#12 DIVISION OF OCCUPATIONAL HEALTH			STOCK No. 5262.1							
PLANT	General Electric Corporation General Plant Foundry Division, Building # 22									
ADDRESS	2901 East Lake Road Erie, Pennsylvania,									
PRODUCT OR SERVICE	Brass, beryllium, copper, aluminum copper, malleable iron and steel and aluminum castings									
PERSON RESPONSIBLE	Carl Gorny, Employee Relations and Safety Director									
PHYSICIAN	R. B. Mutter, M.D.									
DENTIST	None									
NURSE	*Alice Manning, R.N.									
SAFETY SUPERVISOR	Carl Gorny									
INDUSTRIAL HYGIENIST	A. J. DeSorbo, Schenectady, N.Y.									
INSURANCE CARRIER	Electrical Mutual Insurance Company									
LEGAL OWNER	Corporation									
RECOMMENDATIONS	Ear plugs should be worn at all high-level noise operations.									
REMARKS	*Staff of five nurses. Employees receive annual chest X-ray. Dust survey conducted annually by G.E. industrial hygiene facilities. Surveyed for radiation 6/17/58; dust, metallic oxide fumes and carbon monoxide 9/15/59. The following alloys of copper, aluminum and beryllium are handled occasionally: <table border="0"> <tr> <td>Brass</td> <td>Aluminum, beryllium alloy</td> </tr> <tr> <td>Bil G25H, Be .45 - .75 per cent</td> <td>1 ounce of Be per 100 lbs of new metal (aluminum)</td> </tr> <tr> <td>B50R61, Be .35 - .50 per cent</td> <td></td> </tr> </table> Inspection Sept. 10, 1964 by F.G. Benson & J. Pietro				Brass	Aluminum, beryllium alloy	Bil G25H, Be .45 - .75 per cent	1 ounce of Be per 100 lbs of new metal (aluminum)	B50R61, Be .35 - .50 per cent	
Brass	Aluminum, beryllium alloy									
Bil G25H, Be .45 - .75 per cent	1 ounce of Be per 100 lbs of new metal (aluminum)									
B50R61, Be .35 - .50 per cent										

OPERATION
Sand Preparation Area - Basement

HAZARD

CONTROL MEASURE

Binning sand	Silica dust	General ventilation Approved respirator American Optical Intermittent operation (2-3 hrs. per 8 hr. day)
--------------	-------------	--

Preparation of core mix	Silica dust	Enclosed operation Exhaust ventilation
	Corn starch	
	Mogul Cereal Binder B242	
	Mogul Cereal Binder Col	
	New York, N.Y.	
	Dextrose dust	
	Globe Dextrose Co.	
	Corn Products Co.	
	New York, N.Y.	
	Sodium silicate dust	
	Kerosene vapors	
	Korbond FB-300 Corn Oil	
	United Oil Manufacturing Co.	
	Erie, Pa.	

Core Room

Bench core manufacture (8 stations) (CO ₂ is used to harden core)	Silica dust Lack of oxygen Carbon Dioxide	General ventilation Sand is damp
Blower core manufacture (6 stations)	Silica dust	General ventilation Sand is damp
Core baking (gas fired ovens 400-450° F.)	Conductive heat Carbon Monoxide Kerosene vapors Decomposition products	Ovens are exhausted locally.
Core packing	Silica dust	General ventilation Sand is damp
Core pasting	Lyquagrip Core Paste Whitehead Brothers Co. 75 Westminster St. Providence, R.I. Dermatitis Graphite Dust Talc dust	General ventilation Small quantities Brush application Personal hygiene
Roll-out core machine	Silica dust	General ventilation Sand is damp

CONTINUED ON SUBSEQUENT PAGES

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
DIVISION OF OCCUPATIONAL HEALTH

PLANT INFORMATION RECORD
Stock No. 5258.3

PLANT General Electric Corporation, Bldg. #64

D. C. Motor & Generator Division

ADDRESS 2701 East Lake Road

Eric, Pennsylvania

PRODUCT OR SERVICE Electric Motors and Generators

PERSON INTRODUCED Carl Salzer, Safety Specialist and Personnel Mgr.

PHYSICIAN R. D. Matter, M.D.

DENTIST Bone

NURSE Alice Manning, R.N.

Staff of five nurses

SAFETY SUPERVISOR Carl Salzer

INDUSTRIAL HYGIENIST None

INSURANCE CARRIER Electric Mutual Insurance Co.

LEGAL OWNER Corporation

RECOMMENDATIONS None

REMARKS D. C. generators and electric motors are fabricated and assembled.

Many of the operations require handling of epoxies. Radiation survey

conducted 6-12-58.

Inspection

DATE August 11, 1961 by

R. D. Matter

1. HAZARDS AND CONTROL MEASURES ON REVERSE SIDE

<u>Operation</u>	<u>Hazard</u>	<u>Control Measure</u>
Applying epoxy resin to rotters	Epoxy resin vapors	Local exhaust ventilation
Commutator turning	Copper dust Mica dust Dermatitis	Local exhaust ventilation Personal hygiene Hand creams
<u>Aerospace - model shop</u> Applying epoxy resin to commutator components	Epoxy resin vapors	Local exhaust ventilation
Baking of epoxy dipped components electric oven 400°F.	Epoxy resin fumes	Local exhaust ventilation
Cleaning of metal parts	Xylene vapors Dermatitis	General ventilation Personal hygiene Hand creams
Heavy machining turret lathes bores grinders mills drills backs	Steel alloy dust Copper dust Soluble & insoluble cutting oils Dermatitis Carborundum dust	General ventilation Personal hygiene Skin creams
Welding oxyacetylene electric arc inert gas (Argon)	Iron oxide fume Intense visible light Ultraviolet & infrared radiation Carbon monoxide Ozone Lack of oxygen	General ventilation Helmet Goggles
Motor cleaning	Naphtha vapors Dermatitis	General ventilation Closed unit Brush
<u>Aerospace assembly area</u> <u>Light machining</u> lathe mill drill band saw cross cut	Mica dust Mineral wool dust Plastic dust	<u>Bay-D</u> Local exhaust ventilation to bag collector (re-circulates air)

<u>Operation</u>	<u>Hazard</u>	<u>Control measure</u>
Machining boiler plates turret lathes mills bores drills	Iron oxide dust	General ventilation
Inspecting Metallic components Magnus Aja-Lif	Kelite Spray White Mist Los Angeles, Calif. Kerosene vapors Dermatitis	General ventilation Occasional operation Personal hygiene
Paint spraying boiler plates	Paint pigment mist Xylene vapors mist Dermatitis	Local exhaust ventilation Personal hygiene Hand creams
Paint drying boiler plates Gas oven 260°F.	Paint pigment fumes Xylene vapors Carbon monoxide Conductive heat	Local exhaust ventilation
<u>Shaft machining area</u> Machining motor shafts mills lathes	Iron oxide dust Soluble oil Dermatitis	General ventilation Hand creams Personal hygiene
Shaft grinding	Iron oxide dust Carbonundum dust	General ventilation
<u>Field core area</u> Field coil winding	Epoxy vapor Thinner vapors C.E. Spec. 9424 Dermatitis	General ventilation Hand cream Personal hygiene
Winding leads	Mineral wool dust Asbestos dust Dermatitis	General ventilation Small quantity Occasional operation Personal hygiene Hand cream
Brazing wire leads	Zinc, Tin, Copper oxide fume HCL	General ventilation
Core winding (soldering)	Lead Iron oxide fume HCL	General ventilation

Copy of an Original Record
 Date Recd. 11/12/60
 ARCHIVES
 U.S. DEPT. OF COMMERCE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
#9 DIVISION OF OCCUPATIONAL HEALTH

PLANT INFORMATION RECORD
STOCK No. 3388.3

General Electric Corporation
PLANT Locomotive and Car Equipment Manufacturing
Building #6

ADDRESS 2901 East Lake Road

Erie, Pennsylvania

PRODUCT OR SERVICE Locomotive and locomotive components

PERSON INTERVIEWED Dick Morano, Safety Specialist

PHYSICIAN R. B. Nutter, M.D. ph. extension 2004

DENTIST None

SURGE *Alisa Manning, R.N.

SAFETY SUPERVISOR Dick Morano

INDUSTRIAL HYGIENIST None

INSURANCE CARRIER Electric Mutual Insurance Company

LEGAL OWNER Corporation

RECOMMENDATIONS Improve housekeeping and exercise care to avoid spillage of cyanide salts in the work area.

Remove the mechanical obstruction from the exhaust hood in the operation involving the fabrication of field coil insulation

REMARKS * Staff of five nurses

Inspection

September 2, 1964

By P. G. Santos & J. Flerro

OPERATION	HAZARD	CONTROL MEASURE
<u>Commutator Testing Bay-C (Sections # 9, 10)</u>		
Spinning commutators	Noise	Operation to be further evaluated
Four commutators were spinning at the time of visit. May run as many as ten. The noise is continuous. Four shifts of workers are exposed. No ear plugs worn.		
<u>Coil Forming Area</u>		
Coil winding	Mica dust	General ventilation
	Fiberglass dust	Personal hygiene
	Dermatitis	Hand creams are available
Equilizer assembly	Epoxy resin vapors	General ventilation
	Cardolite Resin NC-513 (catalyst) vapors	
	3-M Chemical Co.	
	St. Paul, Minnesota	
	Hysol Hardner HZ-3416 vapors	
	Hysol Corporation	
	Olean, N.Y.	
	Dermatitis	Hand Creams are available
		Personal hygiene
Wire cutting	Copper dust	General ventilation
Wire brushing	Wire stripping	General ventilation
	compound vapors	Personal hygiene
	E.E. Spec. #306	Hand creams are available
	Dermatitis	
Wire cleaning	Nitric acid	Local exhaust ventilation
steam heat	Silver cyanide	Goggles
	Dermatitis	Rubber aprons and gloves
Mixing silver and sodium cyanide pellets	HCN	Local exhaust ventilated hood
gas fired pot	CO	Occasional operation
		(Mixing one hour every two weeks)
		Amynitrate ampules
Operation is sloppily conducted resulting in spillage of cyanide pellets. Acid cleaning tanks in vicinity increase the hazard potential.		
Lead loop winding	Mineral wood dust	General ventilation
	Dermatitis	Hand creams
		Personal hygiene
Molding armature coils (varnish application)	Acetone vapors	General ventilation
	Dermatitis	Personal hygiene
		Hand creams

CONTINUED ON SUBSEQUENT PAGES

<u>Operation</u>	<u>Hazard</u>	<u>Control Measure</u>
Curing varnished armature coils electric fired ovens (6) 2000°F.	Acetone vapor Varnish fume	General ventilation
Wrapping ground insulation (shellac and varnish application)	Acetone vapors Isopropyl alcohol vapors Mica dust Fiberglas dust Dermatitis	General ventilation Personal hygiene Hand creams
Machine taping of wire (automatic unit)	Fiberglas dust Mica dust Dermatitis	General ventilation Hand creams Personal hygiene
<u>Dip room</u> Dipping armature coils into varnish	Toluol vapor GE Spec. 1511 Solvent vapors	Local exhaust ventilation Intermittent operation Occasional operation (3 hrs. per week)
Winding and cleaning stator coils	Mica dust Toluol vapors Dermatitis	General ventilation Personal hygiene Hand creams
Mechanical wire wrapping (automatic machine)	Toluol vapor Mica dust Mineral wool dust Dermatitis	General ventilation Personal hygiene Hand creams
Fabricating insulation for field coils	Mineral wool dust Ethylene dichloride vapors Epoxy resin vapors Epon trichloride dust Formvar 7/70E vapors Shawinigan Resin Corp. Springfield 1, Mass. Araldite No. 772 vapors Dermatitis	Exhaust hood ventilation (hood is mechanically constructed) Intermittent operation Most chemicals are used in small quantities Impervious rubber gloves
Drying of fabricated field coil insulation	Solvent vapors (as above) Epoxy resin fumes	General ventilation
Dye mixing & impregnation of Fiberglas rolls (operation is conducted under vacuum)	Mineral wool dust Toluol vapors Isopropyl alcohol vapors G.E. Spec. 2311 Dye dust Dermatitis	Exhaust ventilation Impervious gloves

Operation

Armature wedge manufacturing

Hazard

Textolite dust

G.E. Spec. AI9B52A2

G.E. Spec. 115A

Melamine dust

G.E. Spec. AI9B23A1

G.E. Spec. 11508-B

Control Measure

Local exhaust ventilation

Cutting u-piece asbestos

Asbestos dust

Local exhaust ventilation

Molding & curing Fiberglas mats electrically heated oven 2000F.

Varnish fumes

General ventilation

Isopropyl alcohol vapors

Shearing Fiberglas & mica mats

Mineral wool dust

General ventilation

Mica dust

Personal hygiene

Dermatitis

Hand cream

Mica dust

Local exhaust ventilation

Cutting mica drills (3) rip saws

Laminating mica on Fiberglas

Mineral wool dust

Local exhaust ventilation

Mica dust

Personal hygiene

Methyl ethyl ketone vapor

Hand creams

Glue vapor

G.E. Spec. Sterling 620 glue

Dermatitis

Fabricating silicone & Fiberglas mats

Toluol vapors

Local exhaust ventilation

Mineral wool dust

Personal hygiene

Dermatitis

Hand creams

Curing fabricated silicone & Fiberglas mats electric heated oven 200 - 2900F.

Varnish fumes

Local exhaust ventilation

Toluol vapors

Dusting silicone and Fiberglas mats prior to laminating

Pumice dust

General ventilation

Intermittent operation

Field coil winding area

Field coil winding (silver soldering)

Copper dust

General ventilation

Zinc, Tin, Copper

Silver soldering is an occasional operation

Silver oxide fume

Operation

#598 Generator coil winding & insulating

Hazard

Epoxy resin vapors

G.E. Spec. XLJ051 (Catalyst vapors)

Toluol vapors

Isopropyl alcohol vapors

G.E. Spec. 80M Permafil

Dermatitis

Zinc

Tin

Copper

Silver oxide fume

Control Measure

General ventilation

Brush application

Personal hygiene

Hand creams

Silver soldering on

generator coils is done

intermittently

Molding & baking generator coils

electric heated oven 175°C.

Varnish fumes

Toluol vapors

G.E. Spec. S-xllk (Fluorocarbon release) vapors

General ventilation

Generator coil winding (heat lamps for drying)

Mineral wool dust

Varnish fumes

Toluol vapors

Dermatitis

Infrared radiation

General ventilation

Personal hygiene

Hand creams

Cleaning generator coils

Cakite liquid

detergent

Dermatitis

Personal hygiene

Hand creams

Induction brazing

Copper oxide fumes

Zinc oxide fumes

Tin oxide fumes

General ventilation

Intermittent operation

Annealing armature bars
gas fired furnace

Conductive heat

Carbon monoxide

General ventilation

Wrapping field coilsDipping field coils into
varnish

Toluol vapors

Dermatitis

General ventilation

Personal hygiene

Hand creams

Baking dipped field coils
electric fired oven 140°F.

Toluol vapors

Varnish fumes

General ventilation

Manual cleaning of field
coil terminals
(motor driven wire brush)

Varnish dust

Copper oxide dust

General ventilation

Impregnating fieldcoils
with varnish
(100 lbs. air pressure)

Toluol vapors

Solvaasol vapors

General ventilation

Enclosed operation

<u>Operation</u>	<u>Hazard</u>	<u>Control Measure</u>
Curing impregnated field coils electric fired oven 160°F.	Varnish fumes Toluol vapors Conductive heat	Local exhaust ventilation
*Asbestos putty mixing	Asbestos dust Talc dust Silica flour dust Varnish solvent vapors Boron trifluoride dust (hardener) Butyl perbenzoate vapors (catalyst)	General ventilation Intermittent operation Occasional operation (maximum 2 hours per day for mixing)
*This operation is to be relocated and will incorporate exhaust ventilation. The operation is to be further evaluated. Boron trifluoride and butyl perbenzoate are used in very small quantities.		
Wrapping field coils	Mineral wool dust Epoxy resin vapors 111 - Trichloroethane vapors Dermatitis	General ventilation Personal hygiene Hand creams
Braxing field coil leads (silver solder)	Zinc Tin Copper Silver oxide fumes Borax flux fumes	General ventilation
Machining field coils drills mills	Copper dust	General ventilation
Dipping field coils into shellac	Isopropyl alcohol Dermatitis	General ventilation Personal hygiene Hand creams
Removing asbestos from field coils	Asbestos dust	Local exhaust ventilation
<u>Cables, Terminals, Bus Rings, Wire Processing</u> Rolling & extruding copper strip (resistance welding)	Copper oxide fumes Soluble cutting oils Dermatitis	General ventilation Intermittent operation Personal hygiene Hand creams
Strip annealing electric fired oven 550°F.	Conductive heat	Local exhaust ventilation

RECEIVED
GENERAL ELECTRIC CORPORATION
BUILDING #6
MAY 19 1960

Operation	Hazard	Control Measure
Coil forming machine	Copper dust Insoluble cutting oils Dermatitis	General ventilation Personal hygiene Hand creams
Machine wire insulating	Toluol vapors Mineral wool dust Dermatitis	Local exhaust ventilation
Drying of insulated wire electrical furnace N heated 325°F.	Toluol vapors Varnish fumes Conductive heat	General ventilation
Impregnating field coils (100 lbs. air pressure)	Toluol vapors Solvaso vapors	General ventilation Enclosed operation
Curing impregnated field coils electrically heated oven 100°F.	Conductive heat Toluol vapors Varnish fumes	Local exhaust ventilation
<u>Wire terminal area</u> Stripping plastic from terminals	Plastic dust Steel alloy dust	General ventilation
Silver soldering	Zinc Tin Copper Silver oxide fumes Borax Flux fumes	Local exhaust ventilation
Terminal cutting rip saw	Copper dust	General ventilation
Resistance welding on terminals	Copper fumes	Local exhaust ventilation
Sanding terminals belt sander	Copper dust Carborundum dust	Local exhaust ventilation
Silver plating	Nitric acid Silver cyanide Dermatitis	Local exhaust ventilation Gloves Aeryl nitrite ampules are available
Tinning field coils	Lead oxide fume Tin oxide fume Soldering flux fumes G.E. Spec. 810B3	Local exhaust ventilation

<u>Operation</u>	<u>Hazard</u>	<u>Control Measure</u>
Coil Winding	Mineral wool dust Dermatitis	General ventilation Hand creams Personal hygiene
Paint dipping coils	Solvesso thinner vapors	General ventilation
<u>Commutator assembly area</u> Machining commutators rip saw mill	Copper dust	General ventilation
Braxing on commutators	Copper Zinc Tin Copper Silver oxide fume Flux fume G.E. Spec. 810B3	Local exhaust ventilation
Commutator turning vertical boring mills (2) lathes (4)	Mica dust Copper dust	Local exhaust ventilation
Curing commutators electrically heated ovens 140 - 210°C.	Conductive heat	General ventilation
Cutting commutator components (punch press)	Copper dust	General ventilation Personal hygiene Hand creams
Paint spraying	Paint pigment mist Toluol vapors	Local exhaust ventilating hood
Descaling metal components steam heated unit	Kalite - 3360 (sodium hydroxide) Dermatitis	Local exhaust hood ventilation Mechanical operation Limited exposure
<u>Punch Press area</u> Cutting metallic components punch presses (28)	Mild steel dust Noise	General ventilation Intermittent exposure
Light machining lathes drills punches V & O Automatic punch press	Mild steel dust Noise	General ventilation Intermittent exposure

REGION
COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
#5 DIVISION OF OCCUPATIONAL HEALTH

PLANT INFORMATION RECORD
Stock No. 53833

General Electric Corporation
PLANT Locomotive and Car Equipment Manufacturing
Building No. (24)
ADDRESS 2901 East Lake Road
Erie, Pennsylvania

PRODUCT
OR SERVICE Locomotive and locomotive components

PERSON
OF INTEREST Dick Morane, Safety Specialist

PHYSICIAN R. D. Mutter, M.D.

DENTIST None

NURSE *Alice Manning, R.N.

SAFETY SUPERVISOR Dick Morane

INDUSTRIAL HYGIENIST None

INSURANCE CARRIED Electric Mutual Insurance Co.

LEGAL OWNER Corporation

RECOMMENDATIONS

REMARKS *Staff of five nurses.

TYPE OF Inspection

DATE August 19, 1964

BY P.G. Rentos & J. Pierro

RECEIVED
10-1-64
10-1-64

RECEIVED
10-1-64
10-1-64

OPERATION	HAZARD	CONTROL MEASURE
<u>Compartment Assembly</u>		
Welding electric arc	Iron oxide fume Intense visible light Ultraviolet and infrared radiation	General ventilation Helmet
Sigmatic welding (CO ₂ A)	Carbon monoxide Ozone Oxides of nitrogen Lack of oxygen	
Grinding	Carborundum dust Steel alloy dust	Local exhaust ventilation
<u>Compound Molding Room</u>		
Compression molding electric heated unit 250° F.	Phenolic resin fumes Asbestos dust Mica dust	General ventilation Small quantities Intermittent operation
<u>Mixing Room</u>		
Mixing G.E. Spec #91 Compound	Lime dust G.E. Spec. #Silex Diamond dust Asbestos dust	Enclosed room Local exhaust ventilation Occasional operation (2-3 hrs. per week.)
Curing Asbestos mixture steam heated unit, 325°C.	Conductive heat Asbestos dust	Local exhaust ventilation
Grinding of asbestos molded units	Asbestos dust	Local exhaust ventilation

996 South Main Street
Headville, Pennsylvania
October 27, 1964

73
Cooker like yours
going to be here
soon!

R. B. Nutter, M.D.,
Supervising Physician
Health & Hygiene Subsection
General Electric Company
2901 East Lake Road
Erie, Pennsylvania

Dear Doctor Nutter:

Pursuant to our recent plant evaluation, we are submitting to you a detailed analysis of our findings. At your request, this information is broken down as to building and further subdivided with regard to location and operation.

Before continuing further, we wish to thank you and your safety representatives for the courtesy and cooperation received. We also wish to acknowledge the assistance of Miss Childs, whose efficient scheduling aided in expediting our activities.

The comments which appear under remarks are not intended to be unduly critical. We simply wish to indicate to you certain problem areas requiring greater consideration by your safety personnel. In most instances, each point was individually discussed with the responsible safety representative and, quite often, the situation was immediately remedied.

In most cases control measures and personal protective devices are available. The use and maintenance of the latter, however, should be more strongly enforced. In this regard special emphasis should be given to operations where high noise levels are generated. Where noise control cannot be effected by other means, the use of ear protective devices should be mandatory. Greater supervision should also be given to operations requiring the handling of epoxy resins. The use of impervious protective clothing and gloves should be obligatory in order to preclude the possibility of contact dermatitis.

Many chemicals of various descriptions are used throughout the plant. In most instances, these are stored in containers which are inadequately labeled. As a result, the employee may be unaware of the toxicity of the material he is handling. Chapter 4, Article 432, Section 9 of the Rules and Regulations for the Department of Health requires that all containers of hazardous chemicals be appropriately identified and labeled.

2

5/20/44
Murray Avenue
New York, N.Y.

7. LOCATION: Insulation Department - Fourth Floor

OPERATION: Asbestos putty mixing

REMARKS: This operation is to be relocated on second floor. Several chemicals of high toxicity are handled intermittently without mechanical exhaust ventilation. Until such time as additional studies are conducted, it is suggested that the workers be supplied with a U. S. Bureau of Mines approved dust respirator.

The new installation should incorporate engineering measures to control contaminant dispersion.

8. LOCATION: Field Coil Winding Area - Third Floor

OPERATION: Field coil terminal cleaning

REMARKS: The operator's position should be adjusted as to make maximum use of the present exhaust system. The piling of equipment in front of the exhaust should be avoided as this acts to reduce its efficiency of collection.

9. LOCATION: Cables, Terminals, Bus Rings - First Floor

OPERATION: Sanding terminals

REMARKS: The exhaust system on the belt sander does not appear to be working effectively. The system should be checked for cleanliness or need of repair.

10. LOCATION: Shafts and Keys Section 64642 Transportation Motor Assembly Area

OPERATION: Spray painting of metallic components

REMARKS: The respirator worn by the worker was unapproved. If the use of a respirator in this operation is to be continued, the worker should be supplied with one approved by the U. S. Bureau of Mines for organic vapors.

The local exhaust hood does not appear to be working effectively. It may require maintenance or cleaning.

11. LOCATION: Shafts and Keys Section 64642 Transportation Motor Assembly Area

OPERATION: Fan blade testing

REMARKS: Employees are intermittently exposed to high levels of noise. Ear plugs are provided but not worn.

12. LOCATION: Railway Generator Armature Spin Test Section 64653

OPERATION: TIG welding commutators

REMARKS: We wish to further evaluate exposures to copper oxide fume during this operation.

SEARCHED

INDEXED
SERIALIZED
FILED
FBI - NEW YORK
JUN 10 1964

COMMONWEALTH OF PENNSYLVANIA
996 South Main Street
Harrisburg, Pennsylvania
September 14, 1959

SUBJECT: Occupational Diseases
(Adele A. Putman
General Electric, Erie, Pa.)

SEP 15 1959

TO: Jan Lieben, Director
Division of Occupational Health

Thru: E. J. Bader, Chief
Industrial Hygiene Section
Division of Occupational Health

FROM: J. W. Knauber
Regional Industrial Hygienist
Region III

This woman was employed at the same operation, a field coil repair, for 13 years. During this period, she was exposed to woven glass tape, mica tape, various resins and glues, and epoxy resins. Early this spring she developed a rash on her arms. At the time of this rash, there was no lost working time. However, she was referred to a dermatologist located in Erie, Dr. Marus. Dr. Marus' original diagnosis was that this was not an industrial dermatitis.

On June 23, 1959, the dermatitis re-occurred and the woman was off work from June 23 through July 20, 1959; this included her regular 2 weeks paid vacation. She reported back to work on July 20th and, late that same day, was reported off sick, due to her dermatitis, by Dr. Nutter, Plant Medical Doctor. Dr. Nutter stated that the dermatitis had cleared and that she was physically able to resume work on August 3, 1959. However, both Dr. Nutter and Dr. Marus are definitely against her resuming her previous job, and she is presently laid off from work pending the re-hiring in another job in which she will not be exposed to the causative agent.

Dr. Nutter stated that Dr. Marus performed patch tests some time between June 23 and July 20, 1959, and that the causative agent of dermatitis was a putty used as a filler in the field coil manufacture. The putty consists of asbestos, oil and an alcohol thinner. The composition of the oil, if needed, can be determined by contacting the General Electric, Schenectady office.

JWV/rh

SEARCHED
INDEXED
SERIALIZED
FILED

① Was this C.D. investigation requested?
② Were any recommendations?

Commonwealth of Pennsylvania
Department of Health

BUREAU OF INDUSTRIAL HYGIENE

Report of Survey

General Electric Company
2801 East Lake Road
Erie, Pennsylvania

On January 14, 1964, in response to a request from Mr. H. A. Weber, safety director, a survey was conducted in the wood shop of General Electric Company, to determine the exposure of employees to asbestos dust. Mr. G. D. Kauffman, Foreman of the department, was present during the survey.

RECOMMENDATIONS

None.

DETAILED FINDINGS

This department was engaged in the processing of asbestos board. The equipment consisted of saws, drill presses, a sanding wheel, and a Pantograph. All the equipment was exhaust ventilated and, as the accompanying table indicates, no concentration exceeded the maximum allowable limit of 5 million particles per cubic foot of air.

Housekeeping in this department was good.

5-1-64
H. A. Weber
Safety Director, GE Company

South

4.20
2.50

Rolling wheel

4.40

Photograph

0.04

*Maximum allowable limit - 5 million particles per cubic foot of air

Survey by -

C. F. Kennedy
District Industrial Hygienist

W. G. Kaiser
Jr. Asst. Ind. Hygienist

January 20, 1964

KRM:ern

RECEIVED
JAN 23 1964
FEDERAL BUREAU OF INVESTIGATION
U. S. DEPARTMENT OF JUSTICE

Commonwealth of Pennsylvania
 Department of Health
 BUREAU OF INDUSTRIAL HYGIENE

Table 1

Asbestos Data

General Electric Company
 2801 East Lake Road
 Erie, Pennsylvania

Location Asbestos*
 (millions of particles
 per cubic foot of air)

Time 2.80
 Date 2.30

West 0.80

Drill press 3.00
 March 2.80

Commonwealth of Pennsylvania
Department of Health

BUREAU OF INDUSTRIAL HYGIENE

Report of Investigation

General Electric Company
(Building 24)
East Lake Road
Erie, Pennsylvania
April 12, 1951

This investigation was made at the request of Mr. H. A. Weber, director of safety.

RECOMMENDATIONS

1. Adjust or redesign exhaust ventilation at drill presses, G. E. Cat. Nos. 17646, 17536, 14866, and band saw No. 7134 to reduce respirable air-borne asbestos dust to less than 5 million particles per cubic foot of air.

DETAILED FINDINGS

Air samples were obtained at several machines to determine concentration of dust in the breathing zone during work on asbestos board. The machines involved were multiple drill presses, G. E. Cat. Nos. 17646, 17536, 14866, and a band saw No. 7134. No investigation was made on machines in the compound molding room owing to production reasons.

Findings are given in Table 1. In most cases the quantities of dust exceeded the amounts recommended for continuous exposure. One exception occurred with the drilling of small, thin asbestos pieces at press, G. E. Cat. No. 14866. However, it is doubtful if such results could be obtained with larger work.

All of the drill presses were equipped with an exhaust system composed of a single flexible hose and hood, which could be moved from point to point. However, it appeared to be impractical where it was necessary to use several of the drills of any one press on the same asbestos piece.

The band saw was also provided with exhaust ventilation which, as shown by findings, did not reduce respirable air-borne dust to work-day limits.

In view of the findings it is recommended that adjustments be made in ventilation as needed to provide positive reduction in dust concentration at the various machines to below recommended limits. It is felt that this is particularly desirable at the drill presses, where failure to properly utilize the present flexible system could produce greater airborne concentration than found during investigation.

Investigation by:

F. W. McDaniel
Senior Industrial Hygienist

W. G. Reiser
Jr. Ass't Industrial Hygienist

Commonwealth of Pennsylvania
Department of Health
BUREAU OF INDUSTRIAL HYGIENE

Table 1

Dust Concentrations

General Electric Company
(Building 24)
East Lake Road
Erie, Pennsylvania

Location (Building 24)	Millions of dust particles* per cubic foot of air	Remarks
Drill Press (O. E. Cat. #17846)	7.6 6.9	Drilling asbestos
Drill Press (O. E. Cat. #17536)	6.9 6.1	Drilling asbestos
Drill Press (O. E. Cat. #14865)	4.1 3.0	Drilling small asbestos pieces
Band Saw (#7134)	6.1 3.0	Sawing asbestos

*Maximum allowable concentration for asbestos dust--5 million particles per
cubic foot of air

April 20, 1961

PCH:peh

REPRODUCTION OF ORIGINAL RECORD
MADE BY THE
BUREAU OF INDUSTRIAL HYGIENE

REPRODUCTION OF ORIGINAL RECORD
MADE BY THE
BUREAU OF INDUSTRIAL HYGIENE

Report of Investigation
General Electric Company
Erie, Pennsylvania
(Building 24)

April 20, 1931

P. W. McDaniel
Erie District

Philip C. Hill

I am calling your attention to a couple of numerical errors in the report of the above-mentioned investigation submitted with your memorandum of April 18. In editing the report we have made the corrections which we feel must be the correct ones. In case we have not done it correctly you will probably want to communicate with the General Electric Company.

In your recommendations you list Catalog Nos. of the drill presses as 17548, 17538, and 14888 and of the band saw as No. 7134. In the first paragraph of the detailed findings you have indicated one of the drill presses to be 14888. We have changed this to read 14888. The last item on the Table indicates the band saw to be No. 7534. We have changed this to read 7134.

I hope that we have made the correct assumption in this case.

PCH:psh

Reproduction of an Original Record
Please Check
PA STATE ARCHIVES
Harrisburg, PA 17120-0030
Official Commission

Commonwealth of Pennsylvania
Department of Health

BUREAU OF INDUSTRIAL HYGIENE

Report of Investigation

General Electric Company
East Lake Road
Erie, Pennsylvania
January 25, 1951

This investigation was made at the request of R. E. Nutter, M. D., Works Physician, and Mr. H. A. Weber, Works Safety Engineer.

RECOMMENDATIONS

1. Revise or improve ventilation at snagger #13325 and saw #14165, Building 24, to reduce dust concentration to safe levels.
2. Provide respirator for the operator of the snagger until changes have been made.

DETAILED FINDINGS

Air samples were obtained to evaluate exposures of personnel to asbestos dust originating in operations at asbestos saws #14165 and #13025, drill press #14762, and snagger #13325, Building 24. This investigation was made as a follow-up to an earlier study of similar nature made in July 1949. Findings of the earlier study reflected the need for improved ventilation at saws #14165 and #13025, snagger #13325, and at several machines which will not be discussed here because, for production reasons, they could not be investigated at this time. Since the previous study, changes in exhaust ventilation have been made at saws #14165 and #13025. No changes were noted at snagger #13325.

Samples were collected in the breathing zone of personnel concerned. The collection medium was distilled water. Dust counts were determined by standard light-field technique and particles were examined for size at a magnification of 1000 diameters. The latter operation showed that collected particles were within the respirable range.

RECEIVED
JAN 26 1951
BUREAU OF INDUSTRIAL HYGIENE
DEPARTMENT OF HEALTH
COMMONWEALTH OF PENNSYLVANIA

Results of findings are given in Table 1. Dust counts reflect improvement in ventilation at saws #14155 and #13025. Findings for other machines investigated show no marked changes.

In view of the results, it was recommended that the exhaust ventilation at snagger #13325 be improved to lower dust concentrations to safe levels of 5 million particles per cubic foot of air or less, and that the operator use a respirator until this is achieved. Improvement was also recommended for saw #14155, ventilation for which, though much better than in 1949, is still not as effective as desired.

No changes were recommended for drill press #14752 since the mobile exhaust hood with which it is equipped, when properly placed, appeared to give sufficient control of dust.

February 5, 1951

PCB:pah

Investigation by:

P. W. McDaniel
Senior Industrial Hygienist

W. G. Reiser
Jr. Asst. Industrial Hygienist

SEARCHED
SERIALIZED
INDEXED
FILED

Commonwealth of Pennsylvania
Department of Health
BUREAU OF INDUSTRIAL HYGIENE

Table 1

Dust Concentrations*

General Electric Company
East Lake Road
Erie, Pennsylvania

Location	Millions of particles per cubic foot of air (present findings)
<u>General Shop</u>	
Asbestos saw (#14186)	3.8 6.0 5.7
Asbestos saw (#13025)	1.8 3.2 2.4
Snagger (#13325)	17.8 18.0 18.2
Drill press (#14752)	4.8 3.6 5.4

*Threshold limit value for asbestos dust - 5 million particles per cubic foot of air

Recorded in Original Record

Commonwealth of Pennsylvania
Department of Health

BUREAU OF INDUSTRIAL HYGIENE

Report of Investigation

Control Division
General Electric Company
East Lake Road
Erie, Pennsylvania
July 11, 12, 13, 14, 1949

This investigation was made at the request of Dr. E. D. Mutter, Medical Director, and Mr. Harry Weber, Safety Director, and is one of a series of reports to be made on exposures throughout the entire plant.

RECOMMENDATIONS

Control Division

Building 24

1. Install additional ventilation or revise present installation, as needed, to provide control of dust generated at asbestos saws G. E. catalogue #11161 and #13025, snagger #13325, hand saw #1114, snagger #DPE 225 (compound welding room), and drill press #10570 (compound welding room).
2. Provide respirator for use of operator when loading mixer in compound mixing room.

Building 5

1. Put partition on window side of paint-spray booth (second floor building 5), to reduce effects of open windows. Top of booth should also be extended further over table if pieces to be sprayed cannot be kept within the plane of the booth face.

Building 10

1. Eliminate possible excessive exposures to acid vapors and oxides of nitrogen during acid dip by using hoist for handling large pieces or by increasing air flow through hoods at the acid tanks.

- 2 -

DETAILED FINDINGS

Central Division

Building 24

The principal exposures tested at this location were those resulting from dust generated at operations involving the cutting and shaping of asbestos board, cutting and processing a synthetic resin board (known as Texolite), and the mixing and processing of a compound consisting of asbestos, silica, and lime. The latter compound was molded and baked after mixing.

Exposures were evaluated by collecting and counting air-borne dust at the breathing level of operators of various machines including saws, snuggers, drill presses, and the mixing machine used for preparation of the compound indicated in the preceding paragraph. Samples were collected in distilled water and timed to give a fair representation of exposures of personnel working at the various machines.

The number of dust particles in samples was determined by the light-field technique and is shown in Table 1. Sizes of collected dust were determined by measurement at 1000 diameters magnification. The latter operation showed that collected particles were within the respirable range. Dust counts showed that, in most instances involving the machining of asbestos articles, the weighted exposure of personnel operating the machines was too high. This finding was based on the present accepted limit of 5,000,000 particles of asbestos per cubic foot of air.

Counts of dust obtained at machines handling Texolite were of lower general range than those found for asbestos. Since this dust was a synthetic resin type, the results were not believed to indicate excessive exposures.

In view of the dust counts it was considered advisable to reduce concentrations encountered by operators of several machines used in shaping asbestos articles. The machines in question were asbestos saws G. E. catalogue #14145 and #13023, snagger #13325, hand saw #1134, snagger #DPC225 (compound molding room), and drill press

REPRODUCTION OF AN ORIGINAL RECORD
MAINTAINED IN THE
FBI ARCHIVES
DATE 11-17-2009

#10370 (compound molding room). It is therefore recommended that the ventilation where provided be increased, or that the system be re-designed as needed to reduce dust concentrations. Machines not so equipped should be provided with mechanical exhaust ventilation.

Dust counts also showed the high exposure of the operator while loading the mixing machine used in connection with the production of molded asbestos articles. While the exposure time was relatively short, it is believed good practice to provide a respirator for the operator to be worn during the loading period. A recommendation to that effect is made.

Building 5 (second floor)

Exposures investigated included those occurring at a trichloroethylene degreasing tank #M-2450, a nearby heat-treating tank using a molten cyanide-bearing salt, and at a paint-spraying booth. No numbers were obtained for the latter two locations but they were considered sufficiently familiar to the safety director of the division as to require no additional identification.

Air samples were collected at the breathing level in the vicinity of the degreasing tank, and trichloroethylene content was determined by decomposition of the sample and measurement of chlorine obtained. Analysis indicated that weighted exposures were not excessive, although it was shown that too fast a drag-out of work from the tank could give high concentrations of the air-borne solvent. This occurred in spite of the fact that the tank was equipped with good lateral-slot-type ventilation. While it is believed that recommendations for protection of health are unnecessary, it should be pointed out that even small amounts of trichloroethylene in the air may, on decomposition, yield products that are corrosive to certain metals.

Study was made of the possibility of exposure to air-borne cyanide at the heat-treating tank near the degreaser discussed above. No sampling of air was considered necessary because examination showed that the visible fumes from the molten salt

REPRODUCTION OF AN ORIGINAL RECORD
MAY BE MADE
PA STATE ARCHIVES
350 NORTH ZEEB RD
MILWAUKEE, WIS. 53233

Commonwealth of Pennsylvania
Department of Health
BUREAU OF INDUSTRIAL HYGIENE

Table 1

Dust Concentrations
(Building 24)

General Electric Company
East Lake Road
Erie, Pennsylvania

Location	Millions of particles of dust per cubic foot of air	Remarks
<u>General Shop</u>		
Asbestos saw (G.E. cat. #14165)	32.8 26.4 32.0	Sanding asbestos
Asbestos saw (G.E. cat. #13025)	24.4 28.0 32.0	Sanding asbestos
Snagger #13325	19.2 19.0 17.6	Snagging asbestos
Hand saw #1134	21.2 16.8 19.0	Sanding asbestos
Drill press #14752	11.8 8.0 8.0	Drilling Taxolite
Drill press #14665	11.6 12.0 13.0	Drilling Taxolite
Circular saw #13369	14.0 12.0 14.8	Sanding Taxolite
<u>Compound Mixing and Holding Rooms</u>		
Mixer	21.2 22.4 24.0	Loading mixer with silica, asbestos, and lime
	9.6 7.6	Mixer operating
Snagger #225	17.6 16.8 22.8	Snagging molded asbestos-silica articles
Drill press #10570	15.0 20.0 17.6	Drilling molded asbestos-silica articles

REPRODUCTION OF AN ORIGINAL RECORD
PLEASE CHECK
PA STATE ARCHIVES
SERIALS
11/13/2000
1052

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
BUREAU OF INDUSTRIAL HYGIENE
Sample and Laboratory Report

Name & Address of Co. General Electric Company, East Lake Road, Erie

Product Mfg. [Electrician] apparatus Material Sampled Settled dust

Date Collected July 12, 1949 By McDaniel

Disposition of Sample Harrisburg Date July 12, 1949

Analysis desired for Free silica and asbestos on 7A49, free silica or thought to be present *SEE BELOW

Apparatus only on 7B47 Collecting Medium

C.L. No.	Dist. No.	Sampling Location and Operation	Time	Air Volume
----------	-----------	---------------------------------	------	------------

3364 7A49 Compound molding room

3365 7B47 Compound molding room

REPORT OF ANALYSIS

*Sample 7A49 may contain silica, calcium silicate, and asbestos.
Sample 7B47 believed to be quartz

C.L.	Dist.	%Free silica	
3364	7A49	58.23	Analysis by V.M. Vought
3365	7B47	98.49	

The remainder of 3364 (7A49) is not chrysotile asbestos, but looks like one or another of the amphibole family of minerals closely related to chrysotile. Chrysotile is fibrous but these minerals are not. These minerals are formed of platelets and are columnar.

PA STATE ARCHIVES

Date August 23, 1949

A. E. Galloway
Principal Chemist

File

OCCUPATIONAL HEALTH

401 Buttonwood Street
West Reading, Penna. 19602
December 27, 1971

General Electric Apparatus Service Shop
Lehigh Valley Industrial Park No. 2
Allentown, Penna. 18103

Attention: Mr. William Green
Plant Manager

Gentlemen:

During an inspection of your plant by Mr. Craig S. White, industrial hygienist, it was observed that adequate local exhaust ventilation is not used to control atmospheric contaminants generated by Babbitting and large motor insulation burn-off operations.

In view of the foregoing, and in keeping with good industrial hygiene practice, the following recommendations are made:

1. Continue with your plans to install local exhaust ventilation at Babbitting and large motor insulation burn-off operations to prevent atmospheric contamination of the work environment.
2. Provide local exhaust ventilation at the abrasive blasting operation for motor stators.
3. Install local exhaust ventilation at all silver soldering operations to prevent employees' exposures to copper fume. (This recommendation was previously made in our January 31, 1969 report, which indicated that employees' exposures to copper fume exceeded the threshold limit value of 0.1 milligram per cubic meter of air.)

Please advise this office of the steps taken to comply with the above recommendations.

SEARCHED

INDEXED

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
OCCUPATIONAL HEALTH
COMPLIANCE REPORT

DATE January 31, 1969

RETURN THIS FORM TO HARRISBURG AFTER EXPIRATION OF INDICATED COMPLIANCE PERIOD

To: Industrial Hygienist, Region II - West Reading

A thirty day compliance clause has been inserted in the report sent

General Electric Service Shop
668 East Highland Street
Allentown, Pa.

Date of Report January 31, 1969

March 3
(February 1969)

DATE OF SURVEY - January 8, 1969

REPORT OF REINSPECTION

A reinspection was made at this location on March 12, 1969

Recommendations were:

Complied with ☒

Not Complied with ☐

Remarks: CEPPE AND CAUTION DICE FUMES

1. Require that the worker at the silver soldering operation correct his activities in the booth used for the housing burnout operation, or
install local exhaust ventilation at the silver soldering operation, preferably in the form of a movable duct which could be located directly over the lead being soldered.
2. Continue to purchase a non-cadmium containing silver solder.
3. Until Recommendation No. 1 is accomplished, require that workers engaged at the silver soldering operation wear U. S. Bureau of Mines approved respirators for protection against metal fume having a threshold limit value of 0.1 milligram per cubic meter of air or greater.
4. Establish a maintenance program for these respirators in accordance with Section 50, Article 150.

no more work
all done

CE
March 3, 1969

Signature

John N. Durey

Title

Industrial Hygienist I

REGION West Reading - II
PROD. MFG. OR SERVICE
Electric Motor Repair
DATE OF ACTIVITY 7/13/69

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF HEALTH
OCCUPATIONAL HEALTH
FIELD ACTIVITY REPORT

EMPLOYEES
MALE
FEMALE
TOTAL 22
COUNTY 39
IND. CODE 76

PLANT General Electric Service Shop
ADDRESS 668 East Highland Street, Allentown
ZIP 18103
PERSON INTERVIEWED Mr. Fethi M. Ulgen
TITLE Manager

PURPOSE: INVEST. SURVEY, INSPECT, PRELIM. & CONF. VIST.

REASON: ADDITIONAL INFO RE: COMPL. REQUEST; SOURCE

SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	RECOMMENDATIONS		ACCOMPLISHED		
		W	WRITTEN - V - VERBAL	YES	NO	IN PROG.
<u>Cu fume</u>	<u>22</u>	<u>See below</u>				

SAMPLES COLLECTED NO. & KIND TOTAL

DETERM. MADE NO. & KIND TOTAL

MEDICAL - C.O. REPORTED, NO. & KIND

FUNCH CARD YES ☒ NO ☐ FOLDER YES ☒ NO ☐

REMARKS

Follow up visit made to determine compliance with recommendations made subsequent to a 1/8/69 survey. Mr. Ulgen has sent a letter to C.O. outlining proposed plans. This company plans to relocate in the L.V.I.P. sometime this coming summer and plans are on the boards now for extensive ventilation not only at the areas that are currently exhausted but also at the area in question during the survey - the silver soldering operation.

Following is the status on the recommendations.

1. Require Ag soldering to be conducted in the housing burnout hoods or install additional L.E.V. - completed - A 36 pedestal fan has been installed behind the worker engaged at the soldering operation. The fumes will be blown into the L.E.V. at the impregnator. The I.H. feels this is sufficient for the time being. Soldering cannot be conducted at the housing burnout hoods because these are in constant use. During the F.U. visit such a setup, i.e. "blowing" the fumes into the impregnator L.E.V. appeared to be adequate.
2. Purchase non cadmium containing Ag solder. - completed - This company has always purchased a non Cd Ag solder.
- 3 & 4. OSHA approved respirator and maintenance program. - completed - An order of MSA respirators are on hand with a supply of replacement cartridges. The respirators are also properly maintained.


Therefore of all 4 recommendations all of them have been accomplished. Mr. Ulgen also stated that the amount of time spent on Ag soldering has been cut down to a maximum of three hours/day at 30 minute intervals. If this company is not in a new building by August of 1969 more stringent ventilation control will be requested at that time.

J. Garis

1.5

Division of Occupational Health
505 State Office Building
300 Liberty Avenue
Pittsburgh, Pennsylvania 15222

September 4, 1968



General Electric Apparatus Service Shop
4930 Duluthville Hollow Road
West Milford, Pennsylvania 15122

Attention: Mr. E. G. Gerenda
Manufacturing Engineer

Confidential:

Your Application for Approval of Air Recirculation System has been reviewed. This system has not been approved by the Department.

1. A significant problem should not arise in exhausting only 578 cfm to the outside.
2. Mica dust, the contaminant collected, is a relatively hazardous material having a threshold limit value of 20 million particles per cubic foot.

Since your request has not been approved, steps must be taken as soon as possible to exhaust this system to the outside. Please notify this office within 15 days of the steps you are taking and the expected completion date.

Thank you for your cooperation in this matter. If we can be of any assistance or if you have any questions, please let us know.

Very truly yours,

Nicholas Farnick
Regional Industrial Hygienist
Region V

F/H-T/as

cc Central Office 1 ✓

File

T/P

090000Z11 SEP 68

RECEIVED

Division of Occupational Health
Pittsburgh, Pennsylvania

Handwritten signature and date:
9/10/68

401 Buttonwood Street
West Reading, Penna. 19602
June 9, 1969

General Electric Company
Housewares Division
1801 South 12th Street
Allentown, Pennsylvania 18103

Attention: Mr. Carl Swartz
Superintendent

Gentlemen:

During an inspection in your plant by Mr. John Garis, industrial hygienist, the following recommendations were made:

1. Keep the perchloroethylene bucket in the degreasing area covered when not in use.
2. Replace unapproved respirators with those approved by the United States Bureau of Mines for respiratory protection against nuisance and pneumoconiosis-producing dusts in the polishing shop.

In order to insure that the most benefit is derived from the use of respiratory protective devices and to prevent a false feeling of security, it is the practice of this office to suggest the use of only those devices which have been approved by the aforementioned agency.

For your information we are enclosing a copy of our Hygienic Information Guide entitled "Personal Respiratory Protective Equipment."

Please notify this office, in writing, of the steps you have taken to accomplish the above recommendations.

Thank you for your cooperation in this matter.

Very truly yours,

Kenneth M. Sacharov
Regional Industrial Hygienist
Division of Occupational Health

ENCLOSURE
100-100147
Enc.