



Conforms to Hazard Communication Standard 29CFR 1910.1200 Rev. September 1985

Manufacturer/Supplier Name	The Lincoln Electric Company	Product Type	Covered electrode
Address:	22801 St. Clair Avenue Cleveland, Ohio 44117	Classification	E6010
Telephone No.	(216) 481-8100		

IMPORTANT!

* The term "hazardous" in "Hazardous Materials" should be interpreted as a term required and defined in the Hazards Communication Standard and does not necessarily imply the existence of any hazard.

[illegible]

* OSHA PEL (Permissible Exposure Limit) Value limits are the same as TLV unless otherwise listed.

Other	Wt%	TLV mg/m ³
Cotton steel core wire	85	10*

• **Non Flammable:** Welding arc and sparks can ignite combustibles and flammable products. See 249.1 referenced in Section VI.

Threshold Limit Value:

The TLV should be regarded as a general limit for Welding Fume NOC — (Not Otherwise Classified) is 5 mg/m³. ACGIH-1985 preface states "The TLV-NVA should be used as guides in the control of health hazards and should not be used as fine lines between safe and dangerous concentrations." See Section V for specific fume constituents which may have TLV Threshold Limit Values published by the American Conference of Governmental Industrial Hygienists.

DO A 061518
CONFIDENTIAL

Trade Name: Fleet-weld SP

Sizes: All

Date: September 23, 1995

Effects of Overexposure SECTION IV — HEALTH HAZARD DATA continued

Electric arc welding may create one or more of the following health hazards:

Fumes and Gases can be dangerous to your health. Common entry is by inhalation.

Short-term (acute) overexposure to welding fumes may result in discomfort such as dizziness, nausea, or dryness or irritation of nose, throat, or eyes.

Long-term (chronic) overexposure to welding fumes can lead to siderosis (iron deposits in lung) and affect pulmonary function.

Arc Rays can injure eyes and burn skin.

Electric Shock can kill.

Emergency and First Aid Procedures: Call for medical aid. Employ first aid techniques recommended by the American Red Cross. IF BREATHING IS DIFFICULT give oxygen. IF NOT BREATHING employ CPR (Cardiopulmonary Resuscitation) techniques. IN CASE OF ELECTRICAL SHOCK, turn off power and follow recommended treatment. In all cases call a physician.

SECTION V — REACTIVITY DATA

Hazardous Decomposition Products

Welding fumes and gases cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, the process, procedure and electrodes used.

Other conditions which also influence the composition and quantity of the fumes and gases to which workers may be exposed include: coatings on the metal being welded (such as paint, plating, or galvanizing), the number of welders and the volume of the work area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities).

When the electrode is consumed, the fume and gas decomposition products generated are different in percent and form from the ingredients listed in Section II. Decomposition products of normal operation include those originating from the volatilization, reaction, or oxidation of the materials shown in Section II, plus those from the base metal and coating, etc., as noted above.

Reasonably expected fume constituents of this product would include: Primarily iron oxide; secondarily complex oxides of manganese, silicon, and sodium.

Maximum fume exposure guideline for this product is 5.0 mg/m³.

Gaseous reaction products may include carbon monoxide and carbon dioxide. Ozone and nitrogen oxides may be formed by the radiation from the arc.

One recommended way to determine the composition and quantity of fumes and gases to which workers are exposed is to take an air sample from inside the welder's helmet if worn or in the worker's breathing zone. See ANSI/AWS F1.1 "Method for Sampling Airborne Particles Generated by Welding and Allied Processes," available from the American Welding Society, 550 N.W. LeJeune Road, Miami, Florida 33126.

SECTION VI AND VII — CONTROL MEASURES AND PRECAUTIONS FOR SAFE HANDLING AND USE

Read and understand the manufacturer's instructions and the precautionary label on the product. See American National Standard Z49.1, "Safety in Welding and Cutting" published by the American Welding Society, 550 N.W. LeJeune Road, Miami, Florida, 33126 and OSHA Publication 2206 (29CFR1910), U.S. Government Printing Office, Washington, D.C. 20402 for more detail on many of the following:

Ventilation

Use enough ventilation, local exhaust at the arc, or both, to keep the fumes and gases from the worker's breathing zone and the general area. Train the welder to keep his head out of the fumes.

Respiratory Protection

Use respirable fume respirator or air supplied respirator when welding in confined space or general work area when local exhaust or ventilation does not keep exposure below TLV

Eye Protection

Wear helmet or use face shield with filter lens shade number 2-14 or darker. Shield others by providing screens and flash goggles.

Protective Clothing

Wear hand, head, and body protection which helps to prevent injury from radiation, sparks, and electrical shock. See Z49.1. At a minimum this includes welder's gloves and a protective face shield and may include arm protectors, apron, hood, and body protection as well as substantial clothing. Train the welder not to permit electrically live parts or electrodes to contact skin... or clothing or gloves if they are wet. Insulate from work and ground.

Disposal Information

Dispose of this product in accordance with applicable regulations.

DO A 061519
CONFIDENTIAL