

MEMORANDUM

PLANT ASBESTOS PROJECT

By

J. F. Schultz

Union Carbide Corporation

Texas City Plant

July 19, 1985

UCTC 06788

Table of Contents

1.	Foreward.....	1
2.	Introduction.....	2
3.	Summary.....	3
4.	Recommendations.....	6
5.	Discussion.....	9
6.	Housekeeping.....	11
7.	Asbestos Identification.....	11
8.	Acknowledgement.....	12
9.	Appendix	
	Cost Estimate	
	Identification of Piperack Priorities	

PAGE 1

FOREWARD

The Texas City Plant is concerned about the potential health hazards of asbestos. Accordingly, development of an action plan addressing this concern was authorized. The primary objectives of the action plan are:

1. To ascertain the magnitude of asbestos insulation requiring repair and which therefore presents a potential for release of asbestos fibers to the environment.
2. To recommend corrective action which will eliminate, in-so-far as possible, asbestos contamination of the environment.

UCTC 06790

PAGE 2

INTRODUCTION

An assessment of the amount of exposed "asbestos suspect" insulation was completed for the entire plant (exclusive of office buildings, control rooms, laboratories and shops). This assessment was accomplished through site surveys performed by inspection teams appointed by the department heads. Valuable assistance was given these teams by hourly insulator craftsmen and leadmen and Industrial Hygiene departmental personnel. Cost estimates in the +30% range were made by the plant insulator group.

UCTC 06791

PAGE 3

SUMMARY

Due to the weathered condition and to some degree damage to the insulation weather barrier, and to the insulation itself, significant amounts of exposed "asbestos suspect" insulation exists in the plant.

Estimates of the quantity of asbestos suspect insulation requiring repair together with a cost estimate for correcting the exposed or damaged areas are tabulated below. The arrangement of the tabulation also prioritizes the problem areas in descending order.

UCTC 06792

<u>Estimated Insulation</u>				
<u>Repair Required</u>				
<u>Priority</u>	<u>Location</u>	<u>Equipment(ft²)</u>	<u>Piping(Lin.ft)</u>	<u>Estimated Cost</u> <u>M\$</u>
1.	No. 2 Olefins	12,500	11,100	325.0
2.	Phenolic Resins (B-176) and Solvent Resins Piperack	240	2,210	56.4
3.	Bldg. 45	400	2,220	155.7
4.	Acids & Esters Bldg. 17	minor		
	Bldg. 21 and 24	2,818	690	80.2
	Bldg. 54	none	305	
5.	No. 3 Olefins	2,280	12,764	465.2
6.	Plant Piperacks	none	16,171	402.4
7.	OXO OXO Syn Gas (B-139 etc.) Bldg. 79 Bldg. 83		3,410 189 530	47.0
8.	E. O. D. Bldg. 51 Bldg. 219	minor 700	720 3,300	20.6 65.7
9.	Ethanol & DES	minor	1,420	47.2
10.	No.1 Steam Plant No.3 Steam Plant		719 295	68.2 18.2
11.	In-plant Distribution	none	1,233	26.2
12.	Pump Houses #4 #6 #7		105 35 27	<u>13.1</u>
Grand Total				1791.1

PAGE 5

The criteria used when prioritizing the potential asbestos problem areas are as follows:

1. Potential exposure of asbestos to plant personnel.
2. Potential for contaminating the community.
3. Exposed insulation which is highly visible and easily seen by the casual observer.

UCTC 06794

RECOMMENDATIONS

The overall action plan recommended is as follows:

1. As soon as possible (this year if possible) begin to correct the exposed asbestos containing insulation by, removing or covering the insulation using metal or mastic weather barriers at these "high priority" locations:
 - a. No. 2 Olefins
 - 1) The Firebird, exhaust duct, and Waste Heat Boiler.
Action: Remove.
 - 2) The three columns and associated equipment from the old butadiene (vinyl acetate and acetone recovery) unit. Action: Remove
 - 3) Flue gas breeching, cracking furnaces at building 105. Action: Remove.
 - 4) Dead 1 1/2" and 2" acetylene lines in 5th Street piperack. Action: Remove.
 - 5) Exhaust mufflers in building 103. Action: Mastic Coat.
 - 6) Pipelines where the insulation is intact but weather barrier has deteriorated. Action: Mastic Coat.

- b. Phenolic Resin Unit - Building 176
 - 1) Tanks and piping. Action: Remove.
 - 2) No. 70 Column Flask Tank. Action: Remove.
 - 3) Pipelines in piperack between buildings 122 and 176. Action: "Metal out" and/or Mastic Coat.
- c. Building 45 Hydrogen Converters.
 - 1) No. 3, 4, and 5 Hydrogenators. Action: Remove asbestos and re-insulate with non-asbestos.
 - 2) No. 1 and 2 Hydrogenators. Action: Install metal weather barrier.
 - 3) Piping. Action: Use metal or mastic weather barrier where insulation is intact.
- d. Building 24.
 - 1) Acid Still Fore column. Action: Remove.
 - 2) Acid Still. Action: Remove.
 - 3) Acid Refining Column. Action: Remove.
 - 4) No. 2 Esters Refining Still. Action: Remove asbestos insulation and replace with non-asbestos.
 - 5) Condensate Tank. Action: Remove asbestos insulation and replace with non-asbestos.
 - 6) 4: Dead Oxide Line. Action: Remove.

2. Each department including those not listed above will work out an action plan to correct the problem areas in their respective departments using the asbestos suspect survey data obtained by the inspection teams. The magnitude of the corrective work required for the entire plant precludes completion in one year. However department action plans should target for completion within a 2 to 4 year period.
3. Each department will include in their 1986 budget preparations funds for correcting their most obvious and/or greatest exposure potential areas.
4. Subsequent years budgets to include funds until resolution of the problem areas is completed.

DISCUSSION

Included in the appendix of this report is a tabulation of cost estimates for the various departments. These cost estimates were developed by the plant insulator group and have a +30% accuracy.

When planning repairs to the exposed asbestos insulation, the following guidelines are suggested.

1. Determine whether or not the insulation contains asbestos. If the insulation does not contain asbestos fibers, a decision to defer repair should be made. Economic considerations (energy conservation, production restraints, etc.) or safety considerations may result in a decision to go ahead with the repair anyway.
2. If the asbestos containing insulation is in poor condition (hanging loose, broken up, sagging, etc.), remove the old insulation and replace with asbestos free material.
3. If the weather barrier is in poor condition (or essentially gone), but the insulation itself is in fairly good condition:
 - a) Fill up the voids or breaks with non-asbestos filler if necessary.
 - b) Cover straight runs of piping with metal and/or mastic weather barrier.
 - c) "Mastic in" valves, 90° elbows, and other non-uniform sections.
 - d) Use a combination of metal or mastic weather barrier or columns and other equipment.
4. If the weather barrier has breaks, is damaged, or missing over short reactions repair using a generous coating of mastic.

5. If the insulation has "end or "edge" exposure, generously coat these exposed areas with an approved mastic. This treatment should be considered where "dead" or out-of-service piping or equipment has insulation which needs to be repaired.
6. If the asbestos containing insulation is in poor condition and is installed on "dead lines" or out-of-service equipment, remove and dispose this insulation.
7. Reference to the "Remarks" column of the inspection data sheets (Main Piperack Survey, Unit Equipment Survey, or Unit Piping Survey data sheets) will generally include comments on suggested repair.
8. Seek advice from the plant insulator group as required.

PAGE 11

HOUSEKEEPING

The entire plant places itself in a position of being open for censure from regulatory agencies when loose insulation is allowed to lie on the ground or has been left where it has fallen from equipment, piping, etc. Picking up and removing this insulation for disposal should be done on a continuing basis.

ASBESTOS IDENTIFICATION

Distinctive warning identification such as yellow adhesive backed film with black lettering is recommended for identifying asbestos containing insulation on equipment and pipe lines.

Pipelines in piperacks should be thusly identified approximately every 100 - 150 feet.

UCTC 06800

PAGE 12

ACKNOWLEDGEMENT

The response by the plant to the request for "walk through inspections" of the operating areas and the plant piperacks was outstanding. Suitable recognition of everyone who participated may be impossible. However, recognition of the following for their commendable support and effort is in order because without their help this project could not have gotten off the ground.

DEPARTMENT

INDIVIDUALS

Energy Systems

W. D. (Bill) Wilkins
W. N. Parker
R. A. Rivera
C. R. Malveaux
O. B. Hayden

Ethylene Oxide Derivatives

T. F. Hanrahan

No. 2 Olefins

T. W. Cates
Henry G. Parker

Ethanol and DES

F. G. McWhorter
J. A. McKenzie

Solvents and Acids

Frank L. Campbell
J. L. Lamb
J. B. Richards

In-Plant Distribution

J. L. Pedraza
B. C. Wedhorn

UCTC 06801

DEPARTMENT

INDIVIDUALS

Solvent Vinyls

D. B. Rygaard
W. E. Benskin
R. F. Garza
R. J. Hadley
R. Hernandez
H. Martinez
B. L. Nall
J. Nunez
E. K. Sumrall

Vinyl Acetate

Donald R. Kirkland

No. 3 Olefins

N. Dean Sharp
Roy M Hughes
O. T. Mallett
Angel Echevarria

OXO and OXO Syn Gas

Marcie Laundrie
Dan O'Neil
J. D. Duston
L. M Gonzalez

Industrial Hygiene

Kirk E. Martin
C. W. Perry
D. W. Harkreader

Also, the support and assistance received from the Insulator Craft group was outstanding. Special thanks and appreciation is due these people:

J. E. Barnes
H. P. Smith
H. G. Kelly Jr.
Keye Harding
D. R. Labry
P. J. Bartlett

July 19, 1985

COST ESTIMATES
PLANT ASBESTOS PROJECT

DEPARTMENT	AREAS INVOLVED	MATERIAL M\$	INSULATOR LABOR M\$	SUBTOTAL M\$	MISC AND ESCALATION M\$	TOTAL M\$
Energy Systems	Main Piperack	23.9	285.7	309.6	92.8	402.4
	No.1 Steam Plant	8.0	46.3	54.3	13.9	68.2
	No.3 Steam Plant	1.3	13.0	14.3	3.9	18.2
	Pump Houses	1.5	8.6	10.1	3.0	13.1
E. O. D.	Bldg. 51	1.0	15.1	16.1	4.5	20.6
	Bldg. 219	2.0	49.0	51.0	14.7	65.7
No.2 Olefins		18.0	236.2	254.2	70.8	325.0
Ethanol-D.E.S.	Bldg. 15	1.8	15.4	17.2	4.6	21.8
	Bldg. 94	2.2	17.9	20.1	5.3	25.4
Solvents and Acids	Bldg. 17	1.9	26.7	28.6	8.0	36.6
	Bldg. 21	--	1.5	1.5	0.5	2.0
	Bldg. 24	0.4	20.9	21.3	6.3	27.6
	Bldg. 54	0.4	10.4	10.8	3.2	14.0
In-Plant Distribution	Bldg. 19	9.7	12.5	22.2	4.0	26.2
Solvent Vinyls	Bldg.176 & P/R	2.4	41.5	43.9	12.5	56.4
Vinyl Acetate	Bldg.110 & 111	none	none	none	none	none
No. 3 Olefins		24.7	338.5	363.2	102.0	465.2
OXO-Syn Gas	Bldg. 45	3.0	66.7	69.7	20.0	89.7
	Bldg.45 Converters	9.3	43.6	52.9	13.1	66.0
	Bldg. 79	0.5	6.9	7.4	2.1	9.5
	Bldg. 83	0.5	14.9	15.4	4.5	19.9
	Bldg.282 (Syn Gas)	0.5	13.1	13.6	4.0	17.6
	GRAND TOTALS	113.0	1,284.4	1,397.4	393.7	1,791.1

(1) Escalated labor cost by 30% for scaffolding, asbestos disposal and contingencies.

UCTC 06803

INTERNAL CORRESPONDENCE

P. O. BOX 471, TEXAS CITY, TEXAS 77590

July 19, 1985

TO: P. D. Balmert
L. E. Calvert
S. J. Footer
R. W. Klein
R. A. Mendez
F. S. Provenzano
D. R. Reem

Gentlemen:

Attached is a copy of my memorandum "Plant Asbestos Project" for your comment and approval.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J. F. Schultz".

J. F. Schultz

UCTC 06787