



## **PURPOSE OF INSPECTION**

The purpose of the inspection by the U.S. Environmental Protection Agency (USEPA) at Terminal Ready Mix, Inc. (Terminal or Facility) was to describe, evaluate, and document compliance with the Clean Water Act (CWA) and their National Pollutant Discharge Elimination System (NPDES) permit.

## **BACKGROUND**

Terminal is a ready-mix concrete producer and concrete road paving contractor with 40 employees in Lorain, Ohio. Terminal is located on the Black River and receives bulk sand and stone material at the Facility via barge. Terminal also produces concrete onsite. Bulk sand and stone material are stored in piles both at the water level near the Black River and farther uphill near the concrete production area. Terminal samples their industrial storm water discharges from 2 onsite stormwater basins. These basins are covered by the Ohio Environmental Protection Agency (OEPA) Industrial Storm Water General Permit (Permit) (OEPA Facility ID # 3GR01276\*FG; Federal NPDES Identifier # OHR000006) which has an Effective Date of June 1, 2017. Permit # OHR000006 expired on May 31, 2022, and Terminal has 90 days from June 1, 2022 (the Effective Date of Permit # OHR000007) to submit a Notice of Intent (NOI) to OEPA to receive continued coverage under Permit # OHR000007. Terminal's industrial storm water discharges continue to be authorized under Permit # OHR000006 during this interim period.

## **INSPECTION**

Jake Berger and Anne Marie Vincent of USEPA first arrived at the Facility at 7:56 a.m. EDT and were met by John Falbo, Jr. (Vice President). Jake Berger and Anne Marie Vincent showed him their credentials and identification and were instructed to meet with Beth Mehal (Procurement and Compliance).

### Opening Conference

USEPA staff explained that the purpose of the inspection was to:

- Review Terminal's records, including sample measurements, monitoring activities, and storm water plans, as required by the Permit for Facility ID # 3GR01276\*FG;
- Conduct a walkthrough of the Facility;
- Identify locations where storm water control had the potential to be insufficient; and
- Inform Terminal of areas of concern regarding the records review and facility walkthrough.

## Records Review

USEPA began reviewing hard copy and electronic records provided by Terminal with Beth Mehal at 8:06 a.m. EDT. The following areas of concern were identified:

- Section 2.1.2.9 of the Permit requires Terminal to “train all employees who work in areas where industrial materials or activities are exposed to storm water, or who are responsible for implementing activities necessary to meet the conditions of this permit (e.g., inspectors, maintenance personnel), including all members of your Pollution Prevention Team. Training shall cover both the specific control measures used to achieve the conditions in this Part, and monitoring, inspection, planning, reporting, and documentation requirements in other parts of this permit. Ohio EPA requires that training be conducted at least annually.” Terminal has no records of providing any employee training related to storm water pollution prevention since 2016.
- Section 4.1.1 of the Permit requires Terminal to conduct Routine Facility Inspections of all areas of the Facility where industrial materials or activities are exposed to storm water and of all storm water control measures at least once each calendar quarter. Terminal has no record of ever performing these inspections.
- Section 4.2.1 of the Permit requires Terminal to conduct Quarterly Visual Assessments of storm water discharges. Terminal has no record of ever performing these inspections.
- Section 5 of the Permit requires Terminal to review and update their Storm Water Pollution Prevention Plan (SWPPP). Terminal’s most recent SWPPP was dated February 15, 2012, indicating that it had not been updated since the previous permit cycle (Permit # OHR000005).
- Section 5.1.7 of the Permit requires the SWPPP to be signed and dated by a responsible corporate officer. The 2012 SWPPP was not signed.
- Section 6.2.1.2 of the Permit requires Terminal to conduct Benchmark Monitoring of industrial storm water, take an average of the monitoring concentration values, compare these averages to the benchmark concentration, and take additional actions if the average monitoring values exceed the benchmark concentration. Terminal conducted this sampling but made no calculations of the average measured concentrations and did not compare their data to the benchmark concentrations. Therefore, Terminal never determined if they were meeting or exceeding the benchmark concentrations.

USEPA ended the records review by requesting that the following documents be provided electronically as soon as possible to USEPA after the inspection:

- Documentation or verification of Terminal’s NOI submission to OEPA to receive continued coverage under Permit # OHR000007; and

- Detailed drawings, maps, or diagrams showing the flow and conveyance of storm water across the site.

The records review portion of the inspection concluded at 10:19 a.m. EDT and was immediately followed by a Facility walkthrough tour with Beth Mehal.

### Facility Walkthrough

USEPA staff made the following observations during the Facility walkthrough, further documented in the Photograph Log (attached):

- Dandy bags covering the inlets to the storm water basins appeared to not be regularly maintained, as sediment build-up has occurred (Photo 3, Photo 4, and Photo 13).
- Excess sediment accumulation is occurring at the sediment trap (Photo 5).
- Material piles of stone and sand in the lower material storage area do not have any containment (Photo 8 and Photo 17).
- Containers of additive mixture and wash mix do not have secondary containment (Photo 10 and Photo 11).
- Water flowing from the rock channels near Basin A is coming from an unknown pipe and continues down to the lower material storage area (Photos 14 – 16).
- There is no containment or management of storm water that comes in contact with the stone and sand piles in the lower material storage area. Sediment runoff and erosion into the Black River is evident (Photos 17 – 20).
- Storm water is seeping from the retaining wall beneath Basin B and is flowing across the lower material storage area towards the Black River.

The Facility walkthrough tour ended at 12:12 p.m. EDT and was immediately followed by the closing conference.

### Closing Conference

USEPA staff relayed the following preliminary comments to John Falbo, Jr. and Beth Mehal during the closing conference:

- Storm water pollution prevention training is required annually for all on-site employees, which has not been conducted in several years according to Beth Mehal.
- Routine Facility Inspections are to be conducted once per calendar quarter.
- Quarterly Visual Assessments are to be conducted once per calendar quarter.

- The SWPPP must be reviewed, updated, and signed by a responsible corporate officer at least once per permit cycle.
- Benchmark Monitoring results are required to be averaged and compared to the benchmark concentration values to determine if additional actions are necessary.
- Terminal needs to submit their NOI to OEPA to receive continued coverage for industrial storm water discharges under Permit # OHR000007, if they have not done so already.
- Deficiencies were observed during the Facility walkthrough, such as general housekeeping of sediment and dandy bags, containment of materials, lack of secondary containment for liquid storage totes, the flow seeping out of the hillside near Basin A, the lack of erosion control and runoff prevention near the large material piles at the water level, and the failed retaining wall beneath Basin B.

USEPA confirmed that no information collected during the inspection was considered Confidential Business Information.

USEPA concluded the inspection and left the Facility at 12:58 p.m. EDT.

**Terminal Ready Mix  
EPA Inspection 6/22/2022  
All photos taken by Jake Berger, Physical Scientist, U.S. EPA  
Camera: Olympus Tough TG-6**



1: P6220001

Description: Basin A

Location: Upper area near material storage and cement production

Camera Direction: South

Date/Time: 6/22/2022 – 10:34 a.m. EDT

\* Photograph time stamps are in Central Daylight Time due to camera settings, actual time of photograph is noted in the caption below each image.



2: P6220002

Description: Basin A overflow structure

Location: Upper area near material storage and cement production

Camera Direction: North

Date/Time: 6/22/2022 – 10:38 a.m. EDT



3: P6220003

Description: Catch basin inlet sediment bag

Location: Front driveway

Camera Direction: South

Date/Time: 6/22/2022 – 10:41 a.m. EDT



4: P6220004

Description: Catch basin inlet

Location: Front driveway

Camera Direction: Southwest

Date/Time: 6/22/2022 – 10:44 a.m. EDT



5: P6220005

Description: Sediment trap

Location: Front driveway

Camera Direction: Northeast

Date/Time: 6/22/2022 – 10:50 a.m. EDT



6: P6220006

Description: Truck rinse and exterior spray rack station

Location: Front driveway

Camera Direction: Northwest

Date/Time: 6/22/2022 – 10:53 a.m. EDT



7: P6220007

Description: Stone and sand piles

Location: Upper material storage area

Camera Direction: Southwest

Date/Time: 6/22/2022 – 10:59 a.m. EDT



8: P6220008

Description: Property edge along Black River; lower material storage area

Location: Edge of upper material storage area

Camera Direction: Southeast

Date/Time: 6/22/2022 – 11:09 a.m. EDT



9: P6220009

Description: Additive mixture for concrete

Location: Upper material storage area

Camera Direction: West

Date/Time: 6/22/2022 – 11:13 a.m. EDT



10: P6220010

Description: Tote of concrete additive mixture with no secondary containment

Location: Upper material storage area

Camera Direction: North

Date/Time: 6/22/2022 – 11:15 a.m. EDT



11: P6220011

Description: Wash water additives for truck exteriors

Location: Upper material storage area

Camera Direction: East

Date/Time: 6/22/2022 – 11:16 a.m. EDT



12: P6220012

Description: Basin B (overflow outlet is overgrown and not visible).

Location: Upper material storage area

Camera Direction: West

Date/Time: 6/22/2022 – 11:19 a.m. EDT



13: P6220013

Description: Dandy bag in catch basin

Location: Concrete production area

Camera Direction: Northwest

Date/Time: 6/22/2022 – 11:23 a.m. EDT



14: P6220014

Description: Basin A rock channel #1

Location: Driveway down to lower material storage area

Camera Direction: Northwest

Date/Time: 6/22/2022 – 11:32 a.m. EDT



15: P6220015

Description: Basin A rock channel #2

Location: Driveway down to lower material storage area

Camera Direction: West

Date/Time: 6/22/2022 – 11:33 a.m. EDT



16: P6220016

Description: Flow path from rock channel #2

Location: Driveway down to lower material storage area

Camera Direction: South

Date/Time: 6/22/2022 – 11:35 a.m. EDT



17: P6220017

Description: Sand pile near the shoreline of the Black River

Location: Lower material storage area

Camera Direction: South

Date/Time: 6/22/2022 – 11:46 a.m. EDT



18: P6220018

Description: Stone pile and shoreline

Location: Lower material storage area

Camera Direction: West

Date/Time: 6/22/2022 – 11:49 a.m. EDT



19: P6220019

Description: Lower material storage area along south side of property/Black River shoreline

Location: Lower material storage area

Camera Direction: North

Date/Time: 6/22/2022 – 11:54 a.m. EDT



20: P6220020

Description: Erosion rills along south edge of property and the Black River shoreline

Location: Lower material storage area

Camera Direction: South

Date/Time: 6/22/2022 – 11:57 a.m. EDT



21: P6220021

Description: Retaining wall seepage below the backside of Basin B, located above/uphill

Location: Lower material storage area

Camera Direction: East

Date/Time: 6/22/2022 – 12:04 p.m. EDT



22: P6220022

Description: Flowpath of sediment seeping from retaining wall

Location: Lower material storage area

Camera Direction: Southeast

Date/Time: 6/22/2022 – 12:04 p.m. EDT