

cc: WAB-4
EAB-1
WAB-1
AAW-1 ✓
N5771302-1

PLAINTIFF'S EXHIBIT

BAB-402

June 28, 1955

Mr. J. A. Smith, Chief Coordinator
Phasco Services, Inc.
Two Rector Street
New York 6, New York

North Denver 100,000 AM Repeat

Dear Sir:

We reply to Mr. Bennett's June 17, 1955 letter, etc.
relative to arrangement to accommodate future electrostatic dust
collector.

Of the several arrangements we believe that the electro-
static should be located immediately following the dust collector
so that it will have the full benefit of uniform gas velocity thru-
out its vertical cross section. This uniform velocity is first
established by the tubular air heater and then later by the particular
arrangement of the new 5 inch aerotec dust collector. Should the
precipitator be located on the outlet of the induced draft, highly
stratified gas velocities result that are difficult to iron out,
especially if further pressure drop occasioned by a velocity equalizer
device is to be avoided.

We also believe that precipitator performance is not affected
whether it operates at a negative pressure or at a positive pressure,
but uniform gas velocities are essential in both cases.

Since we are locating the dust collector immediately follow-
ing the air heater, the precipitator should then next follow it.

Therefore we desire the 181 alternate arrangement which has
been estimated by B & W Company, and adjusted by you to about \$23,000
before erection and fee. This estimate should be checked by you as
the indicated drawing weights are about 52,000 lbs. indicating in turn
a rather high unit cost including insulation, based by us at 15¢ for
steel and 30¢ per sq. ft. for insulation. An inconsistency appears to
us in that B & W cost implies a cost of about \$190 ft. run of additional
and small sized ductwork of about 143 ft. at about \$27,000 whereas your
estimate for 24 ft. run of much larger breeching at \$5500 is \$230 per
ft. run. Either B & W is high or you are low.

WAD00046

J. A. Smith - Chasco Services, Inc.

Could you also review the orientation of the induced draft fan as the gas approach is rotating opposite to the rotor rotation. Therefore we believe that the fan should be turned end for end.

D & V layout can be improved as to the location of the gas recirculation fan and its source of gas supply. By locating it at the outside of either induced draft fan rather than in the middle, the gas can be accepted by it so that no north-south run of gas recirculation fan discharge duct is required before the duct takes the east-west run toward the boiler.

Altho neither of the drawings forwarded reveal the breeching route to the stack it appears that the basic view continues of a single large sized opening serving two boilers. We are agreeable to this view in which case we presume that said opening will be on the west side of the stack.

Yours very truly,

PUBLIC SERVICE COMPANY OF COLORADO

R. F. Thorne
Chief Mechanical Engineer

RFT/lf

WAD00047