

U.S. DEPARTMENT OF LABOR
BUREAU OF LABOR STANDARDS
Office of Occupational Safety
Room 601, 411 N. Akard Street
Dallas, Texas 75201

April 8, 1969

Mr. James H. Biorer, President
Pittsburg Corning Corporation
1 Gateway
Pittsburg, Pennsylvania

Dear Mr. Biorer:


(A recent survey of your establishment revealed that certain conditions did not meet the Safety and Health Requirements of the Walsh-Healey Public Contracts Act.)

The Act stipulates that "No part of such contract will be performed nor will any of the materials, supplies, articles or equipment to be manufactured or furnished under said contract, be manufactured or fabricated in any plants, buildings or surroundings or under working conditions which are unsanitary or hazardous or dangerous to the health and safety of the employees engaged in the performance of the contract."

Enclosed is a notice listing those unsatisfactory conditions found, and you should take corrective action immediately.

You are requested to notify me on or before the compliance date on the notice concerning action taken to correct the unsatisfactory conditions.

Sincerely yours,



Wendell R. Blair
Regional Director

Enclosure

cc: Mr. Charles Van Horne, Wks. Manager, Denton, Texas

THIS DOCUMENT WAS NOT A RECORD OF
PPG INDUSTRIES, INC. DID NOT COME FROM
IT'S FILES AND CANNOT BE AUTHENTICATED
BY PPG INDUSTRIES, INC.

19761
BB 0008422 1

U.S. DEPARTMENT OF LABOR
BUREAU OF LABOR STANDARDS

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

NOTICE OF
SAFETY AND HEALTH VIOLATIONS

NAME OF FIRM Pittsburg Corning Corporation					CONTRACT NUMBER	
STREET ADDRESS Box 3057 - Tyler, Texas		CITY Owentown	COUNTY Smith	STATE Texas	ZIP 75701	
OFFICIALS CONTACTED - NAME AND TITLE Charles E. Van Horne, Wks. Manager			PLANT SURVEY MADE WITH Mr. Van Horne		COMPLIANCE DATE	
			REPORT FURNISHED TO James H. Bierer, President		May 8, 1969	
			USDL SAFETY ENGINEER M. Padilla, Industrial Hygienist		DATE OF SURVEY 2/13/69	
A SURVEY OF YOUR FACILITIES HAS REVEALED CONDITIONS WHICH DO NOT COMPLY WITH USDL SAFETY AND HEALTH REQUIREMENTS UNDER THE PUBLIC LAW CHECKED.					PUBLIC LAW - 74-848 WALSH-HEALEY PUBLIC CONTRACTS ACT	
THE CONDITIONS ARE LISTED BELOW WITH REFERENCE TO CODES AND STANDARDS WHICH HAVE BEEN ADOPTED AS THE DEPARTMENT'S SAFETY AND HEALTH REQUIREMENTS.					PUBLIC LAW 89-286 MCNAMARA-O'HARA SERVICE CONTRACTS ACT	
THESE UNSATISFACTORY CONDITIONS MUST BE CORRECTED. PLEASE ADVISE REGIONAL DIRECTOR <u>Wendell R. Blair</u> ON OR BEFORE <u>May 8, 1969</u> AS TO THE CORRECTIVE ACTION TAKEN.					PUBLIC LAW - 89-209 ARTS AND HUMANITIES ACT	
					PUBLIC LAW 89-333 VOCATIONAL REHABILITATION ACT	

NO.	CODE-STANDARD REFERENCE	CORRECTIONS REQUIRED
		UNSATISFACTORY CONDITIONS NOTED ON INDUSTRIAL HYGIENE SURVEY OF 2/13/69
1	50-204.264	Process Area No certified first aiders. Ex: Recommend that several employees be trained so that each shift will have qualified personnel to take care of emergencies.
2	50-204.275, Ind. Vent. ACGIH 5-98	Local exhaust ventilation not according to standards. <i>WHAT ARE THE STANDARDS?</i> Ex: Local exhaust ventilation system was tested with the following findings: a. Grinder hood, 25-50 fpm at face. b. Feeder at material point of entry, 50 fpm. <i>66-1970</i> c. Scrap feeder at material point of entry, 50 fpm. d. Sewing ducts 500 fpm at face. Recommend that employer make a study of present local exhaust ventilation with professional advice, to come up to standard. <u>It is believed that present system is below the required capacity.</u> <i>(1) ACCORDING TO PAR. 50-204.275, IF AN EMPLOYEE IS WEARING AN APPROVED RESPIRATOR IN AN EMPLOYER'S SHOP, THE CC. IS NOT IN VIOLATION. OUR EMPLOYEES USE RESPIRATORS IN ALL DUST AREAS</i> <i>(2) I HAVE NO REFERENCE IN MY COPY OF THE WALSH-HEALEY PUBLIC CONTRACTS ACT (SECTION 1) OF SUGGESTED SUCTION VELOCITIES OR RATES.</i> <i>(1) ARRANGEMENTS WERE MADE...</i>

BB 0008423 1

PITTSBURGH CORNING CORPORATION

April 11, 1969

Mr. Wendell H. Blair, Regional Director
 U. S. Department of Labor
 Bureau of Labor Standards
 Office of Occupational Safety
 Room 601
 411 North Second Street
 Dallas, Texas 75201

NOTE: THIS DOCUMENT DID
 NOT COME FROM PPG FILES

Subject: Letter of 4/3/69 to Mr. J. H. Sierer, President,
 Pittsburgh Corning Corporation.
Re: Survey Plant - Tyler, Texas - 2/13/69

Dear Mr. Blair:

The following action is being taken to correct the occupational safety conditions noted in the report dated February 13, 1969.

1. Safe Standards - Ref. 50-204,264.

All supervisory employees were enrolled in a first aid course given by the American Red Cross with the first session given 4-10-69. The course is to consist of three sessions and by 5-20-69 there will be fully qualified personnel on all shifts.

2. Dust Sampling - Ref. 50-204,275.

Pittsburgh Corning Corporation uses the services of Dr. E. Grant, M.D., Medical Director, PPG Industries, and his staff, to monitor its production facilities for compliance with A.C.C.P.A. threshold limits for dust concentrations. (See attachments II and III). In addition, the Industrial Hygiene Foundation conducts periodic dust measurements to ascertain the dust concentrations present. (See attachment I).

For those areas in which dust concentrations exceed the threshold limits, it is required, as a condition of employment, that each employee wear a dust free 55 Respirator 604-72010 approved by the U. S. Bureau of Mines.

6-6-1976

BB 0008424

Mr. W. H. Blair

April 11, 1969

2. Corn Standard (continued)

In reference to the sentence of your report where you state, "It is believed that the present system is below the required standard", the dust research data do not support this belief. Since PPG Industries Corporation retains the services of Dr. Milton Corn, a consulting engineer and authority in the field of industrial hygiene and air pollution, Dr. Corn approves all new installations as well as any modifications of our dust collecting systems.

If you should need any additional information or there is need for additional surveys, please advise.

Yours very truly,

PITTSBURGH CORNING CORPORATION

Ryle Hunt
 Ryle M. Hunt
 Vice President of Manufacturing

Attn:
 J.H.A.

cc: Mr. James H. Liferer
 Mr. L. B. Green
 Mr. J. Clark Henderson
 Mr. C. E. von Horn

NOTE: THIS DOCUMENT DID
 NOT COME FROM PPG FILES

BB 0008425

66-19764

MORTON CORN, PH.D., B. CH. E.
CONSULTING ENGINEER
310 BOWER HILL ROAD
PITTSBURGH, PENNSYLVANIA 15228

INDUSTRIAL HYGIENE
AIR POLLUTION

TELEPHONE
412 - 861 6237

May 1, 1969

Mr. Wendell R. Blair, Regional Director
U. S. Department of Labor
Bureau of Labor Standards
Office of Occupational Safety
Room 601
411 North Akard Street
Dallas, Texas 75201

Subject: Letter of 4/8/69 to Mr. J. H. Bierer, President,
Pittsburgh Corning Corporation.

Re: Survey Plant - Tyler, Texas - 2/13/69

Dear Mr. Blair:

I am writing to clarify the letter from Byrl M. Stout,
Vice President of Manufacturing, Pittsburgh Corning Corporation
to you dated April 11, 1969.

I have been working with Pittsburgh Corning Central
Engineering engineers on dust control in their Port Allegheny,
Pennsylvania Works. The manufacturing operation in this plant
is similar to that in the Tyler, Texas Plant. We are installing
an entire ventilation system and dust collectors at Port
Allegheny.

However, it should be noted that I have never visited or
surveyed the Tyler, Texas Plant of this Corporation. I first
saw the letter from Mr. Stout to you on April 28, 1969. At
that time, Mr. Stout suggested that I visit the Tyler Plant and I
was scheduled to do so on May 7, 1969. I have just assured
that all the engineering skills which have been brought to
on the Port Allegheny Plant dust control system will be focused
on the Tyler Plant.

Sincerely yours,

Morton Corn, Ph.D.

cc: Dee E. Grant, M.D.
Byrl Stout

66-19765

BB 0008426

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

APPENDIX B

DUCT VELOCITY DETERMINATIONS
(Primary Data and Calculations)

1976

BB 0008427

PITOT TUBE TRAVERSE
Duct 1 (17" Line)

In front of 40" feeder, Line #1, feeds from Lines 1, 2, 3 before blower.

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/2	0.00	0.000	0
2	1 3/8	-0.04	-0.200	-801
3	2 1/2	0.16	0.400	1602
4	3 7/8	0.32	0.566	2267
5	5 3/4	0.44	0.663	2655
6	11 1/4	0.60	0.774	3100
7	13 1/8	0.58	0.762	3052
8	14 1/2	0.48	0.693	2775
9	15 3/8	0.20	0.447	1790
10	16 1/2	0.08	0.283	1133
Totals			4.388	17573
Averages			0.439	1757

$$Q = 2769 \text{ cfm}$$

PITOT TUBE TRAVERSE
Duct 2 (5" Line)

$$VP \text{ Centerline} = 0.02 \text{ "H}_2\text{O}; V = 566 \text{ fpm}$$

$$Q = 63 \text{ cfm}$$

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

1976

BB 0008428

PITOT TUBE TRAVERSE
Duct 3 (6" Line)

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/8	1.20	1.095	4385
2	1/2	1.15	1.072	4293
3	7/8	1.10	1.049	4201
4	1 3/8	0.80	0.894	3580
5	2	0.52	0.721	2888
6	4	0.00	0.000	0000
7	4 5/8	0.02	0.141	565
8	5 1/8	0.00	0.000	0000
9	5 1/2	0.00	0.000	0000
10	5 7/8	0.00	0.000	0000
		Totals	4.974	19913
		Averages	0.497	1991

$Q = 391 \text{ cfm}$

PITOT TUBE TRAVERSE
Duct 4 (4" Diam)

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/8	0.2	0.447	1790
2	1/2	0.2	0.447	1790
3	2	0.7	0.837	3352
		Totals	1.731	6932
		Averages	0.577	2311

$Q = 202 \text{ cfm}$

66-19768

BB 0008429

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE
Duct 5 (12" Diam)

12" Duct, Line 1 + 2 main leading to 17" main

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	VP	Air Velocity (fpm)
1	3/8	0.28	0.529	2119
2	1	0.34	0.583	2335
3	1 3/4	0.36	0.600	2403
4	2 3/4	0.36	0.600	2403
5	4 1/8	0.38	0.616	2467
6	7 7/8	0.40	0.632	2531
7	9 1/4	0.42	0.648	2595
8	10 1/4	0.44	0.663	2655
9	11	0.44	0.663	2655
10	11 5/8	0.40	0.632	2531
		Totals	6.168	24695
		Averages	0.617	2470

Q = 1940 cfm

66-19769

BB 0008430

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE
Duct 6 (6" Diam)

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/8	0.04	0.200	801
2	1/2	0.06	0.245	981
3	7/8	0.08	0.283	1133
4	1 3/8	0.10	0.316	1266
5	2	0.10	0.316	1266
6	4	0.06	0.245	981
7	4 5/8	0.06	0.245	981
8	5 1/8	0.04	0.200	801
9	5 1/2	0.02	0.141	565
10	5 7/8	0.02	0.141	565
		Totals	2.333	9339
		Averages	0.233	934

$$Q = 183 \text{ cfm}$$

66-19770

BB 0008431

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE
Duct 7 (6" Diam)

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/8	1.12	1.058	4237
2	1/2	1.26	1.122	4494
3	7/8	1.26	1.122	4494
4	1 3/8	1.28	1.131	4530
5	2	1.26	1.122	4494
6	4	1.32	1.149	4602
7	4 5/8	1.34	1.158	4638
8	5 1/8	1.30	1.140	4566
9	5 1/2	1.22	1.105	4426
10	5 7/8	1.08	1.039	4161
		Totals	11.148	44640
		Averages	1.115	4464

$$Q = 877 \text{ cfm}$$

CG 19771

BB 0008432

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE
Duct 8 (11" Diam)

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/4	0.24	0.490	1962
2	7/8	0.28	0.529	2119
3	1 5/8	0.32	0.566	2267
4	2 1/2	0.34	0.583	2335
5	3 3/4	0.38	0.616	2467
6	7 1/4	0.42	0.648	2595
7	8 1/2	0.42	0.648	2595
8	9 3/8	0.40	0.632	2531
9	10 1/8	0.86	0.927	3713
10	10 3/4	0.78	0.883	3536
		Totals	6.523	26121
		Averages	0.652	2612

Q = 1724 cfm

BB 0008433

GG-19772

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE

17" Duct in Saw Area: Main Duct into Dust Collector

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/2	0.44	0.663	2655
2	1 3/8	0.46	0.678	2715
3	2 1/2	0.68	0.825	3304
4	3 7/8	0.74	0.860	3444
5	5 3/4	0.80	0.894	3580
6	11 1/4	0.82	0.906	3629
7	13 1/8	0.70	0.837	3352
8	14 1/2	0.66	0.812	3252
9	15 5/8	0.72	0.849	3400
10	16 1/2	0.48	0.693	2775
		Totals	8.017	32108
		Averages	0.802	3211

Q = 5061 cfm

GG 19773

BB 0008434

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

PITOT TUBE TRAVERSE

10" Duct into Block Dust Collector

Point	Position (inches from wall)	Velocity Pressure (VP) ("H ₂ O)	$\sqrt{VP}$	Air Velocity (fpm)
1	1/4	1.66	1.288	5158
2	7/8	1.66	1.288	5158
3	1 1/2	1.50	1.225	4906
4	2 1/4	1.40	1.183	4738
5	3 3/8	1.26	1.122	4494
6	6 5/8	0.74	0.860	3444
7	7 3/4	0.70	0.837	3352
8	8 1/2	0.70	0.837	3352
9	9 1/8	0.82	0.906	3629
10	9 3/4	0.84	0.917	3673
		Totals	10.463	41904
		Averages	1.046	4190

$$Q = 2285 \text{ cfm}$$

GG 19774

BB 0008435


NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES

APPENDIX C

PHOTOGRAPHS OF SELECTED PLANT OPERATIONS.

66-19775

| BB 0008436 |



Lines 1 and 2 Feeders Showing Method
of Emptying Bag

NOTE: THIS DOCUMENT
NOT COME FROM PPG FILES



Line 2 Feeders and Bag Collector (Note
Cart for Scrap Feed)

66-19776

| BB 0008437 |



Close up of scrap feed and bag collector
(Line 2) note axial fans directed at carts
and feeder hoods.




Scrap cutter hood and dust collector

NOTE: THIS DOCUMENT DID
NOT COME FROM PIG FILES


66-1977

| BB 0008438 |



Dust collector for scrap hood and feeders (Line 1-3), showing scrap hood entry closest to blower intake.


NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES



Builder on Line No. 2


19778

BB 0008439



Large cutting saw showing hoods

NOTE: THIS DOCUMENT DID
NOT COME FROM PPG FILES



Cutting area dust collector and
two saws with attached hoods

66-19779

| BB 0008440 |



Cutting saw, dust collector
and blower (close up)

NOTE: THIS DOCUMENT DID
NOT COME FROM PPO FILES

NOT COME FROM PPO FILES

19780

BB 0008441