

INTER-OFFICE CORRESPONDENCE

To MR. J. R. HILT
NAME LOCATION
 Date DECEMBER 10, 1981
 From D. M. CONNOR
NAME LOCATION
 Subject VINYL CHLORIDE SAFETY ASSOCIATION MEETING,
HILTON HEAD, SC, SEPT. 24 AND 25, 1981
 Copy to:

Hooker Chemical

PLASTICS DIVISION

RECEIVED

DEC 15 1981

J. A. KING

R. W. Arnold	F. F. Hoy
S. P. Dominick	J. A. King
H. Dubec	C. J. Kleinert
K. H. Garner	T. Nasife
M. W. Handler	R. J. Schuttler

There were 61 attendees, representing 31 companies. Three new companies were admitted this year. (Solvay, Tallyrand Chemicals of New Bedford, Mass., and an Iraqi company.) The association now consists of 46 member companies of which 25 are from the United States. Six earlier members no longer produce PVC or VCM.

As a brief historical review, the VCSA was organized in 1970 with the objective of accident prevention in the PVC and VCM industries by exchanging information on the hazards, safety and use of VCM. There have been a total of 18 meetings. During the mid 70's meetings were held semi-annually to discuss the regulatory rules and interpretations as well as the common safety problems. The association has returned to meeting on an annual basis. There is widespread belief that the VCSA has fulfilled a major role in accident prevention.

I. True Confessions and Incidents

1. Explosion in a Furan-Lined Process Sewer - John McCully, Conoco

This occurred at their VCM plant at Lake Charles, LA, during a maintenance shutdown in a furan-lined gravity drain pipe from towers and other process equipment to an underground tank. There were no injuries or fire. The system was not well grounded, the influent was above the liquid level, there was air in the vapor space and the liquid contained traces of peroxide. Their corrective actions include pH control, relocating the inlet nozzle and a nitrogen purge. They could not determine the exact cause but they were not able to generate a static electrical buildup in the lined pipe.

OCC 2989

2. Control Room/Laboratory Explosion - Bob Oubri, Dow

The incident occurred at their Saskatchewan, Canada VCM plant on May 27, 1981. A badly leaking ball valve on a caustic scrubber drain line allowed liquid VCM to flow into a 4" underground drain pipe. The vinyl fumes backed up into the laboratory through a floor drain even though there were liquid traps. The lab was not x-proof and was located adjacent to the control room separated by a cinder block wall.

Ignition occurred and the blast burned 4 of 5 employees who had evacuated the lab due to the fumes. There was very extensive roof damage, the lab was demolished, the cinder block wall was destroyed and the control room was severely damaged.

They have isolated their sewer lines and initiated blank-out procedures for the caustic drain line. There was an OSHA inspection and investigation with no citation.

3. Nitrogen Inhalation Incident - Glen Schaaf, BFG

This occurred at their bulk PVC plant in Pedricktown, NJ. The post-polymerization reactor was taken out of service for maintenance to enter and repack the stuffing box. The nitrogen was not exhausted from the reactor and the vessel was not checked for O₂ or VCM content. The operator fudged the Reactor Entry Sheet. The maintenance man entered the vessel with no respirator or harness. The first indication of a problem was when the 3-minute alarm activated and was not silenced. Typically, the person in the vessel must silence the alarm at 3-minute intervals. Fortunately, they were able to rescue and revive the employee. Both employees had 10-12 years experience and were considered very good performers with excellent safety records.

BFG was proud of their vessel entry procedure but a survey indicated that it was not being followed. This is now a "serious" violation and cause for discharge. They are trying to re-educate their employees, increase commitment to knowing and following procedures and increase awareness toward correcting unsafe acts of others.

4. Lauroyl Peroxide Fire - Ron Kaminski, BFG

This occurred at their bulk PVC plant in Plaquemine, LA. Contrary to procedure, the empty reactor was at 80°C jacket temperature when the lauroyl peroxide was charged. As the operator bent over to install the manhead "O"-ring, the lauroyl peroxide spontaneously decomposed and the ensuing flash burned the operator over 25% of his body, requiring five weeks of hospitalization. The flame extinguished within seconds.

The direct cause was operator error in not cooling the reactor jacket. They have changed procedures to minimize chance of reoccurrence.

Lauroyl peroxide is considered to be a very safe catalyst. This is only the second known case of an incident with lauroyl peroxide in 30+ years of industrial use.

5. Explosion in EDC Waste Gas Decomposer - Glen Schaaf, BFG

This occurred in Convent, LA during various stages of a plant start-up when the process was upset. The decomposer column was about two feet diameter and about 15 feet high. The level alarm was out of service and the decomposer was operating at a high draw-off rate. A detonation of explosive gas mixture occurred in the top of the column which blew the top, severed an EDC line and caught fire. Two employees were injured. They felt that this was a major explosion and fire.

They speculate that nitrogen trichloride or chlorine oxide formed in the head space. Both are unstable with high energy release. As a corrective action, they are going to a liquid-full system with modifications to prevent gas accumulation.

6. Amoco Polypropylene Plant Fire - Darwen Rhoads, Tenneco

This was discussed because propylene and vinyl chloride both have potential for severe detonation.

The Amoco Delaware plant was built in 1961 and had a capacity of 270 MM lbs/year. There were three reactor trains with ~ 50 feet separation. The reactors were 10,000 gallon.

Four mechanics were forced to work overtime to unplug the 4" diameter recirculation line which goes from the bottom of the reactor through a pump and heat exchanger to the top nozzle. There is an automatic valve on the recirculation line at the top of the reactor. The mechanics removed the wrong set of nuts while trying to disconnect the valve actuator. This allowed the plug of the Tufline valve to blow out, resulting in a vapor cloud of propylene and hexane which subsequently ignited. A schematic of the valve is shown as Attachment I.

There were some contributing factors in addition to human error.

- The valve design was not consistent between the top and bottom of the reactor.

- Tufline had redesigned their valve to prevent the booby trap but the redesigned version was not installed.
- The mechanics forced to work overtime were the ones least familiar with the procedures involved.

In the explosion, six people died, twenty-eight were injured, damage was 65 \$MM and 200 jobs were lost.

II. Special Reports

1. Reactor Lockout Device - Glen Schaaf, BFG

A BFG task force reviewed VCM release incidents for the past 10 years, excluding relief valve venting.

While charging	-	19 incidents
During reaction	-	12 "
While blowing down	-	17 "
Total		48 incidents

The task force felt that a lockout device would be 75 percent effective in preventing incidents with non-computer controlled reactor plants.

They have designed a key interlock system and will evaluate it on a prototype basis. The key station ties together the VCM charge valve, the manhead and the drain valve with the reactor pressure signal such that an operator cannot inadvertently open the wrong reactor. The prototype uses Best Manufacture lock system at a cost of 1000-1500 \$/vessel.

Castell Safety Inc. has a commercial valve interlocking system. ICI has used Castell for many years on reactors, tank car unloading, etc. They claim that it is very reliable but requires good maintenance. PFG commented that Kirk Locks also has a commercial system.

2. Small Reactor Plant Safety Survey - Jerry Brumbaugh, General Tire

Attachment II summarizes the responses from 20 plants in the survey that had been previously conducted by mail. There was a wide variety of opinion and some misunderstanding of questions. However, the recurring theme of responses was that procedures should be up-to-date and followed and the operating personnel must be well-trained.

One item of interest was that only 3 of 20 respondents distill their recovered VCM prior to reuse.

Another general comment was that trying to be too sophisticated can lead to trouble.

The survey covered only PVC plants in the U.S. In the future, the foreign manufacturers will also be included in any surveys.

3. Operator Training Survey Report

Responses to the questionnaire from the U.S. PVC manufacturers were presented and discussed. Again, the main theme was that operator training is considered to be very important, but there was very little uniformity in how the training was conducted. The summaries of the 32 respondents are shown as Attachment III.

4. Implementing an Effective Plant Safety Program - Steve Broulliard, Diamond Shamrock

This was a summary of the safety programs at their Independence VCM plant since their 1978 start-up. In essence, their requirements for an effective program are:

- Management support by day-to-day active participation
- People selection and new employee orientation
- Best available technology on plant and equipment
- Grass-roots support of the programs

5. Computer Safety Survey - Jim Gabbett, Georgia-Pacific

There were 6 respondents to the Computer Plant Questionnaire which had been previously submitted. The important points were:

- Four of the plants have independent computer and manual backup
- Information overload in the form of excessive messages and alarms from the computer is a common problem
- In general, the respondents did not appear to have other common problems
- Different operating philosophies are evident in the answers

Comments in reference to the Georgia-Pacific plant:

- Prior to charging, the computer selects a reactor (1 of 12), shows plant status, shows reactor status, shows recipe code, shows product number and calls up the recipe. Then verifies "Go".
- They have two operators and one technician on the panel at all times.
- They use the Taylor 1010 with TABL (Taylor Advanced Batching Language).
- Georgia-Pacific recently went to "closed mode" on their reactors.

Some incidents at computer operated plants were described:

1. At Georgia-Pacific

- a) The operator selected an incorrect reactor number and told the computer to drop a live batch.
- b) When this did not happen, the operator asked the computer for verification and this time, he punched in the correct reactor number.
- c) The computer verified ok to drop for that reactor.
- d) Thinking that the dump valve was stuck, the operator went to the wrong reactor, removed the cap from the I/P converter which controlled the dump valve position and manually opened the valve. The live batch still had $\approx$ one hour left in its cycle.
- e) The unexpectedly high pressure blew the top of the strainer $\approx$ 50 feet into the air but fortunately no one was injured.

2. At Georgia-Pacific

A computer malfunction caused the operator to go from "computer" to "panel" mode. The computer problem was traced to a circuit board which was replaced. When the operator went back to "computer", simultaneously valves went to the open position ejecting VCM at 6000 lbs/minute through an opened reactor. The operator quickly returned to "panel" and used the panel pushbuttons to close the valves and secure the leak.

Uncertain on what had happened, the operator returned to "computer" control and again VCM surged through the open reactor. It was finally determined that the Master Mode switch was defective preventing the computer from coming on-line.

OCC 2994

3. At Air Products, the situation occurred where the computer was printing only gibberish.
4. At Tenneco, a faulty card opened the VCM valve going into an open reactor. This bled down the line but the charge pump was not running so there was no continuing large emission.
5. ICI comments:
 - All software changes are done formally.
 - They have had only 20 minutes of computer downtime in 18 months.
 - Their program includes a phantom reactor for problem simulation and training at the control room.

The detailed responses to the computer survey are shown as Attachment IV.

6. VCM Safety Condensation System - B. Terwiesch, C. W. Huls

The process was devised because of concern with runaway reactions in their 200 M² reactor ($\approx$ 150,000 lbs. VCM per batch). They developed a stepwise procedure independent of electrical service to protect against explosion, avoid VCM emissions and have no adverse effect on properties.

The procedure consists of a 20 minute intermittent let down of vapors from the top of the reactor, through a foam trap and condenser and ultimately, into a VCM accumulator. Cooling water is supplied to the condenser by gravity from a large elevated storage tank. The system is tied into computer control on a pressure increase signal. Typically, the pressure release is intermittent but can be continuous if required.

Additional comments:

- The process has been used once on an emergency basis during a general power failure.
- The process has been used very frequently on a non-emergency basis. They load the recipe with maximum catalyst charge with confidence that the heat surge can be controlled by this technique if necessary.
- The process can be used for suspension and emulsion.

The concept is covered in Patent No. 4004880, 1/25/77, "Method and Apparatus for Controlling Continuous Exotherm Reaction". It is available for licensing.

This discussion generated considerable interest among the attendees (and some scepticism about its effectiveness).

7. Resin/Compound Ignition Hazards - John McCully, Conoco

Conoco experienced a severe problem on start-up of a fluidized bed dryer. This was a two-stage dryer with a back-mixed first stage and plug flow second stage, heated with steam coils. (Probably a Niro unit, who now insist on hot water coils instead of steam.)

There was a process upset. The inlet temperature to the plug flow section overheated to 215°C vs. 100°C normal max. The dryer was shutdown. When an exhaust fan was started to purge HCl from the dryer, there was a mild explosion and fire inside the plug flow section. The burning mass was very difficult to extinguish. Parts of the dryer got very hot, the baffle bowed and part of it melted.

This experience, coupled with a previous one in which a Gaylord box containing uncooled dry blend started emitting HCl after 16 hours and the center core fused orange, led them to an in-depth investigation of the decomposition conditions for PVC and dry blend.

The investigation focused on two instruments - the DSC (differential scanning calorimeter) and ARC (accelerating rate calorimeter) which measures heat release on a programmed temperature increase.

The investigation showed that PVC and dry blend can become exothermic at 185°C (370°F) when exposed to air. The decomposition can occur at lower temperature in a closed container, and pressure increases rapidly once the decomposition begins. They believe that exothermic decomposition occurred in the fluid bed dryer and led to the explosion and fire. Their experimental data is shown as Attachment V.

8. VCM Tank Car Wreck - Everson Weekly, Pantasote

A derailment occurred at 5:30 a.m. on January 8, 1981 on the outskirts of Pt. Pleasant (pop. ~ 7,000), West Virginia, about 3/4 mile from the Pantasote plant. Speculation is that a cold wave to 10°F caused the rail to separate. The rails had been checked sonically one week prior to the incident. Contention was that train speed was not a factor.

OCC 2996

Five VCM cars (25,000 gallons with head shields) and two hopper cars were involved. The major problem was one VCM car which tipped onto its side and slid into a coupling on a hopper car. This sheared off the dome and all of the top valves in the VCM car. The resulting cloud extended for a half mile into a low lying corn field, adjacent to a river. The weather was cold with no wind so the cloud did not readily disperse. Families were evacuated for a half mile radius.

The Pantasote plant became the command post for the company representatives, Chemtrec, PPG representatives, the railroad representatives, local authorities, fire and sheriff departments. It required 1-1/2 days to define the nature of the leak, devise a unique patch, fabricate and install the patch to stop the leakage. By this time, the damaged car had lost about 2/3 of its cargo ($\approx$ 125,000 lbs.). Ultimately, all of the cars were set back on the tracks with no fire or explosion. Chronology of events is shown as Attachment VI.

Throughout the incident, there were extensive communications with the media and with the public. State and federal EPA and OSHA and Coast Guard were in contact but had little involvement.

Pantasote stressed the importance of in-plant and external communications and recommends that spark-proof tools and emergency kits be available as well as a detailed print of a railcar.

Discussion from the floor centered around different patching techniques. Dow has been working on a bladder which can be inserted and then expanded with a quick-curing thermoset. The Compressed Gas Association has another technique which could be applicable under some circumstances. (I am making contact and will make sure that any worthwhile information is disseminated.)

III. Regulatory Update - John Barr, Air Products

His comments on the various regulatory areas are shown below.

OSHA

1. The entire carcinogen policy is under review with a 2-3 year goal. Will probably remain on the books but not likely to be used unless a "significant risk" develops.
2. The lead standard is under partial stay. There may be some easement in respirator requirements but no real help.

3. Women in the workplace - There appears to be a general acceptance of the employer's right, under appropriate conditions, to exclude fertile females if it is believed that potential fetal damage exists.

Note: By show of hands, 9 companies have a policy of not employing fertile women for PVC operations. Five other companies used to have this policy but have reversed their position.

4. Reopening the vinyl chloride standard is not anticipated within the next 2-3 years.

EPA:

1. The carcinogen policy is being rewritten but the final timing is uncertain.
2. The vinyl chloride standard still has potential for administrative changes but effect cannot be defined.

Note: The luncheon talk by Gary Baise on future revisions to the VCM standard was summarized by J. A. King and is shown as Attachment VII.

3. Nothing substantial on RCRA listings, Superfund or Pretreatment.
4. Potential revision of the Clean Air Act is a hot potato. Most attention is on the conventional pollutants with little being given to the 112 hazardous pollutants. He does not see much change.
5. Water Quality Criteria - VCM, TCE and EDC are on the list to review.

FDA:

1. There has been no final action on rigid PVC for packaging.
2. Further action on plasticizer is unlikely until more tests have been conducted.

Video Tape Demonstration on OSHA-VCM Standard:

This was a 45 minute audio-color presentation made by Air Products and OSHA under a cooperative agreement. It is basically directed at orientation of new employees. Apparently, it was worthwhile for industry to be involved since they were able to temper some rash inaccurate statements that OSHA was trying to include in the presentation.

As far as anybody knows, OSHA has done nothing with the film since it was produced.

IV. Regulatory Incidents, Special Reports

1. Hazardous Materials Notification - H. Dubec, HCPC

Emphasis was on need to communicate anticipated process or material changes with the operating personnel. Impending use of a new raw material was a contributing factor in the Burlington walk-out which ultimately led to unfounded employee charges, OSHA and EPA visits, a NIOSH health hazard survey and landfill problems.

Question - How many companies have a formal corporate policy notifying Police/Fire Departments about hazardous materials?

13 Yes - mostly foreign

13 additional Yes on informal policy

2. OSHA Inspection/Respiratory Protection - Dave Lull, Diamond Shamrock

He detailed the lengthy, disagreeable hassle with OSHA at their Delaware City, Delaware plant. The situation started in February 1979 when they refused admittance to a female OSHA hygienist. In September 1979 - nine visits later - they had a closing conference. A week later, they were notified of seven citations (two serious, five willful) with fines totalling \$52,000. The major points of disagreement were on having the lowest level alarm and requiring mask usage at 5 ppm.

After additional meetings, an administrative hearing and review and appeal, the citations were reduced to one willful and several serious with fines of \$14,300. Ultimately, this was settled at \$4720. Diamond still has their lowest level alarm at 5 ppm.

3. OSHA/EPA Inspection Questionnaire

The results are self-explanatory and are shown in Attachment VIII.

4. PVC Dust - John Vaughan, ICI

He presented the results of a survey of health effects on worker exposure to PVC dust. The survey was conducted by the Institute of Occupational Medicine, Edinborough, on 800 workers. Their preliminary report in 1979

indicated that there was evidence of some health effects but their final report concludes that PVC dust is not in itself a health hazard although some minor effects were noted. Their summary is shown as Attachment IX.

V. Association Business

Officers elected for the coming year are:

Chairman	- Doug Frey, Diamond Shamrock
Vice Chairman	- Jim Wallace, ESSO Canada
Program Chairman	- Henry Rzempoloch, Pantasote

The next meeting is to be held in Toronto.



D. M. CONNOR

DMC/nl
Attachments

OSHA Issues Hazard Alert in Wake of Amoco Explosion


prevent further tragedies like the October, 1980 fire and explosion at the Amoco, New Castle Delaware polypropylene plant which leveled the plant, killed six people and injured 28 others, the OSHA Philadelphia Regional Office sent out a hazard alert to OSHA compliance officers and others in the chemical process and oil industries.

The alert addresses the underlying cause of the Amoco explosion—failure to train craftsmen that removing attachments to block valves will cause the valve itself to fall apart as the attachments—in this case a pneumatic controller—are an integral part of the valve as shown in the sketch on this page.

The following is excerpted from the Alert sent out by OSHA Regional Administrator David Rhone. It should be studied carefully by all OCAW members in the oil and chemical process industries.

"The employers' responsibilities with regard to this hazard include but are not necessarily limited to the following items:

1. Mechanics or operators whose job it is to assemble, adjust or disassemble valves or attachments to valves shall be trained in the safe assembly, disassembly, or adjustment of each type of valve-attachment assembly.



2. Mechanics or operators who have not been so trained shall not be assigned to perform such duties without supervision by those foremen or operators who have been trained.
3. Attachments to valves which regulate hazardous materials shall not be connected to the valves with the same bolts which preserve the integrity of the valve, without assurance that such attachments would not be removed while the valve is in service.

Background: A recent investigation of an explosion and fire at a chemical plant revealed that when workers removed the pneumatic controller from a block valve, the valve itself fell apart. The reason for this was that the bracket which connected the controller to the valve was attached to the valve with the same four bolts which held the bonnet of the valve to the body (see sketch).

On October 21, 1980 four mechanics were assigned to perform a slurry line cleanout for a ten thousand gallon polypropylene reactor. The slurry line ran from the bottom of the reactor through a pump, a slurry cooler (heat exchanger) and then back to the top of the reactor through a four inch line.

The slurry line had been isolated from the system by the closing of the two block valves, one at the top and one at the bottom of the reactor. Each block valve had a pneumatic controller attached but the connecting mechanisms were different. The valve at the top was a plug valve. The controller was attached to a bracket which was in turn

attached to the valve bonnet by the same bolts which held the bonnet in place.

The valve at the bottom was a ball valve. Because of its configuration the same type of bracket connection could not be used. The controller on this valve was connected to a bracket which in turn was held in place by two large "U" bolts which attached around the top and bottom flanges of the valve.

The mechanics split into two groups. Two men began opening lines at the top of the reactor while the other two broke the lines at the bottom. They cleaned out the slurry lines and broke for dinner. When they returned they were asked by the chief operator to rod-out the block valve at the top of the reactor. That valve still had the controller attached.

The company operating procedure required that the controller be removed prior to the opening of any lines to determine the position of the valve, but since this had been overlooked, the mechanics decided to remove it even though the valve was obviously closed.

It was at this juncture that the two mechanics made the fatal error. They removed the four bolts which attached the bracket to the valve. Those same four bolts held the valve together.

Upon removal, the plug and bonnet shot out and contents of the reactor, ten thousand gallons of propylene and hexane at 150 psi, poured out through the four inch opening. An enormous gas cloud formed and within three minutes an explosion occurred which could be heard over ten miles away.

LIFELINES

OCAW HEALTH AND SAFETY NEWS

Vol. 8, Nos. 1, 2

April 1981

Published in cooperation with the OCAW Union News, 1636 Champa St., Denver, Colo. 80202.

E. J. Rousselle, Vice President
Anthony Mazzocchi
Director, Health and Safety Dept.



Sylvia Krekel
Occupational Health Specialist
Rafael Moore
Industrial Hygienist
Steve Wodka, Intl. Representative

Items of interest for the May issue should be sent in by April 20.

Subscription price for non-members is \$5 per year.

ATTACHMENT II

Question No. 1: Most Important Safety Considerations

What are some of the most important safety considerations that you would investigate to evaluate the overall plant safety status?

	Number of Replies
(a) Containment of vinyl chloride	
1. Relief valve and rupture disk system and condition	(6)
2. Emergency relief containment capacity and recovery system	(3)
3. Cooling and electrical backup for reactors	(3)
4. Reactor controls	(2)
5. Unloading and storage and handling of VCM	(2)
6. Reactor S/S system	(2)
7. Control of reactor bottom valve	(1)
8. Emergency shutdown systems	(1)
9. Agitator alarms	(1)
10. Reactor area manned at all times	(1)
11. Maintenance records for vessels in VCM service	(1)
12. Vessel integrity program	(1)
(b) Contingency - preventing fires and explosions in the event of V.C. escape	
1. Fire protection system	(6)
2. Plant layout	(4)
3. Presence of safety equipment	(2)
4. Plant emergency plan	(1)
5. Electrical equipment properly grounded	(1)
6. Use of fire safe valves	(1)
7. Ability to handle large quantities of V.C. gas	(1)
(c) Good safety and operational management	
1. Up to date procedures - complete operating manual - plant follows procedures	(11)
2. Training and education of all personnel	(10)
3. Maintenance status - P.M. program	(7)
4. Housekeeping	(6)
5. Attitude of management and personnel	(5)
6. Safety organization	(2)
7. Operator involvement in safety	(1)
8. Inspection system	(1)
9. Engineering standards - design criteria being followed	(1)
10. Proper raw material storage	(1)
11. Regular safety sessions	(1)
12. Inter-action between Production and Maintenance	(1)
(d) Indicators	
1. Past Records - frequency and severity records	(4)
2. Monitoring and emission records	(2)
3. Most recent systems safety analysis review	(1)

Question No. 2: Reactor Discharge Valve Control

How do you prevent the wrong reactor from being opened?

	Number of Replies
1. Operator training and procedures	(8)
2. Clear identification of reactors	(6)
3. Mechanical locking system - two people to open	(4)
4. Discharge port is covered with a locked cover	(4)
5. Fixed discharge piping - batch always contained	(4)
6. Reactor discharge valve interlocked with reactor pressure	(3)
7. Two valves	(2)
8. Software interlocks	(2)
9. Warning light system - indicates safe to open	(2)
10. Electrical interlocks	(1)
11. Communications	(1)
12. Pressure gauge mounted beside valve	(1)
13. Slow opening valves - time to discover mistake	(1)
14. Drop valve actuated from reactor top - near pressure gauge and sight glass	(1)
15. Working on a locking device	(1)

Question No. 3: Charge Volume Control

(a) How do you measure water, VCM, catalyst, suspending agents?

	Weight	Meter	Volume
Water	0	15	1
VCM	7	10	1
Catalyst	9	0	3
Suspending Agents	8	2	1

(b) How do you prevent over or under charging?

1. Visual checks on levels	(7)
2. Operator training, procedures, signing charge sheet	(6)
3. Calibrating meters - maintenance	(3)
4. No independent mechanism to prevent over/under charging	(2)
5. N/A	(2)
6. Dual meters	(1)
7. Computer controlled	(1)

(c) How do you control charging sequence?

1. Operator training and procedures	(12)
2. Computer	(3)
3. Sequence controlled by mechanical stepper switch	(1)
4. N/A	(2)
5. No answer	(2)

Question No. 4: Gasket Replacement Control

(a) Do you replace gasket --

Number of
Replies

	<u>Yes</u>	<u>No</u>	<u>No Answer</u>	<u>N/A</u>
1. After each opening	7	5	7	1
2. After major maintenance	15	0	4	1
3. Once per year	3	1	14	2

(b) Pressure of the pressure test --

1. After each opening psig - 50, 200, 90, 30,
 Vacuum, 80% of R/D rating, 15" Hg vacuum
2. After major maintenance psig - 100, 140, 150, 85, 120, 150, 135,
 120, 180, 60, reaction pressure,
 rating - 10%
3. Once per year psig - 170, 175, 180

(c) How often is a manway gasket re-used?

- | | |
|--|-----|
| 1. Inspected visually and re-used if passes inspection | (8) |
| 2. Never re-used | (3) |
| 3. 10 - 15 times | (3) |
| 4. 10 - 20 charges | (1) |
| 5. 50 charges | (1) |
| 6. 100 - 150 charges | (1) |
| 7. No answer | (2) |

(d) Are your manway gaskets O-rings or flat gaskets?

<u>O-Rings</u>	<u>Flat</u>	<u>N/A</u>
10	8	2

Question No. 5: Safety Valve Control on Reactors

(a) How often do you inspect your safety valve nozzle?

- | | |
|--|-----|
| 1. Each time the reactor is entered or opened | (7) |
| 2. After every charge | (4) |
| 3. Approximately every 3 days | (1) |
| 4. Once per week | (1) |
| 5. Once per month | (1) |
| 6. Once every 30 - 50 batches | (1) |
| 7. Two parallel relief nozzles - each with 2 rupture discs
and no pop safety valves | (1) |
| 8. Do not use safety valves on reactors - use double rupture discs | (1) |
| 9. No answer | (4) |

OCC 3004

Question No. 5: Safety Valve Control on Reactors

	(b) How often do you test your safety valves?	Number of Replies
1.	Once per year	(14)
2.	Every 6 months	(1)
3.	N/A	(5)

(c) Are safety valves removed and cleaned after each release?

Yes 15

No 0

Yes was the only answer if the question was answered, except -- "no reactor releases - should be done - no policy."

Question No. 6: Reaction Shortstop

(a) Do you have a reaction shortstop system?

Yes 17

No 2

N/A 1

(b) Is the injection automatic or done by an operator?

Automatic 5

Operator 16

No answer 3

If automatic, what initiates the operation?

- Agitator RPM
- High reactor pressure
- Loss of power to agitators
- Over pressure or temperature or loss of agitation
- Loss of agitation, agitator motor, high water pressure, power failure

Question No. 6: Reaction Shortstop

		Number of Replies
	(c) Is this system independent for each reactor or a common system for several reactors?	
Independent	10	
Common	6	
Both systems	1	
No answer	4	

	(d) How often was your system operated last year?	
Less than 10	6	
10 to 100 times	4	
Over 100 times	4	
N/A	6	

Many times the shortstop system was used in non-emergency situations.

	(e) How often was your system tested last year?	
Daily	2	
Weekly	1	
Monthly	3	
Yearly	1	
N/A	13	

Question No. 7: Reactor Pressure Control

	(a) How do you prevent pluggage in reactor pressure transmitters?	
1. Water injection		(6)
2. Inspection and manual cleaning		(10)
3. Solvent cleaning system		(1)
4. Dual pressure systems		(2)
5. N/A		(1)
6. Not a problem		(1)

Question No. 7: Reactor Pressure Control

Number of
Replies

(b) Do you have alarms for high pressure?

Yes 18
No answer 1
N/A 1

(c) Approximately what percent of normal
operating pressure is the alarm set for?

1. Less than 110%	(9)
2. Between 110 - 120%	(5)
3. Over 120%	(2)
4. No answer	(4)

Question No. 8: VCM Pump Control

What protection do you have to prevent remote
operated VCM pumps from starting with suction
and discharge valves closed?

1. Operator training, procedures, etc.	(5)
2. Automatic valves interlocked with pump	(5)
3. None	(6)
4. No answer	(2)
5. CRT display	(1)
6. No remote pumps	(1)

Question No. 9: VCM Storage Tanks

(a) Do you have sprinkler protection for
your VCM storage tanks?

Yes 20
No 2

-- Use monitor nozzles on older installations.
-- No, for some larger tanks

Question No. 9: VCM Storage Tanks

(b) How often are these tanks opened for internal inspection:

	Number of Replies
1. Once per year	(3)
2. 2 - 5 years	(8)
3. 6 - 10 years	(3)
4. Over 10 years	(2)
5. No regular basis (many use ultrasonic inspection)	(3)
6. No answer	(1)

Virgin monomer tanks inspected infrequently. Day tanks inspected more frequently.

(c) Have you had any corrosion problems in VCM storage tanks?

Yes 4

No 16

Those indicating they have corrosion problems are in recovered VCM tanks or day tanks, not virgin VCM.

Question No. 10: Recovered VCM Handling

(a) Do you distill your recovered VCM?

Yes 3

No 17

N/A 1

(b) How do you control polyperoxide formation in your recovered VCM system?

1. Short retention time	(7)
2. Add an inhibitor	(6)
3. pH control - keep basic	(4)
4. Keep O ₂ levels low	(3)
5. No precautions taken	(3)
6. No answer	(3)

Question No. 11: Reactor Entry

Do you require:

	<u>Yes</u>	<u>No</u>	<u>N/A</u>	<u>No Answer</u>
1. All flanges blinded	13	6	1	
2. VCM flanges blinded only	3	12	1	5
3. Manway watch	16	4	1	
4. Mechanical manway watch	4	11	1	4
5. Safety belt only	6	11	1	3
6. Safety belt and wristlets only (3 answered - wristlets only)	2	11	1	3
7. Safety belt and wristlets with line attached (2 answered - safety belt with line attached)	2	12	1	3
8. Lab entry analysis VCM/O ₂	2	14	1	3
9. Portable analyzer entry analysis VCM/O ₂	17	2	1	
10. Respirator worn at all times	15	3	1	1
11. Respirator worn at certain jobs	6	6	2	6
12. Gloves to be worn	13	4	1	2

ATTACHMENT III

SUMMARY OF OPERATOR TRAINING QUESTIONNAIRE

The following is a summary of the 32 responses to the operator training questionnaires:

1. What is the approximate number of people in your total work force involved in manufacturing?

0 to 100	19
100 to 300	8
300+	6

Some responses covered several different plants.

2. Do you have a formal training program for operating personnel:

Yes	28	No	4
-----	----	----	---

3. Does your plant organization have a full-time person whose primary responsibility is training?

Yes	17	No	15
-----	----	----	----

4. If your answer to No. 3 is "yes," to which functional part of the organization does this person report? (Employee relations, manufacturing, technical, etc.)

Typical responses:

- a. Manufacturing department (8 responses)
- b. Employee relations department controls overall program with a coordinator from the manufacturing department implementing most of program at unit level (4 responses)
- c. Employee relations
- d. Safety
- e. Technical

5. If your answer to question No. 3 is "no," who in your organization is primarily responsible for training?

Typical responses:

- a. Operating supervisor or foreman
- b. Safety Department
- c. Manufacturing engineer
- d. Personnel

6. How long does the typical operator spend in the training program?

At least half of the respondents indicated the length of their program as 3 to 6 weeks.

Page Two
Summary of Operator Training Questionnaires

7. Is your program one continuous cycle or is it divided into several stages separated by practical on-the-job experience? Could you please describe (Example: Orientation/limited training - 1 week, advanced - 1 week, recycle training - 2 days)

Typical responses:

- a. Five phases (I - Orientation - 3 weeks; II - Departmental Training - 2-3 weeks; III - On the Job and Advanced; IV - Self-study Pilot Book Training; and V - Advanced Classroom Training)
 - b. Three weeks operator training; 2 weeks supervisor training 3 months OJT, annual review
 - c. One continuous cycle of classroom and OJT
 - d. Three days formal classroom, 1 month OJT, 2 days recycle classroom training per year
 - e. 90-day apprentice training; 45 days OJT and classroom, qualification courses in process, mechanical, electrical, instrument
 - f. Orientation one-half week; Buddy on the job 2-3 months, probationary period until passes test.
8. Please check those of the following topics which are included in your training program:

<u>X</u>	Orientation	<u>X</u>	Regulatory (EPA, OSHA, RCRA)
<u>X</u>	Safety	<u>X</u>	Industrial Hygiene
<u>X</u>	Fire Fighting	<u>X</u>	Respirator Protection
<u>X</u>	Process Technology	<u>X</u>	Company Philosophy
<u>X</u>	Instrumentation	<u>X</u>	Company Organization
<u>X</u>	Basic Equipment		

List others not mentioned above: EEO, Company Policy.

9. As a part of your operator training program, do you use proficiency tests to evaluate the effectiveness of the program?

Yes 22 No 10

10. Do you use tests to qualify operators for promotion:

Yes 14 No 18

11. What do you feel are the strengths of your program?

Page Three
Summary of Operator Training Questionnaires

Typical responses:

- a. Six weeks formal training
- b. Locally produced video tapes
- c. Management support
- d. Operator input
- e. Uniform format for procedures
- f. Company philosophy and attitude

12. What area of your program would you like to improve:

Typical responses:

- a. Supervisor training
- b. Detailed orientation for advanced program
- c. Operator retention of material
- d. Improve higher technology training
- e. Add formal followup
- f. Formalized testing
- g. More formal procedures
- h. Full time supervisor for training
- i. Follow-up on a more formal basis

13. Which, if any of these training aids do you use in your operator training program?

All of the following are being used to some degree:

Film
Slide/tapes Presentation
Video Tape
Commercially Produced Video Tapes
Home-made Video Tapes
Mock-up Equipment or Process Area
Demonstration Instruments

14. Do you use video tape recordings produced at your facility by your own people?

Yes 11 No 19

If "yes," could you please comment on the effectiveness of this technique? Do you recommend this technique to others?

Page Four
Summary of Operator Training Questionnaires

Typical responses:

- a. Good for repetitive routine information
- b. Very good because of local background
- c. Very relevant
- d. Prepared by a special training division
- e. Good - but still learning how to do it
- f. Only 25% good enough to re-use
- g. Two respondents said not using but plan to start.

9/18/81

COMPUTER CONTROL SAFETY QUESTIONNAIRE

Dear VCSA Member,

Computer control of PVC plants has very definite safety benefits. However, there are some safety problems which computers introduce which are not readily apparent. The purpose of this questionnaire is to survey computer-operated plants to discover any special problems related to computers, either design or operator interface related, and how these have been solved.

1. COMPUTER/MANUAL OPERATION

Note: In all cases, #5 is Georgia-Pacific.

The HCPC Addis Plant is #2 but they were not identified at the meeting.

A) Do you have provisions for independent computer and manual operation?

1. No
2. Yes
3. Not Totally
4. Yes
5. Yes
6. Yes

B) How do you isolate the computer from the plant during manual operation or when the plant is down for computer repairs?

1. The portion of the computer used for temperature control is kept active when the computer is in repair. No manual control is possible in other portion when computer is down.
2. A key switch which turns complete plant control into manual operation.
3. Mechanical disconnect, at I/O and at remote (air supply to valve, etc.)
4. Switch all devices to manual operation
5. There is a relay switching system that is activated on computer failure or by manual request. This system deactivates panel push-buttons during computer operation and isolates the computer I/O from the device relays during manual or panel mode.
6. Have MANUAL/AUTO switch which electrically isolates computer. Had one incident during trouble shooting of computer when switch was bypassed accidentally. Future design will consider more tangible isolation than switch.

C) Have you had any problems with the computer opening valves or reactors which were out of service for maintenance?

1. No operation is possible without computer.
2. No-air is removed from solenoid operated valves when out of service.
3. Once - installed lockout on positioners.
4. One occasion due to human error.
5. No - All valves on reactors down for maintenance are "air-failed" so that they cannot open.
6. Air supply to reactors is locked out during maintenance.

D) How do you maintain operator proficiency on manual operation during long periods of computer operation?

1. No manual operation is made.
2. We do not run full production without computers.
3. Don't try.
4. Once per month each operator must operate manually for at least four hours.
5. We do not, at this time, have a specific program or method. This has not been a problem for us because our computer up-time averages about 98%.
6. Schedule periods of MANUAL operation in order to maintain proficiency.

2. OPERATORS TRAINING

A) How do you train new operators?

1. Through education in special lecture program and on the job training.
2. On-the-job with a background of basic theory once familiar with job.

3. Some classroom and theory - mostly on the job buddy system.
4. Formal Class Room Training for approximately four weeks. Then work with existing operator for approximately two months.
5. New computer operators receive most of their training by working with experienced operators. They also spend approximately eight hours with one of the computer programmers for technical instruction about the computer.
6. New operators are not trained on the computer until all other jobs in plant are mastered. Training involves several weeks of on the job dual operation with experienced operator, on both MANUAL and COMPUTER modes.

B) Do you have refresher training for experienced operators?

1. Yes
2. Yes - Limited to last job rotation otherwise operators are encouraged to keep current at all times.
3. Yes
4. Sometimes when operating procedures are updated.
5. We do not have regularly scheduled retraining classes for experienced operators, but retraining is done if operational performance indicates the need.
6. No

C) How do you retrain after major program revisions?

1. By lecture and simulation training.
2. Process and staff engineering will assist in this effort.
3. Written, classroom, and demonstration.
4. Systems Engineer conducts training sessions. Includes practice on CRT.
5. When possible, major changes are made gradually and training classes are held to inform operators of the effects of the changes on them.

6. (1) 12-15 hours classroom
- (2) 1 to 3 days water batching

D) How do you communicate minor program revisions to all operators?

1. Either by an official transmittal note or either by starting meeting of the day.
2. Memos and log book.
3. Written - notice and description.
4. Operator log book and notices.
5. This is done through operation department communication channels. (IE., instructions in supervisors instruction log).
6. Have separate log book to record all revisions.

3. FIRST-LINE SUPERVISOR TRAINING

A) How do you train new supervisors?

1. By on the job training.
2. Allow upgrade system to cover vacancies.
3. A - Senior operator system leads to promotion.
B - No formal method - probationary period.
Both - Use outside training programs.
4. New first line supervisors are promoted from the operators ranks and are already familiar with operation. Other training consists of familiarization with maintenance procedures, company policy, etc.
5. New supervisors do not undergo any formal training because they are all ex-computer operators.

6. Had problems during startup of plant because supervisors had no time for first hand solo operation of computer, following the classroom sessions. Since then, however, all new supervisors selected have come from best computer operators.

B) Do you have refresher training for experienced supervisors?

1. Not done usually, except on emergency training.
2. They participate in all training sessions for each unit.
3. Yes
4. Yes - Same as with operators. In addition they get refresher on supervisory skills.
5. No
6. No

C) How do you retrain after major program revisions?

1. By a lecture and simulation training.
2. Process engineering will assist in this effort.
3. Same as operators.
4. Same as operators.
5. They attend the same training classes that operators attend for major changes.
6. (1) 12-15 hours classroom.
(2) 1 to 3 days water batching.

D) How do you communicate minor program revisions to all supervisors?

1. By an official transmittal note.
2. Memos and log book.
3. Written and discussions.
4. Same as operators.
5. The same as for operators, through operation department's communication channels.
6. Separate log book to record all revisions.

E) Have you had any problems with first-line supervisors losing proficiency with computer operations because of problems in other non-computer-operated parts of the plant? How are these problems overcome?

1. Very few case only. We give them refreashing education and make them supervisors.
2. No - Most first-line supervisors have only a limited working knowledge of computer operations.
3. Some refresher period and assignment with capable operators.
4. No
5. We do not attempt to keep a supervisor completely up-to-date on computer operations. We feel that with two console operators and two senior operators on each shift, it is unnecessary to keep supervisors proficient on the computer.
6. Yes - Require supervisors to spend more time in control room and place more responsibilty on outside operators.

4. INFORMATION OVERLOAD

A) Have you had any problems of operators being swamped with computer messages and alarms so that some are ignored? How are these problems overcome?

1. No - Only important messages and alarms are kept, so there will be no neglecting possible.
2. Yes - Use of two people helps to overcome problems when the extra person is available.
3. Yes -
 1. Establish higher threshold for emergency alarms.
 2. Have some data indicated, not alarmed.
 3. Hardwire really critical alarm.
 4. Training employees.
4. Yes - Added a second operator in control room to handle all operations after the reactors. In another plant - the supervisor assists the operator.
5. Yes - We are constantly working to eliminate unnecessary messages and redundant alarms to reduce the amount of information being fed to the operators.
6. Yes -
 1. Revised program to reduce number of alarm messages.
 2. Use separate printers for messages and alarms.
 3. Some critical alarm messages are printed with exposed type in order to make them stand out.

5. OPERATOR COMPLACENCY

A) Have you had any problems with operators relying too heavily on the computer to correct all mistakes? How are these problems overcome?

1. No - Cross checks by operators are inserted at important locations.
2. No
3. A- No
B- Yes - have mandatory log sheets to record reaction to alarm.
4. No - Not since instituting manual operations once per month.
5. No
6. Yes - Diligent follow up on all incidents (major and minor) where mistakes using the computer are made. Operator making mistake is counseled and other operators are informed.

6. MAJOR PROGRAM REVISION SIMULATIONSA) Do you perform any plant-scale simulations when major program revisions are made?

1. No
2. On start-up we provide dummy batches to walk through the program.
3. No - Except water batch tests.
4. No
5. No
6. Yes - Charge full batch quantities of water, VCM, and all additives except catalyst. Use catalyst solvent to simulate catalyst. Simulate alarm conditions, including emergency shortstop. Period lasts from 1 to 3 days.

7. OPERATOR/SUPERVISOR PROGRAM VARIABLE CONTROLA) Do you use an operator/supervisor control key to limit changes to program variables through the CRT?

1. No
2. Yes - Key switch
3. Yes - Many are not accessible to operators.
4. No
5. Yes
6. Have key - but do not use it.

B) How do you limit program variable changes by ^{operators} operations?

1. _____
2. Some parameters cannot be charged from CRT - engineer has to charge (key-switch).
3. Yes - written authorization and record.
4. Through directed operator CRT keyboard function.

5. By requiring them to obtain permission and key from supervisor.
6. Program variables are changed by engineers. Have not had problems with operators changing program variables. Had some problems with operators tampering with FLAG changes in order to get programs to run. Educated operators to high danger of this and revised programs for better operability.

C) How do you change formulation variables, such as catalyst and suspending agents?

1. No operators are involved in recipe changes.
2. Done with consultations with process engineering group through supervisor. Engineer normally makes changes.
3. By CRT, but only as written authority.
4. Process Control Engineer or Shift Supervisor accomplishes through CRT keyboard.
5. We have programs that allow operators to change the amount of ingredients used within certain limits and this is not a permanent change. Permanent changes to recipes are made by the programmers on request from the technical group.
6. Formulation page has variables which can be changed from CRT entries. The change must be input twice in order to be accepted. CRT changes are valid for one batch only. Long term formulation changes are made by engineers.

8. REACTOR CHARGE VOLUME CONTROLS

A) If you have primary and secondary measurement devices on charge quantities, how do you allow operator acceptance of deviations between primary and secondary devices?

1. Only one measurement is present.
2. Yes - Deviations are questioned by operators, and supervision makes decision. Also process engineering can be consulted.
3. Computer queries, then operator must get visual field verification before proceeding.
4. Variance limits set, but Shift Supervisor has some discretion if barely over limit.

5. We have no secondary measuring devices.
6. Deviation during charge - steps charge, operation must repair problem or deselect one of devices. Deselection procedures are written, with acceptable limits. On some chemicals, high value is accepted, on others, low value is selected.

9. VALVE STATUS INDICATIONS

- A) How do you handle problems with valve status indicators, such as microswitches? Do you override the computer hold or alarm, or do you manually adjust in the field on each batch?
1. _____
 2. a) We override only after manually checked in field.
b) Adjust in field if problem persists.
 3. Allow override after field inspection, then write ASAP work order.
 4. Device is visually checked in the field before overriding computer hold status. Device is not operated post next work day without repair.
 5. If a position indicator fails (valve in the proper position and in contact with switch) an "override" can be placed on the device by using the "supervisory key" until it can be repaired by the I & E Group.
 6. Diligent maintenance is required to keep microswitches in good condition. Use override and manual field adjustment to overcome problems. Neither is an acceptable solution, but is necessary for operation. Repeat that follow up on problems must be prompt and diligent.

10. PLEASE DESCRIBE OTHER COMPUTER-RELATED SAFETY PROBLEMS OR INCIDENTS AND HOW YOU RECOMMEND TO CORRECT THEM.

1. _____
2. Operators do not always respond to computer initiated emergency type alarms - Computer print-out is reviewed duly by process engineer and recommendations made to production - Training sessions W/operators helps.
3. Preparing thorough fault-free analysis of computer operations on corporate basis.

4. None

5. In some instances, operators in the field have resorted to manipulating the instrument to process transducers (I to P's) by hand to force a valve or device to move contrary to computer command. This is a rather simple procedure that, only involves unscrewing the cover and using a finger, nut, bolt, rock or some other object to hold the pneumatic switch in the desired position.

Our solution to the problem was to make this act a severe violation of safety procedure with resulting severe penalties for violators. Since instituting this policy, we have had no further problems.

6. _____

ATTACHMENT V

THE EXOTHERMIC DECOMPOSITION OF PVC AND DRY BLEND

I. EXPERIENCES WITH EXOTHERMIC DECOMPOSITION OF PVC

A. Fluid Bed Dryer Explosion and Fire

During a dryer startup, the inlet air temperature to the plug flow section of the dryer reached 215°C. The dryer was shut down. An exhaust fan was started to purge HCl from the dryer. Immediately there was a mild explosion and fire inside the plug flow section.

B. Exothermic decomposition experiences with dry blend and flexible compound.

II. CALORIMETRIC STUDIES OF PVC DECOMPOSITION

A. Instruments Used

1. DSC--Du Pont 990 Thermal Analyzer and Pressure Differential Scanning Calorimeter
2. ARCTM--Columbia Scientific Industries Accelerating Rate Calorimeter

B. Material Tested

1. General purpose suspension resin.
2. Twin screw pipe dry blend.

C. Results

1. DSC--Open Cup, Air Atmosphere

	<u>Resin</u>	<u>Dry Blend</u>
Exotherm Began At	185°C	200°C
Endotherm(s) Began At	225 and 255°C	260°C
Exotherm Resumed At	265°C	275°C
Ignition Occurred At	440°C	425°C

2. ARCTM--Open Cup, Air Atmosphere

	<u>Resin</u>	<u>Dry Blend</u>
Exotherm Began At	185°C	185°C
Endotherm Began at	203°C	225°C
Exotherm Resumed At	215°C	240°C

II. CALORIMETRIC STUDIES OF PVC DECOMPOSITION (CONTINUED)

C. Results (Continued)

3. ARCTM--Closed Bomb, Air Atmosphere

Resin


Exotherm Began Below	140°C
Endotherm Began At	170°C
Exotherm Resumed At	190°C
Pressure in Bomb	5 psig at 140°C
	1,050 psig at 190°C

Dry Blend


Exotherm Began At	217°C
Pressure in Bomb	100 psig at 220°C
	1,350 psig at 230°C

III. CONCLUSIONS

- A. PVC resin and dry blend decomposition can become exothermic at 185°C when exposed to air at atmospheric pressure.
- B. The exothermic decomposition can start at a lower temperature in a closed pressure container.
- C. The pressure in a closed container increases rapidly with temperature once the decomposition begins.
- D. Exothermic decomposition probably did occur in the fluid bed dryer and lead to the explosion and fire.



OCC 3027



ATTACHMENT VI

VCM
TANK CAR
DERAILMENT

OCC 3029

Thursday, January 8, 1981

- 5:30 AM Henry Rzempoluch, Plant Manager, is contacted by railroad and informed of VCM tank car derailment.
- 6:00 AM Rzempoluch visits the disaster site and finds two hopper cars and five VCM tank cars involved. At least one VCM car has a serious leak.
- 6:30 AM Jim Ferrell, Traffic Manager for Pantasote, and Rzempoluch are at the scene with local authorities and railroad employees. It was decided by local authorities at the suggestion of Pantasote to secure the area. By this time, the railroad had contacted CHEMTREC.
- 7:00 AM CHEMTREC contacts PPG in New Martinsville, West Virginia. Union Carbide in Charleston is also contacted in case their expertise is needed.
- 7:30 AM Vapor cloud had increased to about one half acre. Local authorities and railroad evacuate families within one half mile radius.
- 8:00 AM Ferrell contacts Bob Baker of PPG in New Martinsville; advises him of the situation and requests a response team.
- Rzempoluch; three Pantasote production foremen; and Everson Weekley, Safety Supervisor, visit the scene to determine extent of damage. Scott Air Paks are used by two men who examine the overturned cars. At this point we feel only one car has a serious leak. We find that dome valves have been completely sheared off allowing VCM to escape.
- 9:00 AM Rzempoluch and Weekley formulate a program to monitor vinyl leaks. This is done by a Century Unit. A command post is set up at the plant and "walkie talkies" are used to relay information from the scene.
- 11:00 AM Weekley returns to the plant and briefs local authorities, railroad officials and Pantasote personnel. Levels in the area are 60 ppm at 500 yards and 150 ppm at 200 yards.
- Pumps for the city water wells are shutdown since they could prove to be an ignition source and cause an explosion. Public is informed that there is no contamination problem.
- 12:00 NOON Sheriff Bob Fruth is appointed to read a statement to the press and answer questions on the extent of the disaster.
- Bill Shaw, Train Master for Chessie System, arrives. Several railroad officials are now at the scene.
- Hulcher Emergency Service is called in to handle the cleanup.
- Security is now stepped up and local authorities (sheriff, city and state police) are joined by railroad police.

OCC 3030

1:00 PM Task force from PPG arrives and are taken to the site to make an assessment.

Richard Fleece, Regional Manager for the Chessie System, arrives and helps to coordinate cleanup efforts. EPA, West Virginia Department of Health, and West Virginia Air Pollution Control Commission by now have contacted us by telephone.

2:00 PM A conference is held to determine how to patch the leak. We know that all dome valves have been sheared off and that we must plug leaks and clear the atmosphere before cars can be raised. We must also be able to unload the remaining monomer.

5:00 PM Regional Supervisor for Hulcher arrives and inspects the damaged car.

7:00 PM Meeting held at the Point Pleasant Motor Inn to discuss progress on patching the leak, the possibility of explosion, health hazards involved, security, evacuation, etc.

Consensus is that since all valves have been sheared, this is a unique situation.

Friday, January 9, 1981

10:00 AM PPG states that they are beginning to fabricate a patch.

12:00 NOON Ron Escue, an employee for Huntington Piping, is called to the disaster site; and he then takes the lead in designing and fabricating a patch.

3:00 PM The leak from the Safety Relief on the tank car is patched. Gauge and vapor lines are also secured by the same patch.

5:00 PM Both liquid lines are patched and the car is ready to be raised.

6:00 PM Meeting at Point Pleasant Motor Inn to discuss progress made up to this point. Another task force from PPG's Lake Charles VCM plant arrive.

Saturday, January 10, 1981

8:00 AM - 3:00 PM Cars are raised, set back on tracks, and moved to Pantasote's yard for unloading on Monday morning.

OCC 3031

INSTITUTE OF OCCUPATIONAL MEDICINE

EPIDEMIOLOGICAL AND CLINICAL STUDIES OF POLYVINYLCHLORIDE WORKERS

by

C A Soutar, S Gauld, M Lloyd, L H Copland, J F Hurley

ABBREVIATED SUMMARY

We have reported previously a medical survey of 818 present and past workers at a factory making polyvinylchloride (PVC) in which we showed that exposure to fine PVC dust was associated with a slight average reduction in tests of breathing capacity, and with the presence of small spots visible in X-rays of the lungs.

The present studies were designed to identify any chest illness in men who had worked in dustier plants in the factory but who had not been seen in the previous survey, and to examine similarly men working at a second factory manufacturing PVC; to re-examine the relationship between PVC dust exposure and small spots in the chest X-ray since in the first study there had been some disagreement between expert readers over the interpretation of the X-ray appearances, and to discover how seriously men may have been affected by PVC dust.

Two hundred and twenty-nine additional men were seen at the first factory, and little chest illness was found among them. One hundred and twenty-seven men were seen at the second factory, and even less illness was found in this workforce. Each man was sent a brief confidential medical report.

The X-rays were re-read by the same three experienced readers whose results were reported previously, and also by another panel of five readers. The readings confirmed the results of our earlier study, in that PVC dust exposure was found to be associated with the presence of small spots in the chest X-ray.

OCC 3032

Again, only some readers detected the effect of PVC dust, and the reasons for these differences probably include the slight degree of the abnormalities, which cannot be distinguished in an individual X-ray from changes related to age.

These changes of the chest X-ray were slight, on the borderline between normality and abnormality, and clinical examinations of a group of men who had these spots indicate that the health of their lungs was no worse than that of a group of men of similar age and smoking habits who had normal chest X-rays (except for a slight increase in sputum). We conclude that the presence of these spots does not indicate that PVC dust has seriously affected the lungs. Some men who had experienced relatively high estimated dust exposures were also examined if their breathing tests results were lower than those of other men. The non-smokers selected in this way all had healthy lungs, but some of the smokers had serious reductions of their breathing tests. This was probably the result of their smoking habit, and there was no evidence to suggest that PVC dust had seriously damaged their lungs.

We conclude that exposure to PVC dust has been shown to cause a slight reduction of tests of breathing and slight abnormalities of the chest X-ray, but that there is no evidence that PVC dust has caused serious illness among the workforce, although the possibility of a rare idiosyncratic response to dust cannot be excluded.

For details of this work, please refer to Institute of Occupational Medicine Technical Memorandum TM/81/8.

ATTACHMENT VIII

SUMMARY OF OSHA/EPA INSPECTION QUESTIONNAIRE

The following is a summary of the 26 responses to the OSHA/EPA Inspection Questionnaire:

1. Do you have, for your supervisors and other employees, a written set of guidelines for use when a regulatory agency inspector arrives at the plant gate?

Yes 15 No 11
2. Have you had either an OSHA or EPA inspection of your plant in the past 12 months:

OSHA 10 EPA 18 None 7
3. If you had an OSHA inspection was it regarding the VCM standard or was it involved with another area?
 - a. VCM standard (five responses)
 - b. VCM, noise, heat, dust lead
 - c. General - triggered by employee complaint
4. If you had an EPA inspection, was it regarding NESHAPS-VCM or was it about something else?

Typical response:

- a. NESHAPS
 - b. NPDES permit
 - c. Hazardous waste - RCRA
 - d. Permit to burn coal
 - e. Landfill permit
 - f. Incinerator operation
 - g. PCB's
 - h. PVC dust
 - i. Safety relief valve discharges
5. Did you receive any citations or notices of violation? If you wish, could you please describe the nature of the violation?

Typical response:

- a. Notice of violation - improperly labelled PCB tank
- b. No violation but not satisfied with aqueous effluent sampling procedure
- c. Two OSHA citations on record keeping - one invalid - the other due to math error in number of injuries reported

- d. OSHA citations: Inadequate maintenance on area monitoring equipment and working in an area with greater than 5 ppm VCM, not wearing respirator
 - e. OSHA - serious and fine; other and no fine
 - f. OSHA - High VCM levels in reactors during cleaning - no respirator
 - g. Incomplete compliance with VCM opening loss regulations and non-compliance with relief valve emissions even though all emissions were reported correctly and on time.
6. Could you give a brief summary of your recent experience with an OSHA or EPA inspection?

Typical reponse:

- a. OSHA inspection included 3 days of personnel monitoring for VCM and 1 day of PVC dust monitoring and other visits to the plant
- b. EPA was in the area and noticed black smoke from the incinerator stack and demanded an immediate inspection of the facility. We obliged and corrected the problem - also sent a letter to the EPA explaining the problem.

9/18/81

OCC 3035