To: Frank Stumpf

From: Harry Schneider

Subject: Fallout - Keystone Lamps Co.
Flatington, Pa.

EXHIBIT
DSN 101

00146

Date: 3/29/65

Complaint

The above job was sprayed by W=Armstrong, Phila in Jan. 1965. Mr. Hilner contacted me that fallouts are occuring in several areas.

I visited the jot on 3/29/65 with Mr. Hilner. The Type 'D' material had delaminated cleanly from the deck in four areas of about 2 square feet each The mat showed signs of continuing this action, as it could be seen hanging from the deck in the areas of fallout.

Don Hilner reported the weather conditions were possibly at or below the freezing mark when material was applied, However, since condensation could be seen on the deck, he knew there was no ice film present. The deck was wiped clean and spraying progressed. The area below is shop for manufacturing tubing & small parts for lamps.

Samples will be brought to lab the week of 4/5/65 for analysis. Please check for any signs of "rolling oil" used in making tubing or can we detect that freezing occured after application. Conditions seem to parallel FOB Balto, but different base and material and application!??