3. No smoking, eating or drinking is to take place once beyond the clean room at the job site. Prior to smoking, eating or drinking, workers will fully decontaminate by showering. Each worker will then dress into a new clean disposable coverall to east, smoke or drink. This new coverall can then be used to reenter the work area.

4. Work footwear will remain inside work area until completion of the job.

5. Pre-Asbestos Removal Preparation

   a. The contractor will thoroughly seal all openings and fixtures including, but not limited to, heating and ventilating ducts, sky lights, doors, windows, and lighting with polyethylene taped securely in place.

   b. Polyethylene sheets (6 mil minimum) will be used to cover the entire floor and wall surfaces.

   c. The contractor will set up a decontamination facility in a predesignated area which will house the changing room, shower area, and equipment area.

   d. Adequate toilet facilities should exist in the work area to avoid decontamination for this purpose. Where such facilities do not exist, the contractor will provide portable service.

   e. Procedures will be written for evacuation of injured workers. Aid for a seriously injured worker will not be delayed for reasons of decontamination.

8006 0384

PRODUCED BY FORD