FILE NAME: Ford (FD)

DATE: 1975 Oct 24

DOC#: FD029

DOCUMENT DESCRIPTION: Technical Service Bulletin

A. Anderson, Exhibit 2
5/4/98 Block v Maremont

TECHNICAL SERVICE BULLETIN

FORD PARTS AND SERVICE DIVISION

OCTOBER 24, 1975 — BULLETIN NUMBER 99

FORD — MERCURY LINCOLN — FORD TRUCKS

"Our goal: No unhappy owners."

BULLETIN CONTENTS

FORD

ARTICLE NO			PAGE
GENERAL			
1264	1976 MODEL RADIO FLOAT PROGRAM	1976 ALL CARS EQUIPPED WITH AM FM MONAURAL, AM FM MPX, AM FM STEREO TAPE AND AM FM STEREO SIGNAL SEARCH	4
BODY			
1265	DOOR TRIM PANEL - BULGE AND/OR MOULDING CRACKS IN PULL HANDLE AREA	1975 FORD MODELS 53L 60L	5
1266	FRONT SEAT BACK ANGLE ADJUSTMENT	1975 ½ GRANADA EQUIPPED WITH FLIGHT BENCH SEAT – MODELS 54H & A	6
1267	HEADLAMP COVER ORNAMENT ASSEMBLY PLASTIC INSERT MISSING	1975 FORD ALL VEHICLES SO EQUIPPED	7
1268	INSTRUMENT PANEL GLOVE BOX DOOR REPAIR	1974 75 MUSTANG	8
CHASSIS			
1269	BRAKE ASBESTOS FIBER DUST REMOVAL	ALL YEARS ALL CAR LINES	8
1270	UPPER AND LOWER BALL JOINT INSPECTION PROCEDURE	ALL 1974 - 1976 CAR LINES	9
ELECTRICAL			
1271	A C CONDENSER REFRIGERANT LEAK	1974, 75 & 76 TORINO AND ELITE	11
1272	AM FM/MPX STEREO SEARCH RADIO OPTION	1976 FORD, THUNDERBIRD AND ELITE SO EQUIPPED	11
1273	ANTI THEFT ALARM SYSTEM - IMPROVED DIAGNOSIS	ALL VEHICLES SO EQUIPPED	12
1274	BRAKE WARNING LIGHT FUNCTIONS	1976 - ALL CARLINES	13
1275	DOOR AJAR WARNING LIGHT STAYS ON WITH ALL DOORS CLOSED AND LATCHED	1975 76 THUNDERBIRD (TORINO TAXI ONLY) AND MUSTANG (ALL SO EQUIPPED)	14
1276	IGNITION COIL CAPACITOR WASHER MISSING	1976 FORD, TORINO, AND ELITE WITH 351 M or 400 CID ENGINES	14

(Continued on Page 2)

Service Manager	Parts Manager	Service Writer	Technician	Page 1

PROPERTY OF FORD MOTOR COMPANY

5-4-98 am
EXHIBIT
2

PRODUCED BY FOR

Article No. 1267

HEADLAMP COVER ORNAMENT ASSEMBLY —PLASTIC INSERT MISSING

FORD

1975 FORD ALL VEHICLES SO EQUIPPED

On vehicles encountered with the plastic insert (medallion) missing from the headlamp door ornament, the ornament assembly must be replaced. However, should the insert be retrievable, the part can be effectively recemented to the ornament housing using pressure activated vinyl adhesive kit, part number D2AZ-19554-A. Follow the instructions on the label.

PART NUMBER	PART NAME	CLASS
D5AZ 13A186-A	Ornament assembly	B
D2AZ-19554-A	Pressure Activated Vinyl Adhesive Kit	B

WARRANTY STATUS. Reimbursable within the provisions of the Warranty and Policy Manual.

OPERATION SP-13186-A-75

TIME 0.3 Hr. Replace Ornament 0.2 Hr. - Cement Ornament Insert

DLR CODING Basic Part Number 7013A186 - Code 33.

Article No. 1268

INSTRUMENT PANEL GLOVE BOX DOOR REPAIR

FORD

1974-75 MUSTANG

The glove box door is retained to the door inner panel by integral plastic studs that are staked over. Glove box doors with broken staking but no other damage can be satisfactorily repaired by installation of washer head screws, using the following procedure.

1. Remove the glove box door from vehicle and place on a clean work bench.
2. Using a hand held 3.8" twist drill (wrap tape over the sharp edges of the flutes), remove the broken plastic stakes. Remove sufficient stud material so that the washer head screws (No. 8-18 x 1/2") can clamp the inner panel to the door.
3. Install No. 8-18 x 1/2" washer head screws (procure locally).
4. Install glove box door in vehicle and adjust door utilizing the in-and-out adjustment of the lock striker.

WARRANTY STATUS: Reimbursable within the provisions of the Warranty and Policy Manual.

OPERATION: SP-08024-A-75

TIME. 0.3 Hr.

DLR. CODING: Basic Part No. 70[illegible]24 - Code 01

CHASSIS

Article No. 1269

BRAKE ASBESTOS FIBER DUST REMOVAL

FORD

ALL YEARS ALL CAR LINES

LINCOLN MERCURY

ALL YEARS - ALL CAR LINES

TRUCKS

ALL YEARS - ALL TRUCK SERIES

The following Caution Note should be cross referenced in Group 12, Volume I of the Car and Truck Shop Manuals when performing wheel brake repairs.

CAUTION: Dust and dirt conditions present on wheel brake assemblies and rotors and drums, may contain asbestos fibers that can represent a potential health hazard when made airborne by cleaning with compressed air.

All wheel brake assemblies should therefore be cleaned only with a vacuum cleaner suitable for use with asbestos fibers. This type of vacuum cleaner is available through the Rotunda Dealer Equipment Catalog. Dust and dirt from the vacuum cleaner should be disposed of in a manner that prevents dust exposure.

Any repairs done on brake linings, pads, rotors and drums, should be done using properly exhaust ventilated equipment.

WARRANTY STATUS: "INFORMATION ONLY"

PROPERTY OF
FORD MOTOR COMPANY

PRODUCED BY FOR

BODY (cont'd)

rticle No. 1267

HEADLAMP COVER ORNAMENT ASSEMBLY -PLASTIC INSERT MISSING

FORD

975 FORD ALL VEHICLES SO EQUIPPED

ve s encountered with the plastic insert (medallion) g from the headlamp door ornament, the ornament mbly must be replaced. However should the insert be ead the part can be effectively recemented to the ment using pressure activated vinyl adhesive t number D3AZ 19554-A. Follow the instructions on

PART NUMBER	PART NAME	CLASS
[illegible]	Ornament assembly	B
[illegible]	Pressure Activated Vinyl Adhesive Kit	B

WARRANTY STATUS Reimbursable within the provisions of the Warranty and Policy Manual.

PERATION SP 13[illegible] A 75

ME [illegible] Remove Ornament 0.2 Hr Cement Orna

CR CODING [illegible] Part Number 13A186 Code 33

rticle No. 1268

INSTRUMENT PANEL GLOVE BOX DOOR REPAIR

FORD

[illegible] retained to the door inner panel by [illegible] that are staked over. Glove box doors [illegible] staking but no other damage can be satisfac [illegible] installation of washer head screws, using [illegible]

[illegible] and place on

[illegible] tape over [illegible] broken plas [illegible] that the washi [illegible] 8-18 x 1.2 [illegible] clamp the inst [illegible]

3. Install No. 8-18 x 1/2" washer head screws (procure locally).

4. Install glove box door in vehicle and adjust door utilizing the in-and-out adjustment of the lock striker.

WARRANTY STATUS: Reimbursable within the provisions of the Warranty and Policy Manual

OPERATION SP 06024 A 75

TIME 0.3 Hr.

DLR CODING Basic Part No. 7006024 Code 01

T5B — NO 99

CHASSIS

Article No 1269

BRAKE ASBESTOS FIBER DUST REMOVAL

FORD

ALL YEARS ALL CAR LINES

LINCOLN-MERCURY

ALL YEARS ALL CAR LINES

TRUCKS

All Years [illegible]

[illegible]

CAUTION Dust and dirt conditions present on wheel brake assemblies and rotors and drums, may contain asbestos fibers that can represent a potential health hazard when made airborne by cleaning with compressed air.

All [illegible] brake assemblies should therefore be cleaned of [illegible] with cleaners suitable for use with asbestos fibers. [illegible] vacuum cleaner is available through the Rotunda Dealer Equipment Catalog. Dust and dirt from the vacuum [illegible] disposed of in a manner that prevents [illegible]

[illegible] work [illegible] a grinding [illegible] exhaust [illegible]

WARRANTY STATUS: INFORMATION ONLY

PROPERTY OF
FORD MOTOR COMPANY