

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	04/18/2025	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas Inspection)	
Company Name:	T2 Operating Corporation	
Facility Name:	Buckner #D-5 SWD	
Facility Physical Location:	Off U.S. Highway 82 at 33.36356, -93.415611	
(city, state, zip code)	Buckner, AR 71827	
Mailing address:	1800 Wazee Street, Suite 318	
(city, state, zip code)	Denver, CO 80202	
County/Parish:	Lafayette County	
Facility Phone Number	303-579-1129	
Facility Contact:	Gilbert Thompson	
	t.farel@tmdh-energy.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU002313	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Michael Blaha	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

Environmental Protection Agency (EPA) Region 6 inspectors Uma Lad, Kerri McCabe, and Michael Blaha arrived at the T2 Operating Corporation / Buckner #D-5 SWD (“facility”), located off U.S. Highway 82 at 33.36356, -93.415611, at 8:17 AM on 04/18/2025 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with EPA regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the T2 Operating Corporation / Buckner #D-5 SWD facility, which consists of one (3) storage tanks, two (2) separators, and one (1) pump.

Section II – OBSERVATIONS

I observed the facility and associated signage and secondary containment with storage tanks, separators, and pump; see Appendix 1 (Photograph Log), Photo No. 1 through No. 3. For additional GPS location and photo metadata, see Appendix 1.

I observed loose oil inside secondary containment for the separators, see Photo No. 4. I also observed loose oil inside secondary containment for the storage tanks and pump, see Photo No. 5 through No. 7.

I observed two (2) leaking pipes or valves connected to the storage tank battery, see Photo No. 6 and No. 7.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel from T2 Operating Corporation present during the inspection. The areas of concern observed during the inspection include the loose oil inside secondary containment and the multiple leaking pipes and/or valves connected to the storage tanks.

Section IV – FOLLOW UP

Inspector will provide the completed inspection report to company representative(s).

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log* – 7 photos taken 04/18/2025.

**The photos were captured in HEIC format and converted to JPG format for the purpose of drafting the Photograph Log. The original photos are retained with their metadata.*

Appendix 1

Photograph Log 7 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132345306_iOS

Orientation: North

Date of Photo: 04/18/2025

Time of Photo: 8:23 AM

Latitude: 33.363544

Longitude: -93.415611

Photographer: Uma Lad

Description: Looking north, this photo shows the sign at the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132448072_iOS

Orientation: East

Date of Photo: 04/18/2025

Time of Photo: 8:24 AM

Latitude: 33.363441

Longitude: -93.415930

Photographer: Uma Lad

Description: Looking east, this photo shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132450257_iOS

Orientation: Northeast

Date of Photo: 04/18/2025

Time of Photo: 8:24 AM

Latitude: 33.363444

Longitude: -93.415944

Photographer: Uma Lad

Description: Looking northeast, this photo shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132537509_iOS

Orientation: North

Date of Photo: 04/18/2025

Time of Photo: 8:25 AM

Latitude: 33.363619

Longitude: -93.415808

Photographer: Uma Lad

Description: Looking north, this photo shows loose oil inside secondary containment for the separator.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132635415_iOS

Orientation: Northeast

Date of Photo: 04/18/2025

Time of Photo: 8:26 AM

Latitude: 33.363605

Longitude: -93.415650

Photographer: Uma Lad

Description: Looking northeast, this photo shows loose oil inside secondary containment for the tanks.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132714273_iOS

Orientation: East

Date of Photo: 04/18/2025

Time of Photo: 8:27 AM

Latitude: 33.363586

Longitude: -93.415658

Photographer: Uma Lad

Description: Looking east, this photo shows loose oil inside secondary containment for the tanks and a leaking pipe.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Location: Off U.S. Highway 82 at 33.36356, -93.415611		
City: Buckner	County/Parish: Lafayette	State: AR



Photo File Name: 20250418_132751378_iOS

Orientation: North

Date of Photo: 04/18/2025

Time of Photo: 8:27 AM

Latitude: 33.363547

Longitude: -93.415572

Photographer: Uma Lad

Description: Looking north, this photo shows loose oil inside secondary containment for the tanks and a leaking pipe.