

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Jeanne Eckhart	Inspection Date	05/23/2023	Time	14:00
Inspection Due	2018-05-04T00:00:00Z	Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2698000		
		API Well No			
		Lease Name	NRU		
		Well ID	03-02W		
Location	SW 10 24N 07E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.565891	Longitude	-96.54794		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	02/25/2016	Last Test Result	Fail
Casing	3.5	Tubing	2.0625	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 672
FLM Canister Pressure		Actual Pressure	Max Volume		
Lease Status		Determined?	Max Inj Units Barrels Per Month		
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	A fluid level was taken with a properly calibrated EPA Echometer. The fluid level taken during the inspection was 584 feet deep. This well was not connected during the inspection. The casing size was approximately 3.5". Two photographs were taken during this inspection and can be seen in the Inspection Photo Log.				
Inspector Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2023.06.21 08:01:59 -05'00'				
Supervisor Signature	ENOCH JOHNBULL Digitally signed by ENOCH JOHNBULL Date: 2023.06.22 08:56:32 -05'00'				

Appendix 1

Photograph Log

2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.565891, -96.54794		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010155.JPG

Orientation: N

Date of Photo: 05/23/2023

Time of Photo: 1:58 PM

Latitude: 36.565891

Longitude: -96.54794

Photographer: Jeanne Eckhart

Description: This was the injection well OS2698000 sign at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.565891, -96.54794		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010156.JPG

Orientation: NE

Date of Photo: 05/23/2023

Time of Photo: 2:03 PM

Latitude: 36.565891

Longitude: -96.54794

Photographer: Jeanne Eckhart

Description: This was the injection well OS2698000 at the time of the inspection. It was not connected. I observed multiple liners in this well during the inspection and estimated the casing size with on site representative to be ~3.5".