

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/03/2025	Time	09:00
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS0751000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name SBU			
	Allen, TX 75013	Well ID R-W9			
	Phone: 832-300-8221				
Location	SW 10 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.656191	Longitude	-96.653177		
Inspection Reason	Plugging Witnessed	Responsible Company at		CapturePoint, LLC	
		Time of Inspection			
Inspect No.		Date Last MIT	10/26/1988	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 768
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments		Inspector observed Hurricane Services Inc (HSI) tag the top of the bottom cement plug at 2500 feet. HSI loaded the well with 9ppg mud from 2500 feet to 1500 feet. The well was perforated at 1500 feet. HSI squeezed 150 sacks of class A cement at 1500 feet.			
Inspector Signature					
Supervisor Signature					