

To: Bill Kongable
Carl Dubon

Safety Inspection
Aug 26, 1963

The following items were noted as safety hazards in the UCM area inspection conducted Aug 26, 1963

- ✓ 1. Hot condensate splashing on pad by 2254-2#3 ± NW corner of
refining area. Quantity splashing was considered hazardous to
passers-by. (147700)
- ✓ 2. Calibration gas cylinder inside analyzer house not secured. 147701
- ✓ 3. No guard on conveyor belt in catalyst building. (147701)
4. Two air hoses strung across catalyst building is tripping hazard.
5. Crows foot laying in walkway by 22E15
6. Old light bulbs laying at head of stairs by 22E23 o.k. Jack
7. Hoses not racked top deck 22E16 o.k. Jack
- ✓ 8. Silver cover off by 22P54 o.k. Jack
9. Wooden steps by 22E1-1 LC were rotten.
10. Work area under north reactor extremely congested with hoses.

RL Buttz
L. Vickrey