

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	1/27/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Petco Petroleum Corporation	
Facility Name:	Jemm Richards	
Facility Physical Location:	35.981245, -96.571897 (SW Sect. 4, T 18N, R 7E)	
(city, state, zip code)	Drumright, Oklahoma 74030	
Mailing address:	10300 Greenbriar Place	
(city, state, zip code)	Oklahoma City, Oklahoma 73159	
County/Parish:	Creek County	
Facility Phone Number	630-654-2282	
Facility Contact:	Elliot Hedin	
	JDBERGMAN@AOL.COM	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Petco Petroleum Corporation oil and gas facility located near Drumright, Oklahoma on 01/27/2020 for an unannounced inspection. There were no representatives of Petco Petroleum Corporation present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility has a tank battery and is known as the Jemm Richards Lease.

Section II - OBSERVATIONS

This inspection was conducted in response to a reported and observed recent oil spill to a nearby creek under highway 33. With a calibrated YSI Pro 30 conductivity meter, I observed slightly elevated levels of Total Dissolved Solids (TDS) in the creek that measured 2,100 milligrams per liter (mg/L). I observed oil pads and booms in place along the creek to assist in the cleanup of the oil spill. I observed residual oil and oil sheen in the creek during the inspection. An EPA on-scene coordinator from R6 was in the process of monitoring the cleanup actions being conducted, according to the operator. The salt water facility secondary containment pit had recently been pumped out prior to the inspection.

Section III – AREAS OF CONCERN

Clean up activities were underway to address an oil spill that had contaminated soil and water within the area, including the creek, near the spill point of discharge.

Section IV – FOLLOW UP

EPA water enforcement will conduct a follow up inspection in approximately 3 months.

Section V – LIST OF APPENDICES

N/A