

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	August 27, 2018		
Media:	SDWA Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	Diamond 3S, LLC		
Facility Name:	Kennedy		
Facility Physical Location:	SW/4, Sec. 33, T , R		
(city, state, zip code)	Pawhuska, Oklahoma		
Mailing Address:	20102 West Coyote Trail		
(city, state, zip code)	Sand Springs, OK 74063		
County/Parish:	Osage		
Facility Contact	N/A	N/A	
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	OKU000867		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	K.W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date			
	Kent Sanborn		Date
Supervisor Signature/Date for			
	Guy Tidmore		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Diamond 3S, LLC oil production facility located in the Latitude: 36.587028, Longitude: -96.498042 near Pawhuska, on August 27, 2018. No representative of Diamond 3S, LLC was present for the inspection. The inspection was conducted by authority of the Safe Drinking Water Act and the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This injection well is known as the Kennedy 3 well and the lease is known as the Kennedy Lease.

Section II - OBSERVATIONS

I observed that there was contaminated dirt still on the lease roads during the inspection. The tributary had elevated Total Dissolved Solids (TDS) readings. With a calibrated YSI Pro 30 Conductivity Meter, TDS readings between 7,000 mg/L and 17,000 mg/L were taken. The tributary was not flowing during the inspection. I did not observe remedial activities during the inspection. The injection well known as the Kennedy 3 was not injecting during the inspection.

Section III - AREAS OF CONCERN

There were elevated levels of TDS in the tributary during the inspection.

Section IV - FOLLOW UP

Conduct a follow up inspection as needed.

Section V - LIST OF APPENDICES

There are no attachments to this report.