

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	04/11/2023	Time	14:30
Inspection Due		Operator Representative	CEP Mid-Continent, LLC		
Operator Info	CEP Mid-Continent, LLC 1560 E. 21st Street, Suite 215 Tulsa, OK 74114 Phone: 918-281-5274	Inventory ID	OS5307000		
		API Well No			
		Lease Name	O.I.R		
		Well ID	8		
Location	SE 19 22N 12E	Status	Inactive	Well Type	Disposal
Latitude	36.363129	Longitude	-96.052573		
Inspection Reason	Plugging Witnessed		Responsible Company at Time of Inspection	CEP Mid-Continent	
Inspect No.		Date Last MIT	07/20/2022	Last Test Result	F
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 150
FLM Canister Pressure		Actual Pressure	0		Max Volume 24000
Lease Status	Inactive	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Speedy Well Service (SWS) tag the top of cement on the bottom plug and pump the cement top plug on well OS5307000. SWS ran in hole to 2000 feet below land surface and tagged the top of cement on the bottom plug which had been placed on 4/6/2023. SWS pulled up to 255 feet below the land surface and circulated 20 sacks of class A cement to the surface. Inspector observed no areas of concern during the placement of the cement top plug.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2023.05.03 16:09:34 -05'00'				
Supervisor Signature	DAMON MCELROY Digitally signed by DAMON MCELROY DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=DAMON MCELROY, 0.9.2342.19200300.100.1.1=68001003655653 Date: 2023.05.03 21:46:49 -05'00'				

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.363140, -96.052570		
City: Skiatook	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010098

Orientation: N/A

Date of Photo: 04/11/2023

Time of Photo: 1:00 PM

Latitude: 36.363140

Longitude: -96.052570

Photographer: Matthew Allen

Description: Well OS5307000 with cement circulated to surface. No areas of concern at the time of the inspection.