

ATTACHMENT C
Goose Pond Site Inspection Report

Ludowici, Georgia
June 16, 2021

Overview Map





Attributes	
Title	Photo 1
Comment	Taken by Rachel Earwood
Description	Road leading to lake that is pumped, looking from Carolina Bay; striking west.



Attributes	
Title	Photo 2
Comment	Taken by Rachel Earwood
Description	Road to pumped lake, looking toward sand ridge; striking northwest.




Attributes	
Title	Photo 3
Comment	Taken by Rachel Earwood
Description	Road to pumped lake, looking toward sand ridge; striking southwest.




Attributes	
Title	Photo 4
Comment	Taken by Rachel Earwood
Description	Head of ditch looking toward mine/Bay from upland position; striking southeast-south.




Attributes	
Title	Photo 5
Comment	Taken by Rachel Earwood
Description	Soil profile of sample location A4.




Attributes	
Title	Photo 6
Comment	Taken by Rachel Earwood
Description	Ditch, which flows into Bull Swamp Creek, viewed from top of earthen plug; striking southeast.




Attributes	
Title	Photo 7
Comment	Taken by Rachel Earwood
Description	Ditch viewed from top of earthen plug; striking north.




Attributes	
Title	Photo 8
Comment	Taken by Rachel Earwood
Description	Second ditch located closer to overflow pond; striking west.




Attributes	
Title	Photo 9
Comment	Taken by Rachel Earwood
Description	Looking from ledge and downwards toward second ditch with stagnant water; striking east.



Attributes	
Title	Photo 10
Comment	Taken by Rachel Earwood
Description	Looking from ledge and downwards toward second ditch; striking southeast.



Attributes	
Title	Photo 11
Comment	Taken by Rachel Earwood
Description	Unfamiliar plug in second ditch; striking south-southeast.



Attributes	
Title	Photo 12
Comment	Taken by Rachel Earwood
Description	Overflow pond; striking southwest.

