

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/18/2024	Time	11:00
		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS0810000		
		API Well No			
		Lease Name	LONG		
		Well ID	4		
Location	NW 02 22N 07E	Status	Active	Well Type	Dual Completion
Latitude	36.418832	Longitude	-96.526304		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT	10/29/2016	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 780
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Calgary Energy, LLC run in hole and tag the top of the bottom cement plug at 2275 feet below the land surface. Calgary Energy, LLC filled the hole with mud from 2275 feet to 320 feet, then pulled out of the hole and equipped a casing knife on the tubing. Calgary Energy, LLC ran in hole to 320 feet and perforated the casing, then removed the casing knife and ran back into 320 feet below surface. 130 sacks of cement were circulated to the surface. Inspector observed cement standing at the surface with no fall back.				
Inspector Signature	MATTHEW ALLEN		Digitally signed by MATTHEW ALLEN Date: 2024.07.29 19:41:36 -05'00'		
Supervisor Signature	JEANNE ECKHART		Digitally signed by JEANNE ECKHART Date: 2024.07.30 13:38:20 -05'00'		

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.418832, -96.526304		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010493

Orientation: N/A

Date of Photo: 7/18/2024

Time of Photo: 5:35 PM

Latitude: 36.418832

Longitude: -96.526304

Photographer: Matthew Allen

Description: This was well OS0810000 with cement circulated to the surface.