

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/01/2025	Time	10:30	
		Operator Representative great horned owls, LLC				
Operator Info	great horned owls, LLC	Inventory ID OS3046000				
	27411 Myrtle Lake Lane	API Well No				
	Katy, TX 77494	Lease Name MBU				
	Phone: 833-523-3695	Well ID WILFR14				
Location	NE 03 26N 06E	Status	Inactive	Well Type	Enhanced Recovery	
Latitude	36.762917	Longitude	-96.637679			
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	great horned owls, LLC			
Inspect No.		Date Last MIT	05/21/2014	Last Test Result	Fail	
Casing	4.5	Tubing		USDW		
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N Unknown N N N N	Tubings	Annulus	AUTHORIZED		
		Fittings	N	N	Max Pressure	755
		Actual Pressure			Max Volume	
		Determined?			Max Inj Units	Barrels Per Month
		Static Fluid Level				
		Determined?				
		Injection Rate (bpd)				
Inspection Comments		Inspector observed the location for well OS3046000 according to location information on file in the EPA/UIC records. The well appears to have been plugged and the location fully restored. No well present at or near the location.				
Inspector Signature	MATTHEW ALLEN JEANNE ECKHART		Digitally signed by MATTHEW ALLEN Date: 2025.12.09 09:32:56 -06'00'			
Supervisor Signature			Digitally signed by JEANNE ECKHART Date: 2025.12.10 07:15:00 -06'00'			

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.762917, -96.637679		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010757

Orientation: NE

Date of Photo: 10/01/2025

Time of Photo: 10:30AM

Latitude: 36.762917

Longitude: -96.637679

Photographer: Matthew Allen

Description: This was the location of well OS3046000 according to EPA records. At the time of the inspection there was no well present and the location was restored and fully recovered.