

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

July 1, 1987

TO: P. R. Desai

CC: G. F. Painter*
H. J. Shoger*

Re: SHARE Inspection Results


Dear Prayful:

You will find attached a copy of the findings from the SHARE inspection held July 1, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and
2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.



S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Aug. 1, 1987)	60 Days (Sep. 1, 1987)	90 Days (Oct. 1, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008462

Department Title Mainland Chemicals Dept. No. 077 Location B-42, B-41, B-5, B-6 Date of Inspection 7/1/87
 Inspector Sub-D. HANSHAW Phone No. 3144 Inspection Responsibility ENV Prot. Date of Report 7/1/87
 Submitting Report on Cassier, T. Caldwell

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Ord. Number
EP-1	1/2 Gal of Oil (?) in plastic 1 gal container.				
	Should be properly labeled (ID, date, etc.)	✓			
	Location: west of #19 still under switchbank (B42)				
EP-2	Broken Insulation on line				
	(Asbestos?) Fritter. If Asbestos	✓			
	should be sealed to prevent fiber loss. (B42)				
EP-3	South end of #5 still pot near open doorway				
	Unlabeled Drum -				
	Above #5 still pot on platform B-42				
EP-4	open ended line - (≈ 1'14")				
	stairwell walkway	✓			
	personal hazard from spray				
EP-5	south of Tank 552				
	Tanks 513, 514, 521, 522				
	No curbs on pumps to prevent oil from entering clean sewer				
	Tagged on EP-4 on 12/3/86				

513 514 521 522

P.G.

Department Title Maidland Chemical Dept. No. 077 Location Bldg 4 Date of Inspection 7/1/87

Inspector Sub-mitting Report H.H. Price Phone No. 2953 Inspection Responsibility Insulation Date of Report 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Order Number
1N1	Exposed Insulation Bldg 4 1st Floor W. Side	✓	Patch & Seal		
1N2	Exposed Ins. East End No 1 Autoclave and Land Bldg 4	✓	Patch & Seal		
1N3	Exposed ins Asbestos in Bldg 5 3rd Land	✓	Strip & Reinsulate Part of Line		
1N4	Exposed ins and Floor Bldg 6 2 places.	✓	Seal & Patch		
1N5	Exposed Ins. Bldg 4 2 1st Floor S. Wall at door & stairway	✓	Seal		

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

P.O.

Department Title Mandstone Chemicals Dept. No. 027 Location Blkg 456 Date of Inspection 7/1/87

Inspector Sub-mitting Report HH Price Phone No. 2853 Inspection Responsibility Insulation Date of Report 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Order Number
1N6	Exposed Ins. So. East Corner Bldg 42 1st Floor		Patch & Seal		
1N7	Exposed Insulation stair way going to 2nd Floor Both sides stair way Bldg 42	✓	Strip & Reinsulate		
1N8	Exposed Ins and 42 East End #42	✓	Patch & Seal		
1N9	Exposed Asbestos 2nd Floor 42 East End	✓	Strip & Reinsulate		
1N10	Exposed Ins at stair way Both sides going from 2nd to 3rd East end 42 Under Grating	✓	Strip & Reinsulate		

Page 3 of 3

Department Title Maid Land Chem Dept. No. 077 Location 406542 Date of Inspection 7/1/87
 Inspector Submitting Report AH Price Phone No. 2953 Inspection Responsibility Insulation Date of Report 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Corrected	Shop Order Number
1N11	Exposed Ins. 3rd Land East End H ₂ O	✓	Strip & Reinsulate		
1N12	Exposed ins. in Back Tank - Pump Running East West between 298-750	✓	Strip & Ins.		
1N13	Exposed in Back	✓	strip		