

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	04/15/2025	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Enerco Operating Corporation	
Facility Name:	Beauford Su-Tokio Tank Battery and Beauford Armstrong-1, BSU-2, Beauford A-2, Tokio 6-4, 8-1, Armstrong B-2 Tank Battery	
Facility Physical Location:	Off County Road 249 at 33.316453, -93.812277	
(city, state, zip code)	Genoa, AR 71839	
Mailing address:	P.O. Box 1491	
(city, state, zip code)	Shreveport, LA 71164	
County/Parish:	Miller County	
Facility Phone Number	870-953-0287	
Facility Contact:	Terry Collum	Field Supervisor
	terrycollum@enercooperating.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU002310	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Michael Blaha	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

Environmental Protection Agency (EPA) Region 6 inspectors Uma Lad, Kerri McCabe, and Michael Blaha arrived at the Enerco Operating Corporation / Beauford Su-Tokio Tank Battery and Beauford Armstrong-1, BSU-2, Beauford A-2, Tokio 6-4, 8-1, Armstrong B-2 Tank Battery, located off County Road 22 at 33.316453, -93.812277, at 4:40 PM on 04/15/2025 for an unannounced inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with EPA regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Enerco Operating Corporation / Beauford Su-Tokio Tank Battery and Beauford Armstrong-1, BSU-2, Beauford A-2, Tokio 6-4, 8-1, Armstrong B-2 Tank Battery, which consists of ten (10) storage tanks and six (6) separators.

Section II – OBSERVATIONS

I observed the facility, associated signage, and secondary containment with separators and storage tanks; see Appendix 1 (Photograph Log), Photo No. 1 through No. 4. For additional GPS location and photo metadata, see Appendix 1.

I observed low spots on the secondary containment berm for the separators, see Photo No. 5. Inside secondary containment for the separators, I observed loose oil on the ground and a separator that was out of service but not labeled or marked “out of service,” see Photo No. 6. I also observed a pipe that was leaking, see Photo No 7; oil staining was present in the area beneath the leaking pipe. I observed a missing pipe support under the dump valve, see Photo No. 8.

I observed low spots on the secondary containment berm for the tanks, see Photo No. 10. Inside secondary containment for the tanks, I observed loose oil and salt on the ground, see Photo No. 9, No. 11, and No. 12. I observed a pipe that was leaking from a tank, see Photo No 11. I also observed gaps under a tank, see Photo No. 12.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel from Enerco Operating Corporation present during the inspection. Areas of concern at the time of the inspection include:

- Low spots on the secondary containment berms for both storage tanks and separators,
- Loose oil inside secondary containment for the separators,
- Loose oil and salt inside secondary containment for the storage tanks,
- An out of service separator not labeled “out of service,”
- Leaking pipes from a separator and a storage tank,
- A pipe connected to separator missing a pipe support.

Section IV – FOLLOW UP

Inspector will provide the completed inspection report to company representative(s).

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log* – 12 photos taken 04/15/2025.

**The photos were captured in heic format and converted to jpg format for the purpose of drafting the Photograph Log. The original photos are retained with their metadata.*

Appendix 1

Photograph Log 12 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214218046_iOS

Orientation: E

Date of Photo: 04/15/2025

Time of Photo: 4:42 PM

Latitude: 33.316453

Longitude: -93.812277

Photographer: Uma Lad

Description: Looking east, this photo shows Su-Tokio Tank Battery facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214323874_iOS

Orientation: NE

Date of Photo: 04/15/2025

Time of Photo: 4:43 PM

Latitude: 33.316342

Longitude: -93.812447

Photographer: Uma Lad

Description: Looking northeast, this photo shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214906981_iOS

Orientation: S

Date of Photo: 04/15/2025

Time of Photo: 4:49 PM

Latitude: 33.316528

Longitude: -93.812003

Photographer: Uma Lad

Description: Looking south, this photo shows a sign for the storage tanks at the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214446353_iOS

Orientation: NE

Date of Photo: 04/15/2025

Time of Photo: 4:44 pm

Latitude: 33.316364

Longitude: -93.812472

Photographer: Uma Lad

Description: Looking northeast, this photo shows an overview of the tanks at the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214643050_iOS

Orientation: NW

Date of Photo: 04/15/2025

Time of Photo: 4:46 PM

Latitude: 33.316497

Longitude: -93.812011

Photographer: Uma Lad

Description: Looking northwest, this photo shows low spots on the secondary containment berm for the separators.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214430157_iOS

Orientation: E

Date of Photo: 04/15/2025

Time of Photo: 4:44 PM

Latitude: 33.316381

Longitude: -93.812303

Photographer: Uma Lad

Description: Looking east, this photo shows the separators with loose oil on the ground inside secondary containment. The separator on the left side of photo is out of service, but not labeled.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214710011_iOS

Orientation: NW

Date of Photo: 04/15/2025

Time of Photo: 4:47 PM

Latitude: 33.316594

Longitude: -93.812172

Photographer: Uma Lad

Description: Looking northwest, this photo shows a leaking pipe from a separator. Oil staining is present below the leaking pipe.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214756473_iOS

Orientation: SW

Date of Photo: 04/15/2025

Time of Photo: 4:47 PM

Latitude: 33.316578

Longitude: -93.812186

Photographer: Uma Lad

Description: Looking southwest, this photo shows a missing pipe support under the dump valve.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 9

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_214512050_iOS

Orientation: NE

Date of Photo: 04/15/2025

Time of Photo: 4:45 PM

Latitude: 33.316497

Longitude: -93.81205

Photographer: Uma Lad

Description: Looking northeast, this photo shows loose oil on the ground inside secondary containment for the storage tanks.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 10

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_215003522_iOS

Orientation: E

Date of Photo: 04/15/2025

Time of Photo: 4:50 PM

Latitude: 33.316381

Longitude: -93.812164

Photographer: Uma Lad

Description: Looking east, this photo shows lows spots on the secondary containment berm for the storage tanks.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 11

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_215108291_iOS

Orientation: S

Date of Photo: 04/15/2025

Time of Photo: 4:51 PM

Latitude: 33.316539

Longitude: -93.811967

Photographer: Uma Lad

Description: Looking south, this photo shows a leaking pipe at a storage tank. The photo also shows loose oil and salt on the ground inside secondary containment for the storage tanks.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 12

Location: Off County Road 249 at 33.316453, -93.812277		
City: Genoa	County/Parish: Miller	State: AR



Photo File Name: 20250415_215225893_iOS

Orientation: E

Date of Photo: 04/15/2025

Time of Photo: 4:52 PM

Latitude: 33.316372

Longitude: -93.811883

Photographer: Uma Lad

Description: Looking east, this photo shows a gap under a storage tank that extends under the tank and loose oil and produced water inside secondary containment for the tanks.