

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/01/2024	Time	14:40
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID	OS4674000		
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name	Burbank S		
	Allen, TX 75013	Well ID	J-W15		
	Phone: 832-300-8221				
Location	SW 03 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.673477	Longitude	-96.64076		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	05/20/2014	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N	Tubings	Annulus	AUTHORIZED	
		Fittings	N	N	Max Pressure 270
		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
		Static Fluid Level			
		Determined?			
		Injection Rate (bpd)			
Inspection Comments		Inspector observed surface restoration was completed at the well location.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.673477, -96.64076		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010515

Orientation: SSE

Date of Photo: 10/01/2024

Time of Photo: 2:42 PM

Latitude: 36.673477

Longitude: -96.64076

Photographer: Matthew Allen

Description: This was the location for well OS4674000 with surface restoration completed.