

US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

*ALL PHOTOGRAPHS WERE TAKEN BY MICHAEL PRESCOTT USING A HEWLETT
PACKARD PHOTOSMART M547*

*PLEASE NOTE THAT DUE TO AN ERROR IN SETTING THE TIME ON THE
CAMERA, THE DATE AND TIME STAMPS ON THE PHOTOS ARE 36 HOURS
EARLIER THAN WHEN THE PHOTOS WERE TAKEN.*

DATE TAKEN: 11/17/22

PHOTO #: 1

COMMENTS: An oil storage room showing 55-gallon drums of oil and transmission fluid on secondary containment pallets.

SITE LOCATION: Inside the VMF Building




US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 2

COMMENTS: Another oil storage room with a 1000-gallon two compartment aboveground storage tank (AST) for new oil and transmission fluid. Note the fill points for the two compartments are inside this room.

SITE LOCATION: Inside the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 3

COMMENTS: Maintenance bay for washing vehicles and two manhole covers for the two 2000-gallon USTs that collect the washwater for pumping out by a truck for off-site disposal.

SITE LOCATION: Inside the VMF Building



US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 4

COMMENTS: Views of fuel island with dispensers and the covers to the used oil underground storage tank (UST) in the foreground and oil water separator next to the building.

SITE LOCATION: Outside the front of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 5

COMMENTS: Top of diesel UST and fuel dispensers in background.

SITE LOCATION: Outside the front of the VMF Building



US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 6

COMMENTS: Oil and diesel stains around one of the fuel dispensers.

SITE LOCATION: Outside the front of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 7

COMMENTS: Another view of the oil and diesel stains around one of the fuel dispensers looking toward the stormwater drain in the background.

SITE LOCATION: Outside the front of the VMF Building



US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 8

COMMENTS: View of drain where stormwater from the fueling area flows to. There was no oil sheen visible on the surface of the water in the drain.

SITE LOCATION: Outside the front of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 9

COMMENTS: View of storm drain in the foreground and the covered metal parts dumpster and adjacent covered storage area for tires and empty containers.

SITE LOCATION: Outside the back of the VMF Building



US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 10

COMMENTS: Covered storage area
for tires and empty containers.

SITE LOCATION: Outside the back of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 11

COMMENTS: HAZMAT locker for
hazardous materials and wastes.

SITE LOCATION: Outside the back of the VMF Building



US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 12

COMMENTS: Closer view of covered dumpster for used metal parts.

SITE LOCATION: Outside the back of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 13

COMMENTS: View inside opened HAZMAT locker for hazardous materials and wastes.

SITE LOCATION: Outside the back of the VMF Building




US POSTAL SERVICE SPRINGFIELD VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/17/22

PHOTO #: 14

COMMENTS: Another view of the stormwater drain in the foreground and the covered metal parts dumpster to the right and the covered trash dumpster and vehicle parking straight ahead.

SITE LOCATION: Outside the back of the VMF Building



DATE TAKEN: 11/17/22

PHOTO #: 15

COMMENTS: Some oil stains where vehicles were parked.

SITE LOCATION: Outside the back of the VMF Building

