

HFC Import Inspection Worksheet

This worksheet is for inspection of Imported Hydrofluorocarbons (HFCs) subject to 40 CFR Part 84

Insp. No: 202407241020

Insp. Date: 7/24/2024

Inspector(s): E. Michael, E. Nystrom, E. Felix

Start Time/Stop Time: 10:20-10:39

Location of Inspection

Facility Name: Ports America (PA)

Facility Type: Terminal (sea side port)

Address: 5901 Terminal Drive, New Orleans, LA 70115

CBP POC Contact Information: Melinda Tonglet, melinda.f.tonglet@cbp.dhs.gov, 504-670-2169

☐ Indicate here if entry was not filed at time of inspection

Importer Information (from Entry Documents)

☐ Indicate here if consignee is the same as importer

Importer Name: SUTTONS INTERNATIONAL

Importer Address: GORSEY LANE, WIDNES CHESIRE

Importer No : Not Observed

Consignee Name: SUTTONS INTERNATIONAL N.A. INC

Consignee Address: BLDG 4,FLR2,STE 200, 101 CRAWFORD CORNER RD, HOLMDEL NJ, USA

POC Contact Information: 1-732-549-3535

Visual Inspection #1

Product Description: EMPTY CLEAN SHIPPERS OWN CONTAINER

Chemical name/formula: N/A

Container Type: ☐ Service Can ☐ Ton Tank ☒ ISO Tank

☐ Refillable Cylinder ☐ Disposable Cylinder

Shipment No: 22135247518

Shipping Container No: EURO5325272

Arrival Date: 7/22/2024

Listed Qty: 1

Listed Mass: Not Obs.

Actual Mass: Not Obs.

☐ lb ☐ kg ☐ ton

Visual Inspection Notes: "eurotainer" markings observed on ISO tank. No chemical, product name, nor content markings observed on ISO tank. Prior labels appeared to have been removed from container, indicating prior use. ISO tank placard listed tare weight of 9,940 Kg, payload 24060 kg, total capacity 22,400 kg. The total cargo shipment weight was listed in bill of lading as 97,240 kg for 6 total packages. Placard showed ISO tank capable of storing HFCs.

Inspection Summary

Evidence/Samples taken and Description: None

Potential Follow-Up/Areas of Concern (e.g. potential deficiencies, actions taken by facility (if applicable)): Inspectors-in-training Michael & Nystrom led this inspection while being observed by credentialled inspector Felix.

Inspection photo numbers: 1909-1931

Camera Information: S08541, Nikon coolpix

Other:

Photographer: E. Michael

Lead Inspector Signature: Erin Michael

Supervisor Signature: AMELIE ISIN

Digitally signed by AMELIE ISIN
Date: 2024.08.22 16:43:27 -04'00'

Guidance for Inspectors:

Inspector should obtain copies of the following when conducting inspections for CBP:

• Entry documents

• Invoice/Packing lists

• Bill of lading

Inspector should obtain the following key photographs:

• All sides of container to include any labels.