

HFC Import Inspection Worksheet

This worksheet is for inspection of Imported Hydrofluorocarbons (HFCs) subject to 40 CFR Part 84

Insp. No: 20231206-0810

Inspector(s): ☐ E. Felix ☐ N. Dancher ☒ A. Isin ☐ J. Iatropulos

Insp. Date: 12/6/2023

Start Time/Stop Time: Start 8:03am, End 9:00am

Location of Inspection

Facility Name: Price 3

Facility Type: Customs and Border Protection (CBP) Warehouse

Address: 1119 E 230th St, Carson, CA 90745

CBP POC Contact Information: Kent Koike, 310-971-2700

☒ Indicate here if entry was not filed at time of inspection

Importer Information (from Entry Documents)

☒ Indicate here if consignee is the same as importer

Importer Name: Mexichem Fluor Inc.

Consignee Name:

Importer Address: 4990B ICI Road, PO Box 30, St. Gabriel, LA 70776

Consignee Address:

Importer No: 27-178566700

POC Contact Information: sean.cunningham@mexichem.com

Visual Inspection HFC #1

Product Description: HFC-134A

Shipment/ Entry No: 916-5041625-7

Chemical name/formula: 1,1,1,2-Tetrafluoroethane

Shipping Container No: INFL1001123

Container Type: ☐ Service Can ☐ Ton Tank ☒ ISO Tank

Arrival Date: 11/27/2023

☐ Refillable Cylinder ☐ Disposable Cylinder

Listed Qty: 1

Listed Mass: see below Actual Mass: N/A ☐ lb ☒ kg ☐ ton

On tank: Max Gross: 36,000 kg, Tare: 6,340 kg, Capacity: 21,500 Liters
Entry summary form and invoice list 17,880 kg.

Visual Inspection HFC #2

Product Description:

Shipment/ Entry No:

Chemical name/formula:

Shipping Container No:

Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank

Arrival Date:

☐ Refillable Cylinder ☐ Disposable Cylinder

Listed Qty:

Listed Mass: Actual Mass: ☐ lb ☐ kg ☐ ton

Visual Inspection Notes:

Visual Inspection HFC #3

Product Description:

Shipment/ Entry No:

Chemical name/formula:

Shipping Container No:

Container Type: ☐ Service Can ☐ Ton Tank ☐ ISO Tank

Arrival Date:

☐ Refillable Cylinder ☐ Disposable Cylinder

Listed Qty:

Listed Mass: Actual Mass: ☐ lb ☐ kg ☐ ton

Visual Inspection Notes:

Inspection Summary

Evidence/Samples taken and Description: None

Potential Follow-Up/Areas of Concern (e.g. potential deficiencies, actions taken by facility (if applicable)): N/A

Inspection photo numbers: PC060001.jpg-PC060022.jpg

Camera Information: ☐ Nikon Coolpix WD300 ☒ Sony Olympos

Other:

Photographer: ☐ E. Felix ☐ N. Dancher ☒ A. Isin ☐ J. Iatropulos

Lead Inspector Signature:

AMELIE ISIN

Digitally signed by
AMELIE ISIN
Date: 2023.12.22
13:39:36 -05'00'

Supervisor Signature:

Guidance for Inspectors:

Inspector should obtain copies of the following when conducting inspections for CBP:

- Entry documents
- Invoice/Packing lists
- Bill of lading

Inspector should obtain the following key photographs:

- All sides of container to include any labels.