



INTER-COMPANY AND OFFICE CORRESPONDENCE

TO: K. L. Macy, Jr.

FROM: D. L. Young

{ Dept.
Branch
Division
Company

LOCATED AT: Leominster, MA

SUBJECT: Personnel VCM TWA


DATE: September 3, 1981

RE: *JOHN RUSSO*
~~W. Asbury~~ and J. Proctor TWA's greater than 2.0.

Both high TWA's were the results of cleaning a reactor slurry transfer strainer basket. One incident took place in Bldg. 7 and the other in Bldg. 1 West.

To prevent recurrence of these high TWA's, the following will be done:

1. In Bldg. 7, extend exhaust duct to #4 strainer basket vent valve.
2. In Bldg. 1 West, extend exhaust duct to discharge end just above door.


D. L. Young
Production Superintendent
PVC Department

DLY/sma

cc: W. R. Salem

BOR 000128

John Hunter 37 TWA 5/15/81

FIXED IN WELL #7

WATER = 4" #7 NO KEEP OUT
JGL

FLDG #7L
3 TWA
8 H/G

FLDG #1W
1.73 TWA
21.9 H/G

FLDG #1W
37 TWA
6 H/G

FLDG #7E
35 TWA
6 H/G

1WL
5 TWA
3.1 H/G

25

CHECK STROKE COUNT
CALIBRATION PUMP
END READINGS.

#5