

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	10/07/2024	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	H & H Tank Cleaning	
Facility Name:	H & H Tank Cleaning	
Facility Physical Location:	Latitude: 33.35541, Longitude: -92.69422	
(city, state, zip code)	Smackover, AR, 71762	
Mailing address:	PO Box 265	
(city, state, zip code)	Smackover, Arkansas 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-6427	
Facility Contact:	Douglas Hodges rhodges319@aol.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002258	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad (lead)	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha, Kerri McCabe, and I, Uma Lad, arrived at a facility owned by H & H Tank Cleaning, located off a lease road near Gas Plant Road (33.35541, -92.69422) at 6:35 PM on October 7, 2024, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the H & H Tank Cleaning facility, which consists of five (5) storage tanks, one (1) separator, and two (2) out-of-service tanks.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, pipes, valves, and storage tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed loose oil from discharge valves outside of secondary containment, see photo No. 3 - 4. I also observed a discharge pipe connected to a storage tank, see photo No. 5.

Section III – AREAS OF CONCERN

No closing conference was held due to no H & H Tank Cleaning staff being present during the inspection. Areas of concern at the time of the inspection include the loose oil from the discharge valves outside of secondary containment and the discharge pipe connected to the storage tank.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 5 photos taken on 10/07/2024

Appendix 1

Photograph Log

5 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.35541, -92.69422		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: PA070032

Orientation: W

Date of Photo: 10/07/2024

Time of Photo: 6:35 PM

Latitude: 33.35541

Longitude: -92.69422

Photographer: Uma Lad

Description: This photo was taken looking west and shows the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.35541, -92.69422		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: PA070033

Orientation: W

Date of Photo: 10/07/2024

Time of Photo: 6:35 PM

Latitude: 33.35537

Longitude: -92.69418

Photographer: Uma Lad

Description: This photo was taken looking west and shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.35541, -92.69422		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: PA070034

Orientation: W

Date of Photo: 10/07/2024

Time of Photo: 6:36 PM

Latitude: 33.35523

Longitude: -92.69431

Photographer: Uma Lad

Description: This photo was taken looking west and shows a discharge valve with loose oil and no catchment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.35541, -92.69422		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: PA070035

Orientation: E

Date of Photo: 10/07/2024

Time of Photo: 6:41 PM

Latitude: 33.35553

Longitude: -92.69454

Photographer: Uma Lad

Description: This photo was taken looking east and shows a discharge valve with loose oil and no catchment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 33.35541, -92.69422		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: PA070036

Orientation: E

Date of Photo: 10/07/2024

Time of Photo: 6:42 PM

Latitude: 33.35538

Longitude: -92.69460

Photographer: Michael Blaha

Description: This photo was taken looking east and shows a discharge pipe connected to a tank.