

PLANT MANAGER'S SAFETY BOARD MEETING

MINUTES

August 17, 1977

Present:

N. Marabella (for George Bostick)	R. A. Newsom (for W. H. Lane)
P. E. Brubaker	R. C. Martini
J. E. Clark	C. M. McCullough
G. A. Danner	D. W. Metten
G. W. Daues	G. T. Ryan
W. C. Fuller	R. L. Stuart
J. A. Glass	J. G. Trafton

The plant manager dispensed with the prepared agenda and sent the Board members into the plant to talk with people and bring back their comments, concerns, and observations. The following is an abbreviated listing of items discussed during this meeting.

Listing of Concerns by PMSB Members

Brubaker - Visited Shops Area

- Pipefitter expressed concerns about lack of uniformity of application of beard rules.
- Machinists not too aware of the safety suggestion log book
- Electricians' log book contained a 1976 question not answered
- "Should consider incentives for safety"
- Hot weather is a contributing factor

Newsom - PT

- Safety orientation
- Injury report circulation
- Ice machine problem (ice used in iced tea?)
- Improper plugs on heaters and fans

SC 14120

Office and Clerical

- Most people feel that present problem is a "field" problem.

Ryan - West Plant

- Feel like it's a "let down" after startup of AN-5
- Usual problem with goggles and glasses of contract workers
- Pipefitter concerns over use of air masks in AN-5 and use of a back-up fitter with mask
- "Stick to basics" - and follow procedures

STG 2430965

LAM015909

McCullough - Shops, Instrument Dept., West Plant

- Lathe problem in main shop
- Instrument shop - good follow-up is the key
- AN shop entry was hazardous, disorderly
- There was an oil spill in the AN-5 WOB area that had been there three days
- Scaffold problems everywhere
- Hoses in walkways
- Scales in PE Packout - problem area
- Evidence of daily "Quickie" safety meetings
- Difference in levels of understanding by people in same unit or work area
- Supervision walking by little items

Danner - Distribution Areas

- Not close supervision of pumper-gauger operations

Stuart - Plant Streets and Tracks

- Still too much traffic in the plant

Trafton - West Plant

- Contractor safety violations
- Dept. 19 personnel concerned about problems related to fogging of cover goggles
- Sloppy housekeeping
- Maintenance supervision

Fuller - East Plant

- People are concerned that accidents are happening to experienced people

Clark

- Mental lapse is believed to be a key contribution to our loss experience.

SC

14121

STG 2430966

LAM015910

Glass - West Plant

- South of AN-5 control house -- bare wires coming out of conduit
- In WOB area -- oil slick around temporary air conditioner
- Jones Construction -- no safety equipment
- Construction jobs being stopped

Arnold
J. A. Glass *ry*

vf

SC

14122

STG 2430967

LAM015911