

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/04/2025	Time	12:45
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS0751000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name SBU			
	Allen, TX 75013	Well ID R-W9			
	Phone: 832-300-8221				
Location	SW 10 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.656191	Longitude	-96.653177		
Inspection Reason	Plugging Witnessed	Responsible Company at		CapturePoint, LLC	
		Time of Inspection			
Inspect No.		Date Last MIT	10/26/1988	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 768
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Hurricane Services Inc (HSI) tag the top of the middle plug at 1350 feet. HSI loaded the well with 9ppg mud from 1350 to 750 feet. The well was perforated at 750 feet. 300 sacks of class A cement were circulated from 750 feet to surface. Inspector observed cement circulating to surface and standing at the surface with no fallback. Inspector observed completion of well plugging operations in accordance with the EPA approved plugging procedures. A follow-up inspection will be conducted to ensure surface restoration is completed.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.656191, -96.653177		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010572

Orientation: N

Date of Photo: 2/04/2025

Time of Photo: 3:08 PM

Latitude: 36.656191

Longitude: -96.653177

Photographer: Matthew Allen

Description: This was well OS0751000 with cement circulated to surface.