

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	05/13/2025	Time	09:00
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS6273034			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name NBU			
	Allen, TX 75013	Well ID 15-W21			
	Phone: 832-300-8221				
Location	SW 11 27N 05E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.828024	Longitude	-96.741543		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection		CapturePoint, LLC	
Inspect No.		Date Last MIT	01/14/2020	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		AUTHORIZED	
Monitoring Device		Fittings	N	Annulus	N
FLM Canister Pressure		Actual Pressure		Max Pressure	850
Lease Status	Active	Determined?		Max Volume	124000
Barrel Monitor Hooked Up?	N	Static Fluid Level		Max Inj Units	Barrels Per Month
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Top of cement for the middle plug was tagged at 1396 feet below surface. 10lb/gal mud was placed from 1396 to 400 feet below surface. Well OS6273034 was perforated beginning at 350' below surface. 100 sacks of class A cement was circulated from 400 feet to surface. Well OS6273000 plugging procedures were completed as approved by EPA.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN Date: 2025.06.10 13:08:30 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2025.07.02 06:41:46 -05'00'				

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.828024, -96.741543		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010668

Orientation: N

Date of Photo: 5/13/2025

Time of Photo: 11:00 AM

Latitude: 36.828024

Longitude: -96.741543

Photographer: Matthew Allen

Description: This was well OS6273034 with cement circulated to the surface.