

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	4/22/2025	
Media Program:	Water, Clean Water Act (Brine)	
Regulatory Program(s)	Brine (NPDES)	
Company Name:	CapturePoint, LLC	
Facility Name:	North Burbank Unit (NBU) 83 Battery	
Facility Physical Location:	36.764850, -96.717475	
(city, state, zip code)	Webb City, Oklahoma, 74652	
Mailing address:	1833 S. Morgan Road	
(city, state, zip code)	Oklahoma City, Oklahoma, 73128	
County/Parish:	Osage	
Facility Phone Number	918-287-6811	
Facility Contact:	Talia Clark	HSE Tech
FRS Number:	n/a	
Identification/Permit Number:	OKU002216	
Media Identifier Number:	n/a	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Matthew Allen	EPA/Region 6 ECDW	Inspector
Talia Clark	CapturePoint, LLC	HSE Tech
EPA Lead Inspector Signature/Date		
	Matthew Allen	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Matthew Allen arrived at the CapturePoint, LLC / North Burbank Unit (NBU) 24 Battery (EPA ID No. OKU002216) at 9:47 AM on 4/22/2025 for an announced inspection. This was an EPA inspection in response to a National Response Center Spill Report (NRC No. 1420537) which was received by EPA Region 6. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. CapturePoint, LLC representative, Talia Clark, participated during the inspection. There was no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the CapturePoint, LLC North Burbank Unit 83 Battery, where NBU well 92-2 released oil into a nearby, unnamed tributary of Salt Creek.

Section II – OBSERVATIONS

I observed the well location for well 92-2. At the time of the inspection, the well had been plugged and restored. See photo No. 1 and 2, Appendix 1 (photo log). For additional GPS location information and photo metadata, see the attached photo log.

I observed the restored portion of the impacted tributary. See photo No. 3 and 5.

I observed a TDS field reading of 384.2 mg/L in the main channel of the impacted tributary. See photo No. 4.

Section III – AREAS OF CONCERN

There were no areas of concern at the time of the inspection.

Section IV – FOLLOW UP

No follow-up required.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 5 photos

Appendix 1

Photograph Log 5 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.764847, -96.717474		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010642

Orientation: W

Date of Photo: 4/22/2025

Time of Photo: 9:47 AM

Latitude: 36.764847

Longitude: -96.717474

Photographer: Matthew Allen

Description: This was the well location where the spill originated, post plugging and restoration.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.764847, -96.717474		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010643

Orientation: W

Date of Photo: 3/5/2025

Time of Photo: 9:48 AM

Latitude: 36.764847

Longitude: -96.717474

Photographer: Matthew Allen

Description: This was a view toward the east, across the well location, looking toward the unnamed tributary of salt creek.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 36.764847, -96.717474		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010644

Orientation: SSE

Date of Photo: 4/22/2025

Time of Photo: 9:48 AM

Latitude: 36.764840

Longitude: -96.717477

Photographer: Matthew Allen

Description: This was a view of the restored area along the impacted tributary of Salt Creek.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 36.764847, -96.717474		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010645

Orientation: E

Date of Photo: 4/22/2025

Time of Photo: 9:51 AM

Latitude: 36.764802

Longitude: -96.717421

Photographer: Matthew Allen

Description: This was a TDS field reading of 384.2 mg/L taken in the main channel of the impacted tributary.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Location: 36.764847, -96.717474		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010646

Orientation: S

Date of Photo: 4/22/2025

Time of Photo: 9:57 AM

Latitude: 36.764802

Longitude: -96.717421

Photographer: Matthew Allen

Description: This was an overview of the impacted portion of the unnamed tributary after the area was restored.