



Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	03/12/2024	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Tom #14	
Facility Physical Location:	Latitude: 33.34403, Longitude: -92.68669	
(city, state, zip code)	Smackover, AR, 71724	
Mailing address:	100 East 7 th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry C. Langley jloc58@yahoo.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002236	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date	UMA LAD  Digitally signed by UMA LAD Date: 2024.04.09 16:16:32 -05'00'	
	Uma Lad	Date
Supervisor Signature/Date	JEANNE ECKHART  Digitally signed by JEANNE ECKHART Date: 2024.04.09 16:19:47 -05'00'	
	Jeanne Eckhart	Date

Section I – INTRODUCTION**PURPOSE OF THE INSPECTION**

EPA Region 6 inspectors Michael Blaha, Kerri McCabe, and I, Uma Lad, arrived at Jerry Langley Oil Company, LLC, Tom #14, located off a lease road near All Gulf Road (33.34403, -92.68669) at 2:00 PM on March 12, 2024, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Jerry Langley Oil Company, LLC, Tom #14, which consists of two (2) storage tanks.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, pipes, valves, and tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed a low point in the secondary containment berm, see photo No. 3. I observed a leak from a capped secondary containment drainage pipe, see photo No. 4.

Section III – AREAS OF CONCERN

No closing conference was held due to no Jerry Langley Oil Company, LLC staff being present during the inspection. Areas of concern at the time of the inspection include the low point on the secondary containment berm and the leak from the capped secondary containment drainage pipe.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 4 photos taken on 03/12/2024

Appendix 1

Photograph Log

4 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.34403, -92.68669		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010200**Orientation:** WNW**Date of Photo:** 03/12/2024**Time of Photo:** 2:11 PM**Latitude:** 33.34403**Longitude:** -92.68669**Photographer:** Uma Lad**Description:** This photo was taken looking west-northwest and shows the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.34403, -92.68669		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010201**Orientation:** S**Date of Photo:** 03/12/2024**Time of Photo:** 2:12 PM**Latitude:** 33.34393**Longitude:** -92.68671**Photographer:** Uma Lad**Description:** This photo was taken looking south and shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.34403, -92.68669		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010202**Orientation:** SE**Date of Photo:** 03/12/2024**Time of Photo:** 2:14 PM**Latitude:** 33.34421**Longitude:** -92.686710**Photographer:** Uma Lad**Description:** This photo was taken looking southeast and shows low areas on the secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: 33.34403, -92.68669		
City: Smackover	County/Parish: Union	State: Arkansas

**Photo File Name:** R0010203**Orientation:** NW**Date of Photo:** 03/12/2024**Time of Photo:** 2:15 PM**Latitude:** 33.34376**Longitude:** -92.68644**Photographer:** Uma Lad**Description:** This photo was taken looking northwest and shows two (2) capped secondary containment drainage pipes. The drainage pipe on the left was leaking at the time the inspection.