

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	03/25/2025	Time	13:35
		Operator Representative	McCann Resources, Inc		
Operator Info	McCann Resources, Inc 1613 West 6th Street Bartlesville, OK 740033404 Phone: 918-337-4747	Inventory ID	OS2217000		
		API Well No			
		Lease Name	Parker		
		Well ID	W-85		
Location	SW 15 27N 12E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.812512	Longitude	-96.004684		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	McCann Resources, Inc		
Inspect No.		Date Last MIT	05/22/2018	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure		Fittings	N	N	Max Pressure 182
Lease Status	Inactive	Actual Pressure			Max Volume
Barrel Monitor Hooked Up?	N	Determined?			Max Inj Units Barrels Per Month
Barrel Fluid Level (%)		Static Fluid Level			
Flowline Hooked Up?	N	Determined?			
Injecting	N	Injection Rate (bpd)			
Inspection Comments	Well inaccessible by vehicle at the time of the inspection. Inspector observed well OS2217000, at the time of the inspection the well was 4.5" casing reduced to 1" valves. Inspector contacted Mr. McCann at the time of the inspection to address the lack of access and the need to schedule the overdue MIT.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.812512, -96.004684		
City: Bartlesville	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010627

Orientation: SSE

Date of Photo: 3/25/2025

Time of Photo: 1:35PM

Latitude: 36.812512

Longitude: -96.004684

Photographer: Matthew Allen

Description: This was well OS2217000 at the time of the inspection. The well was casing reduced to 1-inch fittings. The road to the well was impassible by vehicle.