

LEAK DETECTION REPORTING FORM ABERDEEN PVC PLANT

1. Honeywell Chromatograph No.	<u>New unit</u>									
2. Date	<u>12-30-78</u>									
3. Time	<u>1500</u>									
4. Monitoring Point With High Readings	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>	<u>4</u>
5. Readings, PRM	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>	<u>10</u>
6. Operator Action Result	<u>Reported same to shift supervisor</u>									
7. Shift Supervisor Action Result	<u>went with OP to check out AREA</u>									
8. Maintenance Action Result	<u>Found Gasket in 944 cond leaking called in maints man to work on same</u>									
9. Verified By	<u>[Signature]</u>									
10. Operator	<u>[Signature]</u>									
Shift Supervisor	<u>Alton Lewis</u>									

DTH 000105036