

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Michael Blaha	Inspection Date	05/23/2023	Time	14:55
Inspection Due		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC	Inventory ID	OS3127000		
	1717 South Boulder, Suite 900	API Well No			
	Tulsa, OK 74119	Lease Name	NRU		
	Phone: 918-392-3396	Well ID	NWN C-1		
Location	SW 32 25N 07E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.596746	Longitude	-96.577109		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	10/10/2020	Last Test Result	Fail
Casing	6	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 678
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	A fluid level was taken with a properly calibrated EPA issued Echometer. The fluid level observed during the inspection was 426 feet deep. The well was not connected during the inspection. The casing size was approximately 6-inch. One photograph was taken during the inspection and can be seen in the Inspection Photo Log.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.596746, -96.577109		
City: Fairfax	County/Parish: Osage County	State: Oklahoma



Photo File Name: R0010164

Orientation: E

Date of Photo: 5/23/2023

Time of Photo: 2:57 PM

Latitude: 36.596746

Longitude: -96.577109

Photographer: Jeanne Eckhart

Description: Contango Resources, LLC Well No. C-1 overview.