


ATTACHMENT C

Campbell Sand & Gravel, Co. Big Escambia Mine (North) Site Inspection Photographic Log

Escambia County, Florida
*(unless notated otherwise in comment section of
field tables)*

December 6, 2022

Overview Map





Title	Photo 1
Comment	Taken by Rachel Earwood
Description	Striking northeast/north; upstream. Looking toward Campbell property used for mining (Big Escambia Mine North) with bridge in horizon. Red arrow in top photo indicates direction of flow.



Title	Photo 2
Comment	Taken by Rachel Earwood
Description	Striking south, southwest; downstream. Looking toward highway bridge (FL-4). Red arrow in top photo indicates direction of flow.



Title	Photo 3
Comment	Taken by Rachel Earwood
Description	Striking northeast, north; upstream. Close-up of bridge at facility taken from Fischer Landing boat launch parcel. Red arrow in top photo indicates direction of flow.



Title	Photo 4
Comment	Taken by Rachel Earwood
Description	Striking northeast, east; downstream. Big Escambia River taken from bridge/Fannie Road. Red arrow in top photo indicates direction of flow.



Title	Photo 5
Comment	Taken by Rachel Earwood
Description	Striking north, northwest; upstream. View of Big Escambia Creek from further northward off bridge. Red arrow in top photo indicates direction of flow.




Title	Photo 6
Comment	Taken by Chris Parker; Escambia County, AL
Description	Striking east. Looking toward Big Escambia Creek, standing water present past initial tree line.




Title	Photo 7
Comment	Taken by Chris Parker; Escambia County, AL
Description	Striking west, southwest; upstream. Water flowing from mine pond to floodplain of Big Escambia Creek. Red arrow in top photo indicates direction of flow.




Title	Photo 8
Comment	Taken by Chris Parker; Escambia County, AL
Description	Striking southeast; downstream. Looking toward floodplain of Big Escambia River. Red arrow in top photo indicates direction of flow.



Title	Photo 9
Comment	Taken by Chris Parker
Description	Striking northwest; upstream. Mine pond. Red arrow in top photo indicates direction of flow.



Title	Photo 10
Comment	Taken by Chris Parker
Description	Striking south, southeast; downstream. Receiving pond. Red arrow in top photo indicates direction of flow.



Title	Photo 11
Comment	Taken by Chris Parker
Description	Striking north, northeast. U-shaped berm taken from walkable road.



Title	Photo 12
Comment	Taken by Chris Parker; Escambia County, AL
Description	Striking southeast. Mine pond taken from fill in wetland.



Title	Photo 13
Comment	Taken by Chris Parker
Description	Old sorter at the wash plant.




Title	Photo 14
Comment	Taken by Chris Parker
Description	Dredge, idle since approximately 2019.



Title	Photo 15
Comment	Taken by Chris Parker
Description	Striking east; downstream. Ditch from wash plant leading to wetland area adjacent to Big Escambia Creek. Red arrow in top photo indicates direction of flow.



Title	Photo 16
Comment	Taken by Chris Parker
Description	Striking north; upstream. Ditch from wash plant leading to same wetland area. Red arrow in top photo indicates direction of flow.



Title	Photo 17
Comment	Taken by Chris Parker
Description	Striking north; upstream. Taken from reference wetland area. Red arrow in top photo indicates direction of flow.



Title	Photo 18
Comment	Taken by Chris Parker
Description	Striking north; upstream. Taken from area below wash area. Ditch draining from wash area towards reference wetland. Red arrow in top photo indicates direction of flow.




Title	Photo 19
Comment	Taken by Chris Parker
Description	Striking northeast; upstream. Taken from area near wash area. Channel from pond at wash plant that connects to ditch leading from wash area to reference wetland. Red arrow in top photo indicates direction of flow.



Title	Photo 20
Comment	Taken by Chris Parker
Description	Striking northeast; upstream. Big Escambia Creek approximately 0.2 miles north of its confluence with the Escambia River. Red arrow in top photo indicates direction of flow.



Title	Photo 21
Comment	Taken by Chris Parker
Description	Striking southeast; downstream. Big Escambia Creek north of its confluence with the Escambia River. Red arrow in top photo indicates direction of flow.



Title	Photo 22
Comment	Taken by Chris Parker
Description	Striking south; downstream. Big Escambia Creek from the facility bridge. Red arrow in top photo indicates direction of flow.



Title	Photo 23
Comment	Taken by Chris Parker
Description	Striking northwest; upstream. Big Escambia Creek from the facility bridge. Red arrow in top photo indicates direction of flow.

PAGE INTENTIONALLY LEFT BLANK