

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	06/09/2025	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act-National Pollution Discharge Elimination System (Brine)	
Company Name:	Calgary Energy, LLC	
Facility Name:	Tidal Osage 1 Lease	
Facility Physical Location:	Latitude: 36.536835, Longitude: -96.404341	
(city, state, zip code)	Hominy, OK, 74035	
Mailing address:	4444 E. 146 th St. N	
(city, state, zip code)	Skiatook, OK, 74070	
County/Parish:	Tulsa	
Facility Phone Number	918-798-4510	
Facility Contact:	Blaine Haag	Co-Owner
	bhaag.calgaryenergyllc@gmail.com	
FRS Number:	n/a	
Identification/Permit Number:	OKU000893	
Media Identifier Number:	n/a	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Matthew Allen	EPA/Region 6 ECDW	Inspector
EPA Lead Inspector Signature/Date		
	Matthew Allen	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 Inspector, Matthew Allen, arrived at the Calgary Energy, LLC/Tidal Osage 1 Lease (EPA ID No. OKU000893) at 9:45 AM on 06/09/2025 for a follow-up inspection. This was an EPA follow-up inspection in response to an initial spill inspection conducted 4/23/2025 (NRC No. 1429257). The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There was no other federal, state, or local agency representative present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the Calgary Energy, LLC, Tidal Osage 1 Lease, where the Tidal Osage 1 well 1-2 released oil to the surface from a subsurface casing leak.

Section II - OBSERVATIONS

I observed the release point for the spill which was the Tidal Osage 1 well 1-2. The well was temporarily abandoned and was not in production at the time of the inspection. A catchpit had been installed at the location. I observed crude oil on the surface of the catchpit. See photos No. 1 and No 2. For additional GPS location information and photo metadata, please see Appendix 1 (photo log) attached to this report.

I observed an additional catchpit at the spill location which did not contain crude oil. See photo No. 3.

Section III – AREAS OF CONCERN

The primary area of concern was the crude oil located in the catchpit. No progress was made to prevent recurrence of the spill event. More than 45 days had passed since the spill inspection on April 23, 2025.

A temporary solution was applied to the well in 2021 but failed to prevent recurrence of the purging event.

A permanent solution to the failed well casing should be achieved to prevent additional recurrence of the spill event.

Section IV – FOLLOW UP

EPA inspector conducted a follow-up phone call with Calgary Energy, LLC representative, Blaine Haag, at the end of the inspection. Mr. Haag stated he was submitting an Osage 139 form to the BIA Osage Agency to begin the process of repairing or plugging the well.

EPA inspector will conduct follow-up calls, field meetings and inspections to ensure the impacted area is returned to “pre spill” condition.

EPA inspector will continue follow-up with Calgary Energy, LLC to observe the permanent solution to the recurrent purging problem.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 3 photos taken 6/09/2025

There are no additional appendices.

Appendix 1

Photograph Log

3 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.536835, -96.404341		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010691

Orientation: ESE

Date of Photo: 06/09/2025

Time of Photo: 9:51 AM

Latitude: 36.536835

Longitude: -96.404341

Photographer: Matthew Allen

Description: This was the facility signage observed at the spill location.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.536835, -96.404341		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010689

Orientation: W

Date of Photo: 06/09/2025

Time of Photo: 9:50 AM

Latitude: 36.536835

Longitude: -96.404341

Photographer: Matthew Allen

Description: This was the source of the spill, Tidal Osage 1 well number 1-2. The well was inactive at the time of the surfacing event. The catch pit was covered in oil at the time of the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 36.536835, -96.404341		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R001090

Orientation: E

Date of Photo: 06/09/2025

Time of Photo: 9:51 AM

Latitude: 36.536835

Longitude: -96.404341

Photographer: Matthew Allen

Description: This was an additional catchpit installed by the operator.