

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	01/16/2025	Time	09:25
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS3865000		
		API Well No			
		Lease Name	NBU		
		Well ID	102 W6		
Location	SW 06 26N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.759562	Longitude	-96.703548		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	06/09/2021	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 764
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed the location of well OS3865000. At the time of the inspection, surface restoration was complete.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.759562, -96.703548		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010565

Orientation: NNW

Date of Photo: 1/16/2025

Time of Photo: 10:25 AM

Latitude: 36.759652

Longitude: -96.703548

Photographer: Matthew Allen

Description: This was the location of well OS3865000 with the casing cutoff and capped 3 feet below the land. Surface restoration completed.