

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	01/13/2026	
Media Program:	Water (CWA)	
Regulatory Program:	Water (CWA) Brine Program (Oil & Gas Inspection)	
Company Name:	Enerco Operating Corporation	
Facility Name:	Fouke D-3 SWD System; Goldman A, Goldman-Mariman, Hunter Collins Leases	
Facility Physical Location:	Off County Road 22 at 33.31399, -93.82719	
(city, state, zip code)	Genoa, AR 71840	
Mailing address:	11535 East Ricks Circle	
(city, state, zip code)	Dallas, TX 75230	
County/Parish:	Miller County	
Facility Phone Number	870-953-0287	
Facility Contact:	Terry Collum	Field Supervisor
	terrycollum@enercooperating.com	
FRS Number:	N/A	
Identification/Permit Number:	ARU002309	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Tom McKay	EPA / Region 6	Inspector
Uma Lad	EPA / Region 6	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6	Inspector / Enforcement Officer
Terry Collum	Enerco Operating Corporation	Field Supervisor
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Tom McKay, Uma Lad, and Kerri McCabe arrived at the Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases, located off County Road 22 at 33.31399, -93.82719, at 9:40 AM on 01/13/2026 for an announced inspection. We met with Terry Collum, Field Supervisor for Enerco Operating Corporation. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection. EPA previously inspected this facility on 04/14/2025.

FACILITY DESCRIPTION

EPA conducted an inspection on the Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases. The Fouke D-3 SWD System consists of three (3) saltwater tanks, one (1) slop tank, three (3) injection pumps, and one (1) saltwater disposal (SWD) injection well. The Goldman A, Goldman-Mariman, Hunter Collins Leases consists of seven (7) oil storage tanks, four (4) heater treaters, and one (1) “not in use” storage tank.

Section II – OBSERVATIONS

I observed the facility, associated signage, injection well, storage tanks, heater treaters, and secondary containment see Appendix 1 (Photograph Log), Photo No. 1, No. 2, No. 7, and No. 8. For additional GPS location and photo metadata, see Appendix 1.

I observed two (2) injection pumps leaking crude oil at the Fouke D-3 SWD System, see Photo No. 3 through Photo No. 6. Loose oil surrounded the pumps.

Section III – AREAS OF CONCERN

EPA Region 6 inspectors Tom McKay, Kerri McCabe, and Uma Lad held a closing conference with Mr. Collum and discussed the following areas of concern at the time of the inspection:

- Two (2) injection pumps leaking crude oil; and
- Loose oil surrounding the leaking injection pumps.

Section IV – FOLLOW UP

Inspector will provide the completed inspection report to the company representatives.

On January 17, 2026, Mr. Collum submitted documentation demonstrating that Enerco Operating Corporation completed repairs on the injection pumps to stop the leaks and removed the loose oil surrounding the pumps.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 8 photos taken 01/13/2026.

Appendix 1

Photograph Log

8 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719					
City:	Genoa	County:	Miller County	State:	AR	Direction:	SSW
Filename:	R0011236.JPG	Photo Date:	01/13/2026		Time:	09:54:47	
Photographer:	Uma Lad			Witness Name:	Kerri McCabe/Tom McKay		



Description:	This photo was taken facing south-southwest and shows the facility sign for Fouke D-3 SWD System.		
Latitude:	33°18'52.83" N	Longitude:	93°49'38.826" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719						
City:	Genoa	County:	Miller County	State:	AR	Direction:		SSW
Filename:	R0011237.JPG	Photo Date:		01/13/2026		Time:	09:46:28	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing south-southwest and shows an overview of the Fouke D-3 SWD System.		
Latitude:	33°18'52.548" N	Longitude:	93°49'39.348" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719					
City:	Genoa	County:	Miller County	State:	AR	Direction:	SSW
Filename:	R0011238.JPG	Photo Date:	01/13/2026		Time:	09:55:08	
Photographer:	Uma Lad			Witness Name:	Kerri McCabe/Tom McKay		



Description:	This photo was taken facing south-southwest and shows one leaking injection pump at the Fouke D-3 SWD System.		
Latitude:	33°18'52.77" N	Longitude:	93°49'38.664" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719						
City:	Genoa	County:	Miller County	State:	AR	Direction:	SSW	
Filename:	R0011239.JPG	Photo Date:		01/13/2026		Time:	09:47:38	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing south-southwest and shows loose oil from the leaking injection pump in Photo No. 3.		
Latitude:	33°18'51.768" N	Longitude:	93°49'39.096" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719					
City:	Genoa	County:	Miller County	State:	AR	Direction:	SW
Filename:	R0011241.JPG	Photo Date:		01/13/2026		Time:	09:54:54
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay	



Description:	This photo was taken facing south-southwest and shows a second leaking injection pump with loose crude oil and salt at the Fouke D-3 SWD System.		
Latitude:	33°18'52.824" N	Longitude:	93°49'38.832" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719						
City:	Genoa	County:	Miller County	State:	AR	Direction:	SW	
Filename:	R0011242.JPG	Photo Date:		01/13/2026		Time:	09:52:32	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing southwest and shows the second leaking injection pump at the facility.		
Latitude:	33°18'52.368" N	Longitude:	93°49'39.204" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719						
City:	Genoa	County:	Miller County	State:	AR	Direction:	S	
Filename:	R0011244.JPG	Photo Date:		01/13/2026		Time:	09:56:41	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing south and shows a facility sign for the Goldman A, Goldman-Mariman, Hunter Collins Leases.		
Latitude:	33°18'52.38" N	Longitude:	93°49'37.356" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Facility/Location:		Enerco Operating Corporation / Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases off County Road 22 at 33.31399, -93.82719						
City:	Genoa	County:	Miller County	State:	AR	Direction:		SW
Filename:	R0011249.JPG	Photo Date:		01/13/2026		Time:	10:45:08	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe/Tom McKay		



Description:	This photo was taken facing southwest and shows an over of both the Fouke D-3 SWD System & Goldman A, Goldman-Mariman, Hunter Collins Leases.		
Latitude:	33°18'50.958" N	Longitude:	93°49'36.864" W