

Inspection Report Addendum for Well: MT20000-01067
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 1 of 6	Time: 3:55 pm		
Photo Description: Well sign by wellhead.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 2 of 6	Time: 3:55 pm		
Photo Description: Wellhead. Operator noted well is an active injector. Wellhead was observed to be connected to pipe flowline.			

Inspection Report Addendum for Well: MT20000-01067
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 3 of 6	Time: 3:55 pm		
Photo Description: Volume meter on wellhead read 91035.6 bbl.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 4 of 6	Time: 3:56 pm		
Photo Description: EPA's digital pressure gauge on tubing read 1163 psi on a 3000-psi range gauge. MAIP for well is at 2829 psi.			

Inspection Report Addendum for Well: MT20000-01067
Inspection Date: 10/24/2023

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 5 of 6	Time: 3:55 pm		
Photo Description: Tubing-casing annulus is maintained continuously open to atmospheric pressure. Open hole for tubing-casing annulus was initially observed to be partially buried during the inspection.			

U.S. Environmental Protection Agency Region 8		UIC PHOTOGRAPHIC LOG	
Facility Location: MT20000-01067 (66-W1), Glacier County, UT		Photographer: Gary Wang	Camera: Ricoh WG-5
Date Photograph Taken: 10/24/2023			
Photo No. 6 of 6	Time: 3:57 pm		
Photo Description: Operator dug out additional dirt and debris during inspection to provide greater access to tubing-casing annulus.			

 Inspector signature

 Inspector signature

 Inspector signature