

GOALS AND PLANS FOR 1982

1. CONTINUE TO INFORM ALL PLANT PERSONNEL ON BENZENE TOXICITY DATA.
2. TAKE EXCURSION DATA IN AREA WHERE PERSONNEL MAY BE EXPOSED TO BENZENE WHILE CHANGING FILTERS, OR PUMP SEALS AND ETC.
3. DEVELOP METHOD FOR RUNNING AIR SAMPLES FOR DICYCLOPENTADIENE, METHYL CYCLOPENTADIENES AND BIPHENYL.
4. TAKE EXCURSION DATA IN VARIOUS AREAS OF THE PLANT TO DETERMINE EXPOSURE TO DICYCLOPENTADIENE, BIPHENYL AND METHYL CYCLOPENTADIENE.
5. START A PROGRAM TO DETERMINE HOW MUCH EXPOSURE THERE IS TO WELDING FUMES IN THE WAREHOUSE.
6. COLLECT AIR SAMPLES TO CHECK FOR METALS WHEN CATALYST IS BEING DUMPED.
7. CONTINUE TO MONITOR PERSONNEL FOR EXPOSURE TO BENZENE WHEN CLEANING UP SPILLS. THIS INCLUDES TAKING URINE SAMPLES BEFORE AND AFTER THE WORK PERIOD.
8. RUN YEARLY NOISE SURVEY.

BH/ss
3/22/82