



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION 5
77 WEST JACKSON BOULEVARD
CHICAGO, ILLINOIS 60604**

DATE: MAR 25 2019

SUBJECT: CLEAN AIR ACT INSPECTION REPORT
Hustler Diesel Performance, New Lenox, Illinois

FROM: Cody Yarbrough, Environmental Engineer
AECAB (MN/OH)

THRU: Brian Dickens, Section Chief
AECAB (MN/OH)

TO: File

BASIC INFORMATION

Facility Name: Hustler Diesel Performance

Facility Location: 200 Ford Dr, New Lenox, Illinois

Date of Inspection: March 15, 2019

EPA Inspector(s):

1. Cody Yarbrough, Environmental Engineer
2. Sarah Clark, Environmental Engineer

Other Attendees

1. Receptionist, DS Auto Repair
2. Manager, DS Auto Repair

Contact Email Address: No email provided. Mail hardcopy to: 200 Ford Dr, New Lenox, IL 60451.

Purpose of Inspection: CAA Title 2 Vehicle and Engine Tampering

Facility Type: Automotive performance/repair shop

Regulations Central to Inspection: CAA Section 203(a)(3)(a) and 203(a)(3)(b) – motor vehicle tampering and defeat device prohibitions

Arrival Time: 9:25am CDT
Departure Time: 9:45am CDT

Inspection Type:

- ☒ Unannounced Inspection
☐ Announced Inspection

OPENING CONFERENCE

- ☐ Credentials Presented
☐ CBI warning to facility provided

Process Description:

Hustler's Facebook page (<https://www.facebook.com/Hustlerdp/>) describes the facility as an automotive repair shop. No further information was acquired during the inspection.

TOUR INFORMATION

EPA toured the facility: No

Observations:

Hustler Diesel Performance (Hustler) shares a building with DS Auto Repair (DS Auto), an auto-body repair shop. A receptionist at DS Auto informed us that Hustler's facility is located behind DS Auto, and a manager at DS Auto informed us that the owners of Hustler work full time jobs during the day and run the shop in the evening. The same manager showed us to the entrance of Hustler's shop and said that the door was locked and that the facility would be closed until the owners return in the afternoon, around 3:30pm.

Two Ford pickups located in the Hustler parking lot appeared to have aftermarket exhaust systems. The engine information was not retrievable, but the exhaust pipes downstream of the engine appeared to be straight pipes with no emission control device canisters.

Photos and/or Videos: were taken during the inspection.

Field Measurements: were not taken during this inspection.

SIGNATURES

Report Author: *Colby Yarbrough* Date: March 25, 2019
Section Chief: *Brian D. Evans* Date: 3/25/19

Facility Name: Hustler Diesel Performance
Facility Location: 200 Ford Dr, New Lenox, Illinois
Date of Inspection: March 15, 2019

ATTACHMENTS

1. Appendix A: Digital Image Log

Facility Name: Hustler Diesel Performance
Facility Location: 200 Ford Dr, New Lenox, Illinois
Date of Inspection: March 15, 2019

APPENDIX A: DIGITAL IMAGE LOG

1. Inspector Name: Sarah Clark	2. Date(s) of Inspection: March 15, 2019
3. Company/Facility Name: Hustler Diesel Performance	4. Street Address, City, State: 200 Ford Dr, New Lenox, Illinois
5. Number of Images: 11	6. Archival Record Location: CD-R labeled as "Hustler Diesel New Lenox, IL "Inspection" Photos 03-15-2019"

Image Number	File Name	Date and Time (CDT)	Description of Image
1	RIMG0001.JPG	3/15/2019 9:25	DS Auto Repair entrance
2	RIMG0002.JPG	3/15/2019 9:38	Hustler Diesel Performance entrance
3	RIMG0003.JPG	3/15/2019 9:38	Hustler Diesel Performance parking lot - 1
4	RIMG0004.JPG	3/15/2019 9:38	Hustler Diesel Performance parking lot - 2
5	RIMG0005.JPG	3/15/2019 9:39	Truck 1 license plate
6	RIMG0006.JPG	3/15/2019 9:39	Truck 1 exhaust - 1
7	RIMG0007.JPG	3/15/2019 9:39	Truck 1 exhaust - 2
8	RIMG0008.JPG	3/15/2019 9:39	Truck 1 exhaust - 3
9	RIMG0009.JPG	3/15/2019 9:40	Truck 2 exhaust - 1
10	RIMG0010.JPG	3/15/2019 9:40	Truck 2 license plate
11	RIMG0011.JPG	3/15/2019 9:40	Truck 2 exhaust - 2