

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	12/12/2023	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Jamie Oil, Inc.	
Facility Name:	Frost F#3, F#4, and F#5 Tank Battery	
Facility Physical Location:	Latitude: 33.24659, Longitude: -92.60201	
(city, state, zip code)	El Dorado, AR, 71730	
Mailing address:	1190 Cedarglade Road	
(city, state, zip code)	Hot Springs, Arkansas, 71913	
County/Parish:	Union County	
Facility Phone Number	870-814-5299	870-814-2258
Facility Contact:	Jimmy Crain	
	jcrain454@yahoo.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002200	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Chelsey Sherwood	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Tamara Griffin	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		1/30/2024
	Chelsey Sherwood	Date
Supervisor Signature/Date		
	Jeanne Eckhart (acting Chief Mitty Garcia)	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Chelsey Sherwood, Michael Blaha, and Tamara Griffin arrived at Jamie Oil, Inc., Frost F#3, F#4, and F#5 Tank Battery, located off Old Reed Place Road (33.24659, -92.60201) at 12:30PM on 12/12/2023 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on Jamie Oil, Inc., Frost F#3, F#4, and F#5 Tank Battery which contains two oil tanks, an oil separator, and a heater treater.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, oil tanks, oil separator, heater treater, and pipes located at the facility, see Appendix 1 (photo log), photo No. 1 for additional GPS location and photo metadata, see Appendix 1.

I observed **leaking around separator and loose oil within secondary containment, see photo number 2.**

I observed **no caps on pipes from oil tanks, see photo number 3.**

Section III – AREAS OF CONCERN

No closing conference was held due to no Jamie Oil, Inc. staff being present during the inspection. Areas of concern at the time of the inspection include: 1) storage tank open and not cleaned out and should be if out of service; 2) oil tank and separator leaking; 3) loose oil within secondary containment; and 4) no caps on pipes from oil tanks.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 3 photos taken 12/12/2023

Appendix 1

Photograph Log

3 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.24659, -92.60201		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6190

Orientation: E

Date of Photo: 12/12/2023

Time of Photo: 12:35 PM

Latitude: 33.246587

Longitude: -92.602020

Photographer: Chelsey Sherwood

Description: This photo was taken looking E at the facility showing the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.24659, -92.60201		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6191

Orientation: N

Date of Photo: 12/12/2023

Time of Photo: 12:37 PM

Latitude: 33.246537

Longitude: -92.601947

Photographer: Chelsey Sherwood

Description: This photo was taken looking N at the facility showing leaking from separator and loose oil in secondary containment.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.24659, -92.60201		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6192

Orientation: W

Date of Photo: 12/12/2023

Time of Photo: 12:38 PM

Latitude: 33.246584

Longitude: -92.601948

Photographer: Chelsey Sherwood

Description: This photo was taken looking W at the facility showing an overview of the facility. Note no caps on pipes.