

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/4/2025	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Betsy Production Company, Inc.	
Facility Name:	Southern Corley SWD	
Facility Physical Location:	Latitude: 33.40245 Longitude: -92.954405	
(city, state, zip code)	Stephens, AR, 71764	
Mailing address:	1621 Commerce Street	
(city, state, zip code)	Magnolia, AR, 71753	
County/Parish:	Ouachita County	
Facility Phone Number	870-234-5858	
Facility Contact:	Mike Davis debbie@betsypro.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002299	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Michael Blaha (lead)	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Kerri McCabe	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		
	Michael Blaha	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha and Kerri McCabe arrived at Betsy Production Company, Inc. – Southern Corley SWD, located off County Road 2 (33.40245, -92.954405) at 3:10 PM on March 4, 2025, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Betsy Production Company, Inc. – Southern Corley SWD, which consists of one (1) injection well, and four (4) storage tanks.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, pipes, valves, and storage tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed a historical impacted flow path from the facility, see photo No. 3.

Section III – AREAS OF CONCERN

No closing conference was held due to no Betsy Production Company, Inc. staff being present during the inspection. An area of concern at the time of the inspection is the historical impacted flow path from the facility.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 4 photos taken on 3/4/2025

Appendix 1

Photograph Log

3 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.40245, -92.954405		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_213632510_iOS

Orientation: W

Date of Photo: 3/4/2025

Time of Photo: 3:36 PM

Latitude: 33.40245

Longitude: -92.954405

Photographer: Michael Blaha

Description: This photo was taken looking northwest and shows the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.40245, -92.954405		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_213719639_iOS

Orientation: W

Date of Photo: 3/4/2025

Time of Photo: 3:37 PM

Latitude: 33.402456

Longitude: -92.95423

Photographer: Michael Blaha

Description: This photo was taken looking west and shows an overview of the facility.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.40245, -92.954405		
City: Stephens	County/Parish: Ouachita	State: Arkansas



Photo File Name: 20250304_213914160_iOS

Orientation: W

Date of Photo: 3/4/2025

Time of Photo: 3:39 PM

Latitude: 33.402492

Longitude: -92.954636

Photographer: Michael Blaha

Description: This photo was taken looking west showing a historical impacted flow path.