

ENGINEERING
INDUSTRIAL HYGIENE SURVEY DATA SHEET (See instructions on reverse side)
THE TRAVELERS INSURANCE COMPANIES
HARTFORD, CONNECTICUT 06183 (Location 2-5-116)

PAGE 3 OF 4

CUSTOMER GENUINE PARTS CO., INC. - RAYLOC		LOCATION 100 Rayloc Dr. Hancock, Maryland 21750	SURVEY DATE February 28, 1989
POLICY NUMBER/CLAIM NUMBER UB 168 T 3075		BUSINESS UNIT: ☒ SAM/CAD ☐ CAM ☐ FIELD (AMG.) ☐ CLAIM ☐ CSSC ☐ OTHER (EXPLAIN)	

INSTRUMENTATION

INSTRUMENT HI FLOW SAMPLER		MANUFACTURER CILIAN	MODEL HFS-113
SERIAL NUMBER	TIC NUMBER	REASON FOR SAMPLING - INCLUDE PROCESS OR OPERATION DESCRIPTION & CONTROLS	
1017	3/81	Division management's request to assess employee's potential exposure to asbestos fibers in the	
1994	25/82	Brake Shoe Department during typical brake rebuild operations such as chopping, midas belt sorting,	
	68/83	clutch disc drilling, burning, and disc brake riveting. Remanufacturing of automotive parts.	
10459	181/85		
5879	101/84		

COLLECTION (SAMPLING) MEDIA MILIPORE FILTERS (OPEN FACED)	ANALYSIS REQUIRED ASBESTOS FIBERS (Including TEMS Analysis)
--	--

SAMPLE DATA

TIC INST NO.	SAMPLE NUMBER	SAMPLING LOCATION (INCLUDE EMPLOYEE'S NAME)	COLLECTION TIME		COLLECTION DURATION (MINS)	FLOW RATE (LPM)	SAMPLER POSITION	NUMBER OF PERSONS IN AREA	EXPOSURE TIME (MINS)	SHIFT DURATION (MINS)	COMMENTS
			Start	End							
68/83	224F	Darrel Miller	1408	1550	102	2.0	PS	2	450	510	Local exhaust ventilation
		Clutch Disc Driller									
181/85	427F	David Golder	0741	1155	254	2.0	PS	2	450	510	General ventilation
		Burn Room Operator									
181/85	429F	David Golden	1241	1405	84	2.0	PS	2	450	510	General ventilation
		Burn Room Operator									
181/85	217F	David Golden	1405	1549	104	2.0	PS	2	450	510	General ventilation
		Burn Room Operator									

OFFICE Baltimore	ENGINEER J. E. David, III	SIGNATURE <i>Joseph E. David, III</i>	DATE SIGNED 5-19-89
---------------------	------------------------------	--	------------------------

NOVO20298