



REGION 4

ATLANTA, GA 30303

SENT VIA ELECTRONIC MAIL

Tyler Wyatt
Manager
1925 State Road 60 W
Lake Wales, Florida 33859
meyerstowing@yahoo.com

Dear Tyler Wyatt:

On March 21, 2024, the Environmental Protection Agency Region 4 Air Enforcement Branch conducted an inspection of Meyer's Towing Inc. facility located in Lake Wales, Florida. We have enclosed the final inspection report generated for this inspection (Enclosure A).

The EPA previously sent Meyer's Towing Inc. a copy of the draft inspection report in an email dated May 7, 2024, allowing Meyer's Towing Inc. the opportunity to make any comments on the report and to claim any information contained in the report as confidential business information (CBI). In a call on May 16, 2024, Meyer's Towing Inc. notified the EPA that the company does not wish to claim any part of the inspection report as CBI.

If you have any questions regarding this inspection report, please contact me at 404-562-9727, or by email at rivera.lorianny@epa.gov.

Sincerely,

LORIANNY
RIVERA

Lorianny Rivera
Environmental Scientist
South Air Enforcement Section

 Digitally signed by LORIANNY
RIVERA
Date: 2024.05.17 09:24:48 -04'00'

ENCLOSURE A
INSPECTION REPORT

Clean Air Act Title II: Mobile Source Inspection

INSPECTION REPORT

Attached please find the United States Environmental Protection Agency's inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to this Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Date(s):	March 21, 2024
EPA Region/Program Conducting Inspection:	EPA Region 4 Air Enforcement Branch
Company Name:	Meyer's Towing Inc.
Facility Name:	Meyer's Towing Inc.
Facility Physical Location: (street address, building/unit #)	1925 State Rd 60 W
(City, state, zip code)	Lake Wales, Florida 33859

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Approval

Lorianny Rivera

Field Inspector Name

LORIANNY RIVERA Digitally signed by LORIANNY RIVERA
Date: 2024.05.17 09:25:22 -04'00'

Signature

Date

Todd Groendyke

Name of Approving
Official

Chief, SAES

Title

TODD GROENDYKE Digitally signed by TODD
GROENDYKE
Date: 2024.05.17 08:17:43 -04'00'

Signature

Date

Clean Air Act Title II: Mobile Source Inspection

FACILITY INSPECTION WORKSHEET

General Inspection Information			
Facility Name:	Meyer's Towing Inc.	Inspection Date	3/21/2024
Facility Address:	1925 State Rd 60 W Lake Wales, FL 33859	Arrival/Departure Time	10:55 AM EDT 11:57 AM EDT
		Inspection Number/ID:	3601643853
Primary Facility Representative & Title:	Tyler Wyatt, Manager	Inspector(s):	Lorianny Rivera Aleeka Broner
Facility Contact Phone/Email:	863-676-7666 meyerstowing@yahoo.com		
Time Inspector Presented Credentials:	11:00 AM EDT	Compliance Assistance Materials Provided to Facility:	U.S. EPA Small Business Resources Information Sheet Enforcement Alert
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	☒ Yes ☐ No Tyler Wyatt		
Photographer Name:	Aleeka Broner		
Additional Personnel Present:	N/A	Areas Discussed:	☒ CBI ☒ Equipment (OBD scanner, camera) ☒ Safety Requirements
Facility Summary:	The company has been in business for 45 years, and the current owner has been the owner for the last 15 years. They have seven employees. They own all four vehicles in their fleet. The company provides service to Triple A, Pulk County, several other counties, and the sheriff's office.		

Facility Business Activities			
Types of Services (Check all that apply)		Description/Observations (Types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☐	Sells aftermarket parts		
☐	Service shop		
☒	Fleet	The oldest vehicle in the fleet is from 2022. The regular maintenance work is done every 20,000-30,000 miles. Once they reach 180,000-200,000 miles, they trade the vehicles. The maintenance that is not covered by then warranty is done on site.	The company tows approximately 25 vehicles per day.
☐	Other:		

Clean Air Act Title II: Mobile Source Inspection

Personnel Interviewed			
Name	Title/Position	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Tyler Wyatt	Manager	meyerstowing@yahoo.com 863-676-7666	Rivera

Documents Requested		
Document(s)	Status	Notes/Comments
List of the parts ordered during the last 4 months (November, 2023-February, 2024)	☐ Document(s) Provided ☒ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)
	☐ Document(s) Provided ☐ Will Provide After Inspection	☐ Document(s) Denied ☐ Other (see notes)

Vehicles Inspected/Observed				
VIN (last 4 digits)	Identification Number	Appearance of Tampering (Yes/No/TBD)	OBD Data Obtained? (Yes/No)	Observations (e.g., Who Performed Apparent Tampering?)
4615	Vehicle #3 License Plate E4275E	TBD	Yes	
4618	Vehicle #7 License Plate E4020E	TBD	Yes	

PHOTOGRAPH LOG

Meyer's Towing Inc.

Image Number	File Name	Date and Time (incl. time zone and DST)	Description of Image
1	P3211136.JPG	2024:03:21 11:23:26	VIN Number Vehicle #3
2	P3211137.JPG	2024:03:21 11:23:30	VIN Number Vehicle #3
3	P3211138.JPG	2024:03:21 11:23:43	Emission Control Label
4	P3211139.JPG	2024:03:21 11:24:01	Engine Left Side
5	P3211140.JPG	2024:03:21 11:24:14	Engine Right Side
6	P3211141.JPG	2024:03:21 11:24:46	Engine
7	P3211142.JPG	2024:03:21 11:24:57	Exhaust System
8	P3211143.JPG	2024:03:21 11:25:00	DEF Tank
9	P3211144.JPG	2024:03:21 11:25:40	Dash Gauges
10	P3211145.JPG	2024:03:21 11:25:43	Dash Gauges
11	P3211146.JPG	2024:03:21 11:26:18	License Plate
12	P3211147.JPG	2024:03:21 11:34:06	Vehicle Emission Control Information
13	P3211148.JPG	2024:03:21 11:34:10	Manufacture Label
14	P3211149.JPG	2024:03:21 11:34:20	Manufacture Label
15	P3211150.JPG	2024:03:21 11:34:25	Right Side of the Engine
16	P3211151.JPG	2024:03:21 11:34:31	Engine
17	P3211152.JPG	2024:03:21 11:34:42	Transmission Oil
18	P3211153.JPG	2024:03:21 11:34:57	Hose Connected to the Engine
19	P3211154.JPG	2024:03:21 11:35:06	DEF Tank
20	P3211155.JPG	2024:03:21 11:35:17	Exhaust System
21	P3211156.JPG	2024:03:21 11:35:26	Exhaust System
22	P3211157.JPG	2024:03:21 11:36:28	License Plate
23	P3211158.JPG	2024:03:21 11:37:07	Dash Gauges
24	P3211159.JPG	2024:03:21 11:37:18	Dash Gauges

Photographs were taken by EPA inspector Aleeka Broner.